

# ***TRUPACT-II 157 Examination Report***

*Barry H. O'Brien  
Jeffrey M. Lacy  
Kip E. Archibald*

*December 2003*



*Idaho National Engineering and Environmental Laboratory  
Bechtel BWXT Idaho, LLC*



# **TRUPACT-II 157 Examination Report**

**Barry H. O'Brien  
Jeffrey M. Lacy  
Kip E. Archibald**

**December 2003**

**Idaho National Engineering and Environmental Laboratory  
Clean/Close RWMC Project  
Idaho Falls, Idaho 83415**

**Prepared for the  
U.S. Department of Energy  
Assistant Secretary for Environmental Management  
Under DOE Idaho Operations Office  
Contract DE-AC07-99ID13727**





## **ABSTRACT**

This report presents the results of examination and recovery activities performed on the TRUPACT-II 157 shipping container. The container was part of a contact-handled transuranic waste shipment being transported on a truck to the Waste Isolation Pilot Plant in New Mexico when an accident occurred. Although the transport vehicle sustained only minor damage, airborne transuranic contamination was detected in air samples extracted from inside TRUPACT-II 157 at the Waste Isolation Pilot Plant. Consequently, the shipping container was rejected, resealed, and returned to the Idaho National Engineering and Environmental Laboratory where the payload was disassembled, examined, and recovered for subsequent reshipment to the Waste Isolation Pilot Plant. This report documents the results of those activities.



## SUMMARY

On August 23, 2002, a shipment of contact-handled transuranic waste consisting of two TRUPACT-II (transuranic package for transportation, Type II) containers, each containing 14 waste drums, was assembled at the Radioactive Waste Management Complex (RWMC) on the Idaho National Engineering Laboratory (INEEL), and transported to the Waste Isolation Pilot Plant (WIPP) in New Mexico for long-term storage. On August 25, 2002, just prior to arriving at WIPP, the shipment was involved in a vehicle accident. During the shipment receipt process at WIPP, sampling of the radiological assessment filter (RAF) on shipping container TRUPACT-II 157 indicated airborne alpha-contamination of the inner containment vessel (ICV). Consequently, on August 29, 2002, TRUPACT-II 157 was returned to the INEEL to perform recovery and examination of the payload.

TRUPACT-II 157 was disassembled and examined inside the INEEL Test Area North (TAN) Hot Shop in accordance with procedures approved by the Department of Energy Idaho Operations Office (DOE-ID) and Carlsbad Field Office of DOE. Recovery, examination and repackaging of the payload drums was performed from January 27 to February 3, 2003. On February 3 and 4, 2003, the outer containment vessel (OCV), ICV, and 14 waste drums were transported back to the RWMC. On February 5, 2003, the standard waste boxes containing the TRUPACT-II 157 payload drums (excluding one drum found with surface contamination) were placed into three TRUPACT-IIs for return to WIPP. The shipment left the INEEL on February 12, 2003, arriving at WIPP February 13, 2003, where the payloads were placed underground on February 19, 2003.

During the recovery process, videos, still-shot photos, air samples, and smears were taken of the OCV, ICV, various packaging components, and the 55-gal drums that made up the payload. Disassembly and recovery of the TRUPACT-II 157 payload was conducted smoothly and successfully, without complication.

This report addresses only observations made during the recovery and examination of TRUPACT-II 157 per approved examination plan PLN-1169. The examination was not a root cause investigation. The examination of the TRUPACT-II 157 provided the following results:

- The vehicle accident did not compromise the integrity of the TRUPACT-II 157 shipping container as evidenced by the following:
  - No physical damage was observed on either the OCV or the ICV
  - No contamination was found on the exterior or interior of the OCV
  - No contamination was found external to the ICV.
- The vehicle accident did not cause the contamination found in TRUPACT-II 157 as evidenced by the following:

- No damage was found on the ICV lid or the honeycomb spacers, slip sheets, or guide tubes inside the ICV
- No physical damage was evident on the drums inside the ICV
- No shifting of the payload was apparent.
- The contamination found on Drum IDRF741202484 was contained within the ICV.
- The ICV was found to be under vacuum after over 4 months storage prior to initiating the recovery operation. This attests to the high integrity and sealing capability of the TRUPACT-II shipping container.
- Drum IDRF741202484 was found to have localized contamination on top of the drum lid. The contamination found was up to 110 dpm/100 cm<sup>2</sup> alpha, which exceeds the limit of 20 dpm/100 cm<sup>2</sup> alpha.
  - Radiological analysis of the contamination showed it to be consistent with the drum's radiological contents.
- Drum IDRF741202484 was also found to have a loose lock-ring bolt, such that the lock ring could be rotated by hand.
- Contamination smears of drum surfaces adjacent to and below the lock ring of Drum IDRF741202484 were within limits. The first smear on and around the filter was also within limits. The follow-up smear on and around the filter was above the alpha limit but the smear extended farther onto the drum lid surface.
- The results of the examination did not conclusively identify the exact leakage point from drum IDRF741202484. However, it was confirmed that this drum was the source of the contamination.
- A loose lock-ring bolt jam nut was also discovered on Drum IDRF74700411, although the lock-ring bolt was secure.
  - This drum did not have contamination above limits.

## ACKNOWLEDGMENTS

A special thanks to the following people and organizations for successfully recovering and over-packing the waste drums from TRUPACT-II 157, and for providing information for this report.:

- 3100 m<sup>3</sup> Project personnel from the Radioactive Waste Management Complex
- Operations personnel under supervisor D. A. Wale and foreman K. L. Kynaston from Test Area North
- Radiological control technicians under foreman Gary Lusk from Test Area North
- Carpenters from Test Area North who constructed the work platform, ICV box, payload sleeving, and contamination control tent
- Quality engineering support personnel from the 3100 m<sup>3</sup> Project and TAN Operations organizations.
- DOE-ID and CBFO support for the recovery.
- R. B. King for providing Technical Editing.
- Chris Morgan for video editing.



# CONTENTS

ABSTRACT.....	iii
SUMMARY .....	v
ACKNOWLEDGMENTS .....	vii
ACRONYMS.....	xiii
1. INTRODUCTION.....	1
1.1 TRUPACT-II 157 Shipment and Accident.....	1
1.2 Radiological Data on TRUPACT-II 157 Taken at WIPP .....	1
1.3 Return Shipment and Storage at the INEEL .....	2
1.4 TRUPACT-II Assembly .....	3
1.4.1 14-Drum Payload Configuration in TRUPACT-II 157 .....	5
1.5 Recovery Plan .....	6
1.5.1 TRUPACT-II 157 Recovery Plan.....	6
1.5.2 Description of the TAN-607 Hot Shop.....	9
2. THE PAYLOAD EXAMINATION PLAN .....	10
3. QUALITY ASSURANCE.....	11
4. RECOVERY, EXAMINATION, AND DISCUSSION .....	12
4.1 Recovery Operations.....	12
4.2 Sequence of Operations .....	15
4.2.1 OCA/ICV Handling and Payload Removal .....	15
4.2.2 Drum Examination and Over-packing Operations .....	17
4.2.3 Abnormalities Found During the Examination.....	20
4.2.4 Handling of the SWBs and Removal from TAN Hot Shop.....	22
4.3 Radioactive Contamination Surveys of TRUPACT-II 157.....	23
4.4 List of Facts Relevant to TRUPACT-II 157 Recovery and Examination.....	25
5. RESULTS.....	27
6. RECOVERY OPERATIONS LESSONS LEARNED .....	28
7. REFERENCES .....	29

Appendix A—WIPP Reports, Accident Report, and Results of Surface and Airborne Contamination Measurements .....	A-i
Appendix B—TRUPACT-II 157 Payload #6469 Assembly Documents .....	B-i
Appendix C—Operating Procedures for Recovery Operations .....	C-i
Appendix D—Examination Engineers’ Daily Log .....	D-i
Appendix E—Sequence of Operations and Equipment Used .....	E-i
Appendix F—Video Log of Recovery Operations .....	F-i
Appendix G—Resumes of Investigators.....	G-i

## FIGURES

1. TRUPACT-II 157 in the WMF-628 storage module at the RWMC. ....	3
2. TRUPACT-II outer containment assembly (adapted from Reference 2). ....	4
3. TRUPACT-II closure/seal area (adapted from Reference 3). ....	5
4. Example of TRUPACT-II 14-drum payload configuration (adapted from Reference 2).....	6
5. Configuration of payload.....	7
6. Aerial view of TAN.....	9
7. Payload disassembly and drum examination tent.....	13
8. ICV lid with sleeving and surrounding work platform.....	13
9. Processing tent and payload in sleeving prior to lowering into tent.....	14
10. Outer playpen with staged SWBs and ICV box. ....	15
11. ICV lid separation in sleeve. ....	17
12. Lifting the payload from the ICV.....	18
13. Photo of the tamper indicating seal for IDRF741202484.....	20
14. Drum IDRF741202484 inside the examination vestibule. ....	21
15. Photograph of lock bolt jamb nut position on Drum IDRF074700411. ....	21
16. TRUPACT-II 157 drum lid smear results. ....	22



## TABLES

1.	Summary of WIPP RAF samples from TRUPACT-II 157. ....	2
2.	ICV and drum examination summary. ....	19
3.	Results of air sample from inside of the sleeved ICV immediately after lifting the lid by ~18 in. ....	24
4.	Comparison of actinide radiochemical analyses of INEEL drum assay and smears with WIPP analyses of the radiological assessment filters. ....	24



## ACRONYMS

ANL-W	Argonne National Laboratory-West
CAM	constant air monitor
CBFO	Carlsbad Field Office of DOE
CH-TRU	contact-handled transuranic
cpm	counts per minute of radioactivity
DOE	U.S. Department of Energy
DOE-ID	U.S. Department of Energy Idaho Operations Office
dpm	disintegrations per minute of radioactivity
ICV	inner containment vessel
INEEL	Idaho National Engineering and Environmental Laboratory
in. Hg	inch mercury column—a unit of pressure equal to about ½ psi
OCA	outer containment assembly (consisting of the OCV, ICV, and Payload)
OCV	outer containment vessel (without ICV and Payload)
psig	pounds per square inch pressure, gauge
RAF	radiological assessment filter
RWMC	Radioactive Waste Management Complex
SWB	DOT 7A standard waste box
SWEPP	Stored Waste Examination Pilot Plant
TAN	Test Area North
TRU	transuranic
TRUPACT-II	transuranic package for transportation, Type II
VOC	volatile organic compound
WIPP	Waste Isolation Pilot Plant



# TRUPACT-II 157 Payload Examination Report

## 1. INTRODUCTION

The purpose of this report is to document the results of performing the work described in the TRUPACT 157 Payload Examination Plan.<sup>1</sup> The examination was not a root cause investigation. The scope of the report included documentation of the recovery operations procedures, as-found condition of the payload and shipping containers before and during recovery, results of contamination measurements, examination log, compilation of the information collected during the examination that may be used to support transportation and disposition of the inner containment vessel (ICV), documentation of auxiliary examination activities such as containment tents and over-packing of the payload, and lessons learned from the recovery effort. Video tapes, DVD discs, and still images were to be provided to supplement the written report as directed by the project manager.

### 1.1 TRUPACT-II 157 Shipment and Accident

On August 23, 2002, a shipment (IN020271) containing two TRUPACT-II (transuranic packages for transportation, Type II) shipping containers (151 and 157) was released for shipment from the Idaho National Engineering and Environmental Laboratory (INEEL) to the Waste Isolation Pilot Plant (WIPP) in New Mexico. Each TRUPACT-II container was loaded with fourteen 55-gal drums of sludge and filter waste. The shipment was in radiological compliance with TRUPACT-II transportation requirements. Those requirements are that a shipment have a radiological dose rate of <200 mrem/hr at the contact, <20 dpm/100 cm<sup>2</sup> alpha ( $\alpha$ ) emitting radionuclides, and <200 dpm/100 cm<sup>2</sup> beta-gamma ( $\beta\gamma$ ) emitting radionuclides.

On August 25, 2002, the shipment was involved in a vehicle accident about 25 miles before the WIPP truck arrived at WIPP. A pickup truck ran into the rear left of the WIPP truck trailer. Although the WIPP truck received little damage, the pickup truck was heavily damaged. After a full inspection by the New Mexico Department of Transportation, the WIPP truck was allowed to proceed to the site. The New Mexico State Police accident report and a Carlsbad Field Office of DOE (CBFO) analysis of the accident with photographs are provided in [Appendix A](#).

### 1.2 Radiological Data on TRUPACT-II 157 Taken at WIPP

After receipt and processing into WIPP, the TRUPACT-II 151 and 157 shipping containers were removed from the trailer and staged in the Waste Handling Building for unloading.

During the morning of August 25, 2002, the shipping documentation was reviewed and initial surface radiological smears of the shipping containers were completed. No surface contamination was found on either TRUPACT-II. Unloading operations continued until an analysis of the filter, downstream of the vacuum tool used to evacuate the ICV before lid removal, indicated elevated alpha activity in TRUPACT-II 157. The air sample was conducted by drawing a vacuum of approximately 4 in. Hg on the ICV through the vent port. The air sample passed through a radiological assessment filter (RAF). Although not calibrated to quantify airborne contamination, the RAF samples are used by WIPP to assess gross contamination inside the ICV prior to opening. The RAF was subsequently counted on an Eberline Alpha-6 continuous air monitor (CAM). Two measurements were taken 6 minutes apart, yielding indications of 27–30 dpm alpha activity on the filter. The peak channel on the counter was indicative of plutonium contamination. The RAF filter was then transferred to the WIPP radiochemistry lab and subjected to a 10-minute gross alpha-beta count using a gas proportional counter. This indicated alpha and beta activity of approximately 30 dpm and 3.4 dpm, respectively.

The following day (Monday, August 26, 2002), WIPP personnel developed and implemented a procedure to further assess TRUPACT-II 157. Using the procedure, three additional air samples were drawn through the ICV vent port, each time allowing air to refill the ICV after the sampling. Following each sample, ambient air was reintroduced to the ICV over a period >1/2 minute, bringing it back to atmospheric pressure. The resultant RAF filters were evaluated in a manner similar to that reported above. The results of all four samples are summarized in Table 1 (see [Appendix A](#) for a complete summary of the operations and data collected at WIPP). WIPP personnel estimated the first sample to consist of 0.2 m<sup>3</sup> of air, and the remaining samples to consist of 0.7 m<sup>3</sup> of air from the ICV. The difference in volumes was due to the first sample being taken using 4 in. Hg vacuum while the additional samples were taken using 12 in. Hg vacuum.

Due to regulatory considerations, the ICV could not be opened at WIPP. The potential existed for contaminating the inside of the Waste Handling Building. The most prudent course of action was determined to be to replace the outer containment vessel (OCV) lid, reseal the TRUPACT-II outer containment assembly (OCA), and ship TRUPACT-II 157 back to INEEL, which has facilities and personnel trained to handle contaminated waste containers, and where the payload could be evaluated.

Table 1. Summary of WIPP RAF samples from TRUPACT-II 157.

Sample Designation	Sampling Date and Time	Alpha-6 CAM <sup>a</sup> (cpm)	Gross Alpha <sup>b</sup> (dpm)	Gross Beta <sup>b</sup> (dpm)	Am-241 $\gamma$ -spec. <sup>c</sup>	Pu-238 <sup>d</sup>	Pu-239-240 <sup>d</sup>
TP157RAF	8/25/02 13:34, 13:40	5.7 and 5.3	29.7	3.4	2.6	0.7	19.9
157RAF-2	8/26/02 14:40	240	2530 (~1900) <sup>e</sup>	1090	176	Not Available	Not Available
2 <sup>nd</sup> Pull	8/26/02 16:10	465	4380 (~3300) <sup>e</sup>	1450	309	Not Available	Not Available
3 <sup>rd</sup> RAF	8/26/02 18:02	890	6030 (5500) <sup>e</sup>	794	464	132	1640

a. Gross count rate (cpm) in the Pu region of Alpha-6 CAM (efficiency ~20%).

b. Initial counting from the gas proportional counter in dpm.

c. Counted using a geometry-calibrated gamma spectrometer, dpm.

d. Results from radiochemistry extraction and alpha spectrometry, dpm.

e. Gross alpha dpm several hours after sample collection (without Rn decay progenies).

### 1.3 Return Shipment and Storage at the INEEL

On August 28, 2002, TRUPACT-II 157 was resealed and shipped back to the INEEL. When the shipment arrived at the INEEL on August 29, 2002, TRUPACT-II 157 was off-loaded and placed into Resource Conservation and Recovery Act-compliant storage in building WMF-628 at the Radioactive Waste Management Complex (RWMC) (see Figure 1), where it remained in monitored storage until an approved location and method of handling this Resource Conservation and Recovery Act waste was obtained.



PD03-0084-01

Figure 1. TRUPACT-II 157 in the WMF-628 storage module at the RWMC.

## 1.4 TRUPACT-II Assembly

The TRUPACT II container has a USNRC Certificate of Compliance as a Type B with designation B(U)F under 10 CFR 71.12. The TRUPACT-II 157 assembly consisted of a standard TRUPACT-II shipping package and a payload of fourteen 55-gallon drums containing contact-handled transuranic (CH-TRU) waste consisting of filter media and sludges ([Appendix B](#)). The TRUPACT-II containers are designed to transport transuranic waste to WIPP and provide contamination containment in the event of a payload leak.

A TRUPACT-II shipping package is composed of an OCA which includes an OCV, ICV, two aluminum honeycomb spacer assemblies, and the payload. The OCV provides a primary containment boundary and acts as an environmental barrier, the ICV provides a secondary containment boundary, the two aluminum honeycomb spacer assemblies fit within the dished head at each end of the ICV, and the payload goes inside the ICV between the spacer assemblies. Figure 2 illustrates an exploded view of the TRUPACT-II packaging components.<sup>2</sup> Figure 3 presents a detailed view of the closure/seal areas.<sup>3</sup>

The ICV and the OCA each have a seal test port and vent port. The seal test port in each vessel provides access to the volume between the two o-ring seals that exist between the lid and body (upper and lower, respectively) seal flanges. The seal test ports are used to demonstrate the leak tightness of the seals and to verify proper assembly of the packaging prior to shipment. The vent port is used during loading and unloading to facilitate lid installation and removal. A negative pressure of 2 to 4 in. Hg (1 to 2 psig) on the vent port is necessary to allow the locking ring to be freely rotated. At the receiving end of shipment, this same vent port is used to relieve any vacuum or pressure resulting from different atmospheric pressures at the shipping and receiving locations.




Figure 2. TRUPACT-II outer containment assembly (adapted from Reference 2).






Figure 3. TRUPACT-II closure/seal area (adapted from Reference 3).

#### 1.4.1 14-Drum Payload Configuration in TRUPACT-II 157

The payload for TRUPACT-II 157 was the standard 14-drums containing CH-TRU waste. The TRUPACT-II has a U.S. Nuclear Regulatory Commission Certificate of Compliance as a Type B with designation B(U)F) under 10 CFR 71.12. The payload was examined at the Stored Waste Examination Pilot Plant (SWEPP) and certified for shipment according to the WIPP Contact Handled Waste Acceptance Criteria. Prior to shipment, the drums were assembled into a payload in WMF-635. An example of a 14-drum payload and automatic center of gravity lifting fixture is shown in Figure 4. Each drum is a UN 1A2 55-gallon open-top, carbon-steel waste drum with a plastic liner and a vent filter installed in the lid to prevent gas buildup in the drum. The eight older drums had Nucfil 020 self-tapping filters added at the RWMC Drum Venting Facility. The Drum Venting Facility functions to remotely vent the TRU waste drums and insert a filter assembly into the vent hole. The filter assembly allows continuous aspiration of internally-generated gases while containing radioactive particulates inside the drum. The assembly consists of a gasket-sealed, self-tapping, hollow, round-headed screw with an internal filter element. The filters provide a removal efficiency of greater than 99.9% for 0.3 to 0.45  $\mu$  particulates. The filters are either inserted in a hole punched about 5 inches from the top rim, or in a bung hole in the center of the drum lid. The remaining six drums were new, having been recently repacked at Argonne National Laboratory-West (ANL-W) in support of the 3100 m<sup>3</sup> Project. These drums employed Nucfil 013 bung filters in the center of the lid. [Appendix B](#) provides additional assembly information for the payload.




Figure 4. Example of TRUPACT-II 14-drum payload configuration (adapted from Reference 2).

TRUPACT-II 157 contained payload assembly No. 6469. Copies of the shipping documents with information on the contents and weights are provided in [Appendix B](#). Five of the drums, in payload positions 1–5 contain filter media, the other nine drums contain sludge. The filter drums are placed on the second tier of the payload because they are lighter than the sludge drums. Seven of the drums had been opened and liquid absorbent added prior to shipment to meet WIPP free liquid acceptance criteria. Figure 5 illustrates the drum positions, slip sheet orientations, guide tube locations, filter locations, and lock ring chine locations of the payload as they were found during the recovery.

## 1.5 Recovery Plan

### 1.5.1 TRUPACT-II 157 Recovery Plan

Efforts to evaluate options for dealing with TRUPACT-II 157 were initiated in September 2002 at both the INEEL and WIPP. That same month, the Department of Energy Idaho Operations Office (DOE-ID) and CBFO also decided to recover the payload from TRUPACT-II 157 to determine the source of contamination.

A draft recovery plan was developed and submitted to DOE-ID on October 10, 2002. The recovery plan proposed using the Test Area North (TAN) Hot Shop building (TAN-607) to perform the recovery work. TAN-607 was selected because of its capacity to accomplish the TRUPACT-II 157 recovery operation while protecting workers and the environment. On October 11, 2002, a letter was received from the DOE-ID Contracting Officer with direction to proceed and complete the recovery operation no later than December 31, 2002.<sup>4</sup> The final Recovery Plan<sup>5</sup> presented the INEEL approach for achieving the following objectives:

- Return of the OCA to WIPP as soon as possible

# TRUPACT-II 157 PAYLOAD CONFIGURATION

## Drums, Orientations, And Filter Locations As-found

Sketch: Do Not Scale




Figure 5. Configuration of payload.

- Remove the contaminated payload from TRUPACT-II 157
- Inspect and collect data (photographs, radiological smears) of individual payload containers to identify the potential source of contamination
- Over-pack the contaminated payload drums into Department of Transportation 7A standard waste boxes (SWBs) in a configuration meeting TRUPACT-II payload compliance requirements
- Receive the over-packed TRUPACT-II 157 at the RWMC for assembly, certification, and loading into TRUPACT-II shipping containers by the Carlsbad Field Office Mobile TRUPACT-II Loading Team
- Complete shipment of the over-packed TRUPACT-II 157 payload to WIPP
- Complete disposition of the ICV
- Document results of payload inspection and lessons-learned.

Operational readiness and approval to start operations at TAN were completed on schedule, December 2, 2002. However, issues with obtaining regulatory approval to perform the work in the TAN Hot Shop developed in early December 2002. Alternative approaches to performing the required recovery work that addressed the regulatory issues were evaluated during December 2002. A revised regulatory approach that used a dual transfer facility concept was finally selected as the best option with which to proceed. This option capitalized on the successful mockup recovery operation previously performed at TAN.

The revised TRUPACT-II 157 Recovery Plan was approved in February 2003.<sup>5</sup> This plan required shipping the repackaged TRUPACT-II 157 payload to WIPP using the WIPP Mobile TRUPACT-II Loading Team to perform the loading operation at the Advanced Mixed Waste Treatment Plant. TAN and RWMC procedures had to be modified to implement the building of certifiable SWBs, and the completion of certification activities associated with making another shipment to WIPP.

The recovery work, which was completed as planned, included:

- Revising the TAN Safety Analysis Report.
- Submitting regulatory documents to the Idaho Department of Environmental Quality.
- Developing a TRUPACT-II 157 Examination Plan (PLN-1169; Reference 1).
- Preparing an onsite transportation plan.
- Developing operating procedures (TPR-6230 and TPR-6233)<sup>6,7</sup> and associated work implementing documents such as inspection plans, lift plans, and job safety analyses to direct recovery work. These closely mirrored the original implementing documents for the 3100 m<sup>3</sup> Project.
- Training and qualifying operational crews.
- Constructing the work platform for access to the OCV and ICV lids, sleeving to contain contamination during lifting of the ICV lid and payload, and a radiological containment tent for payload processing.



- Completing a mockup of the planned operations.
- Completing a contractor management self-assessment to document operational readiness.

### 1.5.2 Description of the TAN-607 Hot Shop

The TAN-607 Hot Shop (see Figure 6) is a large, existing shielded facility containing a high bay equipped with overhead cranes, a large overhead manipulator, auxiliary wall-mounted manipulators, cameras, video-recording capabilities, and other equipment for remote-handling of radioactive material. Historically, this facility has been used to receive, manipulate, and store spent nuclear fuel and other highly-irradiated materials such as the Three Mile Island core debris. The Hot Shop has remotely operated cranes and video cameras to allow remote operations for high radioactive or contaminated waste.



Figure 6. Aerial view of TAN.

## **2. THE PAYLOAD EXAMINATION PLAN**

A *Payload Examination Plan* (Reference 1) was prepared and used to collect information on the as-found condition of the TRUPACT-II 157 payload and shipping container, and to support disposition of the ICV. The plan also directed documentation of auxiliary examination activities such as containment tents and over-packing of the payload as a reference for future recovery operations. The plan identified additional information to be collected and the items to be included in this examination report. Concurrence with the plan was obtained from CBFO prior to commencement of recovery operations.

### **3. QUALITY ASSURANCE**

The recovery operations were performed using procedures that were reviewed and approved by both the INEEL and CBFO under a qualified DOE Quality Assurance program. Quality inspection plans were prepared for the recovery operations and over-packing of the waste drums.<sup>8,9</sup> Quality Assurance provided oversight and verification of the TAN handling procedures, assembly of SWB payloads, assembly of TRUPACT-II payloads, final review of shipping documents for the shipment of 13 waste drums back to WIPP, and review of the final examination report.

## 4. RECOVERY, EXAMINATION, AND DISCUSSION

### 4.1 Recovery Operations

Recovery operations were performed in accordance with existing TAN operating procedures and new recovery procedures TPR-6230 and TPR-6233 (References 6 and 7, see record copy in [Appendix C](#)). Concurrence for the new recovery procedures and the *Examination Plan* was obtained from CBFO. The examination, which followed PLN-1169, was performed concurrently with recovery operations. The daily log recorded by the examination engineers is provided in [Appendix D](#).


The increase in alpha-contamination collected on the WIPP RAF filter through the progression of four samples indicated high levels of alpha contamination inside the ICV. During initial work planning at the INEEL, there was concern that taking additional air samples using the same vacuum sampling method that was used for the RAF samples could continue to increase the contamination inside the ICV and complicate recovery efforts. Instead, the recovery team and Radiological Engineering decided to take an airborne radioactive particulate sample from inside the ICV immediately after the lid was lifted. This sample, which would comply with INEEL procedures, would assess the airborne contamination as part of the Radiological Work Package to protect workers during the recovery. This methodology was part of the *Examination Plan* and work procedures ([Appendix C](#)) that had CBFO concurrence prior to the start of the recovery operations. During the recovery, a change in emphasis was made to ensure that existing contamination in the Hot Shop did not contaminate the payload after the initial air sample and smears of the ICV were found to be uncontaminated.

The Hot Shop was prepared for recovery operations before TRUPACT-II 157 arrived. Contamination control measures were designed and implemented to control the expected airborne and surface alpha contamination. Zippers and gloves were added to an existing radiological containment tent and it was installed inside the Hot Shop to provide primary contamination containment during payload disassembly (see Figure 7). The design allowed for payload disassembly without personnel entering into the tent. The tent was divided into three vestibules to isolate payload disassembly, individual drum examinations, and when necessary, bagging operations prior to transfer into the SWBs. Reclosable openings were added to accept the payload, and a longitudinal zipper opening on the ceiling allowed the crane cable and drum lifting device to transfer drums through the tent between vestibules. A rolling cart was used to transfer individual drums out of the tent and a second crane was used to lift the drums and place them in SWBs. Windows and port gloves provided work access, while remotely controlled cameras inside the payload vestibule and examination vestibule allowed the examination engineers to view and record the condition of the payload and drums without entering the tent. Six remotely controlled video cameras with pan and zoom, one bore scope camera, two video recorders, and one digital camera were employed to record the operation.

A 40-ft-long primary containment sleeve was constructed to fit around the OCV so that internal components such as the ICV lid and payload could be lifted from the inner vessel and contain any contamination on the payload. The sleeve was fitted with window panels so the payload could be visually examined with the ICV lid lifted approximately 18 in. off the cavity as shown in see Figure 8. The sleeve was constructed such that it could be sealed and separated from the main body, allowing individual components to remain contained after being removed from the OCA. A photo was taken of the payload in the sleeving after removal from the ICV and prior to placement into the tent through a ceiling opening (see Figure 9).




RWMC DRUM DECON TENT  
MODIFICATIONS FOR TRU-PAC INSPECTION  
AND REPACKAGING




PD03-0084-01

Figure 7. Payload disassembly and drum examination tent.



PD03-0078-008

Figure 8. ICV lid with sleeving and surrounding work platform.



PD03-0078-0013


Figure 9. Processing tent and payload in sleeving prior to lowering into tent.

A “playpen” area was set up outside of the primary containment areas to provide an intermediate buffer area where drums could be smeared before placement into the SWBs (see Figure 10). The playpen area consisted of a covered floor surrounded by a temporary partial wall approximately 30 in. high. During recovery operations, these zones changed designations between radiological buffer area and contamination area, depending on the nature of the current operation and status of zone smears. The work area was periodically surveyed before, during, and after the recovery operation in the Hot Shop to verify (a) that existing contamination in other areas of the Hot Shop had not contaminated the ICV, OCV, and waste boxes, and (b) that the TRUPACT-II 157 payload had not contaminated the work areas. Copies of these surveys are provided chronologically in [Appendix A](#).

A work platform was designed and built to accept the TRUPACT-II 157 assembly and provide appropriate height for operator access to the vent ports, lock rings, and internals (refer to Figure 8). The platform was designed in two halves so that the vessel could be placed in the cut-out in one section, and then the other section placed around the vessel. Figure 8 and the other color photos of the recovery operation were taken through a zinc-bromide shielding window, which provided little color contrast.

In addition to preparing the Hot Shop, the operations team trained on mockup assemblies prior to the arrival of the subject vessel. These mockups identified several minor improvements to the disassembly and examination procedures, resulting in a streamlined, efficient process for the final effort.





PD03-0078-053

Figure 10. Outer playpen with staged SWBs and ICV box.

## 4.2 Sequence of Operations

This section summarizes the sequence of operations for the recovery. More information, such as times of occurrence, is provided in Appendix E. A list of the videotapes recorded during the recovery is provided in Appendix F. Resumes of the principal investigators are provided in Appendix G.

### 4.2.1 OCA/ICV Handling and Payload Removal

For clarification, this section presents radiological smear results as being “positive” or “negative.” A positive result indicates contamination above acceptable limits, a negative result falls within acceptable limits. Alpha and beta-gamma limits for surface contamination are  $<20$  dpm/100 cm<sup>2</sup> alpha and  $<1,000$  dpm/100 cm<sup>2</sup> beta-gamma, respectively per PRD-183, Table 2.<sup>10</sup>

On January 27, 2003, the vessel was lifted off the haul trailer by a forklift and transferred into the Hot Shop extension, where the cavity section of the OCA was wrapped in plastic to prevent possible contamination of the vessel by residual Hot Shop contamination. The vessel was then transferred into the Hot Shop and surrounded by the two-piece engineered work platform designed and constructed to fit around the vessel at an appropriate height for recovery operations.

In examining the outer vessel, the team discovered that the vent port tamper indicating device was damaged; however, the OCV lid lock-ring bolt tamper-indicating device was still intact, indicating that the OCV lid had not been removed during storage. With verbal concurrence from CBFO, the decision was made to proceed with recovery operations. Radiological smears of the vessel’s outer surface found no contamination above acceptable limits.

Following TPR-6230 (see [Appendix C](#)), the workers lifted the OCV lid off the cavity and smeared the inner surfaces of the OCV lid and the newly exposed outer surfaces of the ICV lid. In addition, they took air samples to detect the presence of airborne radiation and volatile organic compounds (VOC). Once it was determined that all surface and airborne radiation and VOC results were negative (no contamination above acceptable limits), the OCV lid was moved to a lid stand.

The workers proceeded to unlock the ICV lid. This entailed applying a 4 in. Hg vacuum on the ICV cavity via the vent port to allow the lock ring to rotate. During this process, an operator accidentally rotated the lock ring with light hand pressure prior to installation of the vent port tool. After the vent port tool was installed, it was determined that the ICV was already under 4 in. Hg vacuum, which explained why the lock ring had rotated freely, and no further pumping was required. The onsite CBFO and DOE-ID representatives were notified.


After the ICV lid was unlocked, but prior to lifting it off the cavity, workers lowered a plastic containment sleeve over the OCA and attached it to the outer vessel below the lid joint. The containment sleeve was constructed such that as each item was removed from the OCA it would remain within the containment sleeve, which could be sealed and severed at predetermined locations to maintain containment around each component.

Workers then lifted the sleeve-covered ICV lid approximately 18 in. off the cavity (see Figure 8) and smeared the inner surfaces of the lid and top surfaces of the payload. A radiological air sample was also taken from within the ICV and counted. All smears were negative (no contamination above acceptable limits). The main purpose of the air sample was to verify levels of contamination for personnel working on the payload. It should be noted that the air sample did indicate the presence of a significant amount of radon, a product of the decay of uranium in the payload contents. While not unexpected, this result confirms that the air sample came from inside the ICV cavity as intended, rather than through the HEPA vents on the plastic sleeving. Industrial Hygiene personnel took a VOC air sample, which indicated low levels of an unidentified VOC. Several volatile organic compounds were components of the waste. The air sampling results are included in [Appendix A](#). With these results, the containment sleeve was sealed and separated below the ICV lid, allowing it to be moved to the lid stand (see Figure 11).

With the ICV lid removed, workers performed an extensive visual, video, and photo examination of the ICV interior and the in situ payload. A boroscope was used to seek for evidence of drum rupture or leakage and to determine the integrity of the drum lids and filter vents. Extensive surface smears were performed on the inner surface of the ICV, outer surfaces of the payload, and drum surfaces where accessible through the slip sheets. No physical anomalies were detected on the ICV, payload, or individual drums. The guide tubes in the payload were checked by hand and found to be loose, indicating that the payload had not shifted during transportation or during the traffic accident.

Radiological surface smears of the ICV interior and payload exterior were all negative. Several swab smears were taken of the interior of the vent port, through which WIPP had drawn the air samples that indicated high levels of contamination. The swab smears were negative.

Workers attached the adjustable center of gravity lifting fixture to the payload through small holes in the sleeve, and lifted the payload out of the ICV and into the containment sleeve. Radiation control personnel performed continuous smears of the payload as it emerged from the vessel. All smears were negative. They then sealed and separated the sleeve, and transferred the payload into the radiological containment tent. Once in place, they used the overhead manipulator to remove the sleeve from the payload, allowing further visual examination. No abnormal conditions were observed or recorded.



PD03-0078-011

Figure 11. ICV lid separation in sleeve.

Additional smears were taken of the ICV interior and the legs of the lifting fixture. When all smears were determined to be negative, workers removed the sleeve around the ICV, allowing further visual examination. Before the lid was replaced on the ICV, smears were taken, and video and several still photographs of the ICV interior were recorded. The assembled ICV was then lifted from the OCV, and the newly exposed surfaces subjected to visual examination and surface smears. As all smears were negative, the ICV was placed into its wooden disposal box as procedurally required.

Prior to replacement of the OCV lid, workers took surface smears of newly exposed surfaces, and conducted a visual examination. No anomalies were discovered, and all smears were negative. workers took additional smears of the OCV exterior after the lid was in place, but prior to its removal from the Hot Shop. All of these smears were negative. At approximately 10:00 a.m., January 29, 2003, workers transferred the OCV out of the Hot Shop and placed it onto the transport trailer.

Finally, workers staged six SWBs in the clean area of the Hot Shop to receive drums from the payload as they were examined and released.

#### **4.2.2 Drum Examination and Over-packing Operations**


On January 29, 2003, at approximately 3:30 p.m., workers commenced examination and disassembly of the payload, with a 360-degree video examination of the exterior of the assembled TRUPACT-II 157 payload drums. Over the next day-and-a-half, all 14 drums were removed from the payload, examined, smeared, and over-packed in their assigned SWB. The rest of this section describes the examination process performed.



As described above, the tent was divided into 3 vestibules: payload storage, drum examination, and transfer. Workers lifted each drum was off the payload using a drum lifting device connected to a cable from an overhead crane, and moved them from the payload vestibule into the adjoining examination vestibule (see Figure 12). Prior to any further handling, workers conducted surface smears on the filter vent, top of lid, and lock ring. These samples were submitted for immediate counting while additional smears were being performed over the side and bottom surfaces. Twelve initial smears were conducted of each drum. Maps of those smears are located in [Appendix A](#). Drum IDRF741202484 located in payload position #6 was found to be contaminated.

Workers conducting smears were especially careful to avoid the cross contamination of samples. Concurrent with and subsequent to the contamination smears, the examination team conducted a video examination to determine the integrity of the container, lid, lock ring, and filter vent. This examination included the top, bottom, and 360-degree rotation of the drum side. Any anomalies were noted in the Examination Engineers' Log (see [Appendix D](#)).

In cases where the drum lid initial smear results were negative (13 drums), workers manually checked the tightness of the filter vent and lock-ring bolt. In the case where the drum lid smears were positive (Drum IDRF741202484 in payload position #6), they performed further smears and applied fixative to the affected area before conducting the manual filter vent and lock-ring bolt checks.



PD03-0078-012

Figure 12. Lifting the payload from the ICV.

The examination was completed with an assessment of the container's integrity. Copies of the completed container integrity checklists are included in [Appendix B](#). When the remaining smear results of the side and bottom returned negative, the drum was moved from the examination vestibule into the transfer vestibule, where it was loaded onto a cart and rolled out of the tent. The single drum with positive

smear results was bagged prior to removal from the tent. From there it was lifted by a second crane and lifting device into a clean area where a Maslin smear was performed of all surfaces of the suspended drum, before it was placed in the appropriate standard waste box. Table 2 summarizes the drum examination results.

As noted above, the initial smear indicated contamination levels above allowable limits on a localized region on the lid and filter of drum IDRF741202484. It was therefore handled differently from the other 13 drums. After the initial smears of the lid returned positive (above acceptable levels), workers performed a second follow-up smear, which also showed levels above acceptable limits. Given that smear results of the drum sides and bottom were all negative, the fixative was applied to the lid only. Following application of the fixative, the filter vent and lock ring was checked for hand tightness, similar to the other drums. The filter vent was secure, but the lock-ring bolt could be rotated slightly, about 5 degrees to the extent allowed by the tamper indicating device. The jam nut was snug against the lock chine. The drum was then bagged, taped and placed in its SWB.

The examination engineers asked the operators to read its tamper indicating seal on the bagged drum. While maneuvering the tamper indicating seal into a readable position, the operator discovered that the lock ring could be manually rotated. This action was repeated for the video record. The tamper indicating seal number was ANL-W 3963 (see Figure 13).

Table 2. ICV and drum examination summary.

Chronological Examination Order	Drum Serial Number	Payload Position	Contamination Results	Comments
ICV Cavity			-	Radon levels much higher than background found in air sample of cavity Airborne and smear alpha contamination within limits
1	IDRF004102263	2	-	adjacent to seal test port
2	IDRF004002801	3	-	adjacent to vent port
3	IDRF004101890	4	-	
4	IDRF004102254	1	-	
5	IDRF004002790	5	-	
6	IDRF741202088	7	-	
7	IDRF741202484	6	up to 110 dpm/100 cm <sup>2</sup> alpha on drum lid only	Loose lock bolt, loose lock ring
8	IDRF741205405	8	-	
9	IDRF741201615	9	-	
10	IDRF074700411	13	-	Loose jam nut
11	IDRF741201718	10	-	
12	IDRF741204650	14	-	
13	IDRF074700394	12	-	
14	IDRF074221338	11	-	



PD03-0078-116

Figure 13. Photo of the tamper indicating seal for IDRF741202484.

#### **4.2.3 Abnormalities Found During the Examination**

The drum removal and examination process discovered two drums with abnormal results. Drum IDRF741202484 exhibited a loose lock ring, and contamination on the drum lid that was slightly above acceptable limits (see Figure 14). Smears of accessible areas of the top and bottom of the lock-ring were within acceptable limits. A small area below the lock-ring where the drum lift fixture made contact with the drum surface could not be surveyed. However surveys of the lift fixture clamp after processing the drum were also within limits. The same situation exists for the lift fixture spacer above the lock-ring. The spacer was located away from the lid contamination area. The lock ring closure gap on Drum IDRF741202848 was estimated from the examination photographs to be 0.48 in.

Drum IDRF074700411 had a loose lock ring jam nut (see Figure 15), but the lock ring bolt was secure and contamination smears were all within acceptable limits.


All other drums were in acceptable condition with contamination smears below acceptable limits. Figure 16 shows the position of drums in their as-found orientation with respect to the ICV vent port, along with the results of radiological smears by drum sector.





PD03-0085.01

Figure 14. Drum IDRF741202484 inside the examination vestibule.



PD03-0078-099

Figure 15. Photograph of lock bolt jamb nut position on Drum IDRF074700411.




Figure 16. TRUPACT-II 157 drum lid smear results.

#### 4.2.4 Handling of the SWBs and Removal from TAN Hot Shop

Individual drums from the payload were segregated by waste codes and over-packed into six SWBs. After discovery of contamination above acceptable levels on Drum IDRF741202484, DOE-ID requested that it be isolated in a separate SWB with three dunnage drums, and held for possible further investigation. Accordingly, on January 31, 2003, lids were installed and inspected on all SWBs except for SWB IDRF741202484, and the SWBs were transferred out of the Hot Shop. All the SWBs were smeared and found clean prior to transfer.

SWB IDRF741202484 was held in the Hot Shop until February 3, 2003, when a seventh SWB (007) was transferred into the Hot Shop to receive the contaminated drum IDRF741202484. The drum was placed into SWB IDRF741202484 along with three dunnage drums. Because this SWB will not be shipped to WIPP, the bag on drum IDRF741202484 was not slit prior to closure of the waste box. A fourth dunnage drum replaced the subject drum in SWB IDRF741202484. These boxes were then closed, inspected, smeared clean, and transferred out of the Hot Shop at approximately 3:00 p.m. February 3, 2003.

On February 4, 2003, the ICV in its disposal box and the seven SWBs were loaded onto trailers for return shipment to RWMC. The OCV had previously been loaded onto a trailer and delivered to RWMC.

### **4.3 Radioactive Contamination Surveys of TRUPACT-II 157**

Over 350 contamination smears were taken on the inner and outer surfaces of the OCV, ICV, and individual drums during over-packing of the drums, and of the SWBs and equipment as it left the TAN Hot Shop. Dry Whatman 50 paper was used for the majority of the smears, with sticky-back cloth smears being utilized for the follow-up smears on Drum IDRF741202484. Much of this information has been reported in previous sections of this report. All the contamination smears at TAN were counted for 1 minute for alpha and beta with a currently calibrated Tennelec LB5100. Air contamination samples were counted for 10 minutes. Complete information and smear maps for the TRUPACT-II 157 recovery operations are provided in [Appendix A](#), which also includes smear maps of Drum IDRF741202484 in storage at RWMC, prior to transport to ANL-W, upon receipt back at RWMC, and prior to shipment out with TRUPACT-II 157.

An air sample of the ICV cavity volume was taken immediately after the ICV lid was lifted about 18 in. above the ICV bottom while it was in the sleeving, prior to any additional smears inside the ICV. The sample was taken over 15 minutes and totaled 147 ft<sup>3</sup>. The initial count showed alpha and beta contamination, but the air sample was recounted at 30 and 90 minutes, and the calculated decay half-lives indicated that the contamination was primarily natural radon progenies, so the decision was made not to spray fixative inside the sleeving to control airborne contamination for personnel protection during the payload processing. By the following day, alpha and beta activities had lessened by 258 and 39 times, respectively. Both had decayed almost to background levels by February 3, 2003. Table 3 lists the results of initial and delayed counts of air samples.

All smears yielded results within limits for surface contamination of <20 dpm/100 cm<sup>2</sup> alpha and <1,000 dpm/100 cm<sup>2</sup> beta-gamma per Table 2-2 of PRD-183 (Reference 10) and Table D of 10 CFR 835,<sup>11</sup> with the exception of one drum lid; the initial smear from the lid of waste Drum IDRF741202484 was 39 dpm/100 cm<sup>2</sup> alpha. Two of the three follow-up smears from the top of that drum were also above contamination limits at 33 and 110 dpm/100 cm<sup>2</sup> alpha, respectively. Smear levels for the lid of that drum and the other drums in the top and bottom 7-pack of the payload drum were shown previously in Figure 16.

During the removal of drums from the upper pack, dirt and small stones were noted on the upper 7-pack lower slip sheet. This was expected since the slip sheets were stored in a part of the building open to the outside and the payload was transported over a gravel road between buildings prior to shipment. Some of this material was removed from the slip sheet via a sticky roller and smeared for contamination. The results were within limits (see [Appendix A](#)).

None of the other smears in the payload or in the ICV were above limits. Swabs of the inside of the ICV vent port through which the RAF samples were drawn showed no contamination. The payload slip sheets, reinforcement sheets, guide tubes, plastic shrink wrap, radiological contamination tent, and blotter paper on the Hot Shop floor were smeared for contamination after the drums were over-packed and removed from the Hot Shop. All results were within acceptable limits. A sample of the shrink-wrap was also submitted for gamma-scan; no contamination was found. The tent was stored in a box for possible future reuse as the smears indicated contamination levels were below limits.

Table 3. Results of air sample from inside of the sleeved ICV immediately after lifting the lid by ~18 in.

Date Time of Count	Count Time (min)	Alpha <sup>a</sup> (cpm)	Beta <sup>b</sup> (cpm)	Alpha ( $\mu\text{Ci/cc}$ )	Beta ( $\mu\text{Ci/cc}$ )	Effective Derived Air Concentration Fraction <sup>c</sup>
1/27/03; 1700	1	206	446	9.37e-11	1.83e-10	47
1/27/03; 1735	1	122	218	5.55e-11	8.97e-11	28
1/27/03; 1835	1	40	86.38	1.82e-11	3.55e-11	9.
1/28/03; ~0835	10	0.80	11.50	2.98e-13	1.76e-12	0.15
2/03/03	10	0.40	9.00	1.28e-13	8.80e-13	0.06

a. Efficiency for  $\alpha$  was 28% on 1/27/03, 29.9% on 1/28/03 and 2/03/03. Counts per minute (cpm) registered by the counter is corrected to disintegrations per minute (dpm) by dividing by the counter efficiency.

b. Efficiency for  $\beta\gamma$  was 31% on 1/27/03, 44.3% on 1/28/03 and 2/03/03.

c. Per MCP-357, if the effective derived air concentration fraction is  $\geq 0.3$ , then the sample is recounted after 90 minutes to determine if natural activity is indicated.

Two of the smears from the Drum IDRF741202484 lid and three smears from the inside of the ICV were analyzed for actinides by the INEEL Analytical Laboratories. The results of the INEEL analyses are provided at the end of [Appendix A](#), along with the assay of Drum IDRF741202484 from the SWEPP Assay system. Table 4 compares the plutonium and americium results from the INEEL drum assay and analyses of smears. The smears match the original drum assay. Therefore, the contaminants in the drum lid are consistent with the drum contents. The ratios of Pu-239+Pu-240 to Pu-238 for the INEEL smears. None of the ratios of Pu-239+Pu-240 to Am-241 matched the original drum assay, which was likely because of americium stratification in the waste in the drum.

Table 4. Comparison of actinide radiochemical analyses of INEEL drum assay and smears.

	SWEPP Drum Assay	Analysis of INEEL Smears	
	Drum IDRF 741202484	Drum IDRF741202484 Lid Smears 4 and F1	Inside of ICV Smears 7, 2 and 7
Sample Date	3/6/2002	01/31/03	02/01/03
Activity Ratios	dpm/dpm	dpm/dpm	dpm/dpm
Ratio Pu-239+Pu-240 to Pu-238	39.7 $\pm$ 26.6	41.4 $\pm$ 5.8	37.1 $\pm$ 15.4
Ratio Pu-239+Pu-240 to Am-241 <sup>a</sup>	0.065 $\pm$ 0.035	10.0 $\pm$ 1.2	9.5 $\pm$ 2.3

a. None of the ratios of Pu-239+Pu-240 to Am-241 matched the original drum assay. This was likely because of americium stratification in the waste in the drum.

## **4.4 List of Facts Relevant to TRUPACT-II 157 Recovery and Examination**

The following facts are based on examination of the payload and analysis of the results from the TRUPACT-II 157 recovery and examination.

1. The initial WIPP RAF sample showed slight contamination of 30 dpm/spl gross alpha in an estimated 0.2 m<sup>3</sup> of air.
2. The follow-up WIPP RAF samples showed progressively higher TRU alpha contamination from 1,900 to 5,500 dpm/spl in an estimated 0.7 m<sup>3</sup> of air.
3. The initial RAF sample was collected as part of the disassembly procedure as the ICV was evacuated to about 4 in. Hg. The additional WIPP RAF samples were taken by evacuating the ICV to 12 in. Hg.
4. The tamper indicating device on the OCV vent port was visually intact, but the wire had pulled out of the brass seal, WIPP No. 0067. The tamper indicating device on the locking bolt for the OCV lock ring was still intact, which indicated that the OCV lid had not been tampered with.
5. The ICV was found to still have about 4 in. Hg vacuum after over 4 months of storage at the INEEL, attesting to the integrity and sealing capability of the TRUPACT-II shipping container.
6. An INEEL air sample of a measured volume of 4.2 m<sup>3</sup> (147 ft<sup>3</sup>) from inside the ICV taken immediately after opening initially showed 206 cpm alpha/spl. Delayed counting of the sample indicated that (a) the alpha activity was primarily short-lived radon, which was expected to be present from decay of uranium isotopes in the wastes; and (b) the alpha contamination had decayed to only 0.8 cpm/spl in less than 1 day.
7. Swabs of the inside of the ICV vent port through which the WIPP RAF samples were drawn showed no contamination.
8. The guide tubes were found to be loose during the payload examination indicating that the payload had not shifted within the ICV from the vehicle accident,
9. No visual damage was evident on the OCV, ICV, aluminum honeycomb, payload or drums inside the TRUPACT-II container. These indicate that the vehicle accident did not affect the TRUPACT-II or its payload.
10. Alpha contamination above the limit of 20 dpm/100 cm<sup>2</sup> was found on a portion of the lid of Drum IDRF741202484 in the payload. The initial positive result was 39 dpm/100 cm<sup>2</sup> alpha; two subsequent positive results were 33 and 110 dpm/100 cm<sup>2</sup> alpha. This drum was in payload position No. 6 (see Figure 5).
11. Radiochemical analysis of Drum IDRF741202484 lid smears was consistent with the contents of that drum.
12. The locking bolt and lid locking ring on Drum IDRF741202484 were loose.
13. The lock ring gap was estimated to be 0.48 inches from the examination photographs.

14. Contamination smears of drum surfaces adjacent to and below the lock ring of Drum IDRF741202484 were within limits. The first smear on and around the filter was also within limits. The follow-up smear on and around the filter was above the alpha limit but the smear extended farther onto the drum lid surface.
15. A jam nut on an uncontaminated drum (IDRF074700411) was loose; the lock bolt was tight. This drum was repackaged by ANL-W in April 2002. This drum was in position No. 13 in the payload, immediately below drum IDRF741202484.
16. All of the drum filters were secure.
17. No alpha contamination above allowable surface contamination limits of  $<20$  dpm/100 cm<sup>2</sup> alpha was found elsewhere in the payload, slip sheets, guide tubes, shrink wrap, inside of the ICV, or inside the ICV vent port.

## 5. RESULTS

The recovery and examination of TRUPACT-II 157 provided the following key results:

- The vehicle accident did not compromise the integrity of the shipping container as evidenced by the following:
  - No physical damage was observed on the OCV or ICV
  - No contamination was found on the exterior or interior of the OCV
  - No contamination was found external to the ICV.
- The vehicle accident did not cause the contamination found in TRUPACT-II 157 as evidenced by the following:
  - No damage was found on the ICV lid or the honeycomb spacers, slip sheets, or guide tubes inside the ICV
  - No physical damage was evident on the payload
  - No shifting of the payload was apparent.
- The contamination found on Drum IDRF741202484 was contained within the ICV.
- The ICV was found to be under vacuum after over 4 months storage prior to initiating recovery operations. This attests to the integrity and sealing capability of the TRUPACT-II shipping container.
- Drum IDRF741202484 was found to have localized contamination on top of the drum lid. The contamination found was up to 110 dpm/100 cm<sup>2</sup> alpha, which exceeds the limit of 20 dpm/100 cm<sup>2</sup> alpha.
  - Radiological analysis of the contamination showed it to be consistent with the drum's radiological contents.
- Drum IDRF741202484 was found to have a loose lock-ring bolt, such that the lock ring could be rotated by hand.
- Contamination smears of drum surfaces adjacent to and below the lock ring of Drum IDRF741202484 were within limits. The first smear on and around the filter was also within limits. The follow-up smear on and around the filter was above the alpha limit but the smear extended farther onto the drum lid surface.
- The results of the examination did not conclusively identify the exact leakage point from drum IDRF741202484. However, it was confirmed that this drum was the source of the contamination.
- A loose lock-ring-bolt jam nut was also discovered on drum IDRF74700411, although the lock-ring bolt was secure.
  - This drum did not have contamination above limits.

## **6. RECOVERY OPERATIONS LESSONS LEARNED**

The recovery operation was the first time a contaminated payload was recovered from a TRUPACT-II. The TAN Hot Shop provided an excellent facility and staff for the recovery and examination operations, with appropriate expertise, tooling, and facilities in material handling, radiological control, and payload examination for efficient, uncomplicated processing of the payload. The following general lessons-learned were noted with the recovery. These lessons should be applied in the event that disassembly and recovery of another TRUPACT payload should ever become necessary.

- Mockup training proved highly valuable in streamlining and improving the recovery procedure, and in preparing the crew for the required tasks. Several efficiencies in the procedure and design features of the containment were directly attributable to the mockup exercises.
- Direct, early operator participation in the development of the recovery procedures enhanced the operational safety and efficiency.
- The INEEL radiological work control scheme (TRUPACT sleeving and three-section work tent) provided significant worker protection and efficiencies for the work process as demonstrated by the safe and rapid completion of the project activities in the TAN Hot Shop.
- Open communication and coordination between the INEEL, DOE-ID, and CBFO during the planning, review, approval, and recovery stages allowed the recovery to be conducted safely and within operational constraints. The efficiency of recovery operations could be enhanced by the addition of a CBFO representative with signature authority onsite during recovery operations. This would improve the timeliness of the team's response to procedural changes necessitated by recovery findings.
- An operator should be added to the recovery crew with the sole function of taking still photos of processes and items of interest. A camera should be made available with the acceptance that it may become contaminated.



## 7. REFERENCES

1. PLN-1169, "TRUPACT-II Shipping Container 157 Payload Examination Plan." Revision 0, November 27, 2002.
2. TRAMPAC, DOE Carlsbad Field Office, "TRUPACT-II Authorized Methods for Payload Control (TRAMPAC)," Revision 19A, March 2002, <http://www.wipp.carlsbad.nm.us/library/t2sar/rev19a/Trampac/Trampac.pdf>
3. TRUPACT-II SAR, DOE Carlsbad Field Office, "TRUPACT-II Safety Analysis Report," Revision 19A, March 2002, <http://www.wipp.carlsbad.nm.us/library/t2sar/rev19a/tiisar/sartoc/sartoc.pdf>.
4. Adams, M. L, DOE-ID, letter to R. A. Rosell, BBWI, "Recovery Efforts for Trupact-II Shipping Container 157 (EM-WM-02-205)," CCN: 36810, October 11, 2002.
5. Harrison, S. W., BBWI letter to C. A. Thompson, DOE-ID, CCN No. 39657, "Contract No. DE-AC07-99ID13727 – Approval of Baseline Change Proposal No. IN-03-014, Diesel Fuel Tank Release Characterization and WM-03-017, TRUPACT 157 Recovery Operation," February 3, 2003.
6. TPR-6230, "TRUPACT-II 157 Unloading and Loading Recovery Operations at TAN," Test Area North Operations, Revision 0, November 26, 2002.
7. TPR-6233, "TRUPACT-II 157 Payload Disassembly Operations at TAN," Test Area North Operations, Revision 1, January 22, 2003.
8. INTEC-QA-0208, "Quality Inspection of TRUPACT-157 Unloading and Loading Recovery Operations at Test Area North (TAN), November 27, 2002.
9. INTEC-QA-0221, Quality Inspection of TRUPACT-157 Payload Disassembly Operations at Test Area North (TAN), February 1, 2003.
10. PRD-183, "Radiation Protection – INEEL Radiological Control Manual." Radiological Control, Revision 6, July 6, 2000.
11. 10 CFR 835 Appendix D, "Surface Contamination Values," February 4, 2002.



## **Appendix A**

### **WIPP Reports, Accident Report, and Results of Surface and Airborne Contamination Measurements**

[Electronic Copy of Appendix A](#)



"Italiano, Marc - DOE"  
<Marc.Italiano@wipp.w  
s>

10/09/02 09:15 AM

To: "Rod DOE-ID' Taft (E-mail)" <tafta@id.doe.gov>, "Tom Clements  
(E-mail)" <TLC@inel.gov>

cc:

Fax to:

Subject: FW:

> -----Original Message-----  
> From: Wu, Chuan-Fu - DOE  
> Sent: Wednesday, October 09, 2002 8:03 AM  
> To: Italiano, Marc - DOE  
> Subject:  
>  
> <<TRUPACT-157-Summary(9-9-02).doc>>  
>  
> Chuan-Fu Wu  
> DOE Carlsbad Field Office  
> P.O. Box 3090  
> Carlsbad, New Mexico 88221  
> USA  
> Tel: 505-234-7552; Cell: 505-228-0784  
> Fax: 505-234-7027  
> E-mail: chuan-fu.wu@wipp.ws  
>



TRUPACT-157-Summary(9-9-

*Barry,  
You wanted a copy of this  
Bob*

## **TRUPACT-II 157 Receipt Narrative and Radiological Data Summary** (9/9/02)

TRUPACT-II 157 was received with TRUPACT-II 151 (shipment number IN020271) at the WIPP site at 6:30, August 25 (Sunday), 2002. Upon receipt, shipping documentation was reviewed and initial radiological surveys completed. No removable surface contamination was found on the exterior of either TRUPACT-II shipping casks. Both TRUPACT-IIs were then staged in the parking area behind the Waste Handling Building for subsequent unloading.

At 13:05, procedure WP 05-WH1011, *CH Waste Processing*, was initiated for TRUPACT-II 157. TRUPACT-II 157 was unloaded from the trailer and staged in the CH Bay West TRU Dock north position in the Waste Handling Building.

The TRUPACT-II consists of an Outer Containment Assembly (OCA), an Outer Containment Vessel (OCV) and an Inner Containment Vessel (ICV). The OCV and ICV provide dual containment and are independently sealed. Payload containers (in this case, 55-gallon drums) with varying levels of radioactivity are carried inside the ICV. To avoid potential exposure to workers handling the containers, multiple checks for radioactivity are performed at each step of the unloading and waste handling operations. Checks are made for both surface contamination that could be dislodged during handling and become airborne, as well as for any airborne radioactivity that might be present inside the TRUPACT-II shipping casks before they are opened:

1. Before opening the OCA lid, the exterior of the OCA is carefully surveyed for surface radioactive contamination, and if elevated levels are not detected, then
2. The OCA lid is removed and surveys of the inner surface of the OCV and the outer surface of the ICV are performed, and if elevated levels are not detected, then
3. Before opening the ICV lid, an air sample is drawn from the inside of the ICV through a Radiological Assessment Filter (RAF). The RAF is counted for any detectable levels of man-made airborne radioactivity. If no man-made radioactivity is present, then
4. The ICV lid is removed and surface contamination surveys of the interior surfaces of the ICV lid and the payload containers are performed.

Unloading operations of TRUPACT-II 157 continued until Step 2.4.22 of WP 05-WH1011 was reached. At this step, an air sample was drawn from the ICV through the RAF. The RAF was counted on an Eberline Alpha-6 Continuous Air Monitor (CAM) and indicated 5.7 cpm (counts per minute) at 13:34 and 5.3 cpm at 13:40. With a counting efficiency of approximately 20 %, the counting results were equivalent to approximately 27 to 30 dpm alpha activity. The peak channel on the Alpha-6 for these measurements was Channel 112 in the Region of Interest (ROI) corresponding to the alpha radiation energy for Pu. The WIPP Central Monitoring Room Operator (CMRO) was notified and waste processing on TRUPACT-II 157 was stopped. The radiological survey report for this process was SRV-02-2480.

The RAF sample was transferred to the WIPP onsite Radiochemistry Laboratory at 18:07 for further measurement and analysis. A 10-minute gross alpha/beta counting (using a gas

proportional counter) at 19:46 indicated an alpha reading of approximately 30 dpm, a beta reading of ~3.4 dpm. A separate measurement by a gamma spectrometer indicated an Am-241 activity of approximately 3 dpm. Destructive chemical separation of the RAF (sample ID TP157RAF) started on August 26 (Monday).

The on-shift RadCon Engineer notified the CH RadCon Manager. The CH RadCon Manager instructed the crew to leave the ICV lid in place. At 14:37 Waste Handling personnel suspended processing of TRUPACT-II 157, for further checking and testing to determine if airborne contamination was present inside the ICV.

The WIPP Integrated Waste Operations Manager, senior staff, and the Carlsbad Field Office (CBFO) were notified.

TRUPACT-II 157 was left in the West TRU Dock north position with the OCA lid removed, the ICV lid still sealed, the ICV lid locking ring rotated to the unlocked position, the Inner Vent Port Plug installed and a vacuum of 4" Hg maintained on the ICV. TRUPACT-II 157 was stored in this position overnight until all required personnel could be assembled and a plan of action could be developed to proceed.

On August 26 morning, a *Work Instruction for Additional TRUPACT-II 157 Radiological Assessment Filter Collection* was developed. At 13:00 a pre-job briefing was held for obtaining these additional samples from the ICV. These samples were obtained through the RAF assembly. The first follow-up sample was counted at 14:40 on an Alpha-6, indicating 240 cpm in the ROI corresponding to Pu. The filter sample was then transferred to the Radiochemistry Laboratory at 14:56 for further analysis (sample ID 157RAF-2).

The gross Alpha/Beta counting of sample 157RAF-2 showed an alpha reading of 2530 dpm and a beta reading of 1100 dpm. Gamma spectrometry measurement showed 176 dpm of Am-241.

A second additional RAF sample obtained from the ICV was counted on the Alpha-6 at 16:10, indicating 465 cpm in the ROI corresponding to Pu. This sample was then transferred to the Radiochemistry Laboratory at 16:55 (sample ID 2nd PULL). The Alpha/Beta counting showed 4382 dpm alpha and 1450 dpm beta. Gamma spectrometry measurement indicated 309 dpm of Am-241.

A third additional RAF sample was obtained and counted on the Alpha-6 at 18:02. The sample showed 890 dpm in the Pu ROI. This sample was also transferred to the Radiochemistry Laboratory at 18:09 (sample ID 3rd RAF). The Alpha/Beta counting results from the laboratory indicated 6030 dpm alpha and 794 dpm beta. Gamma spectrometry measurement from this third follow-up sample indicated 464 dpm of Am-241. This RAF was analyzed radiochemically on August 27.

Both the initial sample (TP157RAF) and additional RAF samples, were collected by drawing air through a filter, which reduced the absolute pressure inside the ICV. The initial sample dropped the pressure by 4" Hg. The three replicate samples each dropped the pressure by ~12" Hg. Although detailed measurements of sample volume were not attempted, these pressure drops correspond to air sample volumes of roughly 0.2 and 0.7 m<sup>3</sup>, respectively.

After each sample was collected, air was allowed to re-enter the ICV at a controlled rate (~ ½ – 1 minute to equalize the pressure drop). The sampling port valve was closed before gage pressure returned to zero (thereby assuring that a small negative pressure was maintained for contamination control). Initial counting of the additional RAF samples included radioactivity from radon (Rn) decay progenies (Note: the effective half-life of Rn progenies is approximately 30 minutes). Proportional gas counting results obtained several hours after sample collection indicated that alpha radioactivity (without Rn progenies) of the additional RAF samples was approximately 1900 dpm, 3300 dpm, and 5500 dpm separately. To check the radioactivity level of Rn progenies, an air filter collected at 15:54 on August 26 by a Portable Air Sampler (PAS) was counted several times. The counting results verified that: (1) the Waste Handling Building ambient air contained Rn progenies, and (2) it did not contain long-lived alpha emitters.

The radiological survey report for the process of collection additional RAF samples was SRV-02-2493.

The following table summarizes the Alpha-6 counting, Alpha/Beta counting, and gamma measurement results of the initial RAF (TP157RAF) and the 3 additional RAFs (157RAF-2, 2nd Pull, and 3rd RAF), radiochemical data for plutonium of samples TP157RAF and 3rd RAF were also listed.

The radiochemical results from the onsite Radiochemistry Laboratory were available for the initial RAF at 7:00 on August 27 (Tuesday). At that time, the CBFO management determined that the airborne radioactivity inside the ICV represented an unacceptable level and directed operations personnel to begin the processing of resealing TRUPACT-II 157 and returning it to INEEL.

Table 1 – Summary of Radiological Assessment Filter Samples from TRUPACT-II 157

Sample Designation	Sampling Date & Time	Alpha-6 CAM <sup>1</sup> (cpm)	Gross Alpha <sup>2</sup> (dpm)	Gross Beta <sup>2</sup> (dpm)	Am-241 γ-spec. <sup>3</sup>	Pu-238 <sup>4</sup>	Pu-239/240 <sup>4</sup>
TP157RAF	8/25/02 13:34	5.7, 5.3	29.7	3.4	2.6	0.7	19.9
157RAF-2	8/26/02 14:40	240	2530 (~1900) <sup>5</sup>	1090	176	Not yet analyzed	Not yet analyzed
2nd PULL	8/26/02 16:10	465	4380 (~3300) <sup>5</sup>	1450	309	Not yet analyzed	Not yet analyzed
3rd RAF	8/26/02 18:02	890	6030 (~5500) <sup>5</sup>	794	464	132	1640

<sup>1</sup> Gross count rate (cpm) in the Pu region of Alpha-6 CAM (efficiency ~20%)

<sup>2</sup> Initial counting from the gas proportional counter – values given in dpm


<sup>3</sup> Counted using a geometry-calibrated gamma spectrometer, dpm

<sup>4</sup> Results from radiochemistry extraction and alpha spectrometry, dpm

<sup>5</sup> Gross alpha dpm several hours after sample collection (without Rn decay progenies).



# Total Alpha



Initial Sample 30 dpm 8/25

Samples are taken of the air space inside the tank



REPORTING DEPARTMENT										STATE OF NEW MEXICO									
UNIFORM ACCIDENT REPORT																			
<input type="checkbox"/> ON PRIVATE PROPERTY <input type="checkbox"/> FATAL <input checked="" type="checkbox"/> INJURY <input type="checkbox"/> PROPERTY DAMAGE ONLY <input type="checkbox"/> UNDER \$500 <input type="checkbox"/> \$500 OR MORE <input type="checkbox"/> HIT AND RUN										SHEET 01 OF 04 SHEETS									
DATE OF ACCIDENT: MO 08 / DAY 25 / YR 02										CITY OCCURRED IN: Carlsbad									
COUNTY: Eddy										AT INTERSECTION WITH: N/A									
PERMANENT LANDMARK - COUNTY LINE - INTERSECTION										FOR USE BY ORIGINATOR									
OTHER LOCATION: 2 <input type="checkbox"/> FEET <input checked="" type="checkbox"/> MILES										Incident #02-092067									
MILEPOST LOCATION: 396 <input type="checkbox"/> FEET <input checked="" type="checkbox"/> MILES										OF: US 62-180/State Road 200									
ACCIDENT CLASSIFICATION: <input checked="" type="checkbox"/> On Roadway <input type="checkbox"/> Off Roadway										Vehicle On Other Rdwy <input type="checkbox"/> Other Object <input type="checkbox"/> Other Object									
VEHICLE NO. 1										Posted Speed: 65 Safe Speed: 65									
HEADED: N S <input checked="" type="checkbox"/> W ON: US 62-180										Zip Code: 88220 Phone: 505 887-6010									
Driver's Full Name: Hanway, Jerry E.										Address: 902 Airport, Carlsbad, NM									
Driver License Number: 030520947										Expires: 10-29-2004 Date of Birth: Mo 09 / Day 29 / Yr. 45									
Social Security Num.: 585-14-2032										Occupation: Truck Driver									
Seal Position Code: LR LF CR CF RR RF OTHER										Seal Bel: 6 NA 56 M 0									
Occupant's Name: Rita K. Hanway										Occupant's Address/Zip Code: 902 Airport, Carlsbad, NM 88220									
Vehicle Yr.: 1997										Vehicle Make: KW									
Color: White										Body Style: D6									
Removed To: Destination										Removed By: Driver									
License Yr.: 3/03										State: WY									
License Number: 04104										US DOT/ACC/SCC Number: 1029193									
VIN: 1XKDD99X7R739335										Owner's Telephone: 505-628-0468									
Owner's Name: Cast Transport										Owner's Address: 985 Havana, Henderson, CO.									
Insured By: (Name of Company) Gulf Insurance Group										Policy Number: GA2835948									
Liability Insurance: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No										VEHICLE DAMAGE: <input type="checkbox"/> HEAVY <input type="checkbox"/> MODERATE <input type="checkbox"/> NONE									
VEHICLE NO. 2 - PEDESTRIAN										Posted Speed: 65 Safe Speed: 65									
HEADED: N S <input checked="" type="checkbox"/> W ON: US 62-180										Zip Code: 79360 Phone: 915 758-5684									
Driver's Full Name: Alvidrez, Isreal C.										Address: RT 1, Box 177-I, Seminole, TX									
Driver License Number: 06066716										Expires: 10-25-2004 Date of Birth: Mo 10 / Day 25 / Yr. 82									
Social Security Num.: 462-63-0733										Occupation: Key Energy									
Seal Position Code: LR LF CR CF RR RF OTHER										Seal Bel: 6 NA 19 M B5/C									
Occupant's Name: None										Occupant's Address/Zip Code:									
Vehicle Yr.: 1998										Vehicle Make: Dodge									
Color: White										Body Style: PK									
Removed To: Short's Body Shop-Carlsbad NM										Removed By: Short's Towing									
License Yr.: 3/03										State: TX									
License Number: RL-S47										US DOT/ACC/SCC Number: N/A									
VIN: 1B7HC16XXWS688106										Owner's Telephone: 915-758-5684									
Owner's Name: Epifanio Alvidrez										Owner's Address: RT 1, Box 177-I, Seminole, TX									
Insured By: (Name of Company) State Farm										Policy Number: unknown									
Liability Insurance: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No										VEHICLE DAMAGE: <input type="checkbox"/> HEAVY <input type="checkbox"/> MODERATE <input type="checkbox"/> NONE									
INJURED First Aid Rendered By: Carlsbad EMS										Injured Taken To: Carlsbad Medical Center									
By: Carlsbad EMS										Owner's Phone:									
DESCRIPTION OF PROPERTY AND DAMAGE										Owner's Address/Zip Code:									
OTHER PROPERTY INVOLVED: None										Name: None came forward at scene									
WITNESS: None to date										Age: A-7									
Name:										Address:									
Telephone:										Telephone:									

COMPLETE FRONT OF FORM. 2. REMOVE CARBON AND TISSUE PAPER. 3. TURN OVER AND COMPLETE REVERSE SIDE.

**INJURY CODES**

K- Killed  
K1 Head  
K2 Chest  
A- Incapacitated - Carried From Scene  
A1 Head  
A2 Chest  
A3 Back  
B- Visible Injury  
B1 Head  
B2 Chest  
B3 Back  
C- Complaint - No Visible Injury  
O- No Apparent Injury

**RESTRAINT CODES**

1. Restraints - Not Installed  
2. Restraints - Not Used  
3. Lap Belts - Used  
4. Shoulder Harnesses - Not Used  
5. Shoulder Harnesses - Used  
6. Buckle Harnesses - Used  
7. Ejected From Vehicle  
8. Child Restraint Device  
A. Used Properly  
B. Not Used  
C. Used Improperly  
9. Airbag Deployed  
A. Other Restraints Not Used  
B. Other Restraints Used

ROAD-WEATHER <input type="checkbox"/> Daylight <input type="checkbox"/> Dawn <input type="checkbox"/> Dusk <input type="checkbox"/> Dark Lighted <input checked="" type="checkbox"/> Dark - Not Lighted <input type="checkbox"/> Other		WEATHER <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Raining <input type="checkbox"/> Snowing <input type="checkbox"/> Fog <input type="checkbox"/> Dust <input type="checkbox"/> Wind <input type="checkbox"/> Other		ROAD COND. <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Loose Material <input type="checkbox"/> Other		ROAD SURFACE <input type="checkbox"/> Paved Unstripped <input type="checkbox"/> Paved Center Stripe <input checked="" type="checkbox"/> Paved Center & Edgeline <input type="checkbox"/> Unpaved		TRAFFIC CONTROL <input type="checkbox"/> No Passing Zone <input type="checkbox"/> Stop Sign <input type="checkbox"/> Traffic Signals <input type="checkbox"/> Yield Sign <input type="checkbox"/> R.R. Gate <input type="checkbox"/> 4 Way Stop <input type="checkbox"/> Flashers <input checked="" type="checkbox"/> No Controls <input type="checkbox"/> Other		ROAD CHARACTER <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Curve GRADE <input type="checkbox"/> Level <input type="checkbox"/> Hillcrest <input checked="" type="checkbox"/> On Grade <input type="checkbox"/> Dip		ROAD DESIGN (Check One Or More For Each)																																
												<input type="checkbox"/> 1 Lane <input checked="" type="checkbox"/> 2 Lanes <input type="checkbox"/> 3 Lanes <input type="checkbox"/> 4 Lanes <input type="checkbox"/> Undivided <input type="checkbox"/> Physical Div. <input checked="" type="checkbox"/> Painted Div. <input type="checkbox"/> One Way <input type="checkbox"/> Ramp <input type="checkbox"/> Freeway <input type="checkbox"/> Underpass <input type="checkbox"/> Alley <input checked="" type="checkbox"/> Other <input type="checkbox"/> Conf. Zone																																
APPARENT CONTRIBUTING FACTORS (Check One Or More For Each)														WHAT DRIVERS WERE DOING (Check One For Each)																														
<input type="checkbox"/> Excessive speed <input type="checkbox"/> Speed too fast for conditions <input type="checkbox"/> Failed to yield right of way <input type="checkbox"/> Passed stop sign <input type="checkbox"/> Disregarded traffic signal <input type="checkbox"/> Drove left of center <input type="checkbox"/> Improper overtaking <input type="checkbox"/> Avoided no contact vehicle <input type="checkbox"/> Avoided no contact - other														<input checked="" type="checkbox"/> Following too closely <input type="checkbox"/> Made improper turn <input type="checkbox"/> Driver inattention <input checked="" type="checkbox"/> Under influence of alcohol <input type="checkbox"/> Other improper driving <input type="checkbox"/> Pedestrian error <input type="checkbox"/> Inadequate brakes <input type="checkbox"/> Driverless moving vehicle <input type="checkbox"/> Defective steering				<input type="checkbox"/> Defective tires <input type="checkbox"/> Other mechanical defective <input type="checkbox"/> Road defect <input type="checkbox"/> Other - No driver error <input type="checkbox"/> Traffic control not functioning <input type="checkbox"/> Improper lane change <input type="checkbox"/> Improper backing <input type="checkbox"/> None <input type="checkbox"/> Vehicle skidded before braking				<input checked="" type="checkbox"/> Going Straight <input checked="" type="checkbox"/> Overtaking - Passing <input type="checkbox"/> Right Turn <input type="checkbox"/> Left Turn <input type="checkbox"/> U Turn <input type="checkbox"/> Slowing <input type="checkbox"/> Backing <input type="checkbox"/> Stopped for traffic <input type="checkbox"/> Stopped for signal/sign <input type="checkbox"/> Start in traffic lane <input type="checkbox"/> Start from park <input type="checkbox"/> Parked <input type="checkbox"/> Other																						
DRIVER OR PEDESTRIAN SOBRIETY (Check One Or More For Each)				DRIVER OF PEDESTRIAN PHYSICAL CONDITION (Check One Or More For Each)				PEDESTRIAN ACTION																																				
<input type="checkbox"/> Consumed Alcohol <input type="checkbox"/> Consumed a Controlled Substance <input type="checkbox"/> Had Not Consumed Alcohol <input type="checkbox"/> Sobriety Unknown <input type="checkbox"/> Consumed Medication <input checked="" type="checkbox"/> Tested By Instrument <input type="checkbox"/> Field Sobriety Test <input type="checkbox"/> Eye Gaze / Nystagmus				<input type="checkbox"/> Fatigue/Asleep <input type="checkbox"/> Eyesight Imp. <input type="checkbox"/> Hearing Imp. <input type="checkbox"/> ILL <input type="checkbox"/> Medication <input type="checkbox"/> Amputee <input checked="" type="checkbox"/> No App. Defects <input type="checkbox"/> Other Physical Impairment *Specify _____				All Intersection <input type="checkbox"/> With Signal <input type="checkbox"/> Against Signal <input type="checkbox"/> No Signal <input type="checkbox"/> Diagonal Not All Intersection <input type="checkbox"/> From Behind <input type="checkbox"/> Obstruction <input type="checkbox"/> No Crosswalk <input type="checkbox"/> Crosswalk <input type="checkbox"/> Walking W/ Tr. <input type="checkbox"/> Other* *Specify None																																				
Diagram Drawn By: Officer Jason Waller				Measurements By: Officer Jason Waller				Leave Blank																																				
DIAGRAM See Attached Diagram																																												
Use Supplemental Diagram/Narrative Sheet for additional information NARRATIVE (Describe how accident occurred)																																												
See Attached Narrative																																												
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td rowspan="2">TRAILER OR TOWED VEHICLES</td> <td>TOWED BY VEH.#1</td> <td>1</td> <td>Year</td> <td>1990</td> <td>Make</td> <td>Alloy</td> <td>Lic Yr - State - Number</td> <td>E28197-US Government</td> <td>Type</td> <td>Tru-Pac</td> </tr> <tr> <td>TOWED BY VEH.#2</td> <td>NA</td> <td>Year</td> <td></td> <td>Make</td> <td></td> <td>Lic Yr - State - Number</td> <td></td> <td>Type</td> <td></td> </tr> </table>														TRAILER OR TOWED VEHICLES	TOWED BY VEH.#1	1	Year	1990	Make	Alloy	Lic Yr - State - Number	E28197-US Government	Type	Tru-Pac	TOWED BY VEH.#2	NA	Year		Make		Lic Yr - State - Number		Type											
TRAILER OR TOWED VEHICLES	TOWED BY VEH.#1	1	Year	1990	Make	Alloy	Lic Yr - State - Number	E28197-US Government	Type	Tru-Pac																																		
	TOWED BY VEH.#2	NA	Year		Make		Lic Yr - State - Number		Type																																			
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td rowspan="3">SURVEYOR ACTION</td> <td>VEH. NO. 2</td> <td>Name</td> <td>Isreal Alvarez</td> <td>Violation</td> <td>DWI 2nd Offense</td> <td>W</td> <td>B</td> <td>C</td> <td>Citation No.</td> <td>717210</td> </tr> <tr> <td>VEH. NO. 2</td> <td>Name</td> <td>Isreal Alvarez</td> <td>Violation</td> <td>Careless Driving</td> <td>W</td> <td>B</td> <td>C</td> <td>Citation No.</td> <td>3516728</td> </tr> <tr> <td>VEH. NO. 2</td> <td>Name</td> <td>Isreal Alvarez</td> <td>Violation</td> <td>Driver to be licensed</td> <td>W</td> <td>B</td> <td>C</td> <td>Citation No.</td> <td>3516730</td> </tr> </table>														SURVEYOR ACTION	VEH. NO. 2	Name	Isreal Alvarez	Violation	DWI 2nd Offense	W	B	C	Citation No.	717210	VEH. NO. 2	Name	Isreal Alvarez	Violation	Careless Driving	W	B	C	Citation No.	3516728	VEH. NO. 2	Name	Isreal Alvarez	Violation	Driver to be licensed	W	B	C	Citation No.	3516730
SURVEYOR ACTION	VEH. NO. 2	Name	Isreal Alvarez	Violation	DWI 2nd Offense	W	B	C	Citation No.	717210																																		
	VEH. NO. 2	Name	Isreal Alvarez	Violation	Careless Driving	W	B	C	Citation No.	3516728																																		
	VEH. NO. 2	Name	Isreal Alvarez	Violation	Driver to be licensed	W	B	C	Citation No.	3516730																																		
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Time Notified</td> <td>0145</td> <td>Time Arrived</td> <td>0207</td> <td>Notified By</td> <td>Well State Police</td> <td>Supv. at Scene</td> <td>Lt. Cottrell</td> <td>Checked By</td> <td>Waller</td> </tr> <tr> <td>Officer's Signature</td> <td colspan="2">Jason Waller</td> <td>A-8</td> <td>ID No.</td> <td>2506</td> <td>District</td> <td>03</td> <td>Date of Report</td> <td>08-25-02</td> </tr> </table>														Time Notified	0145	Time Arrived	0207	Notified By	Well State Police	Supv. at Scene	Lt. Cottrell	Checked By	Waller	Officer's Signature	Jason Waller		A-8	ID No.	2506	District	03	Date of Report	08-25-02											
Time Notified	0145	Time Arrived	0207	Notified By	Well State Police	Supv. at Scene	Lt. Cottrell	Checked By	Waller																																			
Officer's Signature	Jason Waller		A-8	ID No.	2506	District	03	Date of Report	08-25-02																																			

New Mexico State Police		Injury Accident Involving WIPP Truck		Case Number	02-092067
Drawn By	Date Drawn	Incident Date	Location	Scale	1 in : 28 ft
Officer Jason Waller	8/26/02	8/25/02	US 62-180 Mile Marker 39		

Diagram Not To Scale

Paved Shoulder

US 62-180 Westbound

Paved Shoulder

Truck Bed Vehicle #2

Truck Bed Vehicle #2

Dirt Median

Cab of Vehicle #2

Paved Shoulder


US 62-180 Eastbound

Reference Line

Paved Shoulder

Reference Point Mile Marker 39 396 feet West

Dirt Right of Way 25  
Rear Tire Fender 50




RP	RL	RP	RL
A 396 E	13 N	H 650 E	44 N
B 415 E	15 N	I 654 E	28 N
C 420 E	17 N	J 970 E	6 S
D 600 E	55 N	K 1007 E	6 S
E 612 E	19 N	L 1027 E	5 S
F 505 E	14 S		
G 651 E	55 N		

HTD-15075  
EV. 7/90

OTHER INFORMATION: The WIPP truck, trailer and Tru-pac containers were inspected at the scene by DOE, Westinghouse and MTD personnel to ensure the safe travel of the waste shipment to the WIPP site. No problems were located with the truck, trailer or Tru-pac containers and the shipment was escorted to WIPP by MTD Officer O'Rielley to ensure it's safe arrival at WIPP.

Case	Date	Location	Case #
08-25-2002	0130	US 62-180 Mile Marker 39	Eddy
Driver No 1			04
Jerry E. Harway			
Driver No 2			04
Israel C. Alvidrez			

  
 C A-10 on Waller #2506  
 New York City Police 08-25-2002

**Thomas L Clements**

03/24/2003 11:38 AM

To: Barry H O'Brien/BHO/CC01/INEEL/US@INEL, Kip E Archibald/ARCHKE/CC01/INEEL/US@INEL, Jeffrey M Lacy/LACYJM/CC01/INEEL/US@INEL  
cc: Bobby A Picker/BAP/CC01/INEEL/US@INEL, Geneine D Staymates/STAYGD/CC01/INEEL/US@INEL, Jerry L Wells@Exchange

Fax to:  
Subject: CBFO Accident Paper with Regards to T-157

fyi.

Thanks Jerry.

----- Forwarded by Thomas L Clements/TLC/CC01/INEEL/US on 03/24/03 12:06 PM -----

**Jerry L  
Wells@Exchange**

03/24/03 11:11 AM

To: Thomas L Clements/TLC/CC01/INEEL/US@INEL, Robert D Newbry@Exchange  
cc: Jerry L Wells@Exchange  
Fax to:  
Subject: CBFO Accident Paper with Regards to T-157

Tom,  
Attached is the accident paper CBFO generated with regards to T-157.

Regards,  
Jerry



Accident\_Unrelated  
\_to\_ICV\_contamination.

## August 25, 2002 Pickup Truck Accident with INEEL Shipment to WIPP Not Related to Contamination Inside TRUPACT #157

TRUPACT 157 was mounted in the center position of the three-position trailer, with the second TRUPACT in the forward position and no payload in the rear position. The pickup truck struck the trailer near the left rear fender area. A horizontal fender member welded to the trailer frame and the left rear-most outer tire absorbed the bulk of the impact (and sustained virtually all of the physical damage to the trailer). The horizontal member also supported a mudflap and carried running lights. Please refer to the accompanying photographs of the accident scene.

With the TRUPACT trailer traveling at ~40 mph and the pickup truck traveling at ~70 mph (accident report values), the relative impact was similar to that of a 30 mph accident (~60 ft/sec and 100 ft/sec respectively). As the pickup truck struck the horizontal member, the mud flap broke free and the horizontal member bent up and forward. As the horizontal member bent away, the outer tire of the rear-most axle was exposed and the pickup truck apparently rode up over that tire. The impact forces at that point were directed up and to the left as the tire rotation spun the pickup truck up and outward. The accident report shows that the initial impact point of the pickup truck back onto the pavement was 24 ft forward of the impact point and ~5 feet to the left of the impact point. The accident report also shows the pickup truck's continued path across the left lane of the eastbound highway and out into the median. While the bed, cab, and frame of the pickup all broke up upon impact, and tumbled to separate locations, the center of mass of these parts came to rest about ~260 ft forward and ~35 ft to the left of the point of impact. The fender and mudflap were knocked off the horizontal member and came to rest about ~110 ft forward and ~35 ft to the right of the point of impact. The left outer rear-most tire of the trailer was damaged and deflated. Subsequent inspections of the condition of the TRUPACT shipping containers indicated no visible contact points with flying debris from the impact.

After inspection and escort to the WIPP site, the two TRUPACT containers were processed according to standard unloading procedures. All processes were normal until the air sample was collected from within the inner containment vessel, and the TRUPACT was re-sealed and shipped back to INEEL for recovery.

During recovery operations, it was determined that the payload assembly had not shifted within the inner containment vessel. This was noted by the fact that the guide tubes inserted through holes in the four plastic slip sheets between the payload containers were clearly not bound and were still loosely in place. If the payload assembly had shifted, even slightly, the guides tubes would bind in their mating depression in the TRUPACT pallet. Even small lateral forces typically cause the guide tubes to resist when removed. In the case of TRUPACT 157, the guide tubes were loose, implying the assembly had not moved from its position when loaded. In addition, careful inspection showed that there were no apparent rubbing or abrasion marks between the payload containers and the inner containment vessel.

In summary, the pickup truck collision with the WIPP shipment did not cause or exacerbate the release of contamination into the inner containment vessel of TRUPACT 157. The inertial differential between 80,000 and 2,500 lb vehicles is enormous. Most of the pickup truck collision energy was split between bending the small horizontal member (holding the trailer fender and mudflap) and the spinning left rear-most tire. There is indirect evidence that the payload had not shifted (even slightly) throughout transit and during the accident impact. This information, along with physical evidence that the retaining ring of one of the payload containers was loose, leads to the conclusion that the contamination inside TRUPACT 157 was unrelated to the pickup truck accident.





Fig 1. Photo showing trailer after accident, with rear TRUPACT position empty



Fig. 2 Photo showing left horizontal fender member bent by Pickup impact



Fig. 3 Photo showing impact marks in the left fender member and damage to tire



Figure 4. Side view of impact area (left rear of trailer)



Fig. 5 Photo indicating no impact from flying accident debris




Fig. 6 Photo showing TRUPACT mounting fixtures still intact







Fig. 7 Photo showing fender assembly ~110 ft forward and ~35 ft to the right of the impact point



Fig. 8 Photo showing 1998 Dodge Pickup after the accident – the driver suffered only minor injuries

 - Tritium Swipe





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: 668<sup>64</sup> 607  
AREA/ROOM: HOT SHOP  
RWP #: 3100 2224 96 02  
LOG #: 9  
DATE: 1-27-03  
TIME: 1400

☐ ROUTINE **JOB DESCRIPTION**

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: CASK # 157 did removal recovery.  
Report Batch #s = 5298, 5297, 5296

Area DATA # 2900 1689 01 18


RCT: Handwritten signature  
PRINT/SIGNATURE

REVIEWED BY: Handwritten signature


## TRUPACT

Cask# 157


Survey NA-157-2




INSIDE OUTER LID RIGHT SIDE



INSIDE OUTER LID LEFT SIDE



INNER LID RIGHT SIDE



INNER LID LEFT SIDE



# Tan Smear Report

Batch ID: smear - 200301271343 Count Date: 1/27/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,298 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location:

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

copy

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127134312-A2	Unknown	-1.00	0.58	15.37	8.81	6.55	21.89
20030127134442-A1	Unknown	-1.00	0.58	15.37	20.10	8.27	21.89
20030127134552-A3	Unknown	2.34	3.39	15.37	20.10	8.27	21.89
20030127134702-A4	Unknown	-1.00	0.58	15.37	11.07	6.93	21.89
20030127134812-A5	Unknown	-1.00	0.58	15.37	38.17	10.45	21.89
20030127134922-A6	Unknown	-1.00	0.58	15.37	33.65	9.95	21.89
20030127135043-A7	Unknown	-1.00	0.58	15.37	90.11	15.05	21.89
20030127135153-A8	Unknown	-1.00	0.58	15.37	26.87	9.15	21.89
20030127135303-A9	Unknown	-1.00	0.58	15.37	69.78	13.44	21.89
20030127135413-A10	Unknown	-1.00	0.58	15.37	35.91	10.20	21.89
20030127135523-A11	Unknown	5.69	4.77	15.37	20.10	8.27	21.89
20030127135633-A12	Unknown	-1.00	0.58	15.37	26.87	9.15	21.89
20030127135743-A13	Unknown	-1.00	0.58	15.37	31.39	9.69	21.89
20030127135853-A14	Unknown	2.34	3.39	15.37	123.98	17.41	21.89
20030127140013-A15	Unknown	-1.00	0.58	15.37	42.68	10.93	21.89

Reviewed by:

*[Signature]*

2/27/010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/27/03  
 Print Time 2:01:24PM



# Tan Smear Report

Batch ID: smear - 200301271326  
 Count Date: 1/27/03  
 Group: A  
 Count Minutes: 1.0  
 Device: LB5100 #324920  
 Count Mode: Simultaneous  
 Batch Key: 5,297  
 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel  
 Survey Location:

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127132619-A <sup>(16)</sup>	Unknown	5.69	4.77	15.37	15.58	7.63	21.89
20030127132749-A <sup>(17)</sup>	Unknown	5.69	4.77	15.37	6.55	6.15	21.89
20030127132859-A <sup>(18)</sup>	Unknown	-1.00	0.58	15.37	15.58	7.63	21.89
20030127133009-A <sup>(19)</sup>	Unknown	5.69	4.77	15.37	17.84	7.96	21.89
20030127133119-A <sup>(20)</sup>	Unknown	-1.00	0.58	15.37	26.87	9.15	21.89

Reviewed by:

010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/27/03

Print Time 1:32:31PM



# Tan Smear Report

Count Date: 1/27/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Patch ID: smear - 200301271238  
 Group: A  
 Device: LB5100 #324920  
 Patch Key: 5296  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location:

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30  $\pm$  0.17 Alpha: 29.90  $\pm$  0.23  
 Beta Rate: 4.10  $\pm$  0.64 Beta: 44.28  $\pm$  0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
A-25	Unknown	5.69	4.77	15.37	20.10	8.27	21.89
123858-A1 (21)	Unknown	2.34	3.39	15.37	6.55	6.15	21.89
124028-A2 (22)	Unknown	-1.00	0.58	15.37	15.58	7.63	21.89
30127124138-A3 (23)	Unknown						

Reviewed by: 

COPY



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

COPY

BARCODE #

BLDG.: <u>HOT SHOP/EXTENSION</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>TRUPACT FLOOR PLAN</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>21002496 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level 6-7-3-03</u>	
LOG #: <u>5</u>	<u>Tru-pact 157 - After Containment Sleeve</u>	
DATE: <u>1/27/03</u>	<u>was accordioned on. Last step in this</u>	
TIME: <u>1500</u>	<u>Rwp Coverage.</u>	

RCT: F. Bush / 7 Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
L-177	801973	10 %
L-177	802224	10 %
Scaler		%βγ
		%α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		



CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# se Rate  
#β / #γ A-27 ted / Gamma Dose Rates  
α alpha

☐ Direct Scan  
○ Swipe (Smear)  
L Large Area Wipe (LAW)  
△ Air Sample  
□ Tritium Swine





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

COPY

BARCODE #

BLDG.: HOT SHOP/EXTENSION  
AREA/ROOM: TRUPACT FLOOR  
PLAN  
RWP #: 31002496 02  
LOG #: 5  
DATE: 1/27/03  
TIME: 1500

☐ ROUTINE **JOB DESCRIPTION**  
☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level  
RBA Masslin Wipe down follow- CCU  
Lid removal TO Lid Stand-

RCT: F. Bush / 7 Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
177-L	801973	10 %
177-L	802224	10 %
		%
Scaler		%βγ
		%α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		



CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area

-x-x- Radiological Barrier



ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ A-29 β / Gamma Dose Rates  
α

☐ - Direct Scan  
○ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



- - Direct Scan
- - Swipe (Smear)
- └ - Large Area Wipe (LAW)
- △ - Air Sample
- ⬆ - Tritium Swipe



COPY

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
	324820	%
Scaler	<del>135100</del>	44.28 %By
	614-30-03	29.9 %α

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x-x- Radiological Barrier**

**ALL dose rates are in mrem/hr, unless otherwise noted.**

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	Neutrons

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: 6-203 668 607  
AREA/ROOM: HOT SHOP  
RWP #: 31002496 02  
LOG #: 9  
DATE: 1-27-03  
TIME: 1530

☐ ROUTINE **JOB DESCRIPTION**

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: Cask #157 recovery

Smear 7-9 used on viewing camera

Report Batch #'s: 5306, 5301, 5299

Alara tank # 29001689 0117


RCT: L. Bina / J. McKinlay  
120 PRINT/SIGNATURE

REVIEWED BY: [Signature]


TRUPACT

CASK # 157


SURVEY # NA -157 -



INSIDE INNER LID LEFT SIDE



INSIDE INNER LID RIGHT SIDE



SLIP COVER

TOP OF  
PAYLOAD  
INSIDE  
CASK

# Tan Smear Report

Batch ID: smear - 200301271720  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,299  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: ICV inner lid/underside/ and top of Payload.

Count Date: 1/27/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127172009-A1	Unknown	2.34	3.39	15.37	22.36	8.57	21.89
20030127172139-A2	Unknown	-1.00	0.58	15.37	4.29	5.72	21.89
20030127172250-A3	Unknown	-1.00	0.58	15.37	17.84	7.96	21.89
20030127172400-A4	Unknown	5.69	4.77	15.37	13.32	7.29	21.89
20030127172510-A5	Unknown	-1.00	0.58	15.37	13.32	7.29	21.89

Reviewed by:

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/27/03

Print Time 5:26:21PM





# Tan Smear Report

Count Date: 1/27/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Batch ID: smear - 200301271736  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,301  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: Q-Tip inside port hole.

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127173603-AX	Unknown	-1.00	0.58	15.37	20.10	8.27	21.89

Reviewed by:

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/27/03  
 Print Time 5:37:35PM



# Tan Smear Report

Batch ID: smear - 200301271808  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,306  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: Smears taken on viewing camera probe.

Count Date: 1/27/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127180850-A17	Unknown	5.69	4.77	15.37	11.07	6.93	21.89
20030127181020-A18	Unknown	2.34	3.39	15.37	17.84	7.96	21.89
20030127181130-A19	Unknown	2.34	3.39	15.37	17.84	7.96	21.89

Reviewed by:

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/27/03

Print Time 6:12:42PM



# AIRBORNE SURVEY RESULTS

# COPY

Use this form in conjunction with MCP-7, MCP-356, MCP-357, TPR-6430, and TPR-6431.

## Initial Count

Facility: TAN Building: 607 Room/Area: Hot Shop  
RWP No.: 31002496 02 ALARA Task No.: 27001689 01 18  
Job Description: TRUPACT-157 Repackage  
Date/Time Taken: 1-27-03 16:23 to 16:48\* Sampler ID: 0785 Sampler Type: STAPLEX  
Total Time (min): 15 (power outage) X Flow Rate (cfm/lpm): 9.8 = Total Vol. (ft<sup>3</sup>/liters): 147  
Comments: 1440 spm βγ = 1.66 FCF using .8570 filter eff.  
865 spm \*(10 min power outage during sampling)

Counter Type: NMC Counter ID No.: 237709 % Eff. βγ: 31  
Count Time (min): 1 Date and Time Counted: 1/27/03 1700 % Eff. α: 28  
Gross CPM βγ: 482 - Bkgd. CPM βγ: 35.7 = Net CPM βγ: 446.3  
Gross CPM α: 206 - Bkgd. CPM α: .1 = Net CPM α: 205.9  
Activity, μCi/cc βγ: 1.83E<sup>-10</sup> + Applicable DAC βγ: 2E<sup>-9</sup> = DAC Fraction βγ: .092  
Activity, μCi/cc α: 9.37E<sup>-11</sup> + Applicable DAC α: 2E<sup>-12</sup> = DAC Fraction α: 46.86  
Respirator Protection Factor: 1 Total DAC Fraction: 46.95  
Effective DAC Fraction: 46.95  
RadCon: F. Bush F. Bush  
(Print Name) (Signature)

## Delayed Count

Counter Type: NMC Counter ID No.: 237709 % Eff. βγ: 31  
Count Time (min): 1 Date and Time Counted: 1-27-03 / 1235 % Eff. α: 28  
Gross CPM βγ: 254 - Bkgd. CPM βγ: 35.7 = Net CPM βγ: 218.3  
Gross CPM α: 122 - Bkgd. CPM α: .1 = Net CPM α: 121.9  
Activity, μCi/cc βγ: 8.97E<sup>-11</sup> + Applicable DAC βγ: 2E<sup>-9</sup> = DAC Fraction βγ: .045  
Activity, μCi/cc α: 5.55E<sup>-11</sup> + Applicable DAC α: 2E<sup>-12</sup> = DAC Fraction α: 27.741  
Respirator Protection Factor: 1 Total DAC Fraction: 27.78  
Effective DAC Fraction: 27.78  
RadCon: F. Bush F. Bush  
(Print Name) (Signature)

## Evaluation

Effective DAC Fraction = Total DAC Fraction ÷ Respirator Protection Factor  
If Effective DAC Fraction < 0.3 then DAC-hour tracking is not required.  
If Effective DAC Fraction ≥ 0.3 then DAC-hour tracking is required.

## Review

RadCon Foreman/Supervisor: G. L. Lusk  
(Print Name)

Date: 11-28-01-28-0



# AIRBORNE SURVEY RESULTS

COPY

## Delayed Count

Counter Type: NMC Counter ID No.: 237709 % Eff.  $\beta/\gamma$ : 31  
Count Time (min): 1 Date and Time Counted: 1-27-03 / 1835 % Eff.  $\alpha$ : 28  
Gross CPM  $\beta/\gamma$ : 122 - Bkgd. CPM  $\beta/\gamma$ : 35.7 = Net CPM  $\beta/\gamma$ : 86.3  
Gross CPM  $\alpha$ : 40 - Bkgd. CPM  $\alpha$ : .1 = Net CPM  $\alpha$ : 39.9  
Activity,  $\mu\text{Ci/cc } \beta/\gamma$ :  $3.55 \text{ E}^{-11}$  + Applicable DAC  $\beta/\gamma$ :  $2 \text{ E}^{-9}$  = DAC Fraction  $\beta/\gamma$ : .018  
Activity,  $\mu\text{Ci/cc } \alpha$ :  $1.82 \text{ E}^{-11}$  + Applicable DAC  $\alpha$ :  $2 \text{ E}^{-12}$  = DAC Fraction  $\alpha$ : .08  
Respirator Protection Factor: 1  $\alpha T_{1/2} = \frac{.453(90)}{1.4 \times 1625} = 38 \text{ min}$   $\beta T_{1/2} = \frac{.623(90)}{1.4 \times 328} = 38 \text{ min}$  Total DAC Fraction: 2.09  
RadCon: F. Bush (Print Name) [Signature] (Signature)

## Delayed Count

Counter Type: \_\_\_\_\_ Counter ID No.: \_\_\_\_\_ % Eff.  $\beta/\gamma$ : \_\_\_\_\_  
Count Time (min): \_\_\_\_\_ Date and Time Counted: \_\_\_\_\_ % Eff.  $\alpha$ : \_\_\_\_\_  
Gross CPM  $\beta/\gamma$ : \_\_\_\_\_ - Bkgd. CPM  $\beta/\gamma$ : \_\_\_\_\_ = Net CPM  $\beta/\gamma$ : \_\_\_\_\_  
Gross CPM  $\alpha$ : \_\_\_\_\_ - Bkgd. CPM  $\alpha$ : \_\_\_\_\_ = Net CPM  $\alpha$ : \_\_\_\_\_  
Activity,  $\mu\text{Ci/cc } \beta/\gamma$ : \_\_\_\_\_ + Applicable DAC  $\beta/\gamma$ : \_\_\_\_\_ = DAC Fraction  $\beta/\gamma$ : \_\_\_\_\_  
Activity,  $\mu\text{Ci/cc } \alpha$ : \_\_\_\_\_ + Applicable DAC  $\alpha$ : \_\_\_\_\_ = DAC Fraction  $\alpha$ : \_\_\_\_\_  
Respirator Protection Factor: \_\_\_\_\_ Total DAC Fraction: \_\_\_\_\_  
Effective DAC Fraction: \_\_\_\_\_  
RadCon: \_\_\_\_\_ (Print Name) \_\_\_\_\_ (Signature)

## Delayed Count

Counter Type: \_\_\_\_\_ Counter ID No.: \_\_\_\_\_ % Eff.  $\beta/\gamma$ : \_\_\_\_\_  
Count Time (min): \_\_\_\_\_ Date and Time Counted: \_\_\_\_\_ % Eff.  $\alpha$ : \_\_\_\_\_  
Gross CPM  $\beta/\gamma$ : \_\_\_\_\_ - Bkgd. CPM  $\beta/\gamma$ : \_\_\_\_\_ = Net CPM  $\beta/\gamma$ : \_\_\_\_\_  
Gross CPM  $\alpha$ : \_\_\_\_\_ - Bkgd. CPM  $\alpha$ : \_\_\_\_\_ = Net CPM  $\alpha$ : \_\_\_\_\_  
Activity,  $\mu\text{Ci/cc } \beta/\gamma$ : \_\_\_\_\_ + Applicable DAC  $\beta/\gamma$ : \_\_\_\_\_ = DAC Fraction  $\beta/\gamma$ : \_\_\_\_\_  
Activity,  $\mu\text{Ci/cc } \alpha$ : \_\_\_\_\_ + Applicable DAC  $\alpha$ : \_\_\_\_\_ = DAC Fraction  $\alpha$ : \_\_\_\_\_  
Respirator Protection Factor: \_\_\_\_\_ Total DAC Fraction: \_\_\_\_\_  
Effective DAC Fraction: \_\_\_\_\_  
RadCon: \_\_\_\_\_ (Print Name) \_\_\_\_\_ (Signature)

## Review

RadCon Foreman/Supervisor: \_\_\_\_\_

G. L. Lusk  
(Print Name)

[Signature]  
(Signature)

Date: 1-28-03

10/10/10





# TAN Hi-Vol Report Delayed Count No Respirator

COPY

Batch ID: Delayed Count Grab Sample NO RESP - 200301280824 Count Date: 1/28/03  
 Group: A Count Minutes: 10.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,309 Operating Volts: 1320  
 Selected Geometry: 1/4" Stainless Steel

Hi-Vol Data on/off time Trupact 157 Hi-vol, 1/27/03 1623 to 1648 (with 10 min. power outage) 15 min. total run time D-785 Staplex sampler, 9.8 cfm.

RWP/AT #

31002496 02 2900689 01 18

J. Johnston

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.10 ± 0.10	Alpha:	29.90 ± 0.23
Beta Rate:	4.30 ± 0.66	Beta:	44.28 ± 0.07

Hi-Vol ID/ Location	Alpha (uCi/ml)	Unc	Alpha MDA (uCi/ml)	Beta (uCi/ml)	Unc	Beta MDA (uCi/ml)
inside Containment after initial opening	2.98E-013	1.09E-013	2.66E-013	1.76E-012	3.07E-013	8.11E-013

Alpha (cpm): 0.80 Beta (cpm): 11.50

DAC Alpha: 0.1500 DAC Beta: 0.0000

Total DAC: 0.1500

Applicable DAC  $\alpha$  = 2.0E-12 uCi/ml, Applicable DAC By = 2.0E-9 uCi/ml

Total Effective DAC: 0.1500

Volume 4,163,040.00 Units ml

Reviewed by:

*[Signature]*



242.11  
23/2001  
.02

## FACSIMILE COVER SHEET

Idaho National Engineering and Environmental Laboratory



## FACSIMILE SHEET

DATE: 2-19-03

TO: K. Archibald

Organization/Location:

Phone Number:

FAX Number: 6-4236

FROM: G. Lusk

Organization/Location:

Phone Number: 4165

FAX Number: 526-6648

## COMMENTS:

This transmittal consists of [ 1 ] pages **EXCLUDING** cover sheet.

## NOTICE OF CONFIDENTIALITY

This facsimile may contain **PRIVILEGED** or **COMPANY PRIVATE** information that is intended solely for the use of the specific individual or entity named above as the addressee and may not otherwise be disclosed, copied, distributed or disseminated. If you are not the intended recipient or have received this transmission in error please destroy your copy and notify the sender immediately by telephone.

PLEASE REMOVE ANY STAPLES



# TAN HI-Vol Report Delayed Count Respirator

Patch ID: Delayed Count Grab Sample NO RESP - 200302030819 Count Date: 2/3/03  
 Group: A Count Minutes: 10.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Patch Key: 5,372 Operating Volts: 1320  
 Selected Geometry: 1/4" Stainless Steel  
 HI-VOL DATA on/off time HI-VOL TAKEN INSIDE CONTAINMENT OF TRUPACT 157 ON INITIAL OPENING, 1-27-03 1623 TO 1648 (10 MIN. POWER OUTAGE) 15 MIN.  
 WPIAT # RUN TIME D-783 STAPLEX, 9.8 CFM

3/00249603 2960/688 0118

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 5.40 ± 0.73 Beta: 44.28 ± 0.07

<u>IID/ Location</u>	<u>Alpha</u> <u>(uCi/ml)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(uCi/ml)</u>	<u>Beta</u> <u>(uCi/ml)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(uCi/ml)</u>
PACT 157 HI-VOL	1.28E-013	8.09E-014	2.66E-013	8.80E-013	2.93E-013	9.01E-013
Alpha (cpm): 0.40	Beta (cpm): 9.00			Total DAC: 0.0600		
ACA Alpha: 0.0600	DAC Beta: 0.0000			Total Effective DAC: 0.0600		
Applicable DAC $\alpha$ = 2.0E-12 uCi/ml, Applicable DAC $\beta$ = 2.0E-9 uCi/ml						
Volume 4,163,040.00	Units ml					

Reviewed by:

*[Signature]*



Idaho National Engineering & Environmental Laboratory

---

INTERDEPARTMENTAL COMMUNICATION  
Direct Read Monitoring Results

---

Date: 04/15/2003

To: DOUGLAS WALE

MS: 9206 526-1102

From: TOBIN MOTT

MS: 5222 526-3688

Subject: TRUPACT REPACKAGING

---

Location: INEL TAN 607

---

Assessment: 3429.00

Work Process: OPERATIONS

Category: WASTE PROCESSING

Task: WASTE REPACKAGING

Industrial Hygiene performed area sampling, per MCP-153, relating to the repackaging of TRUPACT-157 at TAN-607. Sampling is necessary to (1) determine workplace hazard levels, (2) determine appropriate control measures, and (3) ensure compliance with applicable procedures and standards.

The sample results are specific to the following:

THIS ACTIVITY WAS PERFORMED PER THE FOLLOWING DOCUMENTS:

TPR-6230 & TPR-6233 WITH CORRESPONDING JSA'S WERE USED. THIS PROCESS WAS IDEALLY A ONE-TIME ACTIVITY.

THIS ACTIVITY INVOLVED THE REPACKAGING OF DRUMS FROM A TRUPACT CONTAINER TO STANDARD METAL WASTE BOXES. THE DRUMS CONTAINED MIXED LOW LEVEL WASTE (MLLW). THE WASTE WAS KNOWN TO CONTAIN VOLATILE ORGANIC CHEMICALS (VOC'S). CONTAINMENT AND VENTILATION WERE USED AS THE DRUMS WERE TRANSFERRED FROM THE TRUPACT CONTAINER TO THE STANDARD WASTE BOXES.

A RAE SYSTEMS "MINIRAE" PHOTOIONIZATION DETECTOR (PID) WAS USED TO OBTAIN REAL TIME VOC MEASUREMENTS. IT WAS ALSO USED AS A PUMP TO FILL TEDLAR BAGS. THE TEDLAR BAGS WERE THEN QUALITATIVELY MEASURED USING A BRUELL& KJAR (B&K) PHOTOACOUSTIC ANALYZER. HOWEVER, THE B&K ANALYZER WOULD NOT PROPERLY RESPOND DURING TO BUMP TESTING SO THE DATA WAS NOT VALIDATED. THE B&K DATA WAS SUPPLEMENTARY INFORMATION THEREFORE THE FAILED BUMP TEST WAS NOT CRITICAL IN DETERMINING EXPOSURE LEVELS. THE PID WAS THE PRIMARY INSTRUMENT FOR AREA MONITORING. IN ADDITION, THE HEADSPACE OF THE DRUMS HAD BEEN SAMPLED PRIOR TO THE REPACKAGING SO THE B&K DATA WAS NOT ESSENTIAL TO ACQUIRE QUALITATIVE INFORMATION. THE PURPOSE OF THE AREA SAMPLING WAS TO ENSURE NO ELEVATED VOC LEVELS WERE PRESENT. AREA SAMPLES WERE MAINLY COLLECTED IN THE HEADSPACE AREA WHILE THE TRUPACT CONTAINER WAS BEING DISASSEMBLED INSIDE CONTAINMENT PER TPR-6230. AREA SAMPLING WAS ALSO PERFORMED IN THE GENERAL AREA AROUND THE TENT THAT THE PAYLOAD OF THE TRUPACT CONTAINER WAS DISASSEMBLED IN PRIOR TO DRUM REPACKAGING INTO STANDARD METAL WASTE BOXES. AREA SAMPLING WAS PERFORMED ON THE OUTSIDE OF THE TENT TO BE MORE REPRESENTATIVE OF WORKER EXPOSURE. ALL FORMS OF CONTAINMENT WERE EXHAUSTED THROUGH HEPA-FILTERED AIR MOVERS AT A DISTANCE OF APPROXIMATELY 20 FEET FROM ROUTINELY OCCUPIED SPOTS. SMALL PEAK LEVELS OF VOC'S WERE RECORDED BUT DISSIPATED OVER TIME.

HEAT STRESS MEASUREMENTS WERE TAKEN ON THE FIRST DAY AND STAY TIMES WERE NOT DEEMED NECESSARY.

---

Recommended Controls:

Based on this assessment, the following controls were recommended for safe operation.

---

Engineering Controls:

GENERAL DILUTION VENTILATION  
HEPA FILTERED EXHAUST  
NEGATIVE PRESSURE FULL ENCLOSURE  
PARTIAL ENCLOSURE

---

Administrative Controls:

BARRICADES/PHYSICAL BARRIERS  
PREJOB BRIEFING  
DESIGNATED EATING AREA  
HAND WASHING FACILITIES  
HEAT STRESS MONITORING  
POLICIES  
AWARE OF BODY POSITION  
PROCEDURES  
SIGNS  
TRAINING

---

Follow Up Actions:

The actions noted below have been determined per MCP-153, Appendices A,B,C,E and F. They are necessary to ensure continued safe operations.

NO UPDATE REQUIRED

---

The sample results were:

Sample: 1  
Agent: HEAT STRESS

Sample Type: DIRECT READ  
Sample Comments: HEAT STRESS MEASUREMENT. DETERMINED STAY TIMES  
UNNECESSARY BASED ON DRY BULB TEMPERATURES REMAINING STEADY.

Seq#	Sample Date	Sample Time	Location	Measured Value/ Exposure Limit	UOM
1	01/27/2003	13:15	TAN-607 HOT SHOP AND TRUCK EXTENSION	56	WIBGET

Sample: 2  
Agent: ORGANIC VAPORS

Sample Type: DIRECT READ  
Sample Comments: THE MINIRAE PID WAS USED FOR ALL DATA COLLECTION TO ESTIMATE  
VOC CONCENTRATIONS & ENSURES VOC LEVELS WERE NOT ELEVATED IN  
VARIOUS LOCATIONS.



Seq#	Sample Date	Sample Time	Location	Measured Value/ Exposure Limit	UOM
1	01/27/2003	13:15	INSIDE CONTAINMENT AROUND TRUPACT BETWEEN OCV AND ICV. OCV LID WAS OFF.	0.0	PPM
				5.0	PPM
2	01/27/2003	16:15	INSIDE CONTAINMENT. ICV LID WAS OFF & EXPOSED TO PAYLOAD. EMPLOYEES WEREN'T INSIDE SAMPLE SPACE.	0.3	PPM
				5.0	PPM

The sample results were:

Sample: 3  
Agent: ORGANIC VAPORS

Sample Type: DIRECT READ  
Sample Comments: THE MINIRAE PID WAS USED FOR ALL DATA COLLECTION TO ESTIMATE VOC CONCENTRATIONS & ENSURES VOC LEVELS WERE NOT ELEVATED IN VARIOUS LOCATIONS.

Seq#	Sample Date	Sample Time	Location	Measured Value/ Exposure Limit	UOM
1	01/28/2003	10:10	INSIDE CONTAINMENT. ICV LID WAS OFF & EXPOSED TO PAYLOAD.	0.3	PPM
				5.0	PPM
2	01/28/2003	13:30	GENERAL AREA OUTSIDE TENT	0.2	PPM
				5.0	PPM

The sample results were:

Sample: 4  
Agent: ORGANIC VAPORS  
Result Standard:  
Result Time:  
Sample Type: DIRECT READ  
Sample Comments: THE MINIRAE PID WAS USED FOR ALL DATA COLLECTION TO ESTIMATE VOC CONCENTRATIONS & ENSURES VOC LEVELS WERE NOT ELEVATED IN VARIOUS LOCATIONS.

Seq#	Sample Date	Sample Time	Location	Measured Value/ Exposure Limit	UOM
1	01/29/2003	14:16	GENERAL AREA OUTSIDE TENT	2	PPM
				5	PPM

These sample results are measures of hazardous agent levels present in workplace areas or materials. In some cases, these results can be used to estimate or predict employee exposures. However, they do not represent actual employee exposure levels. Employee exposures can only be determined via personal monitoring. The exposure limits (for airborne chemical hazards or physical

agents), that designate safe levels of employee exposure, are noted for comparison only.

---

Recommendations:

The purpose of the area sampling was to ensure no elevated VOC levels were present. Area samples were mainly collected in the headspace area, which did not present an exposure potential. Area monitoring was performed to verify controls. The controls were adequate to protect personnel. Please continue to adhere to control measures noted in the exposure assessment.

Please contact me if you have any questions.

cc: JAN BILLS  
TOBIN MOTT

MS:3125  
MS:5222

Uniform File Code: 5154  
Disposition Authority: A1-21.2-d-2  
Retention Schedule: Cut off when the facility is dismantled. Destroy 75  
years after cut off. (EPI)

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>HOT SHOP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 2496 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level 1-27-03</u>	
LOG #: <u>9</u>	<u>CASK #157 recovery</u>	
DATE: <u>1-27-03</u>	<u>Report Batch #3 = 5302, 5304, 5305, 5308</u>	
TIME: <u>1830</u>	<u>Alara task # 29001489 0118</u>	

RCT: J. D. and L. McKinlay  
PRINT/SIGNATURE

REVIEWED BY: SG Lee

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		26.9 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
			see 213500 printout sheets.				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  A-55  
 $\beta$  Gamma

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 $\Delta$  - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

COPY

Batch ID: smear - 200301271738  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,302  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: ICV inner Plug / 1-smear, 2-Q-Tip

Count Date: 1/27/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127173850-Al(1)	Unknown	5.69	4.77	15.37	8.81	6.55	21.89
20030127174020-Al(1)	Unknown	-1.00	0.58	15.37	20.10	8.27	21.89

A-57

Reviewed by:

*[Signature]*

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/29/03  
 Print Time 12:16:42PM



# Tan Smear Report

COPY

Batch ID: smear - 200301271746  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,304  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: 1-Smear upstream of of filter, 2- Q-Tip inside of port tool.

Count Date: 1/27/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127174625-A (2)	Unknown	-1.00	0.58	15.37	8.81	6.55	21.89
20030127174755-A (10)	Unknown	-1.00	0.58	15.37	11.07	6.93	21.89

A-59

Reviewed by:

*[Signature]*

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/29/03

Print Time 12:17:54PM





# Tan Smear Report

**Batch ID:** smear - 200301271750  
**Count Date:** 1/27/03  
**Group:** A  
**Count Minutes:** 1.0  
**Device:** LB5100 #324920  
**Count Mode:** Simultaneous  
**Batch Key:** 5,305  
**Operating Volts:** 1320  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** Smears outer plug lid plug

**Background (cpm)**  
 Alpha Rate: 0.30 ± 0.17      Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64      Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127175009-A (3)	Unknown	2.34	3.39	15.37	11.07	6.93	21.89
20030127175139-A (4)	Unknown	-1.00	0.58	15.37	17.84	7.96	21.89
20030127175249-A (5)	Unknown	2.34	3.39	15.37	6.55	6.15	21.89
20030127175400-A (6)	Unknown	-1.00	0.58	15.37	8.81	6.55	21.89

605-402

Reviewed by:

*[Signature]*

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date  
Print Time

1/29/03  
12:18:48PM

COPY



# Tan Smear Report

Batch ID: smear - 200301271729 Count Date: 1/27/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,300 Operating Volts: 1320  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: ICV inline filter 1-2 smears/ 3-4 q-tips

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.30 ± 0.17 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.10 ± 0.64 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030127172947-A (C?)	Unknown	-1.00	0.58	15.37	22.36	8.57	21.89
20030127173117-A2 (8)	Unknown	-1.00	0.58	15.37	8.81	6.55	21.89
20030127173227-A3 (11)	Unknown	-1.00	0.58	15.37	20.10	8.27	21.89
20030127173337-A4 (12)	Unknown	-1.00	0.58	15.37	2.03	5.25	21.89

Reviewed by:

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/29/03

Print Time 12:19:45PM

COPY



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: HOT SHOP/EXTENSION  
AREA/ROOM: TRUPACT FLOOR  
PLAN

RWP #: 31002496 02

LOG #: 1

DATE: 1/28/03

TIME: 7:20 0845

☐ ROUTINE **JOB DESCRIPTION**  
☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level

TPA-PACT-157 Recovery Project

RCT: F. Bush / F. Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
RA	800147	10 %
Ekern	501530	10 %
		%
Scaler		%βγ
		%α
R020	802084	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β Beta  
γ Gamma  
A-65 A-65

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

COPY

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.7 % $\beta\gamma$
		29.9 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	1000 NA	201 NA		
17			BOTTOM OF MID SLIP SHEET				
18			SIDES OF DRUMS 1, 6 + 7				
19			BOTTOM <sup>MID</sup> SLIP SHEET				
20			SIDES OF DRUMS 1, 2 + 7				
21			BOTTOM MID SLIP SHEET				
22			SIDES OF DRUMS 1 & 2				
23			BOTTOM OF MID SLIP SHEET				
24			SIDES OF DRUMS 2, 3 + 7				
25			BOTTOM OF MID SLIP SHEET				
26			SIDES OF DRUMS 2				
27			BOTTOM MID SLIP SHEET				
28			SIDE OF DRUMS 2 & 3				
28, 30			TOP OF DRUM #1				
			Smear Numbers correspond to numbers on LB5100 printout				
			See printout for data. F. Bush				

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step-Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  Beta  
 $\gamma$  Gamma  
n

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
☐ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: 607  
AREA/ROOM: Hot Shop  
RWP #: 31002496 02  
LOG #: 8  
DATE: 1/28/03  
TIME: 1730

☐ ROUTINE

## JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: TRU-Pact Recovery Project

Leakage man Smears

Report Batch #'s = 5310, 5311

RCT: McKinley

F. Bush T. Bush


REVIEWED BY: [Signature]

PRINT/SIGNATURE


TRUPACT

CASK # 157


SURVEY # N4 - 157 - 10



INSIDE INNER LID LEFT SIDE



INSIDE INNER LID RIGHT SIDE



SLIP COVER

TOP OF  
PAYLOAD  
INSIDE # ORW in  
CASK Number

- 1 Bottom of CASK
- 2 Side CASK
- 3 MID SLIP SHEET
- 4 Bottom of Drum #2
- 5 MID SLIP SHEET
- 6 Bottom of Drum #3
- 7 Bottom of CASK
- 8 Side of CASK
- 9 MID SLIP SHEET
- 10 Bottom of Drum #5
- 11 Bottom of CASK
- 12 Side of CASK

13+14 Bottom of CASK  
15 Side of Drum  
16+17



# Tan Smear Report

Batch ID: smear - 200301280918 Count Date: 1/28/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,310 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: Inside ICV and on Drums

All smears were Wholman SD

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128091841-A1	Unknown	3.01	3.36	12.70	10.61	6.94	22.27
20030128092011-A2	Unknown	6.35	4.74	12.70	15.13	7.64	22.27
20030128092121-A3	Unknown	3.01	3.36	12.70	12.87	7.29	22.27
20030128092231-A4	Unknown	-0.33	0.33	12.70	6.10	6.16	22.27
20030128092341-A5	Unknown	6.35	4.74	12.70	35.46	10.21	22.27
20030128092451-A6	Unknown	-0.33	0.33	12.70	30.94	9.70	22.27
20030128092612-A7	Unknown	6.35	4.74	12.70	69.33	13.44	22.27
20030128092722-A8	Unknown	-0.33	0.33	12.70	37.71	10.45	22.27
20030128092832-A9	Unknown	-0.33	0.33	12.70	49.01	11.61	22.27
20030128092942-A10	Unknown	-0.33	0.33	12.70	46.75	11.39	22.27
20030128093052-A11	Unknown	3.01	3.36	12.70	21.91	8.58	22.27
20030128093202-A12	Unknown	6.35	4.74	12.70	37.71	10.45	22.27
20030128093312-A13	Unknown	-0.33	0.33	12.70	28.68	9.43	22.27
20030128093422-A14	Unknown	-0.33	0.33	12.70	105.47	16.20	22.27
20030128093542-A15	Unknown	3.01	3.36	12.70	26.42	9.15	22.27
20030128093542-A15	Unknown	3.19	3.54	13.26	28.32	9.62	22.97
20030128093542-A15	Unknown	3.01	3.36	12.70	49.01	11.61	22.27
20030128093652-A16	Unknown	-0.33	0.33	13.50	46.14	11.74	23.27
20030128093802-A17	Unknown	3.01	3.36	12.70	53.52	12.04	22.27
20030128093912-A18	Unknown	-0.33	0.33	12.70	55.78	12.25	22.27

100



# Tan Smear Report

Background (cpm)      Efficiency (%)

Alpha Rate:      0.10 ± 0.10      Alpha:      29.90 ± 0.23

Beta Rate:      4.30 ± 0.66      Beta:      44.28 ± 0.07

*All smears were what was SD*

**COPY**

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128094022-A19	Unknown	3.01	3.36	12.70	12.87	7.29	22.27
20030128094132-A20	Unknown	-0.33	0.33	12.70	64.82	13.06	22.27
20030128094242-A21	Unknown	-0.33	0.33	12.70	87.40	14.88	22.27
20030128094402-A22	Unknown	-0.33	0.33	12.70	73.85	13.82	22.27
20030128094513-A23	Unknown	3.01	3.36	12.70	39.97	10.70	22.27
20030128094623-A24	Unknown	-0.33	0.33	12.70	73.85	13.82	22.27

Reviewed by:

*[Signature]*

REV 010814.SMH

Page 2 of 2

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date  
Print Time

1/28/03  
9:47:35AM



# Tan Smear Report


Batch ID: smear - 200301280953 Count Date: 1/28/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,311 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: Inside ICV and on Drums 1-6 cloth, 7-12 Whatman-6-10-04 All checked samples

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128095355-A1 (25)	Unknown	-0.33	0.33	12.70	19.65	8.28	22.27
20030128095525-A2 (26)	Unknown	3.01	3.36	12.70	6.10	6.16	22.27
20030128095635-A3 (27)	Unknown	3.01	3.36	12.70	15.13	7.64	22.27
20030128095745-A4 (28)	Unknown	-0.33	0.33	12.70	10.61	6.94	22.27
20030128095855-A5 (29)	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27
20030128100005-A6 (30)	Unknown	-0.33	0.33	12.70	30.94	9.70	22.27
20030128100125-A7	Unknown	3.01	3.36	12.70	82.88	14.54	22.27
20030128100236-A8	Unknown	-0.33	0.33	12.70	33.20	9.95	22.27
20030128100346-A9	Unknown	3.01	3.36	12.70	39.97	10.70	22.27
20030128100456-A10	Unknown	3.01	3.36	12.70	44.49	11.16	22.27
20030128100606-A11	Unknown	-0.33	0.33	12.70	8.36	6.56	22.27
20030128100716-A12	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27

Reviewed by: 

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date

Print Time

1/28/03

10:08:27AM



ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.7 %By
		29.9 %α

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x--x- Radiological Barrier**

**ALL dose rates are in mrem/hr, unless otherwise noted.**

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	Neutron

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⌒ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: 1007  
AREA/ROOM: HOT SHOP  
RWP #: 3100-2496-02  
LOG #: 8  
DATE: 1-28-03  
TIME: 1730

☐ ROUTINE

JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: TRUPACT Recovery Project  
(CLOTH SMEARS)  
Report Batch # 5311

RCT: L. McKinley

F. Bush

F. Bush

REVIEWED BY: V. J. R. R.

PRINT/SIGNATURE

TRUPACT

CASK # 157


SURVEY # NA - 157 - 3



INSIDE INNER LID LEFT SIDE



INSIDE INNER LID RIGHT SIDE



SLIP COVER

TOP OF  
PAYLOAD  
INSIDE  
CASK

# Drum Number



# Tan Smear Report

Batch ID: smear - 200301280953  
 Count Date: 1/28/03  
 Group: A  
 Count Minutes: 1.0  
 Device: LB5100 #324920  
 Count Mode: Simultaneous  
 Batch Key: 5,311  
 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel  
 Survey Location: Inside ICV and on Drums ~~1-6 cloth~~ <sup>1-6 cloth</sup> ~~7-12 Whittman~~

COPY

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128095355-A1	Unknown	-0.33	0.33	12.70	19.65	8.28	22.27
20030128095525-A2	Unknown	3.01	3.36	12.70	6.10	6.16	22.27
20030128095635-A3	Unknown	3.01	3.36	12.70	15.13	7.64	22.27
20030128095745-A4	Unknown	-0.33	0.33	12.70	10.61	6.94	22.27
20030128095855-A5	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27
20030128100005-A6	Unknown	-0.33	0.33	12.70	30.94	9.70	22.27
20030128100125-A7	Unknown	3.01	3.36	12.70	82.88	14.54	22.27
20030128100236-A8	Unknown	-0.33	0.33	12.70	33.20	9.95	22.27
20030128100346-A9	Unknown	3.01	3.36	12.70	39.97	10.70	22.27
20030128100456-A10	Unknown	3.01	3.36	12.70	44.49	11.16	22.27
20030128100606-A11	Unknown	-0.33	0.33	12.70	8.36	6.56	22.27
20030128100716-A12	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27

6-11  
1-18-03

Reviewed by:

*[Signature]*

10-11

441.45#  
10/10/97  
Rev. #03

## RADIOLOGICAL SURVEY REPORT

COPY

BARCODE #

BLDG.: TAN hot shop	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: Trupact Tent	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: 31002496	COMMENTS: General Area Dose Rate measured at waist level 9'-30" 1-28-03	
LOG #: 9	Pre-job survey of inside of tent	
DATE: 1/28/03	Report Batch # 5317	
TIME: 1305		

RCT: Jon Johnston  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
	324920	44.2 %
Scaler	See LB5100 Printout	1% $\beta\gamma$
		23.9% $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-15			See Map	See LB5100 Printout -			


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  A-79  
 $\beta$

☐ - Direct Scan  
☐ - Swipe (Smear)  
☐ - Large Area Wipe (LAW)  
 - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

Batch ID: smear - 200301281241  
 Count Date: 1/28/03  
 Group: A  
 Count Minutes: 1.0  
 Device: LB5100 #324920  
 Count Mode: Simultaneous  
 Batch Key: 5,317  
 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRU-PACT 157 RECOVERY-PRE-USE TENT SMEARS

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128124145-A1	Unknown	-0.33	0.33	12.70	146.12	18.82	22.27
20030128124316-A2	Unknown	-0.33	0.33	12.70	234.19	23.52	22.27
20030128124426-A3	Unknown	-0.33	0.33	12.70	130.31	17.85	22.27
20030128124536-A4	Unknown	3.01	3.36	12.70	85.14	14.71	22.27
20030128124646-A5	Unknown	-0.33	0.33	12.70	39.97	10.70	22.27
20030128124756-A6	Unknown	3.01	3.36	12.70	184.51	21.00	22.27
20030128124916-A7	Unknown	-0.33	0.33	12.70	134.82	18.13	22.27
20030128125026-A8	Unknown	-0.33	0.33	12.70	130.31	17.85	22.27
20030128125136-A9	Unknown	-0.33	0.33	12.70	184.51	21.00	22.27
20030128125246-A10	Unknown	3.01	3.36	12.70	60.30	12.66	22.27
20030128125356-A11	Unknown	-0.33	0.33	12.70	21.91	8.58	22.27
20030128125506-A12	Unknown	-0.33	0.33	12.70	51.27	11.83	22.27
20030128125616-A13	Unknown	3.01	3.36	12.70	30.94	9.70	22.27
20030128125726-A14	Unknown	-0.33	0.33	12.70	137.08	18.27	22.27
20030128125846-A15	Unknown	-0.33	0.33	12.70	30.94	9.70	22.27

Reviewed by:

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date  
Print Time

1/28/03  
12:59:59PM

COPY

2000



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: TAN Hot Shop	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: Trupact Tent	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: 31002496	COMMENTS: General Area Dose Rate measured at waist level 1-30" 1-30"	
LOG #: 9	Top of trupact tent after payload was placed in tent and tent was sealed up.	
DATE: 1-28-03	Report Batch # 5318	
TIME: 1359		

RCT: Jon Johnston  
PRINT/SIGNATURE

REVIEWED BY: S. J. L. L.

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
	724820	44.2 %
Scaler	See LB5100 Printout	%
		27.8 %

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				By	α	By	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-6			See Map	See LB5100 Printout			


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underspread Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α A-83  
β Gamma

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe





# Tan Smear Report


Batch ID: smear - 200301281349  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,318  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: OUTSIDE OF TRU-PACT 157 CONTAINMENT TENT

Count Date: 1/28/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Background (cpm)      Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10      Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66      Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
28134957-A1	Unknown	-0.33	0.33	12.70	1.58	5.26	22.27
28135127-A2	Unknown	-0.33	0.33	12.70	33.20	9.95	22.27
030128135238-A3	Unknown	-0.33	0.33	12.70	39.97	10.70	22.27
030128135348-A4	Unknown	-0.33	0.33	12.70	30.94	9.70	22.27
030128135458-A5	Unknown	-0.33	0.33	12.70	28.68	9.43	22.27
030128135608-A6	Unknown	-0.33	0.33	12.70	51.27	11.83	22.27

Reviewed by:



COPY

Pg. 2 of 2



COPY

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS			
Type	Serial #	Efficiency	
		%	
		%	
		%	
Scaler	324920	44.2	%By
		29.9	%α

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x-x- Radiological Barrier**

**ALL dose rates are in mrem/hr, unless otherwise noted.**

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	n

- - Direct Scan
- - Swipe (Smear)
- └ - Large Area Wipe (LAW)
- △ - Air Sample
- ⬆ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<u>JOB DESCRIPTION</u>
AREA/ROOM: <u>HOT SHOP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>310 2496 02</u>	COMMENTS: <u>Cask #157 Icv inside recovery</u>	
LOG #: <u>8</u>		
DATE: <u>1-28-03</u>	<u>Report Batch #3: 5319,</u>	
TIME: <u>1430</u>	<u>Alara Task # 29001689 0118</u>	


RCT: L. Bird  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## TRUPACT

Cask# 157

Survey NH-157-4



INSIDE OF ICV

# Tan Smear Report

Batch ID: smear - 200301281435 Count Date: 1/28/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,319 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: SMEARS TAKEN INSIDE TRU-PACT 157 ICV

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128143520-A1	Unknown	3.01	3.36	12.70	3.84	5.73	22.27
20030128143651-A2	Unknown	-0.33	0.33	12.70	17.39	7.96	22.27
20030128143801-A3	Unknown	-0.33	0.33	12.70	8.36	6.56	22.27
20030128143911-A4	Unknown	-0.33	0.33	12.70	-0.68	4.75	22.27
20030128144021-A5	Unknown	-0.33	0.33	12.70	37.71	10.45	22.27
20030128144131-A6	Unknown	-0.33	0.33	12.70	37.71	10.45	22.27
20030128144251-A7	Unknown	6.35	4.74	12.70	55.78	12.25	22.27
20030128144401-A8	Unknown	-0.33	0.33	12.70	33.20	9.95	22.27
20030128144511-A9	Unknown	-0.33	0.33	12.70	28.68	9.43	22.27
20030128144621-A10	Unknown	-0.33	0.33	12.70	37.71	10.45	22.27
20030128144731-A11	Unknown	-0.33	0.33	12.70	19.65	8.28	22.27
20030128144841-A12	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27
20030128144951-A13	Unknown	3.01	3.36	12.70	12.87	7.29	22.27
20030128145102-A14	Unknown	-0.33	0.33	12.70	134.82	18.13	22.27
20030128145222-A15	Unknown	-0.33	0.33	12.70	39.97	10.70	22.27
20030128145332-A16	Unknown	-0.33	0.33	12.70	33.20	9.95	22.27
20030128145442-A17	Unknown	3.01	3.36	12.70	53.52	12.04	22.27
20030128145552-A18	Unknown	-0.33	0.33	12.70	17.39	7.96	22.27
20030128145702-A19	Unknown	-0.33	0.33	12.70	24.16	8.87	22.27
20030128145812-A20	Unknown	3.01	3.36	12.70	44.49	11.16	22.27

COPY

2-10-77



# Tan Smear Report

Background (cpm)      Efficiency (%)

Alpha Rate:      0.10 ± 0.10      Alpha:      29.90 ± 0.23

Beta Rate:      4.30 ± 0.66      Beta:      44.28 ± 0.07

COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128145922-A21	Unknown	3.01	3.36	12.70	53.52	12.04	22.27
20030128150042-A22	Unknown	-0.33	0.33	12.70	62.56	12.86	22.27
20030128150152-A23	Unknown	-0.33	0.33	12.70	28.68	9.43	22.27
20030128150302-A24	Unknown	-0.33	0.33	12.70	46.75	11.39	22.27
20030128150412-A25	Unknown	-0.33	0.33	12.70	10.61	6.94	22.27
20030128150522-A26	Unknown	-0.33	0.33	12.70	30.94	9.70	22.27

Reviewed by:

*[Signature]*

REV 010814.SMH

Page 2 of 2

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date



Print Time

12/1/74





- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe



COPY

Tan Smear Report

ID: smear - 200301281438  
Count Date: 1/28/03  
Count Minutes: 1.0  
Count Mode: Simultaneous  
Operating Volts: 1320

LB5100 #324920  
Key: 5,320  
d Geometry: 1/4" Stainless Steel  
Location:

Background (cpm) Efficiency (%)  
Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
Unknown	3.01	3.36	12.70	46.75	11.39	22.27
Unknown	-0.33	0.33	12.70	37.71	10.45	22.27
Unknown	-0.33	0.33	12.70	39.97	10.70	22.27
Unknown	-0.33	0.33	12.70	49.01	11.61	22.27
Unknown	-0.33	0.33	12.70	6.10	6.16	22.27
Unknown	-0.33	0.33	12.70	10.61	6.94	22.27

*[Signature]*

red by:



COPY

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS			
Type	Serial #	Efficiency	
elec T	501534	1d	%β
			%
			%
Scaler	324920	44.25	%βγ
		29.9	%α

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x-x- Radiological Barrier**

**ALL dose rates are in mrem/hr, unless otherwise noted.**

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	

- - Direct Scan
- - Swipe (Smear)
- └ - Large Area Wipe (LAW)
- △ - Air Sample
- ⬮ - Tritium Swipe

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: 607  
AREA/ROOM: Hot Shop  
RWP #: 3100 7496 02  
LOG #: 15  
DATE: 1-28-03  
TIME: 1630

☐ ROUTINE JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: Removal of I.C.V. CASK # 157


Report Batch # 5326

Area Task # 2900 1679 0117

RCT: L. B. Red / L. H. N. / L. A. S. / L. H. N. / L. A. S.  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

TRUPACT CONTAINER I.C.V.



# Tan Smear Report

Batch ID: smear - 200301281743  
 Count Date: 1/28/03  
 Group: A  
 Count Minutes: 1.0  
 Device: LB5100 #324920  
 Count Mode: Simultaneous  
 Batch Key: 5,326  
 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: OUTSIDE OF ICV AFTER PAYLOAD REMOVED

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128174359-A (1)	Unknown	3.01	3.36	12.70	3.84	5.73	22.27
20030128174530-A2 (2)	Unknown	3.01	3.36	12.70	3.84	5.73	22.27
20030128174640-A3 (3)	Unknown	-0.33	0.33	12.70	12.87	7.29	22.27
20030128174750-A4 (4)	Unknown	-0.33	0.33	50.77	1.04	10.86	63.07
20030128174750-A4 (5)	Unknown	-0.33	0.33	12.70	6.10	6.16	22.27
20030128174750-A4 (6)	Unknown	-0.33	0.33	14.29	8.46	7.03	24.25
20030128174900-A5 (7)	Unknown	-0.33	0.33	12.70	24.16	8.87	22.27
20030128175010-A6 (8)	Unknown	-0.33	0.33	12.70	44.49	11.16	22.27
20030128175130-A7 (9)	Unknown	-0.33	0.33	12.70	53.52	12.04	22.27
20030128175240-A8 (10)	Unknown	3.01	3.36	12.70	46.75	11.39	22.27
20030128175350-A9 (11)	Unknown	-0.33	0.33	12.70	28.68	9.43	22.27
20030128175500-A10 (12)	Unknown	3.01	3.36	12.70	28.68	9.43	22.27

Reviewed by:

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/28/03  
 Print Time 5:56:12PM

12/14





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

COPY

BARCODE #

BLDG.: <u>HOT SHOP/EXTENSION</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>TRUPACT FLOOR PLAN</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002496 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level 6.6 1-31-03</u>	
LOG #: <u>16</u>	<u>TRU DACT Recovery</u>	
DATE: <u>1/28/03</u>	<u>Report Batch # 5322</u>	
TIME: <u>1630</u>		

RCT: F. Bush / F. Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
177-L	801973	10 %
177-L	802224	10 %
		%
Scaler	324920	44.3 %βγ
		29.9 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
			See printout and map.				



CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ A-101 detected / Gamma Dose Rates  
α

☐ - Direct Scan  
○ - Swipe (Smear)  
└ - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



# Tan Smear Report

Batch ID: smear - 200301281616 Count Date: 1/28/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,322 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: RELEASE OF EXTENDED RBA FOR CAT. A CLOTHING

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128161659-A1	Unknown	-0.33	0.33	12.70	10.61	6.94	22.27
20030128161830-A2	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27
20030128161940-A3	Unknown	-0.33	0.33	12.70	19.65	8.28	22.27
20030128162050-A4	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27
20030128162200-A5	Unknown	-0.33	0.33	12.70	33.20	9.95	22.27
20030128162310-A6	Unknown	-0.33	0.33	12.70	46.75	11.39	22.27
20030128162430-A7	Unknown	-0.33	0.33	12.70	78.37	14.18	22.27
20030128162540-A8	Unknown	-0.33	0.33	12.70	21.91	8.58	22.27
20030128162650-A9	Unknown	-0.33	0.33	12.70	39.97	10.70	22.27
20030128162800-A10	Unknown	-0.33	0.33	12.70	42.23	10.93	22.27
20030128162910-A11	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27
20030128163020-A12	Unknown	-0.33	0.33	12.70	21.91	8.58	22.27

Reviewed by:

*[Signature]*

REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/28/03  
 Print Time 4:31:32PM

11/11/11



COPY

INSTRUMENTS		
Type	Serial #	Efficiency
2/CLT	801534	10 %
		%
		%
Scaler.	324920	44.25% By
		29.9 %α

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #



BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<u>JOB DESCRIPTION</u>
AREA/ROOM: <u>HOTSHOP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 2496 02</u>	COMMENTS: <u>CASK #157 recovery</u>	
LOG #: <u>15</u>	<u>Report Batch # 5324</u>	
DATE: <u>1-28-03</u>		
TIME: <u>1630</u>	<u>Huron P75K &amp; 29 CO 16Y9 0117</u>	

RCT: Fujid / L. McKinlay PRINT/SIGNATURE  
REVIEWED BY: [Signature]

## TRUPACT

Cask# 157

Survey, 1A -157 -



INSIDE OF ICV

# Tan Smear Report

**Batch ID:** smear - 200301281709 **Count Date:** 1/28/03  
**Group:** B **Count Minutes:** 1.0  
**Device:** LB5100 #324920 **Count Mode:** Simultaneous  
**Batch Key:** 5,324 **Operating Volts:** 1320

**Selected Geometry:** 1/4" Stainless Steel

**Survey Location:** TRUPACT 157 RECOVERY- INSIDE ICV AFTER PAYLOAD REMOVED

**Background (cpm)**      **Efficiency (%)**  
 Alpha Rate: 0.10 ± 0.10      Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66      Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128170949-B7 (1)	Unknown	3.01	3.36	12.70	62.56	12.86	22.27
20030128171129-B8 (2)	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27
20030128171240-B9 (3)	Unknown	-0.33	0.33	12.70	39.97	10.70	22.27
20030128171400-B10 (4)	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27
20030128171510-B11 (5)	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27

Reviewed by:



REV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date 1/28/03

Print Time 5:16:21PM

11/11







441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: 607  
AREA/ROOM: HOT SHED  
RWP #: 3100 2496 02  
LOG #: 15  
DATE: 1-28-03  
TIME: 1700

☐ ROUTINE

JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: Cask #157 recovery lid's  
Report Batch #'s = 5325, 5327

Alarm mask # 2900 1680 01 17

RCT:

L. B. ...  
Print/Signature


REVIEWED BY:

J. ...


## TRUPACT

Cask# 157


Survey NA-157




INSIDE OUTER LID RIGHT SIDE



INSIDE OUTER LID LEFT SIDE



INNER LID RIGHT SIDE  
Bottom of Lid



INNER LID LEFT SIDE

# Tan Smear Report

Count Date: 1/28/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Batch ID: smear - 200301281749  
 Group: B  
 Device: LB5100 #324920  
 Batch Key: 5,327  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: OCV LID

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128174955-B11(1)	Unknown	-0.33	0.33	12.70	8.36	6.56	22.27
20030128175726-B12(2)	Unknown	9.70	5.80	12.70	39.97	10.70	22.27
20030128175836-B13(3)	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27
20030128175946-B14(4)	Unknown	-0.33	0.33	243.70	272.59	126.26	229.97
20030128175946-B14(5)	Unknown	3.01	3.36	12.70	130.31	17.85	22.27
20030128175946-B14(6)	Unknown	-0.33	0.33	21.62	124.12	23.71	32.84
20030128180056-B15(7)	Unknown	-0.33	0.33	12.70	37.71	10.45	22.27

Reviewed by:

*DR2*

44



# Tan Smear Report

**Batch ID:** smear - 200301281709 **Count Date:** 1/28/03  
**Group:** C **Count Minutes:** 1.0  
**Device:** LB5100 #324920 **Count Mode:** Simultaneous  
**Batch Key:** 5,325 **Operating Volts:** 1320  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** TRUPACT 157- INSIDE ICV LID AFTER PAYLOAD REMOVED

**Background (cpm)** **Efficiency (%)**  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128171002-C12(8)	Unknown	-0.33	0.33	12.70	26.42	9.15	22.27
20030128171733-C13(7)	Unknown	-0.33	0.33	12.70	3.84	5.73	22.27
20030128171843-C14(10)	Unknown	3.01	3.36	12.70	103.21	16.04	22.27
20030128171953-C15(11)	Unknown	-0.33	0.33	12.70	15.13	7.64	22.27

Reviewed by:

*[Signature]*

COPY

100-100



COPY

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
<i>elect</i>	<i>201534</i>	<i>10 %</i>
		%
		%
Scaler	<i>324920</i>	<i>44.28 %</i> By
		<i>29.9 %</i> α

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x-x- Radiological Barrier**

ALL dose rates are in mrem/hr, unless otherwise noted.

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	A-115

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>HOT SHOP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100249602</u>	COMMENTS: <u>CASK #157 recovery</u>	
LOG #: <u>15</u>	<u>Batch Report # 5323</u>	
DATE: <u>1-28-03</u>		
TIME: <u>1730</u>	<u>Alarm TASK # 29001689 0117</u>	



RCT: L. J. Smith / L. McKinlay  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## TRUPACT

Cask# 157

Survey NA-157-



INSIDE OF OCA



# Tan Smear Report

Batch ID: smear - 200301281658 Count Date: 1/28/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,323 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157- INSIDE OF OCA

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030128165820-A1	Unknown	-0.33	0.33	12.70	8.36	6.56	22.27
20030128165950-A2	Unknown	-0.33	0.33	12.70	6.10	6.16	22.27
20030128170100-A3	Unknown	-0.33	0.33	12.70	12.87	7.29	22.27
20030128170210-A4	Unknown	-0.33	0.33	12.70	-0.68	4.75	22.27
20030128170320-A5	Unknown	-0.33	0.33	12.70	21.91	8.58	22.27
20030128170430-A6	Unknown	-0.33	0.33	12.70	51.27	11.83	22.27

Reviewed by:

RFV 010814.SMH

Page 1 of 1

C:\Program Files\Tennelec Systems\Eclipse\smear report dpm.rpt

Print Date  
Print Time

1/29/03  
7:09:49AM

COPY

100



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: HOT SHOP/EXTENSION  
AREA/ROOM: TRUPACT FLOOR  
PLAN  
RWP #: 31002496  
LOG #: 2  
DATE: 1-29-03  
TIME: 0750

☐ ROUTINE **JOB DESCRIPTION**  
☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level  
To Release Area from CA to RBA.

RCT: Jon Johnston  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

### INSTRUMENTS

Type	Serial #	Efficiency
177-L	801973	10 %
		%
		%
Scaler	225615	40 % $\beta\gamma$
		24 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		



CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Dose Rate  
# $\beta$  / # $\gamma$  A-119 Detected / Gamma Dose Rates  
 $\alpha$  Alpha

☐ - Direct Scan  
○ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
⏏ - Tritium Swipe



**COPY**

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324820	44.2 %By
		28.9 %a

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x-x- Radiological Barrier**

ALL dose rates are in mrem/hr, unless otherwise noted.

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	A-121

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT


BARCODE #

BLDG.: <u>TAN 607</u>	<input type="checkbox"/> ROUTINE	JOB DESCRIPTION
AREA/ROOM: <u>HOT Shop Ext'n 7/25/03</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31005496 02</u>	COMMENTS: <u>TRUPACT 157 Recovery Project. Similar</u>	
LOG #: <u>4</u>	<u>Survey to release from Hot Shop with payload</u>	
DATE: <u>1/29/03</u>	<u>Removed.</u>	
TIME: <u>1245</u>	<u>Report Beta # 5331</u>	

RCT: F. Bush / 7 Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## TRUPACT CONTAINER (OCA)



# Tan Smear Report

Batch ID: smear - 200301291031 Count Date: 1/29/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,331 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157 RECOVERY, UPPER PORTION OF CASK AS IT LEFT HOT SHOP

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.00 ± 0.00 Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66 Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030129103157-A1	Unknown	0.00	0.00	9.05	10.61	6.94	22.27
20030129103328-A2	Unknown	0.00	0.00	9.05	6.10	6.16	22.27
20030129103438-A3	Unknown	0.00	0.00	9.05	1.58	5.26	22.27
20030129103548-A4	Unknown	0.00	0.00	9.05	-5.19	3.52	22.27
20030129103658-A5	Unknown	0.00	0.00	9.05	24.16	8.87	22.27
20030129103808-A6	Unknown	0.00	0.00	9.05	44.49	11.16	22.27
20030129103928-A7	Unknown	3.34	3.34	9.05	73.85	13.82	22.27
20030129104038-A8	Unknown	0.00	0.00	9.05	37.71	10.45	22.27
20030129104148-A9	Unknown	0.00	0.00	9.05	10.61	6.94	22.27
20030129104258-A10	Unknown	3.34	3.34	9.05	42.23	10.93	22.27
20030129104408-A11	Unknown	0.00	0.00	9.05	30.94	9.70	22.27
20030129104518-A12	Unknown	0.00	0.00	9.05	30.94	9.70	22.27
20030129104628-A13	Unknown	0.00	0.00	9.05	8.36	6.56	22.27
20030129104739-A14	Unknown	0.00	0.00	9.05	121.27	17.26	22.27
20030129104859-A15	Unknown	0.00	0.00	9.05	17.39	7.96	22.27
20030129105009-A16	Unknown	0.00	0.00	9.05	35.46	10.21	22.27
20030129105119-A17	Unknown	0.00	0.00	9.05	44.49	11.16	22.27
20030129105229-A18	Unknown	0.00	0.00	9.05	26.42	9.15	22.27
20030129105339-A19	Unknown	0.00	0.00	9.05	26.42	9.15	22.27

COPY





# Tan Smear Report

**Batch ID:** smear - 200301291035 **Count Date:** 1/29/03  
**Group:** B **Count Minutes:** 1.0  
**Device:** LB5100 #324920 **Count Mode:** Simultaneous  
**Batch Key:** 5,332 **Operating Volts:** 1320  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** TRUPACT 157 RECOVERY-LOWER PORTION OF CASK AS IT LEFT THE HOT SHOP

**Background (cpm)**      **Efficiency (%)**  
 Alpha Rate: 0.00 ± 0.00      Alpha: 29.90 ± 0.23  
 Beta Rate: 4.30 ± 0.66      Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030129103553-B21	Unknown	0.00	0.00	9.05	35.46	10.21	22.27
20030129105604-B22	Unknown	0.00	0.00	9.05	71.59	13.63	22.27
20030129105714-B23	Unknown	0.00	0.00	9.05	19.65	8.28	22.27
20030129105824-B24	Unknown	0.00	0.00	9.05	53.52	12.04	22.27
20030129105944-B25	Unknown	3.34	3.34	9.05	6.10	6.16	22.27
20030129110054-B26	Unknown	0.00	0.00	9.05	39.97	10.70	22.27
20030129110204-B27	Unknown	0.00	0.00	9.05	39.97	10.70	22.27
20030129110314-B28	Unknown	0.00	0.00	9.05	30.94	9.70	22.27
20030129110425-B29	Unknown	0.00	0.00	9.05	51.27	11.83	22.27
20030129110535-B30	Unknown	0.00	0.00	9.05	44.49	11.16	22.27
20030129110645-B31	Unknown	0.00	0.00	9.05	-7.45	2.70	22.27
20030129110755-B32	Unknown	0.00	0.00	9.05	17.39	7.96	22.27
20030129110915-B33	Unknown	6.69	4.73	9.05	33.20	9.95	22.27
20030129111025-B34	Unknown	0.00	0.00	9.05	33.20	9.95	22.27
20030129111135-B35	Unknown	6.69	4.73	9.05	1.58	5.26	22.27
20030129111245-B36	Unknown	0.00	0.00	9.05	30.94	9.70	22.27
20030129111355-B37	Unknown	0.00	0.00	9.05	37.71	10.45	22.27
20030129111505-B38	Unknown	0.00	0.00	9.05	3.84	5.73	22.27
20030129111615-B39	Unknown	0.00	0.00	9.05	21.91	8.58	22.27
20030129111735-B40	Unknown	0.00	0.00	9.05	10.61	6.94	22.27

COPY

100



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

Barcode #

BLDG.: TAN Hot Shop  
AREA/ROOM: Tru pack Tent  
RWP #: 310D 2510 02  
LOG #: 10  
DATE: 1-29-03  
TIME: 1630

☐ ROUTINE

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level

Surveys taken during payload disassembly  
Report Batch # 5337

RCT: J. Ely / J. Uly / L. Wick / L. McKinney  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

Jon Johnston [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	344948 See LB 5100	44.25 % Attachment 2
		29.90 % $\alpha$
RD-20	801780	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB 5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step-Off Pad




-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  Beta  
 $\gamma$  Gamma  
n A-127  
Location

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
☐ - Tritium Swipe

Drum # 1



Bottom

# Tan Smear Report

Pg 2 of 2

Batch ID: smear - 200301291806

Group: A

Device: LB5100 #324920

Batch Key: 5,337

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157. DRUM POSITION #1. #11 & #12 ARE CLOTH SMEARS ON BOTTOM OF DRUM

Count Date: 1/29/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

## Background (cpm)

Alpha Rate: 0.00 ± 0.00  
Beta Rate: 4.30 ± 0.66

## Efficiency (%)

Alpha: 29.90 ± 0.23  
Beta: 44.28 ± 0.07

COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030129180638-A1	Unknown	3.34	3.34	9.05	15.13	7.64	22.27
20030129180808-A2	Unknown	3.34	3.34	9.05	33.20	9.95	22.27
20030129180918-A3	Unknown	10.03	5.79	9.05	8.36	6.56	22.27
20030129181028-A4	Unknown	6.69	4.73	9.05	-0.68	4.75	22.27
20030129181138-A5	Unknown	0.00	0.00	9.05	28.68	9.43	22.27
20030129181248-A6	Unknown	13.38	6.69	9.05	44.49	11.16	22.27
20030129181408-A7	Unknown	0.00	0.00	9.05	69.33	13.44	22.27
20030129181519-A8	Unknown	3.34	3.34	9.05	33.20	9.95	22.27
20030129181629-A9	Unknown	0.00	0.00	9.05	26.42	9.15	22.27
20030129181739-A10	Unknown	3.34	3.34	9.05	24.16	8.87	22.27
20030129181849-A11	Unknown	0.00	0.00	9.05	69.33	13.44	22.27
20030129181959-A12	Unknown	0.00	0.00	9.05	116.76	16.97	22.27

Reviewed by:

*[Signature]*



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

Barcode #

Pg 1 of 2

BLDG.: <u>TAN Hot Shop</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Impact Tent</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002510 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>10</u>	<u>Survey taken during payload assembly/disassembly</u>	
DATE: <u>1-29-03</u>	<u>Report Batch # 5332</u>	
TIME: <u>1630</u>		

RCT: J.E.N. / J. E. N. / J. E. N. / J. E. N.  
PRINT/SIGNATURE

REVIEWED BY: J. E. N.

Jon Johnston

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	329820 801530	44.23 % By attachment
		29.98 %
KD-20	801780	
electra	801530	1020

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				By	α	By	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area

-x-x- Radiological Barrier


ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α A-131  
β

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe


Drum # 2

5.0




5.0

5.0



5.0



Bottom



# Tan Smear Report

Pg 2 of 2

Batch ID:	smear - 200301291621	Count Date:	1/29/03
Group:	A	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,333	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	TRUPACT 157- DRUM #2 SMEARS. 11 & 12 ARE CLOTH SMEARS ON DRUM BOTTOM		

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.00 ± 0.00	Alpha:	29.90 ± 0.23
Beta Rate:	4.30 ± 0.66	Beta:	44.28 ± 0.07

**COPY**

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030129162139-A1	Unknown	0.00	0.00	9.05	103.21	16.04	22.27
20030129162309-A2	Unknown	0.00	0.00	9.05	6.10	6.16	22.27
20030129162419-A3	Unknown	0.00	0.00	9.05	15.13	7.64	22.27
20030129162529-A4	Unknown	3.34	3.34	9.05	1.58	5.26	22.27
20030129162639-A5	Unknown	0.00	0.00	9.05	21.91	8.58	22.27
20030129162749-A6	Unknown	0.00	0.00	9.05	28.68	9.43	22.27
20030129162909-A7	Unknown	0.00	0.00	9.05	73.85	13.82	22.27
20030129163019-A8	Unknown	0.00	0.00	9.05	21.91	8.58	22.27
20030129163129-A9	Unknown	3.34	3.34	9.05	24.16	8.87	22.27
20030129163240-A10	Unknown	3.34	3.34	9.05	26.42	9.15	22.27
20030129163350-A11	Unknown	3.34	3.34	9.05	100.95	15.88	22.27
20030129163500-A12	Unknown	10.03	5.79	9.05	94.17	15.39	22.27

Reviewed by:

*[Signature]*



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

Pg 1 of 2

BARCODE #

BLDG.: <u>TAN Hot Shop</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Impact Tent</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002510 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>10</u>	<u>Surveys taken during payload disassembly</u>	
DATE: <u>1-29-03</u>	<u>Report Batch # 15335</u>	
TIME: <u>1630</u>		

RCT: J. Ely / J. Ely PRINT/SIGNATURE

REVIEWED BY: J. Ely

Jon Johnston

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
Electron	801930	10 %
		%
Scaler	324820	44.28 %
	801780	29.90 %
KO-20	801780	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area




-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α A-135  
β

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe

Drum # 3



# Tan Smear Report

Pg 2 of 2

Batch ID: smear - 200301291704

Count Date: 1/29/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,335

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157. DRUM POSITION #3

## Background (cpm)

Alpha Rate: 0.00 ± 0.00  
Beta Rate: 4.30 ± 0.66

## Efficiency (%)

Alpha: 29.90 ± 0.23  
Beta: 44.28 ± 0.07

**COPY**

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030129170434-A1	Unknown	0.00	0.00	9.05	39.97	10.70	22.27
20030129170604-A2	Unknown	6.69	4.73	9.05	12.87	7.29	22.27
20030129170714-A3	Unknown	0.00	0.00	9.05	8.36	6.56	22.27
20030129170824-A4	Unknown	0.00	0.00	9.05	19.65	8.28	22.27
20030129170934-A5	Unknown	3.34	3.34	9.05	12.87	7.29	22.27
20030129171045-A6	Unknown	3.34	3.34	9.05	33.20	9.95	22.27
20030129171155-A7	Unknown	0.00	0.00	9.05	96.43	15.55	22.27
20030129171315-A8	Unknown	3.34	3.34	9.05	37.71	10.45	22.27
20030129171425-A9	Unknown	0.00	0.00	9.05	28.68	9.43	22.27
20030129171535-A10	Unknown	0.00	0.00	9.05	26.42	9.15	22.27
20030129171645-A11	Unknown	3.34	3.34	9.05	191.28	21.36	22.27
20030129171755-A12	Unknown	3.34	3.34	9.05	121.27	17.26	22.27

Reviewed by: 

200



# RADIOLOGICAL SURVEY REPORT

# COPY

Pg 1 of 2

BARCODE #

BLDG.: <u>TAN Hot Shop</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Impact Tent</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 2510 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>10</u>	<u>Survey taken during payload disassembly</u>	
DATE: <u>1-29-03</u>	<u>Report Batch # 5336</u>	
TIME: <u>1630</u>		

RCT: J. Fly / J. Fly / J. Fly / J. Fly  
PRINT/SIGNATURE

REVIEWED BY: J. Fly

Jon Johnston / [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324820	44.28 %
	See LB 5100	Attachment
		29.90 %
RD-20	801780	
electra	801430	


SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				By	α	By	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB 5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand-Off Pad


-x-x- Radiological Barrier  
ALL dose rates are in mrem/hr, unless otherwise noted.  
# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β B  
γ A-139  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe


Drum # 4



5.0



6.0



Bottom



# Tan Smear Report

Pg 2 of 2

Batch ID:	smear - 200301291735	Count Date:	1/29/03
Group:	A	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,336	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	TRUPACT 157. DRUM POSITION #4. SMEARS 11 & 12 ARE CLOTH SMEARS ON DRUM BOTTOM		

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.00 ± 0.00	Alpha:	29.90 ± 0.23
Beta Rate:	4.30 ± 0.66	Beta:	44.28 ± 0.07

**COPY**

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030129173511-A1	Unknown	3.34	3.34	9.05	8.36	6.56	22.27
20030129173641-A2	Unknown	0.00	0.00	9.05	6.10	6.16	22.27
20030129173751-A3	Unknown	0.00	0.00	9.05	24.16	8.87	22.27
20030129173902-A4	Unknown	0.00	0.00	9.05	1.58	5.26	22.27
20030129174012-A5	Unknown	6.69	4.73	9.05	19.65	8.28	22.27
20030129174122-A6	Unknown	0.00	0.00	9.05	21.91	8.58	22.27
20030129174242-A7	Unknown	0.00	0.00	9.05	62.56	12.86	22.27
20030129174352-A8	Unknown	3.34	3.34	9.05	39.97	10.70	22.27
20030129174502-A9	Unknown	3.34	3.34	9.05	60.30	12.66	22.27
20030129174612-A10	Unknown	3.34	3.34	9.05	24.16	8.87	22.27
20030129174722-A11	Unknown	0.00	0.00	9.05	73.85	13.82	22.27
20030129174832-A12	Unknown	0.00	0.00	9.05	182.25	20.88	22.27

Reviewed by: \_\_\_\_\_

*[Signature]*




# COPY

441.45#  
10/10/97  
Rev. #03

## RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: <u>TAN 607 Hot Shop</u> AREA/ROOM: <u>TRUPACT Tent</u> RWP #: <u>3/00 2510 02</u> LOG #: <u>10</u> DATE: <u>1/31/03</u> TIME: <u>1430 - 1800</u>	<input type="checkbox"/> ROUTINE <input checked="" type="checkbox"/> NON ROUTINE (SPECIFY) <input type="checkbox"/> FOLLOW UP JOB DESCRIPTION COMMENTS: <u>General Area Dose Rate measured at waist level</u> <u>Special contamination survey taken during and after disassembly</u> <u>disassembly phase of TRUPACT drums</u>
--	---

RCT: Jon Johnston   
 PRINT/SIGNATURE

REVIEWED BY: 

### SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
 LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
 WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
 MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.


INSTRUMENTS		
Type	Serial #	Efficiency
ZA	800147	10 %
		%
		%
Scaler	225015	40 %βγ
		24 %α
Electra	801530	10 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
	L1-L6					<1000	<20

CA Contamination Area  
 HCA High Contamination Area  
 RA Radiation Area  
 HRA High Radiation Area  
 VHRA Very High Radiation Area  
 RMA Radioactive Material Area  
 ARA Airborne Radioactivity Area  
 RBA Radiological Buffer Area  
 FCA Fixed Contamination Area  
 SCA Soil Contamination Area  
 IIRMA Underground Radioactive Material Area

-x-x- Radiological Barrier  
 ALL dose rates are in mrem/hr, unless otherwise noted.  
 # General Area Dose Rate  
 #@#(cm) Dose Rate at Distance From Source  
 \*# Contact Dose Rate  
 #β / #γ Beta Corrected / Gamma Dose Rates  
 α A  
 β B A-143  
 γ Gamma

☐ - Direct Scan  
 - Swipe (Smear)  
 L - Large Area Wipe (LAW)  
 Δ - Air Sample  
☐ - Tritium Swipe



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT COPY

BARCODE #

BLDG.: TAN 607 Hot Shop	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: Trupact tent	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: 31002510	COMMENTS: General Area Dose Rate measured at waist level	
LOG #: 10	Smear survey to verify levels outside work area of trupact tent for RWP #	
DATE: 1/29/03	31002510, Dose rates are General Area Working Fields with	
TIME: 1830	No Drums on tent. Report BcRAC # 5338	

RCT: Jon Johnston/

PRINT/SIGNATURE

REVIEWED BY:

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
	324920	44.2%
Scaler	See LB 5100 Printout	24.9% $\alpha$
RO-20	801780	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  A-145  
 $\beta$

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

pg. 2 of 2

Batch ID: smear - 200301291827

Count Date: 1/29/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,338

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: 2 SMEARS AFTER EACH DRUM MOVEMENT TO VARIFY RWP CONDITIONS

**COPY**

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.00	± 0.00	Alpha:	29.90	± 0.23
Beta Rate:	4.30	± 0.66	Beta:	44.28	± 0.07

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030129182754-A1	Unknown	0.00	0.00	9.05	12.87	7.29	22.27
20030129182924-A2	Unknown	6.69	4.73	9.05	15.13	7.64	22.27
20030129183034-A3	Unknown	0.00	0.00	9.05	231.93	23.41	22.27
20030129183144-A4	Unknown	6.69	4.73	9.05	195.80	21.60	22.27
20030129183254-A5	Unknown	0.00	0.00	9.05	60.30	12.66	22.27
20030129183404-A6	Unknown	0.00	0.00	9.05	170.96	20.26	22.27

Reviewed by:

*[Signature]*

A-147

of 1





# COPY



Christophe P Oertel

01/30/03 04:50 PM

To: Gary L Lusk/GLL2/CC01/INEEL/US@INEL, D J Sorensen/DSOR/CC01/INEEL/US@INEL  
cc: Leah Street, Dennis McBride

Fax to:  
Subject:

Gary/Rick

Attached is the data we took today on the cask packing plastic. We took several gamma scans of the area background, bagged plastic, and the plastic material alone. The spreadsheet shows the photos of the measurement configurations. The data in the spreadsheet shows that the plastic material had no surface contamination at above background levels for any isotopes other than possibly Cs-137. No statistically significant amounts of Am-241 or Co-60 were noted. The counts per second data were all extremely low and had high uncertainties. If you need further reconciliation regarding Am-241, I recommend a very long gamma count at RML or radiochemistry analysis. Please call if you have further questions.

Chris Oertel 6-3541 521-0076  
K.C. Thompson 6-2259 520-6401  
Mike Evans 6-3541, 6-5247



TAN CASK PLASTIC.xl



TAN CASK PLASTIC


1.30.2003

NTYPE HPGE

70% ALL COUNTS 600 SEC LTIME

OERTEL, THOMPSON, EVANS

ID	ISOTOPE	CPS	PHOTO
BACKGD	Cs-137	27.4	
	Co-60	0.3	
	Am-241	0.01	
PLASTIC1 BAG	Cs-137	43.2	1
	Co-60	0.03	
	Am-241	0.05	
PLASTIC2 BAG	Cs-137	34.7	1
	Co-60	0.02	
	Am-241	0.09	
PLASTIC WRAP	Cs-137	23.1	2
	Co-60	0.02	
	Am-241	0.003	
AT 12"	Cs-137	18.8	
	Co-60	0.01	
	Am-241	0.02	



2 PHOTO1: HpGe detector counting bagged plastic wrap




PHOTO 2: HpGe detector counting laid out plastic wrap

1 2 3 4 5 6 7 8 9 10 11 12



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>TAN 607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Hot Shop</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 2510 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>4</u>	<u>Surveys taken during payload disassembly</u>	
DATE: <u>1/30/03</u>	<u>Report Batch # 53143</u>	
TIME: <u>1300</u>		

RCT: F. Bush / F. Bush / Backus / J. J. J. REVIEWED BY: [Signature]  
PRINT/SIGNATURE

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		29.90 % $\alpha$
KO-20	802084	
Electra	801530	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LBS100 attachment for survey results				

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SCB Surface Contamination Barrier



-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.


# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  A-153  
 $\gamma$  Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
 - Tritium Swipe

Drum # 7



510 @ Containment wall



Bottom

# Tan Smear Report

Batch ID: smear - 200301300942

Group: A

Device: LB5100 #324920

Batch Key: 5,343

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157, DRUM #7, SMEARS 11 & 12 ARE CLOTH SMEARS ON THE BOTTOM OF DRUM.

Count Date: 1/30/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

## Background (cpm)

Alpha Rate: 0.20 ± 0.14

Beta Rate: 5.50 ± 0.74

## Efficiency (%)

Alpha: 29.90 ± 0.23

Beta: 44.28 ± 0.07

**COPY**

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030130094206-A1	Unknown	-0.67	0.47	14.21	3.39	6.21	24.39
20030130094336-A2	Unknown	2.68	3.38	14.21	14.68	8.00	24.39
20030130094446-A3	Unknown	6.02	4.75	14.21	12.42	7.68	24.39
20030130094556-A4	Unknown	-0.67	0.47	14.21	7.90	6.98	24.39
20030130094706-A5	Unknown	-0.67	0.47	14.21	32.75	10.24	24.39
20030130094816-A6	Unknown	6.02	4.75	14.21	50.81	12.07	24.39
20030130094936-A7	Unknown	2.68	3.38	14.21	59.85	12.88	24.39
20030130095046-A8	Unknown	2.68	3.38	14.21	32.75	10.24	24.39
20030130095156-A9	Unknown	6.02	4.75	14.21	19.20	8.61	24.39
20030130095307-A10	Unknown	2.68	3.38	14.21	16.94	8.31	24.39
20030130095417-A11	Unknown	-0.67	0.47	14.21	80.17	14.56	24.39
20030130095527-A12	Unknown	6.02	4.75	14.21	71.14	13.84	24.39

Reviewed by: 





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>TAN 607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>HOT SHOP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002510 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>4</u>	<u>Surveys taken during payload disassembly</u>	
DATE: <u>1/30/03</u>	<u>Report Batch # 5342</u>	
TIME: <u>1300</u>		

RCT: F. Bush / J. Bush / Jackson / R. Johnson PRINT/SIGNATURE REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		29.90 % $\alpha$
R20C	800084	
Electra	801530	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB 5100 attachment for survey results				
	1					<10000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area



-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.


# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  /  $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  A-157  
 $\gamma$  C

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
 - Tritium Swipe

Drum # 5



5.0 @ Containment wall



Bottom

# Tan Smear Report

Batch ID: smear - 200301300908	Count Date: 1/30/03
Group: A	Count Minutes: 1.0
Device: LB5100 #324920	Count Mode: Simultaneous
Batch Key: 5,342	Operating Volts: 1320
Selected Geometry: 1/4" Stainless Steel	
Survey Location: TRUPACT 157, DRUM # 5, SMEAR 11 & 12 ARE CLOTH SMEARS TAKEN ON BOTTOM OF DRUM.	

Background (cpm)	Efficiency (%)
Alpha Rate: 0.20 ± 0.14	Alpha: 29.90 ± 0.23
Beta Rate: 5.50 ± 0.74	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030130090904-A1	Unknown	-0.67	0.47	14.21	7.90	6.98	24.39
20030130091035-A2	Unknown	2.68	3.38	14.21	12.42	7.68	24.39
20030130091145-A3	Unknown	2.68	3.38	14.21	14.68	8.00	24.39
20030130091255-A4	Unknown	-0.67	0.47	14.21	10.16	7.34	24.39
20030130091405-A5	Unknown	-0.67	0.47	14.21	19.20	8.61	24.39
20030130091515-A6	Unknown	2.68	3.38	14.21	46.30	11.64	24.39
20030130091635-A7	Unknown	2.68	3.38	14.21	75.66	14.20	24.39
20030130091745-A8	Unknown	2.68	3.38	14.21	14.68	8.00	24.39
20030130091855-A9	Unknown	2.68	3.38	14.21	32.75	10.24	24.39
20030130092005-A10	Unknown	6.02	4.75	14.21	23.71	9.19	24.39
20030130092115-A11	Unknown	6.02	4.75	14.21	66.62	13.47	24.39
20030130092225-A12	Unknown	-0.67	0.47	14.21	118.56	17.28	24.39

Reviewed by:



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>TAN 607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Hot Shop</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 251062</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>4</u>	<u>Surveys taken during payload disassembly</u>	
DATE: <u>1/30/03</u>	<u>Report Batch #1 = 5345, 5344</u>	
TIME: <u>1340</u>	<u>Report Batch # 5357 is delayed count on success of Drum #6</u>	

RCT: F. Bush / 7 Bush P. Jackson  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28 %βγ
		29.90 %α
RO-20	802084	
electra	801530	102 α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB 5100 attachment for survey results				
	1		outside bag surface			21000	220

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area



-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.


# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β  
γ A-161

☐ - Direct Scan  
○ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe

Drum # 6



5.00e Containment Wall



Bottom

# Tan Smear Report

Batch ID: smear - 200301301043

Group: A

Device: LB5100 #324920

Batch Key: 5,345

Selected Geometry: 1/4" Stainless Steel

Survey Location: FOLLOW UP SMEARS OF DRUM #6, #1 FILTER, #2 TOP OF DRUM, #3 TOP OF DRUM.

Count Date: 1/30/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.20 ± 0.14	Alpha:	29.90 ± 0.23
Beta Rate:	5.50 ± 0.74	Beta:	44.28 ± 0.07

**COPY**

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
FOLLOW UP #1	Unknown	32.78	10.59	14.21	25.97	9.46	24.39
FOLLOW UP #2	Unknown	12.71	6.71	14.21	10.16	7.34	24.39
FOLLOW UP #3	Unknown	109.70	19.24	14.21	41.78	11.19	24.39

These were Cloth Smears

Reviewed by: 





# Tan Smear Report

Batch ID:	smear - 200301301021	Count Date:	1/30/03
Group:	A	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,344	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	TRUPACT 157, DRUM #6, SMEAR 11 & 12 ARE CLOTH SMEARS ON BOTTOM OF DRUM.		

Background (cpm)	Efficiency (%)
Alpha Rate: 0.20 ± 0.14	Alpha: 29.90 ± 0.23
Beta Rate: 5.50 ± 0.74	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030130102158-A1	Unknown	9.37	5.81	14.21	14.68	8.00	24.39
20030130102328-A2	Unknown	2.68	3.38	14.21	28.23	9.73	24.39
20030130102438-A3	Unknown	-0.67	0.47	14.21	21.45	8.91	24.39
20030130102548-A4	Unknown	19.40	8.21	14.21	14.68	8.00	24.39
20030130102658-A5	Unknown	39.47	11.60	14.21	19.20	8.61	24.39
20030130102808-A6	Unknown	6.02	4.75	14.21	28.23	9.73	24.39
20030130102928-A7	Unknown	2.68	3.38	14.21	53.07	12.28	24.39
20030130103038-A8	Unknown	2.68	3.38	14.21	19.20	8.61	24.39
20030130103148-A9	Unknown	6.02	4.75	14.21	25.97	9.46	24.39
20030130103258-A10	Unknown	2.68	3.38	14.21	30.49	9.99	24.39
20030130103409-A11	Unknown	-0.67	0.47	14.21	163.73	20.02	24.39
20030130103519-A12	Unknown	-0.67	0.47	14.21	165.99	20.14	24.39

Reviewed by: \_\_\_\_\_



# Tan Smear Report


Batch ID:	smear - 200301310807	Count Date:	1/31/03
Group:	A	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,357	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	DELAYED COUNT ON DRUM #6		

Background (cpm)	Efficiency (%)
Alpha Rate: 0.30 ± 0.17	Alpha: 29.90 ± 0.23
Beta Rate: 3.90 ± 0.62	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030131080714-A1	Unknown	2.34	3.39	15.37	13.78	7.28	21.50
20030131080844-A2	Unknown	5.69	4.77	15.37	16.03	7.62	21.50
20030131080955-A3	Unknown	-1.00	0.58	15.37	7.00	6.14	21.50
20030131081105-A4	Unknown	22.41	8.87	15.37	4.74	5.71	21.50
20030131081215-A5	Unknown	39.13	11.60	15.37	29.58	9.42	21.50
20030131081325-A6	Unknown	-1.00	0.58	15.37	47.65	11.38	21.50
20030131081445-A7	Unknown	-1.00	0.58	15.37	52.17	11.82	21.50
20030131081555-A8	Unknown	-1.00	0.58	15.37	36.36	10.20	21.50
20030131081705-A9	Unknown	-1.00	0.58	15.37	31.84	9.68	21.50
20030131081815-A10	Unknown	5.69	4.77	15.37	34.10	9.94	21.50
20030131081925-A11	Unknown	5.69	4.77	15.37	160.57	19.61	21.50
20030131082035-A12	Unknown	-1.00	0.58	15.37	185.41	20.99	21.50
FOLLOWUP # 1	Unknown	32.44	10.60	15.37	18.29	7.95	21.50
FOLLOWUP # 2	Unknown	19.06	8.21	15.37	126.69	17.55	21.50
FOLLOWUP # 3	Unknown	102.68	18.65	15.37	20.55	8.26	21.50

Reviewed by: \_\_\_\_\_





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607 - Trupack</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Hot Shop Tent</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002510-02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level 6-11-03</u>	
LOG #: <u>5</u>	<u>Survey of Hood area after wipe down &amp; exterior of tent where drum # 6 was moved out</u>	
DATE: <u>1-30-03</u>		
TIME: <u>1400</u>		

RCT:

K Jackson / K Jackson  
PRINT/SIGNATURE

F Bush / F Bush

REVIEWED BY:

[Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
IA	801260	10 %
Electra	801530	10 %
		%
Scaler	319971	33.9 % $\beta\gamma$
		25.5 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-11			See Survey Map	<1000	<20		
		*	Tacky Roller			<1000	0


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step-Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  Beta  
 $\gamma$  G A-169  
n Neutron


☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 $\Delta$  - Air Sample  
☐ - Tritium Swipe




- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

Drum # 10


3.0



3.0



3.0



3.0

Bottom



# Tan Smear Report

Pg 2 of 2

Batch ID: smear - 200301301535

Count Date: 1/30/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,350

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157 DRUM # 10, SMEARS 11 & 12 ARE CLOTH SMEARS.

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.20	± 0.14	Alpha:	29.90	± 0.23
Beta Rate:	5.50	± 0.74	Beta:	44.28	± 0.07

**COPY**

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030130153557-A1	Unknown	2.68	3.38	14.21	5.65	6.60	24.39
20030130153727-A2	Unknown	-0.67	0.47	14.21	3.39	6.21	24.39
20030130153837-A3	Unknown	-0.67	0.47	14.21	7.90	6.98	24.39
20030130153947-A4	Unknown	9.37	5.81	14.21	-3.39	4.82	24.39
20030130154057-A5	Unknown	12.71	6.71	14.21	25.97	9.46	24.39
20030130154207-A6	Unknown	-0.67	0.47	14.21	28.23	9.73	24.39
20030130154318-A7	Unknown	-0.67	0.47	14.21	50.81	12.07	24.39
20030130154438-A8	Unknown	-0.67	0.47	14.21	19.20	8.61	24.39
20030130154548-A9	Unknown	2.68	3.38	14.21	37.26	10.72	24.39
20030130154658-A10	Unknown	2.68	3.38	14.21	21.45	8.91	24.39
20030130154808-A11	Unknown	2.68	3.38	14.21	188.57	21.37	24.39
20030130154918-A12	Unknown	-0.67	0.47	14.21	175.02	20.64	24.39

Reviewed by: 



COPY

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

Barcode #

BLDG.: TAN 607 Hot Shop  
AREA/ROOM: Trupest Tent  
RWP #: 3100 2510 02  
LOG #: 6  
DATE: 11/30/03  
TIME: 1518

☐ ROUTINE ☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP  
COMMENTS: General Area Dose Rate measured at waist level  
Surveys taken during pay/over disassembly  
Report Batch # 5649

RCT: J.E.H./J.W. [Signature]  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28% $\beta\gamma$
		29.90% $\alpha$
R0-2.0	801780	
electra	801430	10% $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB 5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area




-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  A-175  
 $\gamma$  Monitor

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
 - Tritium Swipe

Drum # 13



# Tan Smear Report

*Pg 2 of 2*

Batch ID: smear - 200301301428	Count Date: 1/30/03
Group: A	Count Minutes: 1.0
Device: LB5100 #324920	Count Mode: Simultaneous
Batch Key: 5,349	Operating Volts: 1320
Selected Geometry: 1/4" Stainless Steel	
Survey Location: TRUPACT 157 DRUM # 13, SMEARS 11 & 12 ARE CLOTH SMEARS.	

<b>Background (cpm)</b>	<b>Efficiency (%)</b>
Alpha Rate: 0.20 ± 0.14	Alpha: 29.90 ± 0.23
Beta Rate: 5.50 ± 0.74	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030130142838-A1	Unknown	-0.67	0.47	14.21	30.49	9.99	24.39
20030130143009-A2	Unknown	16.05	7.49	14.21	-3.39	4.82	24.39
20030130143119-A3	Unknown	2.68	3.38	14.21	12.42	7.68	24.39
20030130143229-A4	Unknown	9.37	5.81	14.21	-7.90	3.61	24.39
20030130143339-A5	Unknown	6.02	4.75	14.21	23.71	9.19	24.39
20030130143449-A6	Unknown	-0.67	0.47	14.21	35.00	10.48	24.39
20030130143609-A7	Unknown	2.68	3.38	14.21	57.59	12.69	24.39
20030130143719-A8	Unknown	-0.67	0.47	14.21	12.42	7.68	24.39
20030130143829-A9	Unknown	2.68	3.38	14.21	28.23	9.73	24.39
20030130143939-A10	Unknown	2.68	3.38	14.21	10.16	7.34	24.39
20030130144049-A11	Unknown	-0.67	0.47	14.21	168.25	20.27	24.39
20030130144159-A12	Unknown	-0.67	0.47	14.21	154.70	19.50	24.39

Reviewed by: \_\_\_\_\_

*[Signature]*



# RADIOLOGICAL SURVEY REPORT

**COPY**

Pg 1 of 2

BARCODE #

BLDG.: <u>TAN 607 Hot Shop</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Truport Pent</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100251002</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>6</u>	<u>Surveys taken during payload disassembly</u>	
DATE: <u>11/30/63</u>	<u>Report Batch # 5348</u>	
TIME: <u>1532</u>		

RCT: J. E. H. / [Signature] PRINT/SIGNATURE [Signature] REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		29.40 % $\alpha$
R0-20	801780	
electra	801430	10 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB5100 attachment for survey results			<1000	<20 <sup>6.4</sup> <sub>1-3</sub>
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier


ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  A-179  
 $\gamma$

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 $\Delta$  - Air Sample  
☐ - Tritium Swipe


Drum # 9

3.0




5.0

3.0



5.0

4.0



2.0

3.0

Bottom



# Tan Smear Report

Pg 2 of 2

Batch ID:	smear - 200301301357	Count Date:	1/30/03
Group:	A	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,348	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	TRUPACT 157, DRUM # 9. SMEARS 11 & 12 ARE CLOTH SMEARS.		

<b>Background (cpm)</b>	<b>Efficiency (%)</b>
Alpha Rate: 0.20 ± 0.14	Alpha: 29.90 ± 0.23
Beta Rate: 5.50 ± 0.74	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030130135749-A1	Unknown	-0.67	0.47	14.21	14.68	8.00	24.39
20030130135919-A2	Unknown	-0.67	0.47	14.21	1.13	5.78	24.39
20030130140029-A3	Unknown	-0.67	0.47	14.21	1.13	5.78	24.39
20030130140139-A4	Unknown	-0.67	0.47	14.21	1.13	5.78	24.39
20030130140249-A5	Unknown	-0.67	0.47	14.21	16.94	8.31	24.39
20030130140359-A6	Unknown	-0.67	0.47	14.21	30.49	9.99	24.39
20030130140509-A7	Unknown	-0.67	0.47	14.21	62.11	13.08	24.39
20030130140629-A8	Unknown	-0.67	0.47	14.21	23.71	9.19	24.39
20030130140740-A9	Unknown	-0.67	0.47	14.21	35.00	10.48	24.39
20030130140850-A10	Unknown	-0.67	0.47	14.21	37.26	10.72	24.39
20030130141000-A11	Unknown	2.68	3.38	14.21	213.42	22.65	24.39
20030130141110-A12	Unknown	-0.67	0.47	14.21	111.79	16.83	24.39

Reviewed by: \_\_\_\_\_

*[Signature]*



# COPY

|BARCODE #

Pg 1082

BLDG.:	TAN 607 Hot Shop	<input type="checkbox"/> ROUTINE	<u>JOB DESCRIPTION</u>
AREA/ROOM:	Inspect Unit	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #:	3100 2510 02	COMMENTS: General Area Dose Rate measured at waist level	
LOG #:	4	Surveys taken during pay load disassembly	
DATE:	11/30/02	Report Batch # 5347	
TIME:	1540		

**RCT:**

*J. Ely J. Giv* *Incl* *Excluded*  
*Mao* *McK. n 10/1*  
PRINT/SIGNATURE  
*Elong Ely*

REVIEWED BY:

*Y. J. Zuck*

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28 %
		29.98 %
R6-20	801730	
Plectra	801430	10 %

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area


**-x-x- Radiological Barrier**

ALL dose rates are in mrem/hr, unless otherwise noted.



#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
**	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	
γ	A-183

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

Drum # 8



5.0



Bottom

# Tan Smear Report

Pg 2 of 2

Batch ID:	smear - 200301301324	Count Date:	1/30/03
Group:	A	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,347	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	TRUPACT 157, DRUM # 8, SMEAR # 11 & 12 ARE CLOTH SMEARS TAKEN ON BOTTOM OF DRUM.		

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.20 ± 0.14	Alpha:	29.90 ± 0.23
Beta Rate:	5.50 ± 0.74	Beta:	44.28 ± 0.07

**COPY**

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030130132407-A1	Unknown	-0.67	0.47	14.21	21.45	8.91	24.39
20030130132538-A2	Unknown	-0.67	0.47	14.21	7.90	6.98	24.39
20030130132648-A3	Unknown	2.68	3.38	14.21	14.68	8.00	24.39
20030130132758-A4	Unknown	6.02	4.75	14.21	1.13	5.78	24.39
20030130132908-A5	Unknown	-0.67	0.47	14.21	25.97	9.46	24.39
20030130133018-A6	Unknown	-0.67	0.47	14.21	46.30	11.64	24.39
20030130133138-A7	Unknown	6.02	4.75	14.21	41.78	11.19	24.39
20030130133248-A8	Unknown	-0.67	0.47	14.21	39.52	10.96	24.39
20030130133358-A9	Unknown	-0.67	0.47	14.21	25.97	9.46	24.39
20030130133508-A10	Unknown	-0.67	0.47	14.21	14.68	8.00	24.39
20030130133618-A11	Unknown	2.68	3.38	14.21	265.36	25.11	24.39
20030130133728-A12	Unknown	2.68	3.38	14.21	136.63	18.42	24.39

Reviewed by:

*[Signature]*



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

Pg 1 of 2

BLDG.: TAN 607 Hot Shop  
AREA/ROOM: Truport Tent  
RWP #: 3100 2510 02  
LOG #: 7  
DATE: 1/30/03  
TIME: 1805

☐ ROUTINE

## JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level

Surveys taken during payload disassembly

Report Batal # 5352

RCT:

J. EN/9.94/ [Signature]  
EL [Signature]  
PRINT/SIGNATURE

REVIEWED BY:

[Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		29.90 % $\alpha$
RA-20	801780	
electra	801430	10 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step-Off Pad




-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  Beta  
 $\gamma$  Gamma  
n A-187

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
☐ - Tritium Swipe

Drum # 12



Bottom



# Tan Smear Report

Pg 2 of 2

Batch ID: smear - 200301301728

Count Date: 1/30/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,352

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel


Survey Location: TRUPACT 157 DRUM # 12, SMEARS 11& 12 ARE CLOTH SMEARS.

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.20	± 0.14	Alpha:	29.90	± 0.23
Beta Rate:	5.50	± 0.74	Beta:	44.28	± 0.07

COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030130172900-A1	Unknown	-0.67	0.47	14.21	-3.39	4.82	24.39
20030130173030-A2	Unknown	-0.67	0.47	14.21	23.71	9.19	24.39
20030130173140-A3	Unknown	2.68	3.38	14.21	10.16	7.34	24.39
20030130173250-A4	Unknown	-0.67	0.47	14.21	-3.39	4.82	24.39
20030130173400-A5	Unknown	2.68	3.38	14.21	12.42	7.68	24.39
20030130173510-A6	Unknown	-0.67	0.47	14.21	28.23	9.73	24.39
20030130173620-A7	Unknown	6.02	4.75	14.21	62.11	13.08	24.39
20030130173741-A8	Unknown	-0.67	0.47	14.21	37.26	10.72	24.39
20030130173851-A9	Unknown	-0.67	0.47	14.21	10.16	7.34	24.39
20030130174001-A10	Unknown	2.68	3.38	14.21	23.71	9.19	24.39
20030130174111-A11	Unknown	-0.67	0.47	14.21	152.44	19.37	24.39
20030130174221-A12	Unknown	-0.67	0.47	14.21	55.33	12.48	24.39

Reviewed by:



11-11-11



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

Barcode #

Pg 1 of 2

BLDG.: TAN 607 Hot Shop  
AREA/ROOM: Truport Tent  
RWP #: 3100 2510 02  
LOG #: 7  
DATE: 1/30/03  
TIME: 1822

☐ ROUTINE

## JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level

Surveys taken during payload disassembly  
Report Batch # 5351

RCT:

JELLY 1/30/03  
Elroy L. Lary  
PRINT/SIGNATURE

REVIEWED BY:

WZK

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	4428 %βγ
		29.90 %α
RD-20	801780	
electra	801430	10% α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step-Off Pad




-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β  
γ  
n A-191  
Location

☐ - Direct Scan  
○ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe

Drum # 14



Bottom

# Tan Smear Report

Pg 2 of 2

Batch ID: smear - 200301301654

Count Date: 1/30/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,351

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157 DRUM # 14, SMEARS 11 & 12 ARE CLOTH SMEARS.

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.20 ± 0.14	Alpha:	29.90 ± 0.23
Beta Rate:	5.50 ± 0.74	Beta:	44.28 ± 0.07

COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030130165453-A1	Unknown	-0.67	0.47	14.21	10.16	7.34	24.39
20030130165624-A2	Unknown	2.68	3.38	14.21	7.90	6.98	24.39
20030130165734-A3	Unknown	2.68	3.38	14.21	14.68	8.00	24.39
20030130165844-A4	Unknown	-0.67	0.47	14.21	14.68	8.00	24.39
20030130165954-A5	Unknown	2.68	3.38	14.21	7.90	6.98	24.39
20030130170104-A6	Unknown	-0.67	0.47	14.21	25.97	9.46	24.39
20030130170224-A7	Unknown	-0.67	0.47	14.21	44.04	11.42	24.39
20030130170334-A8	Unknown	2.68	3.38	14.21	48.55	11.85	24.39
20030130170444-A9	Unknown	-0.67	0.47	14.21	30.49	9.99	24.39
20030130170554-A10	Unknown	-0.67	0.47	14.21	37.26	10.72	24.39
20030130170704-A11	Unknown	-0.67	0.47	14.21	132.11	18.15	24.39
20030130170814-A12	Unknown	-0.67	0.47	14.21	644.76	38.57	24.39

Reviewed by:

*[Signature]*



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>TAN 607 Hot Shop</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Impact Cont</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002510 02</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>7</u>	<u>Special Contamination surveys taken to verify contamination levels</u>	
DATE: <u>1/30/03</u>	<u>during and after disassembly of payload</u>	
TIME: <u>1400-1820</u>		

RCT: J. Ely / J. G. W. / J. B. S. / J. P. S.  
PRINT/SIGNATURE

REVIEWED BY: J. S. S.

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	225065	40 %βγ
		24 %α
electra	801530	10 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
<u>78 1/31/03</u> <u>1-23</u>	<u>11-14</u>					<u>&lt;1000</u>	<u>&lt;20</u>


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand-Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β Be  
γ G<sub>0</sub> A-195  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
☐ - Large Area Wipe (LAW)  
 - Air Sample  
☐ - Tritium Swipe





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>WAPW SWP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP <u>Report Batch # = 5365</u>
RWP #: <u>31008496 02</u>	COMMENTS: <u>CASE # 157 Ann's in SWP FOR SIGNATURE</u>	
LOG #: <u>11</u>	<u>All neutron readings &amp; description unless noted.</u>	
DATE: <u>1-31-03</u>	<u>Alarm MARK # 29 001689 0117</u>	
TIME: <u>1825</u>		

RCT: Jon Johnston PRINT SIGNATURE

REVIEWED BY: JSZ

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.2 %βγ
		29.7 %α
#0-20	812084	
E600	81850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	2200/NA	220/NA		
1-12			see 1135100 print out				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand-Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β Beta  
γ G: A-197  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



1 meter - 20.5 m/hr  
 2 meter - 20.5 m/hr

# Tan Smear Report

Batch ID: smear - 200301311755  
Group: A  
Device: LB5100 #324920  
Batch Key: 5,365  
Selected Geometry: 1/4" Stainless Steel  
Survey Location: SWB SURVEY

Count Date: 1/31/03  
Count Minutes: 1.0  
Count Mode: Simultaneous  
Operating Volts: 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.30 ± 0.17	Alpha:	29.90 ± 0.23
Beta Rate:	3.90 ± 0.62	Beta:	44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030131175548-A1	Unknown	-1.00	0.58	15.37	2.48	5.24	21.50
20030131175718-A2	Unknown	-1.00	0.58	15.37	18.29	7.95	21.50
20030131175828-A3	Unknown	-1.00	0.58	15.37	20.55	8.26	21.50
20030131175938-A4	Unknown	2.34	3.39	15.37	0.23	4.73	21.50
20030131180048-A5	Unknown	-1.00	0.58	15.37	20.55	8.26	21.50
20030131180158-A6	Unknown	-1.00	0.58	15.37	31.84	9.68	21.50
20030131180318-A7	Unknown	5.69	4.77	15.37	79.27	14.17	21.50
20030131180428-A8	Unknown	-1.00	0.58	15.37	22.81	8.57	21.50
20030131180538-A9	Unknown	-1.00	0.58	15.37	29.58	9.42	21.50
20030131180648-A10	Unknown	-1.00	0.58	15.37	22.81	8.57	21.50
20030131180759-A11	Unknown	-1.00	0.58	15.37	11.52	6.92	21.50
20030131180909-A12	Unknown	-1.00	0.58	15.37	22.81	8.57	21.50

Reviewed by:





COPY

441.45#  
10/10/97  
Rev. #03

## RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Warm Shop</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 2496 02</u>	Report Batch # = 5366	
LOG #: <u>11</u>	COMMENTS: <u>CASK #157 Drum's in SWB Pool</u>	
DATE: <u>1-31-03</u>	<u>Shipment.</u>	
TIME: <u>1825</u>	<u>Alarm Tisk # 29001689 0117</u>	
	<u>All SWB neutron readings checked with no excess noted.</u>	

RCT: Jon Johnston  
PRINT SIGNATURE

REVIEWED BY: JSZ

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.2 %βγ
		22.8 %α
RO-20	802084	
EC600	801850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	2700/NA	220/NA		
1-12			See 213 5100 printout				

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Sten-Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β/#γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β E  
γ A-201  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

**Batch ID:** smear - 200301311812  
**Group:** A  
**Device:** LB5100 #324920  
**Batch Key:** 5,366  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** SWB SURVEY

**Count Date:** 1/31/03  
**Count Minutes:** 1.0  
**Count Mode:** Simultaneous  
**Operating Volts:** 1320

Background (cpm)		Efficiency (%)	
<b>Alpha Rate:</b>	0.30 ± 0.17	<b>Alpha:</b>	29.90 ± 0.23
<b>Beta Rate:</b>	3.90 ± 0.62	<b>Beta:</b>	44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030131181249-A1	Unknown	-1.00	0.58	15.37	4.74	5.71	21.50
20030131181419-A2	Unknown	-1.00	0.58	15.37	7.00	6.14	21.50
20030131181530-A3	Unknown	-1.00	0.58	15.37	20.55	8.26	21.50
20030131181640-A4	Unknown	-1.00	0.58	15.37	9.26	6.54	21.50
20030131181750-A5	Unknown	-1.00	0.58	15.37	34.10	9.94	21.50
20030131181900-A6	Unknown	-1.00	0.58	15.37	29.58	9.42	21.50
20030131182020-A7	Unknown	2.34	3.39	15.37	92.82	15.22	21.50
20030131182130-A8	Unknown	-1.00	0.58	15.37	22.81	8.57	21.50
20030131182240-A9	Unknown	-1.00	0.58	15.37	25.07	8.86	21.50
20030131182350-A10	Unknown	2.34	3.39	15.37	18.29	7.95	21.50
20030131182500-A11	Unknown	5.69	4.77	15.37	7.00	6.14	21.50
20030131182610-A12	Unknown	-1.00	0.58	15.37	29.58	9.42	21.50

Reviewed by: \_\_\_\_\_

*[Signature]*





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>WARM SHOP</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100749602</u>	COMMENTS: <u>Report Batch #: 5728</u>	
LOG #: <u>11</u>	<u>CASK #157 drums in SWD for shipment</u>	
DATE: <u>1-31-03</u>	<u>All neutron readings LHO may be unless noted.</u>	
TIME: <u>1825</u>	<u>ALPHA TASK # 29001689 0117</u>	

RCT: Jon Johnston  
PRINT/SIGNATURE

REVIEWED BY: NTL

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.2 %βγ
		22.9 %α
KO-20	502054	
EGCO	501850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	L200/NA	L200/NA		
1-12			SEE LB 5100 PRINT OUT				

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β Beta  
γ Gamma  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



# Tan Smear Report

**Batch ID:** smear - 200301311844  
**Group:** A  
**Device:** LB5100 #324920  
**Batch Key:** 5,368  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:**


**Count Date:** 1/31/03  
**Count Minutes:** 1.0  
**Count Mode:** Simultaneous  
**Operating Volts:** 1320

Background (cpm)	Efficiency (%)
Alpha Rate: 0.30 ± 0.17	Alpha: 29.90 ± 0.23
Beta Rate: 3.90 ± 0.62	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030131184440-A1	Unknown	-1.00	0.58	15.37	7.00	6.14	21.50
20030131184610-A2	Unknown	-1.00	0.58	15.37	7.00	6.14	21.50
20030131184720-A3	Unknown	-1.00	0.58	15.37	16.03	7.62	21.50
20030131184830-A4	Unknown	-1.00	0.58	15.37	11.52	6.92	21.50
20030131184940-A5	Unknown	-1.00	0.58	15.37	20.55	8.26	21.50
20030131185051-A6	Unknown	-1.00	0.58	15.37	29.58	9.42	21.50
20030131185201-A7	Unknown	-1.00	0.58	15.37	65.72	13.05	21.50
20030131185321-A8	Unknown	2.34	3.39	15.37	16.03	7.62	21.50
20030131185431-A9	Unknown	-1.00	0.58	15.37	25.07	8.86	21.50
20030131185541-A10	Unknown	-1.00	0.58	15.37	18.29	7.95	21.50
20030131185651-A11	Unknown	2.34	3.39	15.37	25.07	8.86	21.50
20030131185801-A12	Unknown	-1.00	0.58	15.37	43.13	10.92	21.50

Reviewed by: \_\_\_\_\_





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>workshop</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 7496 02</u>	Report Batch # = 5369	
LOG #: <u>11</u>	COMMENTS: <u>CHSK #157 Audit in SWB Full Shipment</u>	
DATE: <u>1-31-03</u>	<u>All neutron readings &lt; 1.0 mR/hr unless noted.</u>	
TIME: <u>1825</u>	<u>Alarm Mask # 29021689 0117</u>	

RCT: J. Bink McKinlay  
PRINT/SIGNATURE

REVIEWED BY: W. J. Z...

Jon Johnston

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.2 %βγ
		29.9 %α
KC-20	80084	
6600	801850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	2200/RA	220/RA		
1-12			See 2135100 print out				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β Be  
γ G: A-209  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



1 meter - 20.5 m/h

2 meter - 20.5 m/h

# Tan Smear Report

**Batch ID:** smear - 200301311844  
**Group:** B  
**Device:** LB5100 #324920  
**Batch Key:** 5,369  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:**

**Count Date:** 1/31/03  
**Count Minutes:** 1.0  
**Count Mode:** Simultaneous  
**Operating Volts:** 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.30 ± 0.17	Alpha:	29.90 ± 0.23
Beta Rate:	3.90 ± 0.62	Beta:	44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030131184447-B13 (1)	Unknown	2.34	3.39	15.37	9.26	6.54	21.50
20030131190028-B14 (2)	Unknown	-1.00	0.58	15.37	77.01	13.99	21.50
20030131190138-B15 (7)	Unknown	-1.00	0.58	15.37	11.52	6.92	21.50
20030131190248-B16 (4)	Unknown	-1.00	0.58	15.37	18.29	7.95	21.50
20030131190358-B17 (5)	Unknown	2.34	3.39	15.37	31.84	9.68	21.50
20030131190518-B18 (6)	Unknown	-1.00	0.58	15.37	16.03	7.62	21.50
20030131190628-B19 (7)	Unknown	5.69	4.77	15.37	22.81	8.57	21.50
20030131190738-B20 (8)	Unknown	-1.00	0.58	15.37	25.07	8.86	21.50
20030131190848-B21 (9)	Unknown	-1.00	0.58	15.37	29.58	9.42	21.50
20030131190958-B22 (10)	Unknown	-1.00	0.58	15.37	63.46	12.85	21.50
20030131191108-B23 (11)	Unknown	-1.00	0.58	15.37	18.29	7.95	21.50
20030131191218-B24 (12)	Unknown	-1.00	0.58	15.37	31.84	9.68	21.50

64  
2.3-03

Reviewed by: \_\_\_\_\_

DRZ





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

Barcode #

Pg 1 of 2

BLDG.: TAN 607 Hot Shop	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: Truport Pent	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: 3100 2510 02	COMMENTS: General Area Dose Rate measured at waist level	
LOG #: 7	Surveys taken during payload disassembly	
DATE: 11/30/03	Report Batch # 5353	
TIME: 1836		

RCT: J. EN / J. 94 / L. McKinlay  
PRINT/SIGNATURE

REVIEWED BY: J. R. 200

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
ZA	800147	10 %
		%
		%
Scaler	324920	44.23 % $\beta\gamma$
		29.98 % $\alpha$
RD-20	801780	
electra	801430	10 % $\alpha$

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-12			See LB5100 attachment for survey results			<1000	<20
	1					<1000	<20

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area




-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  A-213  
 $\gamma$

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
 - Tritium Swipe

Drum # 11



Bottom

# Tan Smear Report

Pg 2 of 2

Batch ID: smear - 200301301800

Count Date: 1/30/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,353

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT 157 DRUM #11, SMEARS 11 & 12 ARE CLOTH SMEARS.

## Background (cpm)

## Efficiency (%)

Alpha Rate: 0.20 ± 0.14

Alpha: 29.90 ± 0.23

Beta Rate: 5.50 ± 0.74

Beta: 44.28 ± 0.07

COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030130180026-A1	Unknown	-0.67	0.47	14.21	1.13	5.78	24.39
20030130180156-A2	Unknown	6.02	4.75	14.21	7.90	6.98	24.39
20030130180306-A3	Unknown	-0.67	0.47	14.21	19.20	8.61	24.39
20030130180416-A4	Unknown	-0.67	0.47	14.21	-3.39	4.82	24.39
20030130180526-A5	Unknown	6.02	4.75	14.21	12.42	7.68	24.39
20030130180636-A6	Unknown	-0.67	0.47	14.21	35.00	10.48	24.39
20030130180756-A7	Unknown	-0.67	0.47	14.21	86.95	15.07	24.39
20030130180906-A8	Unknown	-0.67	0.47	14.21	19.20	8.61	24.39
20030130181017-A9	Unknown	-0.67	0.47	14.21	23.71	9.19	24.39
20030130181127-A10	Unknown	2.68	3.38	14.21	19.20	8.61	24.39
<del>20030130181237-A11</del>	<del>Unknown</del>	<del>-0.67</del>	<del>0.47</del>	<del>31.95</del>	<del>142.10</del>	<del>30.35</del>	<del>44.88</del>
20030130181237-A11	Unknown	-0.67	0.47	14.21	161.47	19.89	24.39
<del>20030130181237-A11</del>	<del>Unknown</del>	<del>-0.67</del>	<del>0.47</del>	<del>15.76</del>	<del>159.52</del>	<del>21.07</del>	<del>26.32</del>
20030130181347-A12	Unknown	-0.67	0.47	14.21	109.53	16.68	24.39

Reviewed by:

2002



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b> <u>Batch Key # 5358</u>
AREA/ROOM: <u>Hol Shop</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002496 03</u>	COMMENTS: <u>Release Survey TO allow</u>	
LOG #: <u>3</u>	<u>Category "A" Clothing in Extended RBA</u>	
DATE: <u>11/31/03</u>	<u>Smear #16+17 not taken.</u>	
TIME: <u>1105</u>		

RCT: F. Bush / F. Bush / R. Gaber / R. Johnson PRINT SIGNATURE REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	801260	10 %
177-L	802224	10 %
177-L	801973	10 %
Scaler		%βγ
		%α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/μA	<20/μA		


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step-Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β Beta  
γ G A-217  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report


# COPY

<b>Batch ID:</b>	smear - 200301311024	<b>Count Date:</b>	1/31/03
<b>Group:</b>	A	<b>Count Minutes:</b>	1.0
<b>Device:</b>	LB5100 #324920	<b>Count Mode:</b>	Simultaneous
<b>Batch Key:</b>	5,358	<b>Operating Volts:</b>	1320
<b>Selected Geometry:</b>	1/4" Stainless Steel		
<b>Survey Location:</b>	CLEARING HOT SHOP EXTENDED RBA		

<b>Background (cpm)</b>		<b>Efficiency (%)</b>	
<b>Alpha Rate:</b>	0.30 ± 0.17	<b>Alpha:</b>	29.90 ± 0.23
<b>Beta Rate:</b>	3.90 ± 0.62	<b>Beta:</b>	44.28 ± 0.07

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030131102428-A1	Unknown	-1.00	0.58	15.37	11.52	6.92	21.50
20030131102559-A2	Unknown	2.34	3.39	15.37	25.07	8.86	21.50
20030131102709-A3	Unknown	2.34	3.39	15.37	18.29	7.95	21.50
20030131102819-A4	Unknown	12.38	6.72	15.37	2.48	5.24	21.50
20030131102929-A5	Unknown	2.34	3.39	15.37	13.78	7.28	21.50
20030131103039-A6	Unknown	-1.00	0.58	15.37	34.10	9.94	21.50
20030131103149-A7	Unknown	2.34	3.39	15.37	74.75	13.81	21.50
20030131103309-A8	Unknown	2.34	3.39	15.37	36.36	10.20	21.50
20030131103419-A9	Unknown	-1.00	0.58	15.37	31.84	9.68	21.50
20030131103529-A10	Unknown	-1.00	0.58	15.37	18.29	7.95	21.50
20030131103639-A11	Unknown	-1.00	0.58	15.37	29.58	9.42	21.50
20030131103749-A12	Unknown	-1.00	0.58	15.37	34.10	9.94	21.50
20030131103859-A13	Unknown	2.34	3.39	15.37	16.03	7.62	21.50
20030131104009-A14	Unknown	-1.00	0.58	15.37	95.08	15.38	21.50
20030131104130-A15	Unknown	-1.00	0.58	15.37	27.33	9.14	21.50
20030131104240-A18	Unknown	-1.00	0.58	15.37	18.29	7.95	21.50
20030131104350-A19	Unknown	5.69	4.77	15.37	38.62	10.44	21.50

Reviewed by:







## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 %βγ
		29.80 %α
Ro-20	801780	

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x--x- Radiological Barrier**

ALL dose rates are in mrem/hr, unless otherwise noted.

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
**	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	Neutron

- - Direct Scan
- - Swipe (Smear)
- └ - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: WEST OF 668  
AREA/ROOM: TAN  
RWP #: NA  
LOG #: 5  
DATE: 2-3-03  
TIME: 1205

☐ ROUTINE

## JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

Report Date #5375


COMMENTS: Outgoing Shipment Trailer and CASK  
#157 From TAN. CASK is empty NO IGV or  
drum's.

RCT: Spilling / McKinlay  
Paul / McKinlay  
PRINT/SIGNATURE


REVIEWED BY: W. R. Lusk

# TRUPACT

CASK # 157



TRAILER # 8




HIGHEST LEVEL@

CONTACT LO.5

30 CM. LO.5

1 METER LO.5

2 METERS LO.5



# Tan Smear Report

Batch ID: smear - 200302031057

Count Date: 2/3/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,375

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: OCA TRUPACT 157 SHIPMENT SURVEY.

## Background (cpm)

Alpha Rate: 0.10 ± 0.10  
Beta Rate: 5.40 ± 0.73

## Efficiency (%)

Alpha: 29.90 ± 0.23  
Beta: 44.28 ± 0.07

# COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030203105746-A1	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22
20030203105916-A2	Unknown	3.01	3.36	12.70	3.61	6.20	24.22
20030203110026-A3	Unknown	6.35	4.74	12.70	14.91	8.00	24.22
20030203110136-A4	Unknown	3.01	3.36	12.70	5.87	6.60	24.22
20030203110246-A5	Unknown	-0.33	0.33	12.70	21.68	8.90	24.22
20030203110356-A6	Unknown	-0.33	0.33	12.70	44.26	11.41	24.22
20030203110516-A7	Unknown	6.35	4.74	12.70	57.81	12.68	24.22
20030203110627-A8	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
20030203110737-A9	Unknown	3.01	3.36	12.70	14.91	8.00	24.22
20030203110847-A10	Unknown	3.01	3.36	12.70	12.65	7.67	24.22
20030203110957-A11	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
20030203111107-A12	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22
20030203111217-A13	Unknown	-0.33	0.33	12.70	14.91	8.00	24.22
20030203111327-A14	Unknown	6.35	4.74	12.70	100.72	16.06	24.22
20030203111447-A15	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22
20030203111557-A16	Unknown	6.35	4.74	12.70	8.13	6.98	24.22
20030203111707-A17	Unknown	-0.33	0.33	12.70	37.49	10.72	24.22
20030203111817-A18	Unknown	3.01	3.36	12.70	5.87	6.60	24.22
20030203111927-A19	Unknown	6.35	4.74	12.70	23.94	9.18	24.22
20030203112037-A20	Unknown	9.70	5.80	12.70	26.20	9.46	24.22

Reviewed by: \_\_\_\_\_



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>HOT SHOP/EXTENSION</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>TRUPACT FLOOR PLAN</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31002496 02</u>	Report Date: <u>11/5/97</u>	
LOG #: <u>2</u>	COMMENTS: <u>General Area Dose Rate measured at waist level. 64-23-03</u>	
DATE: <u>2/3/03</u>	<u>Contamination Survey to Clear RBA for work.</u>	
TIME: <u>0935</u>		

RCT: F. Bush / F. Bush  
PRINT/SIGNATURE

REVIEWED BY: \_\_\_\_\_

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
GA	301260	10 %
		%
		%
Scaler	324920	44.28 %βγ
		29.90 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		



CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ B and / Gamma Dose Rates  
α A A-225  
R Beta

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



# Tan Smear Report

Job ID: smear - 200302030902  
 Count Date: 2/3/03  
 Setup: A  
 Count Minutes: 1.0  
 Piece: LB5100 #324920  
 Count Mode: Simultaneous  
 Job Key: 5373  
 Operating Volts: 1320

Detected Geometry: 1/4" Stainless Steel  
 Key Location: CLEARING RBA EXTENSION INTO HOT SHOP

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10 ± 0.10 Alpha: 29.90 ± 0.23  
 Beta Rate: 5.40 ± 0.73 Beta: 44.28 ± 0.07

e ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
A-227	Unknown	-0.33	0.33	12.70	21.68	8.90	24.22
203090519-A4	Unknown	3.01	3.36	12.70	-5.42	4.25	24.22
203090629-A5	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22
203090739-A6	Unknown	-0.33	0.33	12.70	17.16	8.31	24.22
203090849-A7	Unknown	3.01	3.36	12.70	44.26	11.41	24.22
203091009-A8	Unknown	-0.33	0.33	12.70	73.62	14.02	24.22
203091120-A9	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22
203091230-A10	Unknown	3.01	3.36	12.70	35.23	10.48	24.22
203091340-A11	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
203091450-A12	Unknown	3.01	3.36	12.70	19.42	8.61	24.22
203091600-A13	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
203091710-A14	Unknown	3.01	3.36	12.70	1.36	5.78	24.22
203091820-A15	Unknown	3.01	3.36	12.70	107.50	16.53	24.22
	Unknown	-0.33	0.33	12.70	3.61	6.20	24.22

Reviewed by:

*[Signature]*

COPY





COPY

441.45#  
10/10/97  
Rev. #03

## RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: <u>607</u>	<input checked="" type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>Hotshop 101</u>	<input type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>31009623</u>	COMMENTS: <u>General Area Dose Rate measured at waist level</u>	
LOG #: <u>5</u>	<u>Tent + Payload Area</u>	
DATE: <u>2-4-03</u>	<u>Report Batch # 5374</u>	
TIME: <u>1100</u>		

RCT: ELAN 15 Jan  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

Page 1 of 3

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS			
Type	Serial #	Efficiency	
R50-50	801912	NA	%
			%
			%
Scaler	324920	42	%βγ
		29	%α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
			<u>See LB5100 Printouts</u>				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*\* Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β E A-229  
γ C

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



Payload Room

# Tan Smear Report

**Batch ID:** smear - 200302041059  
**Group:** A  
**Device:** LB5100 #324920  
**Batch Key:** 5,394  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** TENT TURNTABLE & AREA

**Count Date:** 2/4/03  
**Count Minutes:** 1.0  
**Count Mode:** Simultaneous  
**Operating Volts:** 1320

Page 2 of 3

<b>Background (cpm)</b>	<b>Efficiency (%)</b>
Alpha Rate: 0.30 ± 0.17	Alpha: 29.90 ± 0.23
Beta Rate: 5.30 ± 0.73	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>	
20030204110001-A1	Unknown	-1.00	0.58	15.37	58.04	12.68	24.05	Turn table
20030204110132-A2	Unknown	-1.00	0.58	15.37	58.04	12.68	24.05	"
20030204110242-A3	Unknown	-1.00	0.58	15.37	46.75	11.63	24.05	"
<del>20030204110352-A4</del>	<del>Unknown</del>	<del>-1.00</del>	<del>0.58</del>	<del>208.04</del>	<del>-11.97</del>	<del>1.64</del>	<del>198.91</del>	<del>EL 2-4-03</del>
20030204110352-A4	Unknown	-1.00	0.58	15.37	39.97	10.96	24.05	"
<del>20030204110352-A4</del>	<del>Unknown</del>	<del>-1.00</del>	<del>0.58</del>	<del>33.78</del>	<del>17.75</del>	<del>13.39</del>	<del>44.35</del>	<del>EL 2-4-03</del>
20030204110502-A5	Unknown	-1.00	0.58	15.37	76.11	14.20	24.05	"
20030204110612-A6	Unknown	-1.00	0.58	15.37	94.17	15.57	24.05	"
20030204110732-A7	Unknown	-1.00	0.58	15.37	134.82	18.28	24.05	Tent Floor
20030204110842-A8	Unknown	2.34	3.39	15.37	53.52	12.27	24.05	"
20030204110952-A9	Unknown	-1.00	0.58	15.37	78.37	14.38	24.05	"
20030204111102-A10	Unknown	2.34	3.39	15.37	28.68	9.72	24.05	"
20030204111212-A11	Unknown	-1.00	0.58	15.37	98.69	15.89	24.05	"
20030204111322-A12	Unknown	-1.00	0.58	15.37	62.56	13.08	24.05	"

Reviewed by: \_\_\_\_\_

*[Signature]*

11-11-11



# Tan Smear Report

Batch ID: smear - 200302041210

Group: A

Device: LB5100 #324920

Batch Key: 5,396

Selected Geometry: 1/4" Stainless Steel

Survey Location: TENT TURNTABLE AND AREA. RE-COUNT OF SMEAR # 4

Count Date: 2/4/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320


Page 3 of 3

	Background (cpm)		Efficiency (%)
Alpha Rate:	0.30 ± 0.17	Alpha:	29.90 ± 0.23
Beta Rate:	5.30 ± 0.73	Beta:	44.28 ± 0.07

**COPY**

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030204121025-A4	Unknown	-1.00	0.58	15.37	51.27	12.06	24.05

Reviewed by:





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>EXTENSION</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP <u>Report Batch # 5322</u>
RWP #: <u>3100 2496 02</u>	COMMENTS: <u>loaded SW-3 with the case # 157 drums</u>	
LOG #: <u>8</u>		
DATE: <u>2-3-03</u>	<u>All neutron readings &lt; 1 mrem/hr unless noted.</u>	
TIME: <u>1550</u>	<u>Alarm TASK # 2900 1689 0117</u>	

RCT:

Jon Johnston  
PRINT/SIGNATURE

REVIEWED BY:

[Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	800147	10 %
		%
		%
Scaler	324920	44.28% $\beta\gamma$
		29.9 % $\alpha$
Ro-20	802084	
E600	801850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	2200/NA	220/NA		
1-12			see 23 SKO print out				
	1-3		see map				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Step Off Pad

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  Beta  
 $\gamma$  Gamma  
N Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 - Air Sample  
 - Tritium Swipe



1 meter - 40.5 mm  
2 meter - 40.5 mm



# Tan Smear Report

# COPY

**Batch ID:** smear - 200302031514  
**Group:** A  
**Device:** LB5100 #324920  
**Batch Key:** 5,377  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** SWB SURVEY

**Count Date:** 2/3/03  
**Count Minutes:** 1.0  
**Count Mode:** Simultaneous  
**Operating Volts:** 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.10 ± 0.10	Alpha:	29.90 ± 0.23
Beta Rate:	5.40 ± 0.73	Beta:	44.28 ± 0.07

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030203151439-A1	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22
20030203151610-A2	Unknown	3.01	3.36	12.70	3.61	6.20	24.22
20030203151720-A3	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22
20030203151830-A4	Unknown	3.01	3.36	12.70	3.61	6.20	24.22
20030203151940-A5	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22
20030203152050-A6	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
20030203152210-A7	Unknown	-0.33	0.33	12.70	62.33	13.08	24.22
20030203152320-A8	Unknown	-0.33	0.33	12.70	26.20	9.46	24.22
20030203152430-A9	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22
20030203152540-A10	Unknown	3.01	3.36	12.70	30.71	9.98	24.22
20030203152650-A11	Unknown	-0.33	0.33	12.70	28.46	9.72	24.22
20030203152800-A12	Unknown	-0.33	0.33	12.70	17.16	8.31	24.22

Reviewed by: \_\_\_\_\_





COPY

441.45#  
10/10/97  
Rev. #03

## RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: <u>607</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>EXTENSION</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>3100 2496 02</u>	COMMENTS: <u>Report Batch # 5328</u>	
LOG #: <u>8</u>	<u>Inspected SW13 with CASK # 157 clouds</u>	
DATE: <u>2-3-03</u>	<u>All neutron readings &lt; 1.0 mR/hr unless noted.</u>	
TIME: <u>1550</u>	<u>Alarm TASK # 2900 1689 0117</u>	

RCT: A. B. / McKinlay  
Tom Johnston  
PRINT/SIGNATURE

REVIEWED BY: SLZ

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2A	820147	10 %
		%
		%
Scaler	324820	44.28 %βγ
		29.9 %α
KU-20	802084	
E600	501850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	2200/NA	220/NA		
1-12			See LABVIEW printout.				
	1-3		See map				

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area  
SOP Stand Off Point

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Alpha  
β E  
γ A-239  
n Neutron

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



# Tan Smear Report

# COPY

**Batch ID:** smear - 200302031533  
**Group:** A  
**Device:** LB5100 #324920  
**Batch Key:** 5,378  
**Selected Geometry:** 1/4" Stainless Steel  
**Survey Location:** SWB SURVEY

**Count Date:** 2/3/03  
**Count Minutes:** 1.0  
**Count Mode:** Simultaneous  
**Operating Volts:** 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.10 ± 0.10	Alpha:	29.90 ± 0.23
Beta Rate:	5.40 ± 0.73	Beta:	44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030203153337-A1	Unknown	3.01	3.36	12.70	1.36	5.78	24.22
20030203153507-A2	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22
20030203153618-A3	Unknown	-0.33	0.33	12.70	14.91	8.00	24.22
20030203153728-A4	Unknown	-0.33	0.33	12.70	-7.68	3.60	24.22
20030203153838-A5	Unknown	-0.33	0.33	12.70	21.68	8.90	24.22
20030203153948-A6	Unknown	-0.33	0.33	12.70	28.46	9.72	24.22
20030203154108-A7	Unknown	-0.33	0.33	12.70	57.81	12.68	24.22
20030203154218-A8	Unknown	-0.33	0.33	12.70	26.20	9.46	24.22
20030203154328-A9	Unknown	-0.33	0.33	12.70	26.20	9.46	24.22
20030203154438-A10	Unknown	-0.33	0.33	12.70	21.68	8.90	24.22
20030203154548-A11	Unknown	-0.33	0.33	12.70	23.94	9.18	24.22
20030203154658-A12	Unknown	-0.33	0.33	12.70	17.16	8.31	24.22

Reviewed by: 



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: TAN 607	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: HOT SHOP	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: 31002621 DC	Report Detail # 3378	
LOG #: 10	COMMENTS: General Area Dose Rate measured at waist level 2-4-03	
DATE: 2/3/03	TRUPACT CONTAINMENT TENT SURVEY (BAGGING ROOM)	
TIME: 1900		

RCT: F. Bush / 7 Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 %βγ
		29.90 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-14			See printout and map				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α AI  
β Bi A-243  
γ Gamma

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe





# Tan Smear Report

COPY

Batch ID: smear - 200302031713  
Group: A  
Device: LB5100 #324920  
Batch Key: 5,379  
Selected Geometry: 1/4" Stainless Steel  
Survey Location: BAGGING AREA

Count Date: 2/3/03  
Count Minutes: 1.0  
Count Mode: Simultaneous  
Operating Volts: 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.10 ± 0.10	Alpha:	29.90 ± 0.23
Beta Rate:	5.40 ± 0.73	Beta:	44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)	
20030203171313-A1	Unknown	3.01	3.36	12.70	5.87	6.60	24.22	drum
20030203171443-A2	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22	drum
20030203171553-A3	Unknown	-0.33	0.33	12.70	288.17	26.10	24.22	drum
20030203171703-A4	Unknown	-0.33	0.33	17.02	25.97	11.14	29.81	wood block
20030203171703-A4 5	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22	large block
20030203171703-A4 6	Unknown	-0.33	0.33	14.29	24.15	9.85	26.32	bottom of drum
20030203171813-A5 7	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22	cart
20030203171923-A6 8	Unknown	-0.33	0.33	12.70	26.20	9.46	24.22	"
20030203172043-A7 9	Unknown	-0.33	0.33	12.70	66.85	13.46	24.22	"
20030203172153-A8 10	Unknown	-0.33	0.33	12.70	127.82	17.86	24.22	Floor
20030203172304-A9 11	Unknown	-0.33	0.33	12.70	26.20	9.46	24.22	"
20030203172414-A10 12	Unknown	-0.33	0.33	12.70	39.75	10.96	24.22	"
20030203172524-A11 13	Unknown	-0.33	0.33	12.70	48.78	11.85	24.22	"
20030203172634-A12 14	Unknown	-0.33	0.33	12.70	10.39	7.33	24.22	"

Reviewed by:





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: TAN 607	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: HOT SHOP	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: 31002621 00	COMMENTS: General Area Dose Rate measured at waist level - 2-7-03	
LOG #: 10	TRUPACT CONTAINMENT TENT SURVEY (SURVEY STATION)	
DATE: 2/3/03	Report Batch #'s = 5380, 5383	
TIME: 1900		

RCT: F. Bush / 7 Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28%βγ
		29.90%α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
15-29			See printout and map.				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α Al<sup>241</sup>  
β Be A-247  
γ Gamma

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
□ - Tritium Swipe



Camera Wiped down  
Following Smear #22.  
#  
Smears # 65 and 66  
were post decon

# Tan Smear Report

# COPY


Batch ID: smear - 200302031719  
 Group: B  
 Device: LB5100 #324920  
 Batch Key: 5,380  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: MIDDLE SECTION

Count Date: 2/3/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.10	± 0.10	Alpha:	29.90	± 0.23
Beta Rate:	5.40	± 0.73	Beta:	44.28	± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)	
20030203171935-B13 15	Unknown	-0.33	0.33	12.70	37.49	10.72	24.22	Floor
20030203172905-B14 16	Unknown	-0.33	0.33	12.70	229.45	23.42	24.22	"
20030203173016-B15 17	Unknown	-0.33	0.33	12.70	26.20	9.46	24.22	"
20030203173126-B16 18	Unknown	-0.33	0.33	12.70	32.97	10.24	24.22	"
20030203173236-B17 19	Unknown	-0.33	0.33	12.70	57.81	12.68	24.22	"
20030203173346-B18 20	Unknown	6.35	4.74	12.70	145.89	18.97	24.22	"
20030203173456-B19 21	Unknown	-0.33	0.33	12.70	23.94	9.18	24.22	Drum Dolly
20030203173606-B20 22	Unknown	19.73	8.20	12.70	3,156.30	84.75	24.22	Camera - see next page
20030203173716-B21 23	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22	Gloves
20030203173836-B22 24	Unknown	-0.33	0.33	12.70	98.46	15.90	24.22	"
20030203173946-B23 25	Unknown	-0.33	0.33	12.70	30.71	9.98	24.22	"
20030203174056-B24 26	Unknown	3.01	3.36	12.70	62.33	13.08	24.22	"
20030203174206-B25 27	Unknown	3.01	3.36	12.70	5.87	6.60	24.22	Ten + walls
20030203174316-B26 28	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22	"
20030203174426-B27 29	Unknown	3.01	3.36	12.70	10.39	7.33	24.22	"

Reviewed by:





# Tan Smear Report

**COPY**

Batch ID: smear - 200302031802

Group: B

Device: LB5100 #324920

Batch Key: 5,383

Selected Geometry: 1/4" Stainless Steel

Survey Location: CAMERA 2ND SET Post decon

Count Date: 2/3/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.10	± 0.10	Alpha:	29.90	± 0.23
Beta Rate:	5.40	± 0.73	Beta:	44.28	± 0.07

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030203180233-B16-5	Unknown	-0.33	0.33	12.70	39.75	10.96	24.22
20030203182245-B17-5	Unknown	-0.33	0.33	12.70	64.59	13.27	24.22

Reviewed by: 





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: TAN	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: TRUPACT ICV BOX	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: N/A	COMMENTS: <u>Report Batch # 5374</u> <u>General Area Dose Rate measured at waist level 5-5-03</u>	
LOG #: 6	RBA EXIT SURVEY OF BOX CONTAINING TRUPACT ICV.	
DATE: 2/3/03		
TIME: 1140		

RCT: F. Bush/ *F. Bush* Lewis Bird/ *Lewis Bird*  
PRINT/SIGNATURE

REVIEWED BY: *[Signature]*

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
2/A	801206	10%
		%
		%
Scaler	324920	44.28
		29.90%α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000 / <5000	7-8 2/3/03 <20 / NA		
1-5			See map and 185100 Printout				
	1-5		See map.			21K	NA

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α A-253  
β Be

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe

TOP

⑤

MAXIMUM LOAD  
WT=5000 LBS

③

EMPTY WT/W/ID  
=1700 LBS

L3

L4

522161

④

L5  
TOP

②

522161

MAXIMUM LOAD  
WT=5000 LBS

①

EMPTY WT/W/ID  
=1700 LBS

L7

# Tan Smear Report

COPY

Batch ID: smear - 200302031024 Count Date: 2/3/03  
 Group: A Count Minutes: 1.0  
 Device: LB5100 #324920 Count Mode: Simultaneous  
 Batch Key: 5,374 Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: TRUPACT ICV BOX SURVEY

Background (cpm) Efficiency (%)  
 Alpha Rate: 0.10  $\pm$  0.10 Alpha: 29.90  $\pm$  0.23  
 Beta Rate: 5.40  $\pm$  0.73 Beta: 44.28  $\pm$  0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
1203102442-A1	Unknown	3.01	3.36	12.70	10.39	7.33	24.22
1203102613-A2	Unknown	-0.33	0.33	12.70	14.91	8.00	24.22
1203102723-A3	Unknown	3.01	3.36	12.70	8.13	6.98	24.22
20030203102833-A4	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22
20030203102943-A5	Unknown	-0.33	0.33	12.70	28.46	9.72	24.22

Reviewed by:



COPY

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		29.80 % $\alpha$
Ro-20	8-1780	

[illegible]

CA	Contamination Area
HCA	High Contamination Area
RA	Radiation Area
HRA	High Radiation Area
VHRA	Very High Radiation Area
RMA	Radioactive Material Area
ARA	Airborne Radioactivity Area
RBA	Radiological Buffer Area
FCA	Fixed Contamination Area
SCA	Soil Contamination Area
URMA	Underground Radioactive Material Area
SOP	Step-Off Pad

**-x--x- Radiological Barrier**

**ALL dose rates are in mrem/hr, unless otherwise noted.**

#	General Area Dose Rate
#@#(cm)	Dose Rate at Distance From Source
*#	Contact Dose Rate
#β / #γ	Beta Corrected / Gamma Dose Rates
α	Alpha
β	Beta
γ	Gamma
n	Neutron

- - Direct Scan
- - Swipe (Smear)
- L - Large Area Wipe (LAW)
- △ - Air Sample
- ⬢ - Tritium Swipe

441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

BARCODE #

BLDG.: WEST OF 668  
AREA/ROOM: TAN  
RWP #: NA  
LOG #: 5  
DATE: 2-3-03  
TIME: 1205

☐ ROUTINE

## JOB DESCRIPTION

☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

Report Date #5375



COMMENTS: Outgoing shipment Trailer and CASK  
#157 From TAN. CASK is empty NO IGV or  
drums.

RCT: McKinley F. Bush J. Bush REVIEWED BY: SLT


PRINT/SIGNATURE

# TRUPACT

CASK # 157



HIGHEST LEVEL@  
CONTACT 2015  
30 CM. 2015  
1 METER 2015  
2 METERS 2015



# Tan Smear Report

Batch ID: smear - 200302031057

Count Date: 2/3/03

Group: A

Count Minutes: 1.0

Device: LB5100 #324920

Count Mode: Simultaneous

Batch Key: 5,375

Operating Volts: 1320

Selected Geometry: 1/4" Stainless Steel

Survey Location: OCA TRUPACT 157 SHIPMENT SURVEY.

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.10 ± 0.10	Alpha:	29.90 ± 0.23
Beta Rate:	5.40 ± 0.73	Beta:	44.28 ± 0.07

COPY

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030203105746-A1	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22
20030203105916-A2	Unknown	3.01	3.36	12.70	3.61	6.20	24.22
20030203110026-A3	Unknown	6.35	4.74	12.70	14.91	8.00	24.22
20030203110136-A4	Unknown	3.01	3.36	12.70	5.87	6.60	24.22
20030203110246-A5	Unknown	-0.33	0.33	12.70	21.68	8.90	24.22
20030203110356-A6	Unknown	-0.33	0.33	12.70	44.26	11.41	24.22
20030203110516-A7	Unknown	6.35	4.74	12.70	57.81	12.68	24.22
20030203110627-A8	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
20030203110737-A9	Unknown	3.01	3.36	12.70	14.91	8.00	24.22
20030203110847-A10	Unknown	3.01	3.36	12.70	12.65	7.67	24.22
20030203110957-A11	Unknown	-0.33	0.33	12.70	12.65	7.67	24.22
20030203111107-A12	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22
20030203111217-A13	Unknown	-0.33	0.33	12.70	14.91	8.00	24.22
20030203111327-A14	Unknown	6.35	4.74	12.70	100.72	16.06	24.22
20030203111447-A15	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22
20030203111557-A16	Unknown	6.35	4.74	12.70	8.13	6.98	24.22
20030203111707-A17	Unknown	-0.33	0.33	12.70	37.49	10.72	24.22
20030203111817-A18	Unknown	3.01	3.36	12.70	5.87	6.60	24.22
20030203111927-A19	Unknown	6.35	4.74	12.70	23.94	9.18	24.22
20030203112037-A20	Unknown	9.70	5.80	12.70	26.20	9.46	24.22

Reviewed by: \_\_\_\_\_

*[Signature]*





441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>668</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>outside west 668</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP <u>Report Batch # 5388</u>
RWP #: <u>nil</u>	COMMENTS: <u>SWB shipment to Rev. n.c.</u>	
LOG #: <u>1</u>	<u>meter 10.5, meter 10.5 mpt/1h</u>	
DATE: <u>2-4-03</u>		
TIME: <u>0930</u>		

RCT: J. Bind / J. Johnston / J. Kenney  
Hunt / [Signature] PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 %βγ
		29.9 %α
Ro-20	502054	
E600	501850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	1200/mh	120/mh		
1-6			see 2135100 print out				


CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α A-144  
β B A-261  
γ C

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

Batch ID:	smear - 200302040909	Count Date:	2/4/03
Group:	B	Count Minutes:	1.0
Device:	LB5100 #324920	Count Mode:	Simultaneous
Batch Key:	5,389	Operating Volts:	1320
Selected Geometry:	1/4" Stainless Steel		
Survey Location:	SWB/ICV SHIPMENT TO RWMC		

<b>Background (cpm)</b>	<b>Efficiency (%)</b>
Alpha Rate: 0.30 ± 0.17	Alpha: 29.90 ± 0.23
Beta Rate: 5.30 ± 0.73	Beta: 44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030204090930-B14 (1)	Unknown	-1.00	0.58	15.37	100.95	16.05	24.05
<del>20030204091901-B15</del>	<del>Unknown</del>	<del>1.00</del>	<del>0.58</del>	<del>208.04</del>	<del>11.97</del>	<del>1.64</del>	<del>198.91</del>
20030204091901-B15 (2)	Unknown	2.34	3.39	15.37	6.10	6.60	24.05
<del>20030204091901-B15</del>	<del>Unknown</del>	<del>1.00</del>	<del>0.58</del>	<del>24.80</del>	<del>4.46</del>	<del>8.38</del>	<del>34.80</del>
20030204092011-B16 (3)	Unknown	2.34	3.39	15.37	6.10	6.60	24.05
20030204092121-B17 (4)	Unknown	-1.00	0.58	15.37	30.94	9.98	24.05
20030204092231-B18 (5)	Unknown	-1.00	0.58	15.37	67.07	13.46	24.05
20030204092351-B19 (6)	Unknown	-1.00	0.58	15.37	98.69	15.89	24.05

2-4-03

C.C.  
2-4-03

Reviewed by: \_\_\_\_\_

[Signature]



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: <u>668</u>	<input type="checkbox"/> ROUTINE	<b>JOB DESCRIPTION</b>
AREA/ROOM: <u>outside west 668</u>	<input checked="" type="checkbox"/> NON ROUTINE (SPECIFY)	<input type="checkbox"/> FOLLOW UP
RWP #: <u>NA</u>	Report batch # <u>5388</u>	
LOG #: <u>1</u>	COMMENTS: <u>SWI3 SWIPEMENT TO RUMOR</u>	
DATE: <u>2-4-03</u>	<u>1 meter 20.5 mR/h, 2 meter 20.5 mR/h</u>	
TIME: <u>0930</u>		

RCT: J. Johnston / McKenlay / McKenlay  
PRINT/SIGNATURE REVIEWED BY: J. Johnston

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 % $\beta\gamma$
		29.9 % $\alpha$
Ro. 20	80084	
EG60	801850	

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm/100cm <sup>2</sup> )	
				$\beta\gamma$	$\alpha$	$\beta\gamma$	$\alpha$
*		*	RCM Table 2-2 limits used for this survey.	<u>&lt; 200/100</u>	<u>&lt; 20/100</u>		
1-13			see 213 5100 print out				

CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
# $\beta$  / # $\gamma$  Beta Corrected / Gamma Dose Rates  
 $\alpha$  Alpha  
 $\beta$  B A-265  
 $\gamma$  C

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
 $\Delta$  - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

Batch ID: smear - 200302040901  
Group: A  
Device: LB5100 #324920  
Batch Key: 5,388  
Selected Geometry: 1/4" Stainless Steel  
Survey Location: SWB SHIPMENT TO RWMC


Count Date: 2/4/03  
Count Minutes: 1.0  
Count Mode: Simultaneous  
Operating Volts: 1320

Background (cpm)		Efficiency (%)	
Alpha Rate:	0.30 ± 0.17	Alpha:	29.90 ± 0.23
Beta Rate:	5.30 ± 0.73	Beta:	44.28 ± 0.07

COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030204090202-A1	Unknown	12.38	6.72	15.37	21.91	8.90	24.05
20030204090333-A2	Unknown	-1.00	0.58	15.37	21.91	8.90	24.05
20030204090443-A3	Unknown	5.69	4.77	15.37	15.13	7.99	24.05
20030204090553-A4	Unknown	-1.00	0.58	15.37	6.10	6.60	24.05
20030204090703-A5	Unknown	5.69	4.77	15.37	19.65	8.61	24.05
20030204090813-A6	Unknown	-1.00	0.58	15.37	30.94	9.98	24.05
20030204090933-A7	Unknown	2.34	3.39	15.37	69.33	13.65	24.05
20030204091043-A8	Unknown	-1.00	0.58	15.37	21.91	8.90	24.05
20030204091153-A9	Unknown	-1.00	0.58	15.37	8.36	6.97	24.05
20030204091303-A10	Unknown	-1.00	0.58	15.37	3.84	6.20	24.05
20030204091413-A11	Unknown	-1.00	0.58	15.37	6.10	6.60	24.05
20030204091523-A12	Unknown	-1.00	0.58	15.37	15.13	7.99	24.05
20030204091633-A13	Unknown	2.34	3.39	15.37	8.36	6.97	24.05

Reviewed by:







441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: HOT SHOP/EXTENSION  
AREA/ROOM: TRUPACT FLOOR  
PLAN

RWP #: 3100 2617 CID  
LOG #: 9  
DATE: 2-4-03  
TIME: 1500

☐ ROUTINE **JOB DESCRIPTION**  
☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP

COMMENTS: General Area Dose Rate measured at waist level - Report Batch #5397  
Release of RBA extension is not required.

RCT: 2.15.2nd

PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

## INSTRUMENTS

Type	Serial #	Efficiency
AA	550597	10 %
		%
		%
Scaler	324920	44.28 %B <sub>Y</sub>
		79.9 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				β <sub>Y</sub>	α	β <sub>Y</sub>	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
1-10			See L13 5100 printout				



CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ B α / Gamma Dose Rates  
α A A-269  
R B-104

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

Batch ID: smear - 200302041611  
 Group: A  
 Device: LB5100 #324920  
 Batch Key: 5,397  
 Selected Geometry: 1/4" Stainless Steel  
 Survey Location: RELEASE OF RBA IN HOTSHOP

Count Date: 2/4/03  
 Count Minutes: 1.0  
 Count Mode: Simultaneous  
 Operating Volts: 1320

	Background (cpm)		Efficiency (%)
Alpha Rate:	0.30 ± 0.17	Alpha:	29.90 ± 0.23
Beta Rate:	5.30 ± 0.73	Beta:	44.28 ± 0.07

# COPY

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030204161109-A1	Unknown	2.34	3.39	15.37	17.39	8.31	24.05
20030204161239-A2	Unknown	-1.00	0.58	15.37	17.39	8.31	24.05
20030204161349-A3	Unknown	-1.00	0.58	15.37	26.42	9.46	24.05
20030204161459-A4	Unknown	-1.00	0.58	15.37	6.10	6.60	24.05
20030204161609-A5	Unknown	-1.00	0.58	15.37	28.68	9.72	24.05
20030204161720-A6	Unknown	-1.00	0.58	15.37	35.46	10.48	24.05
20030204161840-A7	Unknown	-1.00	0.58	15.37	76.11	14.20	24.05
20030204161950-A8	Unknown	-1.00	0.58	15.37	24.16	9.18	24.05
20030204162100-A9	Unknown	-1.00	0.58	15.37	19.65	8.61	24.05
20030204162210-A10	Unknown	-1.00	0.58	15.37	19.65	8.61	24.05

Reviewed by: \_\_\_\_\_



441.45#  
10/10/97  
Rev. #03

# RADIOLOGICAL SURVEY REPORT

# COPY

BARCODE #

BLDG.: TAN 607  
AREA/ROOM: HOT SHOP  
RWP #: 31002621 00  
LOG #: 10  
DATE: 2/3/03  
TIME: 1900

☐ ROUTINE **JOB DESCRIPTION**  
☒ NON ROUTINE (SPECIFY) ☐ FOLLOW UP  
COMMENTS: General Area Dose Rate measured at waist level  
TRUPACT CONTAINMENT TENT SURVEY (PAYLOAD ROOM)  
Report Details #s = 5381, 5382, 5384, 5385

RCT: F. Bush / F. Bush  
PRINT/SIGNATURE

REVIEWED BY: [Signature]

## SURVEY DATA AND LEGEND

ALL SWIPE, LARGE AREA WIPE (LAW), AND DIRECT SCAN SURVEY  
LOCATIONS ARE IDENTIFIED ON THE MAP. THOSE LOCATIONS  
WHERE ACTIVITY IS GREATER THAN OR EQUAL TO THE RADCON  
MANUAL (RCM) TABLE 2-2 LIMITS\* ARE RECORDED BELOW.

INSTRUMENTS		
Type	Serial #	Efficiency
		%
		%
		%
Scaler	324920	44.28 %βγ
		29.90 %α

SWIPE No.	LAW No.	DIRECT SCAN No.	LOCATION OR ITEM DESCRIPTION	SWIPE/SCAN (dpm/100cm <sup>2</sup> )		LAW (dpm)	
				βγ	α	βγ	α
*		*	RCM Table 2-2 limits used for this survey.	<1000/ <5000	<20 / NA		
30-68			See map and printout				





CA Contamination Area  
HCA High Contamination Area  
RA Radiation Area  
HRA High Radiation Area  
VHRA Very High Radiation Area  
RMA Radioactive Material Area  
ARA Airborne Radioactivity Area  
RBA Radiological Buffer Area  
FCA Fixed Contamination Area  
SCA Soil Contamination Area  
URMA Underground Radioactive Material Area

-x-x- Radiological Barrier

ALL dose rates are in mrem/hr, unless otherwise noted.

# General Area Dose Rate  
#@#(cm) Dose Rate at Distance From Source  
\*# Contact Dose Rate  
#β / #γ Beta Corrected / Gamma Dose Rates  
α A-273  
β E A-273  
γ C

☐ - Direct Scan  
☐ - Swipe (Smear)  
L - Large Area Wipe (LAW)  
△ - Air Sample  
☐ - Tritium Swipe



# Tan Smear Report

# COPY

Batch ID: smear - 200302031726

Group: C

Device: LB5100 #324920

Batch Key: 5,381

Selected Geometry: 1/4" Stainless Steel

Survey Location:

Count Date: 2/3/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

## Background (cpm)


Alpha Rate: 0.10 ± 0.10  
Beta Rate: 5.40 ± 0.73

## Efficiency (%)

Alpha: 29.90 ± 0.23  
Beta: 44.28 ± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)	
20030203172654-C28 30	Unknown	-0.33	0.33	12.70	60.07	12.88	24.22	Bottom Slip Sheet
20030203174655-C29 31	Unknown	-0.33	0.33	12.70	39.75	10.96	24.22	"
20030203174805-C30 32	Unknown	-0.33	0.33	12.70	57.81	12.68	24.22	"
20030203174915-C31 33	Unknown	-0.33	0.33	12.70	14.91	8.00	24.22	"
20030203175025-C32 34	Unknown	-0.33	0.33	12.70	10.39	7.33	24.22	"
20030203175135-C33 35	Unknown	-0.33	0.33	12.70	-3.16	4.81	24.22	"
20030203175256-C34 36	Unknown	-0.33	0.33	12.70	23.94	9.18	24.22	"
20030203175406-C35 37	Unknown	-0.33	0.33	12.70	-0.90	5.32	24.22	"
20030203175516-C36 38	Unknown	3.01	3.36	12.70	14.91	8.00	24.22	"
20030203175626-C37 39	Unknown	-0.33	0.33	12.70	30.71	9.98	24.22	"
20030203175736-C38 40	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22	"
20030203175846-C39 41	Unknown	3.01	3.36	12.70	26.20	9.46	24.22	Outside Wall Tube
20030203175956-C40 42	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22	" Tube 2
20030203180116-C41 43	Unknown	-0.33	0.33	12.70	5.87	6.60	24.22	Inside Tube 1
20030203180226-C42 44	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22	Tube 2

Reviewed by:







# Tan Smear Report

COPY

Batch ID: smear - 200302031743

Group: D

Device: LB5100 #324920

Batch Key: 5,382

Selected Geometry: 1/4" Stainless Steel

Survey Location:

Count Date: 2/3/03

Count Minutes: 1.0

Count Mode: Simultaneous

Operating Volts: 1320

## Background (cpm)


Alpha Rate: 0.10  $\pm$  0.10  
Beta Rate: 5.40  $\pm$  0.73

## Efficiency (%)

Alpha: 29.90  $\pm$  0.23  
Beta: 44.28  $\pm$  0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030203174329-D1 45	Unknown	3.01	3.36	12.70	10.39	7.33	24.22 Outside Tube 3
20030203180451-D2 46	Unknown	-0.33	0.33	12.70	8.13	6.98	24.22 Inside Tube 3
20030203180601-D3 47	Unknown	-0.33	0.33	12.70	222.68	23.09	24.22 Tent Floor
20030203180711-D4 48	Unknown	-0.33	0.33	12.70	96.21	15.73	24.22 "
20030203180821-D5 49	Unknown	-0.33	0.33	12.70	136.86	18.42	24.22 "
20030203180931-D6 50	Unknown	3.01	3.36	12.70	78.14	14.38	24.22 "
20030203181041-D7 51	Unknown	3.01	3.36	12.70	130.08	18.00	24.22 "
20030203181151-D8 52	Unknown	-0.33	0.33	12.70	105.24	16.37	24.22 "
20030203181311-D9 53	Unknown	-0.33	0.33	12.70	37.49	10.72	24.22 Pallet
20030203181421-D10 54	Unknown	3.01	3.36	12.70	14.91	8.00	24.22 Pallet
20030203181532-D11 55	Unknown	3.01	3.36	12.70	21.68	8.90	24.22 gloves
20030203181642-D12 56	Unknown	-0.33	0.33	12.70	30.71	9.98	24.22 "
20030203181752-D13 57	Unknown	6.35	4.74	12.70	10.39	7.33	24.22 "
20030203181902-D14 58	Unknown	-0.33	0.33	12.70	93.95	15.57	24.22 "
20030203182012-D15 59	Unknown	-0.33	0.33	12.70	19.42	8.61	24.22 "

Reviewed by:





# Tan Smear Report

# COPY


Batch ID: smear - 200302031805  
Group: C  
Device: LB5100 #324920  
Batch Key: 5,384  
Selected Geometry: 1/4" Stainless Steel  
Survey Location: HI-VOL

Count Date: 2/3/03  
Count Minutes: 1.0  
Count Mode: Simultaneous  
Operating Volts: 1320

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.10	± 0.10	Alpha:	29.90	± 0.23
Beta Rate:	5.40	± 0.73	Beta:	44.28	± 0.07

Sample ID	Sample Type	Alpha (dpm)	Unc	Alpha MDA (dpm)	Beta (dpm)	Unc	Beta MDA (dpm)
20030203180516-C23 60	Unknown	-0.33	0.33	12.70	87.17	15.07	24.22
20030203182508-C24 61	Unknown	-0.33	0.33	112.21	213.64	75.30	125.71
20030203182508-C24 62	Unknown	-0.33	0.33	12.70	145.89	18.97	24.22
20030203182508-C24 63	Unknown	-0.33	0.33	27.03	132.99	27.99	41.75
20030203182618-C25 64	Unknown	-0.33	0.33	12.70	62.33	13.08	24.22

Reviewed by:





# Tan Smear Report

**COPY**

Batch ID: smear - 200302031815

Group: E

Device: LB5100 #324920

Batch Key: 5,385

Selected Geometry: 1/4" Stainless Steel

Survey Location: CAMERA IN LAST ROOM

Count Date: 2/3/03

Count Minutes: 1.0


Count Mode: Simultaneous

Operating Volts: 1320

Background (cpm)			Efficiency (%)		
Alpha Rate:	0.10	± 0.10	Alpha:	29.90	± 0.23
Beta Rate:	5.40	± 0.73	Beta:	44.28	± 0.07

<u>Sample ID</u>	<u>Sample Type</u>	<u>Alpha</u> <u>(dpm)</u>	<u>Unc</u>	<u>Alpha MDA</u> <u>(dpm)</u>	<u>Beta</u> <u>(dpm)</u>	<u>Unc</u>	<u>Beta MDA</u> <u>(dpm)</u>
20030203181514-E18 67	Unknown	-0.33	0.33	12.70	4,373.56	99.78	24.22
20030203182845-E19 68	Unknown	16.39	7.49	12.70	3,318.90	86.91	24.22

Reviewed by:





MAR. 26. 2002 11:46AM

TRU SPO

NO.506 P.7

CONTAINER TRANSPORTATION REPORT  
DRUM WASTE PROFILE SHEET

## OLD Container Information

Container Identification: IDRF741202484  
Swepp Barcode: 032696  
Shipping Category: 1001300190  
Test Category: N  
TRUCON Content Code: ID211A  
Package Date: 09-mar-1983  
Gross Weight: 201.4 kg 444.0 lbs  
Gross Weight Error: 0.9 kg 2.0 lbs  
Waste Weight:  
Seal Number: 02484  
Alpha Contam. (dpm): 0.0  
Beta/Gamma Contam. (dpm): 0.0  
Neutron Dose Rate (mrem/hr): 0.0  
Surface Dose Rate (mrem/hr): 2.5

86926

## Unaffected Data Information

Content Code: 001  
Container Type: 001  
Handling Code: CH  
Volume Utilized (percent): 70

Nuclide	Mass (g)	Mass Error (g)
AM241	0.43124	0.17832
PU238	0.00014	0.00008
PU239	1.27359	0.52867
PU240	0.07745	0.0328
PU241	0.00234	0.00106
PU242	0.00058	0.00038
U234	0.02446	0.0134
U235	9.30432	3.83379
U238	4353.71338	1815.10901

Total PU (g): 1.3541  
Fissile Gram Equivalent (Pu239): 10.59301  
Fissile Gram Equivalent Error (Pu239): 4.36934  
Thermal Power (watts): 0.05319  
Thermal Power Error (watts): 0.02199  
Total Alpha Activity (Ci): 1.59844  
Total Alpha Activity Error (Ci): 0.66064  
Plutonium Equivalent (Ci): 1.59655

All radio-assay data is the most recent data.

The assay values have been adjusted per EDF  
RWMC- ~~840~~ (rev. 3) to incorporate the gamma  
spec results. For EPA Hazardous Waste Code,  
Hazardous Constituents, or Hazardous Characteristics,  
please refer to Engineering Design File (EDF) serial  
number: RWMC-803.

RWMC Signature

Role

Date

ANL-W Signature

A-283  
F

Date

JGE-01-2003

**MEMORANDUM INTEROFFICE****INEEL**  
Idaho National Engineering & Environmental Laboratory**Date:** February 13, 2003**To:** Gary Lusk MS 9206 6-4165**From:** John Eisenmenger MS 7113 3-4091**Subject:** Alpha results "TAN TRUPAC-157 smears"  
Lab Sgroup: 01DQ


Five smears were received from TRUPACT-157 by the TRA radioanalytical laboratory. Smears 1 and 4 (from drum #6) were composited into one sample and Smears 7, 2 and 7 (from ICV) were composited into another sample. The samples were analyzed for U234, U235, U238, Pu238, Pu239/240, and Am241 using ACMM-3816. The procedure consists of spiking with isotopic tracers, ashing, digesting with acid and fusing with lithium metaborate. The elements of interest are next separated, purified and mounted for counting by alpha spectroscopy using surface barrier detectors.

A matrix blank (consisting of the same smear material that was used for Smears 7, 2 and 7) and a matrix control (blank filters spiked with known solutions of isotopes of interest) were run with the samples. The samples results were blank subtracted. The control results were within our acceptance criteria.

The results for the samples are attached.

**Analysis by:**

John Eisenmenger  
Radiochemist

**Reviewed by:**

Brian Schuetz  
Radiochemist

cc: Anita Freeman MS 7111  
Rod Hand MS 5210  
Sorenson D J MS 9208  
Clements Thomas MS 2510  
Edelmayer John MS 3428

Uniform File Code: 6404

Disposition Authority: ENV5-c-1

Retention Schedule: Destroy in 75 years

Note: Original disposition authority, retention schedule, and Uniform Filing Code applied by sender may not be appropriate for all recipients. Make adjustments as needed.



ENVIRONMENTAL RESTORATION PROGRAM  
RADIOANALYTICAL ANALYSIS DATA PACKAGE

Case No: N/A  
SDG No.: NA

Lab Name: ALDTRA  
Report No.: JGE-01-2003

INEL ID	Lab Sample ID	Sample Matrix	Anal Type	Sample Value	Sample Uncer	Units	Anal Date	Sample Date	Sample Size	Chem Yield	Detector ID	MDA	DQF
SMEARS 1 & 4	01DQ-01-A	Smear	U234	+8.84E-03	+1.75E-02	PCI/sp1	02/13/03	01/30/03	1	93.1	09	+2.94E-02	
SMEARS 1 & 4	01DQ-01-A	Smear	U235	-1.01E-03	+2.79E-03	PCI/sp1	02/13/03	01/30/03	1	93.1	09	+2.28E-02	
SMEARS 1 & 4	01DQ-01-A	Smear	U238	+1.55E-02	+1.37E-02	PCI/sp1	02/13/03	01/30/03	1	93.1	09	+1.95E-02	
SMEARS 1 & 4	01DQ-01-A	Smear	PU238	+1.18E+00	+1.36E-01	PCI/sp1	02/13/03	01/30/03	1	100.1	27	+4.96E-02	
SMEARS 1 & 4	01DQ-01-A	Smear	PU239/240	+4.88E+01	+3.91E+00	PCI/sp1	02/13/03	01/30/03	1	100.1	27	+6.02E-02	
SMEARS 1 & 4	01DQ-01-A	Smear	AM241	+4.86E+00	+4.28E-01	PCI/sp1	02/13/03	01/30/03	1	90.7	29	+5.66E-02	
SMEARS 7,2&7	01DQ-02-A	Smear	U234	+1.43E-02	+1.75E-02	PCI/sp1	02/13/03	01/28/03	1	84.7	11	+2.01E-02	
BEARS 7,2&7	01DQ-02-A	Smear	U235	-2.18E-03	+4.21E-03	PCI/sp1	02/13/03	01/28/03	1	84.7	11	+2.73E-02	
BEARS 7,2&7	01DQ-02-A	Smear	U238	+7.84E-03	+1.21E-02	PCI/sp1	02/13/03	01/28/03	1	84.7	11	+1.83E-02	
BEARS 7,2&7	01DQ-02-A	Smear	PU238	+3.45E-02	+1.37E-02	PCI/sp1	02/13/03	01/28/03	1	98.6	14	+2.24E-02	
SMEARS 7,2&7	01DQ-02-A	Smear	PU239/240	+1.28E+00	+1.52E-01	PCI/sp1	02/13/03	01/28/03	1	98.6	14	+3.19E-02	
SMEARS 7,2&7	01DQ-02-A	Smear	AM241	+1.35E-01	+2.84E-02	PCI/sp1	02/13/03	01/28/03	1	100.3	13	+1.61E-02	

Analyst: Doo 2-13-03

See Key for Form I.

Comments: Reviewed by: B.K. Schwartz 2/13/03

Idaho National Engineering and Environmental Laboratory

**INTEROFFICE MEMORANDUM**

**Date:** February 5, 2003

**To:** G. L. Lusk MS 9206 6-4165

**From:** T. C. Sorensen *TCS* MS 7111 3-4410

**Subject:** RML GAMMA-RAY ANALYSIS OF TAN TRUPAC-157 SMEAR SAMPLES  
(DATED 01/03) - TCS-003-03

Two sets of smear samples submitted by TAN Operations were counted/screened for radioactivity content by the Radiation Measurements Laboratory (RML) using standardized high resolution gamma-ray spectrometry techniques. The samples were counted for 12 hours in standardized sample geometry. The result of the analysis of the samples is listed on the attached Table 1.

**Note:** Please call if you have any questions or need additional information.  
T. C. Sorensen 3-4410 or Anita Freeman 3-4158

**Attachments:**  
As Stated

**cc:** A. L. Freeman, MS 7111  
C. C. Jensen, MS 7113 *ellg*  
C. D. Morgan, MS 7110  
R. K. Murray, MS 7111  
D. J. Sorensen, MS 9208  
T. C. Sorensen File

Bliss Sample Group Id: 01DQ

Uniform File Code: 6404  
Disposition Authority: ENV5-c-1  
Retention Schedule: Destroy record in 75 years

**NOTE:** Original disposition authority, retention schedule, and Uniform Filing Code applied by the sender may not be appropriate for all recipients. Make adjustments as needed.

**Just the FAX!**

**DATE: February 12, 2003**

**TO: Bobby A. Picker  
CO./DEPT: PROJECT MGMT.  
PHONE NO.: 526-1549  
FAX NO.: 526-4902**

**FROM: Anita L. Freeman  
CO.: TRA Radioanalytical  
PHONE NO: (208) 533-4158  
FAX NO.: (208) 533-4488**

**SUBJECT: TAN TRUPAC-157 SMEARS**

Attached is a copy of the gamma data for the TAN Trupac-157 smears.

TCS-003-03

Radiochemistry is currently counting these samples. John Eisenmenger (3-4091) said he will call you regarding the actinides.

TABLE 1

## RADIATION MEASUREMENTS LABORATORY

## GAMMA-RAY SCREEN ANALYSIS RESULTS

TAN TRUPAC-157 SMEAR SAMPLES 01/2003

<u>Sample ID</u>	<u>RML ID</u>	<u>Manmade Radionuclides</u>	<u>Activity pCi/smpl</u>
DRUM 6 Smears 1, 4	A6020403036	Cs-137	$(4.3 \pm 0.6)E+00$ 2.0 dpm
ICV Smears 7, 2, 7	D5020403037	Co-60 Cs-137	$(2.4 \pm 0.6)E+00$ $(2.6 \pm 0.7)E+00$ 5.3 dpm 5.8 dpm

- Notes:
1. A "None detected" under "Manmade Radionuclides" means that the analyst determined that no manmade true-positive radionuclides were present in the respective sample(s).
  2. The uncertainty associated with any reported activity includes the statistical uncertainty and estimated uncertainties in detector efficiency and the sample geometry (both are typically 5%). Uncertainties are propagated in quadrature and expressed as one standard deviation.
  3. When a sample's matrix differs radically from that of the calibration standard used by the RML, the measured activity may not accurately represent the true radionuclide concentration in that sample. In such cases, a non-zero estimated bias is applied in place of the estimated sample geometry; this bias is not propagated into the total uncertainty and is listed separately.



Cecilia R Hoffman

02/10/03 03:47 PM

To: Thomas L Clements/TLC/CC01/INEEL/US@INEL

cc:

Fax to:

Subject: IDRF741202484

Sorry for the delay, I had software problems this morning.

Attached is the analysis of IDRF741202484. Please call me at 6-4909 if you have any questions.

Cecilia



Analysis of IDRF741202484.doc

## Analysis of IDRF741202484

Two different methods were compared against SAS V. 3.2

- 1) SAS version 3.3.1
- 2) SRAC (INEEL's absolute analysis code - the stand-alone version of SAP)

### SAS V. 3.3.1

- a) SAS V. 3.3.1 was not implemented on the PAN system.
- b) This version improved on the uranium algorithm process.
- c) The mass ratio gamma data was reanalyzed.
- d) The analysis results were identical to SAS V. 3.2.
- e) The material is weapons grade plutonium based on the Pu-241/Pu-239.
- f) Pu-241/Pu-239 mass ratio is 0.19%.
- g) Pu-238/Pu-239 mass ratio was 0.00
- h) The uncertainty associated with Pu-240 is approximately 100%.
- i) The uncertainty associated with Pu-238 is 40%.
- j) There is approximately 1.4 grams of Pu of which 1.3 grams are Pu-239.
- k) The drum primarily contains depleted uranium (4.4 g).
- l) U-235 is present at approximately 9 grams
- m) Am-241 was determined from the Am-241/U-235 mass ratio and it's mass 0.4 g.
- n) The FGE content is 10.6 grams
- o) The TRU alpha activity is 1.6 Ci

### SRAC (stand-alone SAP)

- a) This method relies on a gamma assay to quantify the radioisotopes present in the waste.
- b) The analysis results were similar to SAS V. 3.2 when the statistical uncertainty is taken into account.
- c) There is 1.9 grams of plutonium with 1.8 being Pu-239.
- d) Uranium-238 is present in approximately 4.9 grams.
- e) The drum primarily contains U-238, or depleted uranium.
- f) U-235 is present in 9.4 grams.
- g) The FGE content is 11.2 grams.
- h) The TRU alpha activity is 2.2 Ci.

Reviewing the spectral data indicates that Np-237 is present in a very small quantity (less than 1E-10 grams).

Europium-154 is present in a small quantity (less than 1E-10 grams).

Program: SWEPP Assay System, Version 3.2.1  
Chamber: Drum Assay Chamber  
File: D:\Assaysys\DAC\prod\IDRF741202484.001

Report printed Mon Feb 17 15:39:55 2003  
Active data acquired Wed Mar 06 17:08:56 2002  
Passive data acquired Wed Mar 06 17:10:32 2002  
Background data acquired Wed Mar 06 08:21:22 2002  
Gamma data acquired Wed Mar 06 15:14:00 2002

Recalculation using parameters stored in file.

Container:

Identifier: IDRF741202484  
Type: 55 gallon drum  
Volume: 208.0 liter

Content:

Code: 1  
Type: First-Stage Sludge / Combined Sludge  
Net Weight: 180.5 kg

Bias Correction:

Coefficients:

B0 = (0.0 ± 0.0)                      B1 = (1.550 ± 0.136)                      B2 = (0.0 ± 0.0)  
COV(B0, B1) = 0.0                      COV(B0, B2) = 0.0                      COV(B1, B2) = 0.0  
Contribution to total Pu mass uncertainty: ± 0.119 g

Matrix Precision:

Coefficients: A0 = 0.0      A1 = 0.40      A2 = 0.0  
Contribution to total Pu mass uncertainty: ± 0.54 g

Measurement Results:

Total Pu mass: (1.35 ± 0.56<0.09>) g                      (Note 1)  
U-234 mass: (0.0245 ± 0.0134) g                      (Note 2)  
U-235 mass: (9.3 ± 3.8) g  
U-238 mass: (4.35 ± 1.82)E+3 g  
Pu-238 mass: (1.42 ± 0.81)E-4 g                      (Note 3)  
Pu-239 mass: (1.27 ± 0.53) g  
Pu-240 mass: (0.077 ± 0.033) g  
Pu-241 mass: (2.34 ± 1.06)E-3 g  
Pu-242 mass: (5.8 ± 3.8)E-4 g  
Am-241 mass: (0.431 ± 0.178) g                      (Note 4)  
Thermal power: (0.053 ± 0.022) Watts  
Thermal power density: (7.2 ± 3.0)E-3 Watts/ft\*\*3  
Total activity: (1.84 ± 0.76) Ci  
Alpha activity: (1.60 ± 0.66<0.09>) Ci  
TRU activity: (1.60 ± 0.66) Ci  
TRU activity concentration: (8.8 ± 3.7)E+3 nCi/g  
Pu Equivalent Curies: (1.60 ± 0.66) Ci  
Fissile Gram Equivalent: (10.6 ± 4.4) g

Notes:

- 1 - Determined from Active Assay data.
- 2 - Determined from process knowledge.
- 3 - Default mass fractions used for Pu isotopic masses.
- 4 - Determined from U-235 Mass Ratio.



## **Appendix B**

### **TRUPACT-II 157 Payload #6469 Assembly Documents**

[Electronic Copy of Appendix B](#)

# Payload Assembly Transportation Certification Document, PATCD

Pack:PK102013

WMS Payload Num:  
6469

Shipment Num:IN020271

TRUPACT OCA Body Num:157  
TRUPACT OCA Lid Num:157

Date ICV Closed:22-AUG-2002 00:00  
Current Date:23-AUG-2002 12:55

Contact Dose Rate (mrem/hr):.5

2 Meter Dose Rate (mrem/hr):.5

Cab Dose Rate (mrem/hr):

Type of Payload:Drums

Payload Wgt + Err (lb):5714

Pallet, etc Wgt (lb):265

Total Payload Wgt (lb):5979

TRUPACT Wgt (lb):12731

Loaded TRUPACT Wgt (lb):18710

Trailer Position:B

Trailer Number:20

Subassembly:IN021909												Proc:TPR	1648	TRUPACT-II Assembly Operation	Rev:20				
TOP		Waste Container		IDC	Weight (lb)	Err	FGE (g)	Err	Decay Heat (W)		Err								
Pos																			
1	IDRF004102254	376	126	2	44.0321	8.4488	0.0175	0.1197	0.1056	0.0166	0.0167								
2	IDRF004102263	376	132	2	43.2914	8.2743	0.1053	0.1056	0.1053	0.0167	0.0182								
3	IDRF004002801	376	137	2	43.5645	8.3246	0.1335	0.1053	0.1335	0.0182	0.0169								
4	IDRF004101890	376	143	2	43.5543	8.3790	0.1157	0.1157	0.1157	0.0220	0.0057								
5	IDRF004002790	376	160	2	42.8177	8.1795	0.0532	0.0532	0.0532	0.0220	0.0137								
6	IDRF741202484	001	473	2	10.5830	4.3693	0.0137	0.0137	0.0137	0.0057	0.0057								
7	IDRF741202088	001	499	2	5.5018	2.2747													
					Subtotals:1670	5	233.3548												
Subassembly:IN021910												Total Payload Wgt (lb):5707	Top Wgt + Bot Wgt + Palette Wgt (lb):5972	Total Payload Wgt Err (lb):7	Total Payload Wgt + Err (lb):5979	Total FGE (g):269.3990	Total FGE Err (g):21.2437	2 X Total FGE Err (g):42.4674	Total FGE + 2 X FGE Err (g):311.8884
BOTTOM		Waste Container		IDC	Weight (lb)	Err	FGE (g)	Err	Decay Heat (W)		Err								
Pos																			
8	IDRF741205405	001	516	2	20.1167	8.2684	0.0973	0.2365	0.0732	0.0312	0.0018								
9	IDRF741201616	001	545	2	2.4350	1.0469	0.0038	0.0038	0.0038	0.0018	0.0021								
10	IDRF741201718	001	577	2	7.2532	3.0120	0.0047	0.0047	0.0047	0.0021	0.0049								
11	IDRF074221338	002	584	2	1.2985	0.5860	0.0114	0.0114	0.0114	0.0049	0.0005								
12	IDRF074700394	007	591	2	2.1340	0.9197	0.0010	0.0010	0.0010	0.0010	0.0044								
13	IDRF074700411	007	612	2	0.4436	0.2258	0.0005	0.0005	0.0005	0.0005	0.0044								
14	IDRF741204650	001	612	2	2.3632	0.9865	0.0104	0.0104	0.0104	0.0044	0.0044								
					Subtotals:4037	5	38.0442												
					Totals:5707	7	269.3990					21.2437							


Store Close

00000012

Payload Assembly, Configure 14-Pack

Assembly/Pack Number: PK102013

Date: 15-AUG-2002 22:18



Subassembly Number	Pos	Container Number	IDC	Weight (lb)	Err	DoseRate (mm/hr)	FGE (g)	DecayHeat (W)	Err
IN021509	1	IDRF004102254	376	132	2	2	44.0321	0.1197	0.0175
	2	IDRF004102263	376	137	2	5.5	43.2914	0.1056	0.0166
	3	IDRF004002801	376	137	2	1.5	43.5645	0.1083	0.0167
	4	IDRF004101890	376	143	2	4	43.5543	0.1335	0.0182
	5	IDRF004002790	376	160	2	3	42.8177	0.1157	0.0169
	6	IDRF741202484	001	473	2	0	10.5330	0.0532	0.0220
	7	IDRF741202088	001	499	2	1	6.5018	0.0137	0.0057
			Subtotal: 1670	5	17	233.3548			
IN021910	8	IDRF741205405	001	516	2	19	20.1167	0.2365	0.0873
	9	IDRF741201615	001	545	2	20	2.4350	0.0732	0.0312
	10	IDRF741201718	001	577	2	.1	7.2532	0.0038	0.0016
	11	IDRF074221338	002	584	2	.2	1.2985	0.0047	0.0021
	12	IDRF074700394	007	591	2	.5	2.1340	0.0107	0.0114
	13	IDRF074700411	007	612	2	0	0.4436	0.0010	0.0005
	14	IDRF741204650	001	612	2	0	2.3632	0.0104	0.0044
			Subtotal: 4037	5	39.8	38.0442			

Pallet, etc Weight (lb): 265	2 X Err
Total Assembly: 5972	42.4874
Totals, including Errors: 5979	269.3950
	311.8964
Limits, including Errors: 6545	325.0000
	200

Add Damage Remove Damage Save Config Cancel

Shipment # IP020271(b) Rev. # 0  
TRUPACT #: 157  
ETRAPAC Payload ID# 6464  
Tractor # 20 Trailer # 20  
Trucking Company: TRI-STATE or CAST  
TCO: 130000 Date: 8/14/02

# Assembly

Assembly Type: 55-Gallon Drum

Assembly ID: IN021910

● Main Menu

● Assembly  
Menu

● Create  
Payload

● Create  
Shipment

● Report Menu

Container ID Click to Remove	Shipping Category	Weight / Error	FGE / 2x Error	Decay Heat / Error
<u>IDRF074221338</u>	1001300190	584.1045 / 2.0066	1.3 / 1.1800	0.0047 / 0.0021
<u>IDRF074700394</u>	1001300190	591.0944 / 2.0066	2.13 / 1.8400	0.0114 / 0.0049
<u>IDRF074700411</u>	1001300190	612.108 / 2.0066	0.44 / 0.4800	0.001 / 0.0005
<u>IDRF741201615</u>	1001300190	545.0981 / 2.0066	2.43 / 2.1000	0.0732 / 0.0312
<u>IDRF741201718</u>	1001300190	577.0926 / 2.0066	7.25 / 6.0200	0.0038 / 0.0016
<u>IDRF741204650</u>	1001300190	612.108 / 2.0066	2.36 / 2.0000	0.0104 / 0.0044
<u>IDRF741205405</u>	1001300190	516.0803 / 2.0066	20.12 / 16.5400	0.2365 / 0.0973
<b>Total</b>		4037.686	36.03	

Mark as  
complete



OK

0000013

# Assembly

Assembly Type: 55-Gallon Drum

Assembly ID: IN021909

● Main Menu

● Assembly  
Menu

● Create  
Payload

● Create  
Shipment

● Report Menu

Container ID Click to Remove	Shipping Category	Weight / Error	FGE / 2x Error	Decay Heat / Error
<u>IDRF004002790</u>	3001090528	160.0169 / 2.0066	42.82 / 16.3600	0.1157 / 0.0169
<u>IDRF004002801</u>	3001090528	137.0187 / 2.0066	43.56 / 16.6400	0.1063 / 0.0167
<u>IDRF004101890</u>	3001090528	143.0163 / 2.0066	43.55 / 16.7600	0.1335 / 0.0182
<u>IDRF004102254</u>	3001090528	126.0158 / 2.0066	44.03 / 16.9000	0.1197 / 0.0175
<u>IDRF004102263</u>	3001090528	132.0134 / 2.0066	43.29 / 16.5400	0.1056 / 0.0166
<u>IDRF741202088</u>	1001300190	499.0797 / 2.0066	5.5 / 4.5400	0.0137 / 0.0057
<u>IDRF741202484</u>	1001300190	473.0828 / 2.0066	10.59 / 8.7400	0.0532 / 0.0220
Total		1670.244	233.34	

Mark as  
complete



OK

## Payload Assembly Transportation Certification Document, PATCD

PACK: PK102013

Shipment Num: JN02Q271

**Date /CV Closed:**

Current Date: 22-AUG-2002 19:59

**Contact Dose Rate (mrem/hr):**

Meter Dose Rate (mm/hr):

**Cab Dose Rate (mm/hr):**

Trailer Number: 20

### Type of Payload: Drums

Payload Wgt + Err (lb):5714

**Pallet, etc Wgt (lb): 265**

Total Payload Wgt (lb): 5979

TRUPACT Wgt (lb): 12731

Loaded TRUPACT Wgt (lb): 18710

Trailer Position: B

0

[illegible]

**Close**

Store

**Close**

B-5

Washed loading  
up Brownman  
20/22/02

# Shipment Summary Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 5 of 5

62000000

TRUPACT Number:	157	ICV Closure Date:	08/22/2002	DOT Description:	Waste Radioactive Material, Fissile, N.O.S, 7, UN2918			
Assembly	Container Number	Total Dose Rate (mR/hr)	Hazardous Codes	Radionuclides	Total Activity (TBq)	PE Curies	Weight (kg)	
IN021910	IDRF074221338	2	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U- 238*/ U-233	9.355E-03	1.431E-01	264.90	
	IDRF074700394	.5	D006 D007 D008 D009 D010 D011 D032 F001 F002 F005 F006 F007 F009	*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U- 238*/ U-233	2.188E-02	3.475E-01	268.07	
	IDRF074700411	0	D006 D007 D008 D009 D010 D011 D032 F001 F002 F005 F006 F007 F009	*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U- 238*/ U-233	3.349E-03	3.171E-02	277.60	
	IDRF741201615	20	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U- 238*/ U-233	8.369E-02	2.190E+00	247.21	
	IDRF741201718	.1	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U- 238*/ U-233	5.010E-03	1.096E-01	261.72	
	IDRF741204650	0	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U- 238*/ U-233	1.863E-02	3.174E-01	277.60	
	IDRF741205405	19	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	*AM-241 PU-238 PU-239 PU-240 PU-241 PU-242 U-234 U-235*/ CS-137 SR-90 U- 233 U-238	3.914E-01	7.168E+00	234.05	
				Assembly:	*AM-241 PU-238 PU-239 PU-240 PU-241 PU-242 U-234 U-235 CS-137 SR-90 U- 238*/ U-233	5.333E-01	1.031E+01	1,831.15
				TRUPACT:	*PU-238 PU-239 PU-240 PU-241 PU-242 CS-137 SR-90 AM-241 U-234 U-235 U- 238*/ U-233	2.833E+00	3.081E+01	2588.63
				Shipment:	*PU-238 PU-239 PU-240 PU-241 PU-242 CS-137 SR-90 AM-241 U-234 U-235 U- 238*/ U-233	6.053E+00	6.807E+01	5,072.05
				WSPFs: INW211.001, INW216.001, INW218.001				



# Shipment Summary Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 4 of 5

TRUPACT Number: 157 / ICV Closure Date: 08/22/2002 DOT Description: Waste Radioactive Material, Fissile, N.O.S., 7, UN2918

Dose Rate 1m: .5 2m: .5 Surface: .5

Assembly	Container Number	Total Dose Rate (mR/hr)	Hazardous Codes	Radionuclides	Total Activity (TBq)	PE Curies	Weight (kg)
IN021909 /	IDRF004002790 /	3	D005 D007 D008 D009 D011 D022 F001 F002 F005 F006 F007 F009	1*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90*/ U-233 U-234 U-235 U-238	4.376E-01	3.682E+00	72.57
	IDRF004002801	1.5	D005 D007 D008 D009 D011 D022 F001 F002 F005 F006 F007 F009	1*CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90*/ AM-241 U-233 U-234 U-235 U-238	4.325E-01	3.404E+00	62.14
	IDRF004101890	4	D005 D007 D008 D009 D011 D022 F001 F002 F005 F006 F007 F009	1*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90*/ U-233 U-234 U-235 U-238	4.627E-01	4.219E+00	64.86
IDRF004102254 /	IDRF004102254 /	2	D005 D007 D008 D009 D011 D022 F001 F002 F005 F006 F007 F009	1*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90*/ U-233 U-234 U-235 U-238	4.508E-01	3.807E+00	57.15
	IDRF004102263	5.5	D005 D007 D008 D009 D011 D022 F001 F002 F005 F006 F007 F009	1*CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90*/ AM-241 U-233 U-234 U-235 U-238	4.298E-01	3.383E+00	59.87
IDRF741202088	IDRF741202088	1	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	1*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U-238*/ U-233	1.826E-02	4.114E-01	226.34
	IDRF741202484 /	0	D004 D005 D006 D007 D008 D009 D010 D011 D022 F001 F002 F005 F006 F007 F009	1*AM-241 CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 U-234 U-235 U-238*/ U-233	6.815E-02	1.596E+00	214.55
Assembly: 1*CS-137 PU-238 PU-239 PU-240 PU-241 PU-242 SR-90 AM-241 U-234 U-235 U-238*/ U-233					2.300E+00	2.050E+01	757.48

0000078

Table 6.2-1

**Payload Assembly Transportation Certification Document (PATCD)<sup>a</sup>****IDENTIFICATION PARAMETERS**

Shipment #: IN020271  
 Payload Assembly #: 6469  
 Packaging OCA Body/Lid #: 157  
 Governing Payload Shipping Category: N/A  
 Governing Payload Shipping Category Decay Heat Limit: N/A  
 Governing Hydrogen/Flammable Gas Generation Rate Limit: N/A  
 Type of Payload: 55-Gallon  
 Date ICV Closed: 8/22/02

**TOP PAYLOAD ASSEMBLY COMPOSITION**

Container ID	Weight (lbs)	Error (lbs)	Decay Heat (watts)	Error (watts)	Fissile Mass (FGE)	2x Error (FGE)	Hydrogen Flammable Gas Generation Rate	Flammability Index
IDRF004002790	160.0	2.01	0.12	0.0169	42.82	16.36	1.91E-10	1261
IDRF004002801	137.0	2.01	0.11	0.0167	43.56	16.64	2.62E-10	1730
IDRF004101890	143.0	2.01	0.13	0.0182	43.55	16.76	1.40E-10	924
IDRF004102254	126.0	2.01	0.12	0.0175	44.03	16.90	1.85E-10	1221
IDRF004102263	132.0	2.01	0.11	0.0166	43.29	16.54	6.26E-10	4133
IDRF741202088	499.1	2.01	0.01	0.0057	5.50	4.54	1.85E-09	3141
IDRF741202484	473.1	2.01	0.05	0.0220	10.59	8.74	7.17E-09	12200
Subtotal (B)	1670.2		0.65		233.34			
Subtotal RMS Error (D)		5.3						

**BOTTOM PAYLOAD ASSEMBLY COMPOSITION**

Container ID	Weight (lbs)	Error (lbs)	Decay Heat (watts)	Error (watts)	Fissile Mass (FGE)	2x Error (FGE)	Hydrogen Flammable Gas Generation Rate	Flammability Index
IDRF074221338	584.1	2.01	0.00	0.0021	1.30	1.18	6.31E-10	1074
IDRF074700394	591.1	2.01	0.01	0.0049	2.13	1.84	1.54E-09	2615
IDRF074700411	612.1	2.01	0.00	0.0005	0.44	0.48	1.36E-10	232
IDRF741201615	545.1	2.01	0.07	0.0312	2.43	2.10	9.86E-09	16779
IDRF741201718	577.1	2.01	0.00	0.0016	7.25	6.02	5.08E-10	865
IDRF741204650	612.1	2.01	0.01	0.0044	2.36	2.00	1.41E-09	2395
IDRF741205405	516.1	2.01	0.24	0.0973	20.12	16.54	4.38E-10	746
Subtotal (A)	4037.7		0.34		36.03			
Subtotal RMS Error (C)		5.3						

**PAYLOAD TOTALS**

Weight of Pallets, Reinforcing Plates, Slip Sheets, Guide Tubes, Adjustable Slings, etc. (E) 265 lbs.  
 Total (A+B+E) Weight 5972.9 lbs.  
 Total (A+B) Decay Heat 0.9887 Watts  
 Total (A+B) Fissile Mass 269.3700 FGE  
 Bottom Assembly Weight + Subtotal RMS Error (A+C) 4042.99 lbs.  
 Top Assembly Weight + Subtotal RMS Error (B+D) 1675.55 lbs.  
 Total Weight + Total RMS Error 5980.4 lbs.  
 Total Fissile Mass + Total RMS Error 311.8535 FGE

Total Decay Heat + RMS Error 1.1004 watts**PAYLOAD CERTIFICATION PARAMETERS**

Parameter	Initials
Decay Heat + Error of Each Analytical Category Payload Container Less Than or Equal to Governing Limit	<u>MV</u>
Hydrogen/Flammable Gas Generation Rate of Each Test Category Payload Container Less Than or Equal to Governing Limit	<u>MV</u>
Flammability Index of Each Payload Container Less Than or Equal to 50,000	<u>MV</u>
Bottom Weight Greater Than or Equal to Top Weight	<u>MV</u>
Total Weight plus RMS Error Less Than or Equal to 7265 lbs.	<u>MV</u>
Decay Heat plus RMS Error Less Than or Equal to 40 Watts	<u>MV</u>
Fissile Mass (Pu-239 FGE) plus RMS Error Less Than or Equal to <u>325</u> FGE	<u>MV</u>

I certify that the above payload assembly meets all the requirements for shipment as stated in the TRAMPAC, current revision. The payload assembly is approved for shipment.

*Michael R. Fisher*  
TRANSPORTATION CERTIFICATION OFFICIAL

1 8-23-02  
/ DATE

a Follow instructions in Section 6.2

0000111



## **Appendix C**

### **Operating Procedures for Recovery Operations**

[Electronic Copy of Appendix C](#)

# PRE-JOB BRIEFING CHECKLIST

8/2001  
v. 06

Page 1 of 2

Job Title: TRUPACT 157 OPERATIONS Procedure or Tracking #: TPR-6230

Name/Title of Person Conducting Briefing: K. KYNASTON Date/Time: 1-23-03 1000

**The objective of a good pre-job briefing is to communicate an understanding of scope, hazards, and mitigation to enable the safe completion of work. Follow MCP-3003 for requirements. Additional Radiological Work Permit requirements found in box 10, page 2.**

Initial each box upon completion of the section during the pre-job briefing. Mark N/A in the comment box if this section is not applicable to this job. Initials

**1. Discuss Scope of Work to be Performed and Limiting Conditions** KL

Comments:

**2. Review Hazards of the Job and Mitigation of those Hazards (JSA's, Permits, LO/TO)** KL

Comments:

**3. Review Work Procedures and Initial Conditions Involved** KL

Comments:

**Discuss Emergency Escape Routes** KL

Comments:

**5. Discuss Roles and Responsibilities, Stop Work, Training, and Work Restrictions** KL

Comments:

**6. Discuss Needed Tools and Equipment** KL

Comments:

**7. Discuss Safety, Radiological (see box 10), Environmental Requirements/Wastes** KL

Comments:

**8. Discuss Error Likely/Feedback/Lessons Learned** KL

Comments:

**Summarize Scope, Hazards, and Responsibilities** KL

Comments:

# PRE-JOB BRIEFING CHECKLIST

1/2001  
.06

Page 2 of 2

Title: TRIPACT 157 PROCESSING

Procedure or Tracking #: TRP - 6230

10. Minimum Radiological Work Permit (RWP) Requirements				Additional Notes and Comments and other Building/Equipment/Process specific pre-job checklists covered.		
Scope of work Radiological conditions of the workplace Procedural and RWP requirements Special radiological control requirements Radiologically limiting conditions (may void RWP) Radiological control hold points Communication & coordination with other groups Housekeeping and final cleanup provisions Emergency response provisions						
Print Names of Workers	Training (1)	Badge No.	Craft or Job Title	Company Name (If not INEEL)	Briefing Date	Worker's Initials (2)
JAKE GREEN	W	78007	OPS		1-23-03	EG
RICK Sorenson	NA	27571	Radcon		1-23-03	RA
Gary L. Lusk	NA	56428	Radcon		1-23-03	GL
Ryan CLOTT	NA	63544	OPS		1-23-03	RC
W. Wadsworth	W	52410	E.O.		1/23/03	WW
Jimmy Hernandez	W	58172	Mech.		1/23/03	JH
Andy Armer	W	60479	EO		1-23-03	AA
Rocky Allen	W	56604	Mech.		1-23-03	RA
Rob BARE	W	37396	EO		1-23-03	RB
REX GINN	W	33234	HCO		1-23-03	RG
Lyle McVilay	W	51945	Rct.		1-23-03	LM
DAN D. CHESTER	W	62531	CARP		1-23-03	DC

- (1) Supervisor initials to verify employee's required training for planned work is current. Mark N/A for not applicable.  
 (2) Worker's initials indicate attendance at the pre-job briefing and satisfactory understanding of all items discussed.

By my signature, I indicate that I have conducted the pre-job briefing covering all items indicated above concerning the requirements specified for the work to be performed.

Person Conducting Briefing: [Signature]

Date/Time: 1-23-03 1100



3/2000  
.01

# PRE-JOB BRIEFING ATTENDANCE RECORD

Page 3 of 3

Work Documentation Tracking/Procedure Number: TPR-6230




Attach filled out form to applicable work control/permit documentation prior to starting work OR file as required by area/organizational procedures. Make copies as necessary.

Print Names of Workers	Training (1)	S/Visitor Badge No.	Craft or Job Title	Company Name (2)	Briefing Date	Worker's Initials (3)
Ilene Harrell	MC	45638	Ops		1/23/03	JH
BLAKE F MCMURTRY	MC	44306	CARPENTER		1-23-03	BFW
DARIS WEIMER	MC	46876	OPS		1-23-03	DW
Lewis Bird	MC	52447	RCT		1-23-03	LB
Farrell Bush	MC	61058	RCT		1/23/03	FB
Jonathan Ely	MC	86250	RCT		1/23/03	JE
McI Saunders	MC	40535	SO		1/23/03	MS
Kory Newsom	MC	60271	Inst Tech		1/23/03	KN
Robin Killian	MC	77456	Ops		1/23/03	RK
EC JUSTICE	MC	85504	QI		1/23/03	ECJ
MICHAEL GALASSI	MC	67558	SO		1/23/03	MG
Jody L. Schmalebeck	MC	52993	SO		1-23-03	JLS
Jon D. Johnston	MC	62673	RCT		1-23-03	JDN
Tobin Mott	MC	76252	IH		1/23/03	TM
Scott Hulse	MC	59289	OPS		1/23/03	SH
Bruce Shively	MC	39235	HEO		1-23-03	BS
JD Westfall	MC	40730	Inst.		1-27-03	JDW
Leon BUTLER	MC	34647	HEO		1-27-03	LB

- Supervisor initials block verifying employee's training required to complete the planned work is current, mark N/A for not applicable when special training (ES&H or other) not required.
- Briefing attendee required to fill this block if other than company C-3, may leave blank for company employees.
- Worker's initials to indicate attendance at pre-job briefing and understanding for all items discussed.

412.11  
09/12/2002  
Rev. 09

## DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS) DOCUMENT ACTION REQUEST (DAR)

1. Document ID: TPR-6230		Current Revision ID: 0		See Block 8 for DAR # Info.	
2. Document Title: TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN					
3. Requester: C. Posegatte		Phone: 6-0188	MS: 9602	E-mail: cposegat	S No.: 60227
4. Type: <input checked="" type="checkbox"/> Document <input type="checkbox"/> Drawing		5. Type of action: <input type="checkbox"/> Create <input checked="" type="checkbox"/> Revise <input type="checkbox"/> Cancel			
6. Field Change: <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, will the change be: <input checked="" type="checkbox"/> Permanent or <input type="checkbox"/> Temporary? If Temporary, enter the field change duration:					
7. Proposed Action:					
Item	Page No./ Section/Zone	Description		Justification	
1	pg 7 stp 3.1.1	Add 'L Industrial Hygiene (IH)'		forgot to list	
2	pg 8	Remove 'wall mounts #1 and 2'		Wall mounts #1 & 2 will not be used	
8. Proposal Approval: <input checked="" type="checkbox"/> Accepted <input type="checkbox"/> Deferred <input type="checkbox"/> Rejected If rejected, indicate reason: _____				DAR No.: 97129 (For Accepted Proposals Only!)	
Document Owner Printed Name: Kevin Streeper				Signature:  Date: 11/27/02	
Is this a minor document change? <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, proceed to Block 14. (For Operations procedures, go to Block 11.)					
9. Management Approval (Excluding drawings, minor changes, & field changes):					
Printed Name: <u>HAO 11/27/02</u> Signature: <u>N/A 11/27/02</u> Date: _____					
10. Implementation Actions – Will the proposal require:					
Hazard mitigation per MCP-3562 or MCP-3571? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Training? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Procurement activities? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Building modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Other: _____					
11. Include a list of reviewers and review comments and resolutions with this form or have reviewers sign below.					
Printed Name		Discipline	Org. No.	Signature	Date
John Hansen		Operation	5240		11-27-02
SHAUN COMBA		IH	5240		11-27-02
12. Is document a TPR or EAR? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, indicate procedure validation method used: <input type="checkbox"/> Formal Walkdown <input checked="" type="checkbox"/> Tabletop Analysis <input type="checkbox"/> Limited Trial Use/Field Use <input type="checkbox"/> Partial Validation					
13. <input checked="" type="checkbox"/> Change does not affect a permitted area, TSD facility, or VCO component. (RCRA evaluation NOT required. Proceed to Block 14.) <input type="checkbox"/> Change does affect a permitted area, TSD facility, or VCO component. Is RCRA permit/application modified: <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> Unknown If Yes or Unknown, attach completed Form 435.29 or reference form's location here: _____					
Kevin Streeper		Kevin Streeper		12-2-02	
Evaluator Printed Name		Evaluator Signature		Date	
Is VCO component affected? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, contact the VCO Program Office for direction.					
14. USQ Screening: (To be completed only after final document review.) List any associated change forms: _____					
Is USQ screening required? (See Instructions) <input type="checkbox"/> Not Required (Proceed to Block 15) <input checked="" type="checkbox"/> Required (Submit document and DAR to qualified USQ screener and attach USQ screening form.) 03-USQ-TAN-1075 <input type="checkbox"/> USQ Evaluation Required? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes attach evaluation.					
15. Does this action qualify as a periodic review? <input checked="" type="checkbox"/> No C-4 <input type="checkbox"/> N/A					

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230 Revision: 0 Page: 1 of 52
---	--

Test Area North	Technical Procedure	For Additional Info: <a href="http://EDMS">http://EDMS</a>	Effective Date: 11/26/02
-----------------	---------------------	---	--------------------------

Manual: Detailed Operating Procedures for Test Area North  
Operations

USE TYPE 1

Change Number: 96334

TRUPACT S/N 157

PROCEDURE REVIEW REQUIREMENTS					
DISCIPLINE	REVISION	CHANGE	DISCIPLINE	REVISION	CHANGE
TAN/RWMC OPERATIONS	X	X	TAN INDUSTRIAL SAFETY	X	A/R
MAINTENANCE	X	A/R	TAN QUALITY	X	X
LANDLORD	N/A	N/A	TAN ENVIRONMENTAL	N/A	N/A
TAN/RWMC SYSTEM ENGINEER	X	X	TAN RADCON	X	A/R
TAN SAFETY ANALYSIS	X	A/R	TAN INDUSTRIAL HYGIENE	X	A/R
TRAINING	N/A	N/A	EMERGENCY PLANNER	N/A	N/A
SITE QUALITY ASSURANCE OFFICER (SQAO)	X	A/R	SAFEGUARDS (NMC)	N/A	N/A
			TAN CRITICALITY ENGINEER	N/A	N/A

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 2 of 52**CONTENTS**

1.	INTRODUCTION .....	4
1.1	Purpose .....	4
1.2	Scope and Applicability.....	4
2.	PRECAUTIONS AND LIMITATIONS.....	4
3.	PREREQUISITES .....	7
3.1	Planning and Coordination .....	7
3.2	Performance Documents.....	8
3.3	Special Tools, Equipment, Parts, and Supplies .....	8
3.4	Field Preparations .....	10
4.	INSTRUCTIONS.....	10
4.1	General.....	10
4.2	TRUPACT-II Trailer Preparations .....	11
4.3	Releasing Tiedowns.....	12
4.4	Transfer the TRUPACT-II.....	13
4.5	Unloading a Payload Assembly.....	14
4.6	ICV Lid Installation.....	25
4.7	ICV Removal from the OCV .....	28
4.8	OCV Lid Installation .....	30
4.9	Transfer TRUPACT-II to the Transport Trailer .....	34
4.10	Releasing the TRUPACT-II Trailer.....	37
4.11	Post Performance Activities .....	38
5.	RECORDS .....	39
6.	REFERENCES .....	40

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier:	TPR-6230
	Revision:	0
	Page:	3 of 52

7.	APPENDIXES .....	41
	APPENDIX A – Procedure Basis .....	42
	APPENDIX B – Comment Sheet .....	49
	APPENDIX C – TRUPACT-II Packaging Weights (Pounds) .....	50
	APPENDIX D – OCV/ICV Inspection and Preparation.....	51

## TABLES

3.1.	TRUPACT-II packaging weights (pounds).....	50
------	--	----

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230 Revision: 0 Page: 4 of 52
---	--

## 1. INTRODUCTION

### 1.1 Purpose

The purpose of this document is to provide instructions for the loading and unloading operation of the Transuranic (TRU) Package Transporter (TRUPACT)-II and the removal of the Inner Containment Vessel (ICV) from the Outer Containment Vessel (OCV).

### 1.2 Scope and Applicability

This procedure applies to personnel loading and unloading TRUPACT-IIs and removing the ICV from the OCV. See Appendix A for Procedure Basis.

TRUPACT-II operations performed in this procedure are in compliance with requirements identified in Department of Energy (DOE)/WIPP 02-3183, CH Packaging Program Guidance; DOE/WIPP 02-3184, CH Packaging Operations Manual; and DOE/WIPP 02-3185, CH Packaging Maintenance Manual.

## 2. PRECAUTIONS AND LIMITATIONS

- 2.1 When handling TRU drums, every effort must be made to ensure continued container integrity.
- 2.2 If function-impairing damage is present, the damaged component will be replaced per a Standard (STD)-101, Integrated Work Control Process, work document and in accordance with DOE/WIPP 02-3183/02-3184 and 02-3185 before further use.

(WIPP)

- 2.3 The Adjustable Center of Gravity Lifting Fixture (ACGLF) is designed to handle the weight of an OCV lid, an ICV lid, an empty ICV assembly, or a payload. Payloads include 14-pack or dummy drums. The ACGLF is not designed to handle the weight of a TRUPACT-II container (loaded or empty), a loaded Outer Containment Assembly (OCA) or a loaded ICV. (A forklift is used to move TRUPACT-II containers between the transport vehicle and the platform.)

(WIPP)

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN****Identifier:** TPR-6230  
**Revision:** 0  
**Page:** 5 of 52

- 2.4 The ACGLF with short legs may be set directly on the floor and disconnected from the crane. The ACGLF with long legs can be set on the floor but should have minimal vertical support from the crane to prevent tipping.
- 2.5 The TRUPACT-II container lids must not be interchanged, or the original Certification Leak Test is invalidated.
- (WIPP)
- 2.6 Personnel performing this procedure must wear safety shoes.
- (JSA)
- 2.7 The lifts in this procedure are critical lifts, pre-engineered production lifts, or ordinary lifts per DOE-STD-1090-2001, DOE Hoisting and Rigging Standard.
- (JSA)
- 2.8 IF fossil-fueled vehicles are operating continuously, without the ventilation hoses attached, for more than approximately 10 minutes inside the building, THEN a carbon monoxide monitor must be obtained from Industrial Hygiene (IH) for use.
- (JSA)
- 2.9 Movement of the ACGLF counterweights must not occur with the free load above approximately 6 in.
- 2.10 The interior of the TRUPACT-II is a non-permit confined space. Only hands/arms may break the plane of the TRUPACT-II interior. Contact IH for further direction if the face must break the plane.
- (JSA)
- 2.11 No part of the body may be placed beneath a suspended load with the following exceptions: ACGLF adjustment/leg changes and guiding leg insertion.
- (JSA)
- 2.12 When moving TRUPACT-II containers by forklift, a minimum of two spotters (one on each side of the TRUPACT-II/forklift) must be used.
- (JSA)
- 2.13 During ACGLF operation, non-essential personnel must stay clear of the ACGLF.
- (JSA)

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230 Revision: 0 Page: 6 of 52
---	--

- 2.14 Leather gloves are required when working with hot surfaces.

(JSA)

- 2.15 Nitrile, latex, or butyl rubber gloves and safety glasses with side shields must be worn when using nickel bearing lubricant or anti-seize lubricant.

(JSA)

- 2.16 Heat stress monitoring must be performed. Heat stress stay times vary depending upon environmental conditions, work activities, and personal protective equipment (PPE), and must be re-evaluated as conditions change per MCP-9240, "Managing Heat and Cold Stress at TAN."

(JSA)

- 2.17 Procedure steps or sections may be performed out-of-sequence as directed. The Technical Lead (TL)/Shift Supervisor (SS) marks the steps or sections to be performed out-of-sequence with a "go to \_\_\_\_\_" and records the justification for no adverse impact on the conduct of the procedure in Appendix B, Comment Sheet. After the last out-of-sequence step, the TL/SS marks "return to Step \_\_\_\_\_".

- 2.18 Procedure steps or sections may be re-performed as directed by the TL/SS. The TL/SS marks the step(s)/section(s) to be re-performed with "step(s)/section(s) \_\_\_\_\_ are to be re-performed and resigned", and enters the number of the step(s)/section(s) to be re-performed in the blank and records the justification for no adverse impact on the conduct of the procedure entered in Appendix B, Comment Sheet.

- 2.19 Procedure steps or sections may be marked N/A as follows:

- 2.19.1 Non-conditional steps or sections that contain technical safety requirements (TSR) or safety analysis report (SAR) commitments require a Document Action Request (DAR) to mark the step or section N/A.

- 2.19.2 Non-conditional steps or sections NOT involving TSR and SAR commitments may be marked N/A, initialed and dated by the TL/SS, and a written justification entered in Appendix B, Comment Sheet.

- 2.19.3 Conditional steps or sections must be marked N/A and initialed/dated by the person performing the procedure if the conditions stated by the procedure exist.



**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 7 of 52

- 2.20 Procedure steps or sections may be signed or initialed by the TL/SS, Job Supervisor (JS), or PIC based on personal observation, direct report from the performer, or review of controlled records.
- 2.21 Any problems during procedure performance must be entered into Appendix B. Any documents (NCRs, WOs, DRs, etc.) issued to close, track, or resolve comments must be identified in Appendix B.

**3. PREREQUISITES****3.1 Planning and Coordination**

**NOTE:** *The following is a recommended crew (minimum). Manning may be adjusted as required by the TL/SS.*



3.1.1 TL/SS: As a minimum, ensure the following personnel are available:

- A. Job Supervisor (JS) (continuously present at the job site)
- B. TRUPACT-II Operators (SO)
- C. Mechanic (M)
- D. Radiological Control Technician (RCT)
- E. Heavy Equipment Operator (HEO)
- F. Equipment Operators (EO) - 2
- G. Quality Inspector (QI)
- H. Technical Lead (TL)/Shift Supervisor (SS)
- I. TAN Operator (OP).
- J. Carpenter (C)
- K. Fixative Operator (FO)




3.1.2 JS: Conduct a pre-job briefing with personnel conducting this procedure in accordance with MCP-3003, "Performing Pre-Job Briefings and Post-Job Reviews," including TAN-JSA-6230.

**(JSA)**

# TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN

Identifier: TPR-6230  
Revision: 0  
Page: 8 of 52

3.1.3 TL/SS authorize work:

  
TL/SS

4/27/03  
Date

3.1.4 A current Radiological Work Permit is required.

(JSA)

## 3.2 Performance Documents

INTEC-QA-0208, Quality Inspection Plan of TRUPACT-157 Unloading and Loading Recovery Operations at Test Area North (TAN)

PLN-1169, TRUPACT-II Shipping Container 157 Payload Examination Plan

INEEL Form 433.34, INEEL Lift Plan

INEEL Form 433.34A, INEEL Lift Plan Supplement

INEEL Form 441.63, Special Survey Techniques

## 3.3 Special Tools, Equipment, Parts, and Supplies

**NOTE:** *The following materials and equipment are recommended.*

Item	No.	Comments
Hot Shop crane: CRN-HS-902	1	Annual maintenance completed 3/8/02; due 3/8/03
Oman: OMAN-SP-901	1	Annual maintenance completed 2/30/02; due 2/3/03
Video recording camera and video tapes	A/R	As needed to monitor progress, perform inspections, and etc.
Wall mounts #1	1	Annual maintenance completed 7/14/02
Wall mounts #2	1	Annual maintenance completed 7/16/02
Applicable Lift Plans (INEEL Form 433.34)	A/R	Lift Plan numbers: TP 157-02 (ICV Lid Handling) TP 157-03 (Payload Handling)
Torque wrench (0–75 ft-lb range))	1	Required for OCV lock ring and access/thermal plug installation
Torque wrench (0–25 ft-lb range)	1	Required for OCV seal test/vent plug and vent port cover installation

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230  
Revision: 0  
Page: 9 of 52

Item	No.	Comments
Latex/butyl gloves	A/R	Required for applying anti-seize compound and coating O-rings
Razor knife	1	Required for cutting plastic sleeving.
Alpha and Beta-gamma CAMs	1	As required by ALARA review and RWP
RAMs	1	As required by ALARA review and RWP
Inner Containment Vessel	1	Part of TRUPACT-II
Outer Containment Vessel	1	Part of TRUPACT-II
TRUPACT transportation pallet	1	Required for staging the TRUPACT-II
ACGLF with control console	1	Required for lifting lids and payload
ICV/OCV lid storage stands	2	Required for storing lids
ICV cradle	1	Required to support the ICV
OCV/ICV lock ring mechanical advantage tool	1	Required for turning the OCV/ICV lock ring
OCV/ICV lock ring handles	A/R	Required for turning the OCV/ICV lock ring
Vacuum pump and associated gauge	1	Required for drawing vacuum
Smear extension tool	1	Required for surveying cask and internals
Long vent port tool	A/R	Required for OCV vent port
Short vent port tool	A/R	Required for ICV vent port
1" socket with hex head adapter	1	Required for vent/seal port plugs
GO-NO-GO gauge	1	Required to verify installation of TRUPACT-11 tiedowns
3/8" by 1/4" adapter	1	Required for removal/installation of vent port plug
3/8" drive extension bars	A/R	Required for plug extraction
7/16" socket	1	Required for plug removal
5/8" socket	1	Required for plug removal
Nickel-based anti-seize compound	A/R	Required for lubricating lock-ring bolts
TRUPACT-II platform	A/R	Required for staging the TRUPACT-II
Vacuum grease	A/R	Required for lubricating O-rings
Dynamometer	1	Required to pull lids
Sample tool with HEPA filter	1	Required to maintain cleanliness of sampling equipment

# TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN

Identifier: TPR-6230  
Revision: 0  
Page: 10 of 52

## 3.4 Field Preparations

- 3.4.1 The required alpha and beta-gamma CAMs are operating as required by RadCon.

(JSA)

## 4. INSTRUCTIONS

- NOTE 1:** Steps involving rigging the ACGLF to the crane, ICV/OCV lids, or miscellaneous material; installing or changing ACGLF legs; storing the ACGLF; or servicing the forklift may be performed out of sequence, as appropriate.
- NOTE 2:** Procedure steps, sections, and steps within sections may be performed concurrently as directed by the SS/TL.
- NOTE 3:** Procedure steps or sections will be signed off or initialed by the Performer, TL/SS, or JS based on personal observation, direct report from the performer, or review of controlled records.
- NOTE 4:** The Payload Examination Plan (PLN-1169) may be worked at any time during the performance of this procedure at the direction of the TL/SS/JS.
- NOTE 5:** All radiological surveys will be documented in accordance with MCP-139, "Radiological Surveys."
- NOTE 6:** Quality Inspection Plan, INTEC-QA-0208, must be performed in conjunction with this procedure.

### 4.1 General

11-27-03

- 4.1.1 JS: Ensure applicable prerequisites have been met.
- 4.1.2 **GO TO** the appropriate procedure section from the following table based on the desired task to be performed,  
**THEN RETURN TO** this step.

Task	Section to Perform
TRUPACT-II Trailer Preparations	Section 4.2
Releasing Tiedowns	Section 4.3
Transfer the TRUPACT-II	Section 4.4
Unloading a Payload Assembly	Section 4.5
ICV Lid Installation	Section 4.6
ICV Removal from OCV	Section 4.7
OCV Lid Installation	Section 4.8

# TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN

Identifier: TPR-6230  
Revision: 0  
Page: 11 of 52

Task	Section to Perform
Transfer the TRUPACT-II to Transport Trailer	Section 4.9
Releasing the TRUPACT-II Trailer	Section 4.10
Post-Performance Activities	Section 4.11 and EXIT this procedure.

## 4.2 TRUPACT-II Trailer Preparations

**NOTE:** *The TRUPACT-II may be cleaned and/or dried before transport to a designated area as required. The TRUPACT-II may be cleaned with dampened cloths or a soft brush and water. Used cleaning materials should be managed according to site waste management procedures.*

(WIPP, JSA)

12-1-27-03 4.2.1 JS: **RECORD** TRUPACT-II serial number.

TRUPACT-II serial number 157

(WIPP)

### CAUTION

A visual check should be made to ensure that the air bags on the trailer have fully inflated before the trailer is moved. Failure to do so may cause the tires to rub.

(WIPP)

12-1-27-03 4.2.2 EO: **IF** positioning a trailer is required,  
THEN perform the following as applicable.

✓ 4.2.2.1 EO: Position the transport trailer in the designated loading area.

4.2.2.2 EO: Lower the trailer jacks (landing gear), ensuring the trailer is level.

4.2.2.3 EO: Install wheel chocks.

4.2.2.4 EO: Disconnect tractor from trailer.

4.2.2.5 EO: Install trailer stands on free-standing trailers.

(WIPP)

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN****Identifier:** TPR-6230  
**Revision:** 0  
**Page:** 12 of 52**4.3 Releasing Tiedowns****CAUTION**

To prevent damage to the TRUPACT-II exterior, the tiedown assemblies must be completely lowered to the trailer brackets.

**(WIPP)**

**NOTE:** Steps 4.3.1 and 4.3.2 may be performed concurrently or out of sequence as directed.

1/16 1-27-03

4.3.1 M: Release the tiedown assemblies as follows.

**(WIPP)**

~~4.3.1.1~~ Wire brush the threads exposed below the tiedown adjusting nuts and apply a thin film of nickel-based anti-seize to the exposed threads.

~~4.3.1.2~~ Loosen tiedown adjusting nuts, lift tiedown assemblies from TRUPACT-II lugs, rotate away from lugs, and ensure lowering completely to the trailer brackets.

1/16 1-27-03

4.3.2 M: Rotate the four forklift pocket covers to the UP position, or remove the covers and store in a designated area.

**(WIPP)**

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 13 of 52**4.4 Transfer the TRUPACT-II****CAUTION 1**

When using a forklift in conjunction with the TRUPACT-II, the fork tines must fully engage the pockets. This, however, does not imply contact between the fork uprights and the TRUPACT-II exterior.

**CAUTION 2**

Tip-back may damage the exterior surface when utilizing a forklift to relocate a TRUPACT-II.

(WIPP)

- 141-1-27-03 4.4.1 EO: Remove the TRUPACT-II from the trailer and transfer the TRUPACT-II to the designated area as applicable.

**WARNING**

At least two spotters must be present when moving TRUPACT-IIs with the forklift.

(JSA)

- 141-1-27-03 4.4.2 EO/OP: IF transferring a TRUPACT-II to the platform, THEN remove the platform section in front of the TRUPACT-II opening if required.

- 141-1-27-03 4.4.3 EO/OP: Lay clean plastic on the floor where the TRUPACT-II will rest as directed by the JS if not already done.

- 141-1-27-03 4.4.4 EO/OP: Wrap the TRUPACT-II with plastic as directed by the JS and RCT.

- 141-1-27-03 4.4.5 HEO: Place the TRUPACT-II in the platform as directed.

- 141-1-27-03 4.4.6 EO/OP: Replace the platform section as directed.

- 141-1-27-03 4.4.7 EO/OP: Protect the TRUPACT-II from contamination by wrapping it with poly sleeving/sheets as required.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 14 of 52**4.5 Unloading a Payload Assembly**

**NOTE:** *Rotation of the ACGLF weights may be used to assist in the removal of the OCV lid (breaking the seal); however, care must be taken to ensure the weights are positioned in the 180° and 000° positions respectively prior to lifting the lid.*

(WIPP)

KL 1-27-03

- 4.5.1 TL: Designate a PIC prior to hoisting activities for CRITICAL LIFTS in Section 4.5.

PIC: K.L. KYNASTON

(JSA)

KL 1-27-03

- 4.5.2 M/OP: Remove any tamper indicating devices from the OCV lid if required.

KL 1-27-03

- 4.5.2.1 QI: IF TID has been tampered with,  
THEN stop work and notify TL/SS.

WIPP  
0067KL 1-27-03

- 4.5.3 M: Prepare the OCV lid for removal by removing the following components.

(WIPP)

~~4.5.3.1~~ OCV lid lift pocket covers (remain attached to OCV lid).

~~4.5.3.2~~ OCV test port access plug and thermal plug.

~~4.5.3.3~~ OCV vent port access plug and thermal plug.

~~4.5.3.4~~ OCV vent port cover.

~~4.5.3.5~~ OCV seal test port plug.

KL 1-27-03

- 4.5.4 M: Place removed components in labeled storage container.

- 4.5.4.1 QI: **VERIFY** that components have been placed in labeled storage container.

QI signature: K.L. KynastonDate: 1-27-03KL 1-27-03

- 4.5.5 EO/OP: Cover the remaining exposed areas of the OCV lid with plastic as directed by JS/RCT.



**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 15 of 52**CAUTION**

The two ACGLF counterweights must be located at the 180° and 000° positions respectively, prior to lifting an ACGLF or lid (once the lid is free).

(WIPP)

- 11-1-27-05 4.5.6 OP/EO: Rig or ensure the rigging for the ACGLF to the overhead crane per Lift Plan TP 157-01 (INEEL Form 433.34).

(JSA)

- 11-1-27-03 4.5.7 HEO/OP: With the crane and ACGLF, lower the ACGLF legs into the lift pockets on the OCV lid.

(WIPP)

- 11-1-27-03 4.5.8 EO: Ensure the ACGLF legs are locked.

(WIPP)

**CAUTION**

Three operators should be able to rotate the lock ring with reasonable effort. Do not attempt to rotate the OCV or ICV lock ring assembly with mechanical force other than with the TRUPACT-II lock ring tool (an extension to provide additional leverage and control). Care should be used to prevent the lock ring from slamming into the stops.

(WIPP, JSA)

- 11-1-27-07 4.5.9 EO/M/SO: Rotate the lock ring to the UNLOCK position by performing the following:

(WIPP)

- ~~4.5.9.1~~ Install OCV vent port tool (2077-091-A2).
- ~~4.5.9.2~~ Connect sample tool to the vent port tool/sample tool.
- ~~4.5.9.3~~ Retrieve OCV vent port plug into vent port tool.
- ~~4.5.9.4~~ Connect hose to vent port tool/sample tool.

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230
	Revision: 0
	Page: 16 of 52

~~4.5.9.5~~ Start vacuum pump.

**NOTE:** *The TRUPACT-II vacuum should be periodically checked by isolating the pump from the TRUPACT-II.*

~~4.5.9.6~~ Place valve VAC-V3P-1801 in the VACUUM position.

~~4.5.9.7~~ Open valve VAC-SHV-3524B and evacuate to 3-in. Hg minimum.

~~4.5.9.8~~ Remove OCV lock ring bolts.

~~4.5.9.9~~ Manually rotate the OCV lock ring to the UNLOCKED position.

~~4.5.9.10~~ Close valve VAC-SHV-3524B.

~~4.5.9.11~~ Place valve VAC-V3P-1801 in the OFF position.

~~4.5.9.12~~ Stop vacuum pump.

~~4.5.9.13~~ Disconnect hose from sample tool.

~~4.5.9.14~~ Remove vent port tool/sample tool.

ML: 1/22/03  
4.5.10 RCT: Perform survey of vent port tool/sample tool.

(JSA)

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 17 of 52**CAUTION 1**

When lifting the OCV lid by the lift pockets, the load exerted on the lift pockets must not exceed 7,500 lb (10,000 lb minus ACGLF at 2,500 lb).  
An indication of 10,000 lb or greater may indicate OCV lid binding.

(WIPP)

**CAUTION 2**

The two ACGLF counterweights must be located at the 180° and 000° positions respectively, prior to lifting an ACGLF or lid.

(WIPP)

- 10/1-27-03 4.5.11 HEO/OP: Using the crane, remove OCV lid to a height appropriate for the RCT to survey between the OCV lid and the ICV body.

(WIPP)

- NA 4.5.11.1 W 1-27-03 EO/OP: IF the lid is stuck,  
THEN manually apply pressure to the sides of the lid,  
OR adjust the ACGLF counterweights to help remove the lid.

(WIPP)

- NA 4.5.11.2 W 1-27-03 HEO: IF the lid does separate from the TRUPACT-II,  
THEN adjust the ACGLF counterweights to 180° and 000° respectively, and remove the OCV lid.

**WARNING**

No part of the body may be placed beneath the suspended lid. A survey extension tool must be used to obtain contamination smears.

(JSA)

W 1-27-03 **NOTE:** Step 4.5.12.1 may be performed out of sequence or concurrently, as directed.

- 4.5.12 RCT: Perform contamination surveys of the OCV lid interior and ICV lid exterior.

(WIPP, JSA)

- 4.5.12.1 **RECORD** survey results on survey map.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 18 of 52

- 1-27-03 4.5.13 IH: Take volatile organic compound (VOC) air samples of the OCV lid interior and ICV lid exterior.

(JSA)

**CAUTION**

To prevent damage to the lock ring, the OCV lid must be placed on the lid stand and not on a flat surface.

- 1-27-03 4.5.14 HEO/OP: Place the OCV lid on its designated storage stand.

(WIPP)

**NOTE:** Step 4.5.15.5.19 may be performed in conjunction with rigging for the ACGLF.

- 1-27-03 4.5.15 ICV Lid Removal

**CAUTION**

The two ACGLF counterweights must be located at the 180° and 000° positions respectively, prior to lifting an ACGLF or lid.

(WIPP)

- 1-27-03 4.5.15.1 M: Prepare the ICV lid for removal by removing the following components and placing them in the designated temporary storage box:

(WIPP)

~~A.~~ ICV vent port cover

~~B.~~ ICV outer vent port plug.

- 1-27-03 4.5.15.2 M: Place removed components in labeled storage container.

- 4.5.15.2.1 QI: **VERIFY** that components have been placed in labeled storage container.

QI signature: [Signature] Date: 1-27-03

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 19 of 5210/1-27-03

- 4.5.15.3 EO/OP: Rig or ensure the rigging for the ACGLF, to the overhead crane per Lift Plan TP 157-02 (INEEL Form 433.34).

10/1-27-03

- 4.5.15.4 HEO/OP: With the crane and ACGLF, lower the ACGLF legs into the lifting pockets on the ICV lid.

(WIPP)

**CAUTION**

Three operators should be able to rotate the locking ring with reasonable effort. Do not attempt to rotate the OCV or ICV lock ring assembly with mechanical force other than the TRUPACT-II lock ring tool (an extension to provide additional leverage and control). Care should be used to prevent the lock ring from slamming into the stops.

(WIPP, JSA)

**NOTE:** *The ICV is designed for safe operation with a full internal vacuum. However, due to the possible presence of volatile organic compounds in the payload, general operations of the loaded ICV should be accomplished using less than 15 in.-Hg vacuum.*

(WIPP)

10/1-23-82

- 4.5.15.5 Unlock the ICV lock ring by performing the following.

(WIPP)

~~4.5.15.5.1~~ M: Remove the ICV lock ring bolts (3).

~~4.5.15.5.2~~ M: Remove the ICV seal test port plug.

~~4.5.15.5.3~~ SO: Install ICV vent port tool (2077-091-A1).

~~4.5.15.5.4~~ SO: Attach sample tool to vent port tool.

~~4.5.15.5.5~~ SO: Connect the hose to vent port sample tool.

~~4.5.15.5.6~~ SO: Start vacuum pump.

~~4.5.15.5.7~~ SO: Place valve VAC-V3P-1801 in the VACUUM position.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230  
Revision: 0  
Page: 20 of 52

**NOTE:** *The TRUPACT-II vacuum should be periodically checked by isolating the pump from the TRUPACT-II.*

~~4.5.15.5.8~~ SO: Open valve VAC-SHV-3524B and evacuate to 3-in. Hg minimum.

~~4.5.15.5.9~~ SO: Retrieve the ICV vent port plug into the ICV vent port sample tool.

~~4.5.15.5.10~~ EO: Manually rotate the ICV lock ring to the UNLOCKED position.

~~4.5.15.5.11~~ SO: Close valve VAC-SHV-3524B.

~~4.5.15.5.12~~ SO: Place valve VAC-V3P-1801 in the OFF position.

~~4.5.15.5.13~~ SO: Stop vacuum pump.

~~4.5.15.5.14~~ SO: With RCT concurrence, disconnect the hose from sample tool.

~~4.5.15.5.15~~ SO: With RCT concurrence, remove sample tool.

~~4.5.15.5.16~~ SO: With RCT concurrence, remove vent port tool and plug.

~~4.5.15.5.17~~ RCT/SO: Cover the vent hole with a piece of tape as directed by RadCon.

~~4.5.15.5.18~~ OP: Remove the ACGLF from the ICV lid and stage as directed by the JS to allow installation of the containment sleeve.

~~4.5.15.5.19~~ C/EO/OP: Attach the containment to the TRUPACT-II and retract it down and around the TRUPACT-II such that it can be pulled up around the payload at a later time.

~~4.5.15.5.20~~ OP/RCT: Remove the tape from the vent hole.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 21 of 52

ML 1-27-03 4.5.15.6 EO/OP: Rig or ensure the rigging for the ACGLF, to the overhead crane per Lift Plan TP 157-02 (INEEL Form 433.34)

(JSA)

4.5.15.6.1 PIC: Ensure that INEEL Form, 433.34A. "INEEL Lift Plan Supplement," has been completed and verified for this CRITICAL LIFT.

PIC signature:  Date: 1-27-03

(JSA)

ML 1-27-03 4.5.15.7 EO: Ensure the ACGLF legs are locked.

(WIPP)

**CAUTION 1**

**When lifting the ICV lid by the lift pockets, the load exerted on the ICV lifting pockets must not exceed 5,000 lb (7,500 lb minus ACGLF 2,500 lb). An indication of 7,500 lb or greater may indicate ICV lid binding.**

(WIPP)

**CAUTION 2**

**The two ACGLF counterweights must be located at 180° and 000° positions respectively, prior to lifting an ACGLF or lid.**

(WIPP)

ML 1-27-03 4.5.15.8 HEO/OP: Using the crane, remove ICV lid to a height appropriate for RCT surveys.

(WIPP)

NIP ML 1-27-03 4.5.15.8.1 EO/OP: IF the lid is stuck, THEN manually apply pressure to the sides of the lid or adjust ACGLF counterweights to help remove the lid.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 22 of 52

*NAEL 1-27-03* 4.5.15.8.2 HEO/OP: IF the lid does separate from the TRUPACT-II, THEN adjust the ACGLF counterweight to 180° and 000° positions respectively.

**WARNING**

No part of the body may be placed beneath the suspended lid. A survey extension tool must be used to obtain contamination smears.

(JSA)

**NOTE:** *Step 4.5.15.9.1 may be performed out of sequence or concurrently, as directed.*

*NAEL 1-27-03*

4.5.15.9 RCT: Perform contamination surveys and take air samples of the ICV lid interior and top of payload as directed by RadCon.

(WIPP, JSA)

~~4.5.15.9.1~~ **RECORD** survey results on survey map.

*NAEL 1-27-03*

4.5.15.10 IH: Take VOC air samples of the ICV lid interior and top of payload.

(JSA)

*NAEL 1-27-03*

4.5.15.11 OP: IF directed by RadCon, THEN apply contamination fixative.

**CAUTION**

To prevent damage to the lock ring, the ICV lid must be placed on the lid stand and not on a flat surface.

*NAEL 1-27-03*

4.5.15.12 C/OP: Separate the sleeving under the direction of the RCT.

*NAEL 1-27-03*

4.5.15.13 FO: Apply fixative as necessary to the ICV lid as directed by the JS/RCT.



**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 23 of 524.5.15.14 HEO/OP: Place ICV lid on its storage stand as directed.

(WIPP)

4.5.15.15 RCT/OP: Perform required inspections/surveys of the ICV cavity and payload per the Payload Examination Plan.**WARNING****Only hands/arms may break the plane of the non-permit confined space.  
Contact IH for further direction if the face must break the plane.**

(JSA)

**NOTE:** *Appendix D may be performed concurrently with other sections as directed by the JS.*4.5.15.16 M/SO: Perform inspection, preparation, and cleaning of OCV assembly per Appendix D.

(WIPP)

4.5.16 EO: Attach the appropriate legs to the ACGLF as required.

(WIPP)

**CAUTION****The two ACGLF counterweights must be located at 180° and 000° positions respectively, prior to lifting an ACGLF or lid.**

(WIPP)

4.5.17 OP/SO: Cut holes in the poly sleeving as necessary to allow the ACGLF to engage the payload, as directed by the RCT.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 24 of 52

KL 1-28-03 4.5.18 HEO/OP: Using the crane and the ACGLF per Lift Plan TP 157-03 (INEEL Form 433.34), engage the payload.

(WIPP, JSA)

4.5.18.1 PIC: Ensure that INEEL Form 433.34A, "INEEL Lift Plan Supplement," has been completed and verified for this CRITICAL LIFT.

PIC signature: [Signature] Date: 1-28-03  
KL 1-28-03

(JSA)

KL 1-28-03 4.5.19 EO: Lock the ACGLF legs into the 14-pack payload assembly.

(WIPP)

KL 1-28-03 4.5.20 HEO/OP: Position the ACGLF counterweights to the predetermined positions as marked on the top of the payload.

(WIPP)

**NOTE:** Steps 4.5.21 and 4.5.22 are performed concurrently to remove the payload.

KL 1-28-03 4.5.21 HEO: Monitor the ACGLF indicated balance and adjust counterweights as needed.

(WIPP)

KL 1-28-03 4.5.22 HEO/OP: Slowly raise the 14-pack payload assembly.

(WIPP)

KL 1-28-03 4.5.23 RCT/OP: Perform additional inspections of the payload per the Payload Examination Plan as required.

KL 1-28-03 4.5.24 C/OP: Separate the sleeving under the direction of the RCT.

KL 1-28-03 4.5.25 EO/OP: Place the 14-pack payload assembly in a designated area.

KL 1-28-03 4.5.26 EO: Ensure ACGLF legs are unlocked.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 25 of 52

KL 1-28-03 4.5.27 EO/OP: Ensure the two ACGLF counterweights are located at the 180° and 000° positions respectively, prior to lifting the ACGLF.

(WIPP)

KL 1-28-03 4.5.28 EO: Remove ACGLF from the payload per RadCon direction.

KL 1-28-03 4.5.29 RCT: Perform survey of ACGLF legs as required.

(JSA)

**NOTE:** *Step 4.5.30.1 may be performed out of sequence or concurrently, as directed.*

KL 1-28-03 4.5.30 RCT: Perform contamination surveys of ICV interior surfaces.

(JSA)

4.5.30.1 **RECORD** survey results on survey map.

KL 1-28-03 4.5.31 FO: Apply fixative as necessary to the ICV cavity as directed by the JS/RCT.

KL 1-28-03 4.5.32 OP: Inspect TRUPACT-II interior (ICV) per Payload Examination Plan as required.

**4.6 ICV Lid Installation**

KL 1-28-03 4.6.1 TL: Designate a PIC prior to hoisting activities for CRITICAL LIFTS in Section 4.6.

PIC: R. L. KYNASTON

(JSA)

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 26 of 52**CAUTION**

The two ACGLF counterweights must be located at the 180° and 000° positions respectively, prior to lifting an ACGLF or lid.

**(WIPP)**

W 1-28-03 4.6.2 IF plastic sleeving material was used,  
THEN cut it away (partially or fully) at the direction of RadCon  
personnel as required.

W 1-28-03 4.6.3 HEO/OP: With the crane and ACGLF per Lift Plan TP 157-02 (INEEL  
Form 433.34), lower the ACGLF legs into the lifting pockets of the ICV  
lid.

**(WIPP, JSA)**

4.6.3.1 PIC: Ensure that INEEL Form 433.34A, "INEEL Lift Plan  
Supplement," has been completed and verified for this  
CRITICAL LIFT.

PIC signature: [Signature] Date: 1-28-03

**(JSA)**

W 1-28-03 4.6.4 EO: Ensure the ACGLF legs are locked.

**(WIPP)**

W 1-28-03 4.6.5 SO: Install vent port tool with sample attachment.

W 1-28-03 4.6.6 OP: As directed by RadCon, install additional containment for ICV lid  
installation and initial containment removal from ICV lid.

W 1-28-03 4.6.7 HEO/OP: Using the crane and ACGLF, align the UNLOCK arrows and  
install the ICV lid onto the ICV body.

**(WIPP)**

W 1-28-03 4.6.8 EO: Ensure the ACGLF legs are unlocked.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 27 of 52**CAUTION**

Three operators should be able to rotate the locking ring with reasonable effort. Do not attempt to rotate the OCV or ICV lock ring assembly with mechanical force other than the TRUPACT-II lock ring tool (an extension to provide additional leverage and control). Care should be used to prevent the lock ring from slamming into the stops.

(WIPP, JSA)

- W 1-28-03 4.6.9 SO: Connect the hose to the ICV vent port tool and evacuate the ICV cavity enough to allow the ICV lock ring to rotate freely as follows:
- W 1-28-03 4.6.9.1 Connect the hose to vent port tool.
  - W 1-28-03 4.6.9.2 Start the vacuum pump.
  - W 1-28-03 4.6.9.3 Place valve VAC-V3P-1801 in the VACUUM position.
- NOTE:** *The TRUPACT-II vacuum should be periodically checked by isolating the pump from the TRUPACT-II.*
- W 1-28-03 4.6.9.4 Open valve VAC-SHV-3524B and evacuate to 3-in. Hg minimum.
- W 1-28-03 4.6.10 SO: Manually rotate the ICV lock ring to the locked position.
- W 1-28-03 4.6.11 SO: Close valve VAC-SHV-3524B.
- W 1-28-03 4.6.12 SO: Place valve VAC-V3P-1801 in the OFF position.
- W 1-28-03 4.6.13 SO: Turn off the vacuum system pump and disconnect the hose.
- W 1-28-03 4.6.14 SO: Remove the ICV vent port tool and sample tool.
- W 1-28-03 4.6.15 M: Install and torque the inner vent port plug to 55 to 65 in.-lb or 4.6 to 5.5 ft-lb.
- W 1-28-03 4.6.16 M: Install and torque the outer vent port plug to 55 to 65 in.-lb or 4.6 to 5.5 ft-lb.
- W 1-28-03 4.6.17 M: Install the three ICV lock ring bolts and torque to 336 to 384 in.-lb or 28 to 32 ft-lb each.

(WIPP)

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 28 of 52WU 1-28-03 4.6.18 M: Install and torque the seal test port plug as follows.

4.6.18.1 ICV – seal test port plug to 55 to 65 in.-lb or 4.6 to 5.5 ft-lb.

WU 1-28-03 4.6.19 M: Install and torque the vent port cover as follows.

4.6.19.1 ICV – vent port cover to 55 to 65 in.-lb or 4.6 to 5.5 ft-lb.

**4.7 ICV Removal from the OCV**WU 1-28-03 4.7.1 JS: Ensure the ICV lid has been installed per section 4.6.**CAUTION****The two ACGLF counterweights must be located at the 180° and 000° positions respectively, prior to lifting an ACGLF or lid.****(WIPP)**NA WU 1-28-03 4.7.2 HEO/OP: With the crane and ACGLF per Lift Plan TP 157-04 (INEEL Form 433.34), lower the ACGLF legs into the lifting pockets of the ICV lid if required.**(JSA)**NA WU 1-28-03 4.7.3 RCT/OP: Remove all secondary containment plastic from the ICV lid as necessary.NA WU 1-28-03 4.7.4 RCT/OP: Survey and decontaminate the ICV lid as necessary.WU 1-28-03 4.7.5 EO: Ensure the ACGLF legs are locked.WU 1-28-03 4.7.6 EO/HEO/OP: If the annulus foam is present, remove it and place it in a poly bag as directed by the JS.NA WU 1-28-03 4.7.7 EO/HEO/OP: Move the annulus protector as necessary as directed by the JS/RCT.WU 1-28-03 4.7.8 HEO/OP: Remove the ICV from the OCV and place in a location designated by the JS/SS.WU 1-28-03 4.7.9 EO: Ensure the ACGLF legs are unlocked.WU 1-28-03 4.7.10 HEO/OP: Move the ACGLF to an area designated by the JS.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 29 of 52

11-28-03 4.7.11 OP/RCT/SO: Perform surveys per the Payload Examination Plan as required.

(JSA)

**WARNING**

Only hands/arms may break the plane of the non-permit confined space.  
Contact IH for further direction if the face must break the plane.

(JSA)

11-28-03 4.7.12 RCT/OP: Survey OCV internals and decontaminate as necessary.

(JSA)

11-28-03 4.7.13 IF this procedure is being used for the "Training TRUPACT-II,"  
THEN perform the following:

11-28-03 4.7.13.1 OP: Ensure the ICV lid has been installed per section 4.6.

11-28-03 4.7.13.2 RCT: Survey ICV exterior.

(JSA)

**CAUTION**

The two ACGLF counterweights must be located at the 180° and 000° positions respectively, prior to lifting an ACGLF or lid.

(WIPP)

4.7.13.3 HEO/OP: Using the crane and ACGLF per Lift Plan TP 157-04 (INEEL Form 433.34), lower the ACGLF legs into the lifting pockets of the ICV lid as required.

(JSA)

4.7.13.4 EO: Ensure the ACGLF legs are locked.

4.7.13.5 HEO/OP: If necessary, raise the Training ICV 2 to 6 inches off of the floor and balance.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230

Revision: 0

Page: 30 of 52

NAPCC  
1-28-03

- 4.7.13.6 EO/OP: Center the Training ICV over the Training OCV.
- 4.7.13.7 HEO/OP: Lower the Training ICV into the Training OCV.
- 4.7.13.8 HEO/OP: Align the vent ports within 1 ft of each other.
- 4.7.13.9 SO/EO/OP: Install the annulus foam if required.
- 4.7.13.10 EO: Ensure the ACGLF legs are unlocked.
- 4.7.13.11 HEO/OP: Move the ACGLF to an area designated by the JS.

NAPCC  
1-28-03**4.8 OCV Lid Installation**

- 4.8.1 JS: **VERIFY** inspection completion of OCV lid, body, and applicable components (see Appendix D).

JS signature: [Signature] Date: 1-28-03

(WIPP)

NAPCC  
1-28-03

- 4.8.2 SO: Match the OCV lid and body serial numbers. **RECORD** the OCV lid/body serial number.

OCV Lid/Body serial number: 157

(WIPP)

**QI HOLD**

- 4.8.3 QI: **RECORD** the serial number and calibration due date of the torque wrench used in this section on the test port plug.

Torque wrench serial number: 703615Calibration due date: 5-1-03QI signature: [Signature] Date 1-28-03



**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 31 of 52

1-28-03 4.8.4 M: Install the OCV seal test port plug and torque to 55 to 65 in.-lb or 4.6 to 5.5 ft-lb.

4.8.4.1 QI: **VERIFY** OCV seal test port plug has been installed and torqued to specified values (55 to 65 in.-lb or 4.6 to 5.5 ft-lb).

QI signature: *W. J. J. J.* Date: 1-28-03

1-28-03 4.8.5 OP/EO: Rig or ensure rigging for the ACGLF to the overhead crane per Lift Plan TP 157-01 (INEEL Form 433.34).

(JSA)

**CAUTION**

The two ACGLF counterweights must be located at 180° and 000° positions respectively, prior to lifting an ACGLF or lid.

(WIPP)

1-28-03 4.8.6 HEO/OP: Using the crane and the ACGLF, lower the ACGLF legs into the lifting pockets on the OCV lid.

(WIPP)

1-28-03 4.8.7 EO: Ensure the ACGLF legs are locked.

(WIPP)

1-28-03 4.8.8 HEO/OP: Install the OCV lid onto the OCV body.

(WIPP)

1-28-03 4.8.9 EO: Ensure ACGLF legs are unlocked.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 32 of 52**CAUTION**

Three operators should be able to rotate the lock ring with reasonable effort. Do not attempt to rotate the OCV or ICV lock ring assembly with mechanical force other than with the TRUPACT-II lock ring tool (an extension to provide additional leverage and control). Care should be used to prevent the lock ring from slamming into the stops.

(WIPP, JSA)

4.8.10 Rotate the lock ring to the LOCK position by performing the following.

(WIPP)

1001-28-034.8.10.1 SO: Install the OCV vent port tool.1001-28-034.8.10.2 SO: Connect the hose to the OCV vent port tool and evacuate the OCV cavity to allow the OCV lock ring to rotate freely as follows.~~4.8.10.2.1~~ Start the vacuum pump.~~4.8.10.2.2~~ Place valve VAC-V3P-1801 in the VACUUM position.

**NOTE:** *The TRUPACT-II vacuum should be periodically checked by isolating the pump from the TRUPACT-II.*

~~4.8.10.2.3~~ Open valve VAC-SHV-3524B and evacuate to 3-in. Hg minimum.1001-28-034.8.10.3 SO: Manually rotate the OCV lock ring clockwise to the locked position.1001-28-034.8.10.4 SO: Close valve VAC-SHV-3524B.1001-28-034.8.10.5 SO: Place valve VAC-V3P-1801 in the OFF position.1001-28-034.8.10.6 SO: Turn off the vacuum pump system and disconnect the hose.1001-28-034.8.10.7 SO: Remove the vent port tool.1001-28-034.8.10.8 HEO/OP: Remove the ACGLF as directed.

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230
	Revision: 0
	Page: 33 of 52

- 4.8.11 **QI: RECORD** the serial number and calibration due date of the torque wrenches used in this section on port plugs and lock ring bolts.

Torque wrench serial number: 704213

Calibration due date: 2-27-03

Torque wrench serial number: 703615

Calibration due date: 5-1-03

QI signature: RC Justice Date 1-28-03

- 4.8.12 **M:** Install and torque the appropriate vent port plug and seal test port plugs as follows:

111 1-28-03

4.8.12.1 OCV – vent port plug to 55 to 65 in.-lb or 4.6 to 5.5 ft.-lb.

111 1-28-03

4.8.12.2 OCV – vent port cover to 55 to 65 in.-lb or 4.6 to 5.5 ft.-lb.

111 1-28-03

4.8.12.3 OCV – seal test port access plug and thermal plug to 420 to 540 in.-lb or 35 to 45 ft.-lb.

111 1-28-03

4.8.12.4 OCV – vent port access plug and thermal plug to 420 to 540 in.-lb or 35 to 45 ft.-lb.

**QI HOLD**

- 4.8.13 **QI: VERIFY** torque of OCV vent port plug and cover and sign below.

QI signature: RC Justice Date 1-28-03

**QI HOLD**

- 4.8.14 **QI: VERIFY** torque of vent port/access plug and thermal plug, and seal/test port access plug and thermal plug, and sign below.

QI signature: RC Justice Date 1-28-03

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230

Revision: 0

Page: 34 of 52

- ML 1-28-03 4.8.15 M: Install the six OCV lock ring bolts and torque to 336 to 384 in.-lb or 28 to 32 ft-lb each.

(WIPP)

- 4.8.15.1 QI: **VERIFY** OCV lock-ring bolts have been installed and torqued to specified values (336 to 384 in.-lb or 28 to 32 ft-lb).

QI signature: RC Quintan Date: 1-28-03

- ML 1-28-03 4.8.16 EO/M/SO: Install the OCV lid lift pocket covers.

ML 1-29-03 **4.9 Transfer TRUPACT-II to the Transport Trailer**

- ML 1-29-03 4.9.1 EO/HEO: Perform the following, if applicable:

NPW 1-24-03 4.9.1.1 Position the transport trailer in a designated parking area.

4.9.1.2 Lower the trailer jacks (landing gear), ensuring the trailer is level.

4.9.1.3 Install wheel chocks.

4.9.1.4 Disconnect tractor from trailer.

4.9.1.5 Install trailer stands on free-standing trailers.

NPW 1-29-03

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN****Identifier:** TPR-6230  
**Revision:** 0  
**Page:** 35 of 52**WARNING**

At least two spotters must be present when moving TRUPACT-IIs with the forklift.

**(JSA)****CAUTION 1**

Tip-back may damage the exterior surface when utilizing a forklift to relocate a TRUPACT-II.

**(WIPP)****CAUTION 2**

It is necessary to align the tiedown lugs with the tiedown U-bolts prior to setting the TRUPACT-II into place. Caution must be used to lower the TRUPACT-II slowly onto the trailer.

**NOTE:** *Platforms may be disassembled and reassembled as necessary to facilitate TRUPACT-II movement.*

**(JSA)**141-29-03

4.9.2 OP: Remove plastic from the OCV as directed by RadCon.

141-29-03

4.9.3 OP: IF necessary, move the TRUPACT-II to a designated area in order to remove the remaining plastic as directed by the JS with RCT concurrence.

**NOTE:** *Step 4.9.4.1 may be performed at any time after the survey has been completed.*

141-29-03

4.9.4 RCT: Perform surveys of OCV.

**(JSA)**

4.9.4.1 **RECORD** survey results on survey map.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230

Revision: 0

Page: 36 of 52

111 1-24-03 4.9.5

EO: Load the TRUPACT-II designated for position number 1 (a) onto the trailer with the vent port on the driver's side of the trailer.

(WIPP)

111 1-24-03 4.9.6

EO: If applicable, load the TRUPACT-II designated for position number 2 (b) onto the trailer with the vent port on the driver's side of the trailer.

(WIPP)

111 1-24-03 4.9.7

M: Install the four (4) tie-down assemblies for each TRUPACT-II loaded on the trailer. Secure the tie-downs on all TRUPACT-II containers as follows:

(WIPP)

4.9.7.1

Using a wire brush, remove any foreign matter from the following tiedown components, as required:

A. U-bolt threads

B. nuts.

4.9.7.2

Lubricate the threaded areas of U-bolts and nuts using anti-seize or general purpose lubricant, as required.

(JSA)

4.9.7.3

Lift U-bolts (4), up and position toward and over the packaging tiedown lugs.

4.9.7.4

Tighten the (2) adjusting nuts for each tiedown U-bolt.

111 1-24-03 4.9.8

M: Using the GO-NO-GO gauge, check the gap between the disk spring retainer block and the compression plate assembly on each tie-down.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 37 of 52

**NOTE:** Steps 4.9.8.1 through 4.9.11 may be worked concurrently and/or out of sequence as directed by the JS.

NA 1-29-03  
1-29-03

4.9.8.1 **M:** IF the gap on any tiedown fails the GO-NO-GO check, THEN adjust the affected tiedown(s) as follows:

**NOTE:** Failure of the block to move upward with each adjustment indicates galling of the threads and imminent failure of the bolt.

- A. IF the gap is too large, THEN turn adjusting nuts upward (clockwise) an equal amount while ensuring that the block moves upward with each adjustment of the nut.
- B. IF the gap is too small, THEN turn adjusting nuts down (counterclockwise) an equal amount.

NA 1-29-03  
1-29-03

4.9.8.2

**QI:** Using the GO-NO-GO gauge, **VERIFY** the gap between the disk spring container block and compression plate assembly on each tiedown.

QI signature: [Signature] Date 1-29-03

1-29-03 4.9.9 **M:** Ensure a lock pin has been inserted through each tie-down handle.

1-29-03 4.9.10 **M:** Rotate or reinstall the TRUPACT-II forklift pocket access covers.

1-29-03 4.9.11 **QI:** Inspect the TRUPACT-II forklift pocket access covers for damage.

**4.10 Releasing the TRUPACT-II Trailer**

NA 1-29-03 4.10.1 **EO:** Connect the TRUPACT-II tractor and the TRUPACT-II trailer as necessary:

4.10.1.1 **EO:** Move trailer stands from freestanding trailers if necessary.

4.10.1.2 **EO:** Connect the TRUPACT-II tractor and the TRUPACT-II trailer, if applicable.

4.10.1.3 **EO:** Raise the trailer jacks (landing gear), if applicable.

4.10.1.4 **EO:** Remove the wheel chocks.

# TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN

Identifier: TPR-6230  
Revision: 0  
Page: 38 of 52

## CAUTION

A visual check should be made to ensure the airbags on the trailer are fully inflated before the trailer is moved. Failure to do so may cause the tires to rub on the bottom of the rear TRUPACT-II.

(WIPP)

1-29-03 4.10.2 EO: Remove the TRUPACT-II tractor/trailer to the area designated by the JS.

### 4.11 Post Performance Activities

1-2-03 4.11.1 JS: Conduct a post-job review in accordance with MCP-3003.

2/3/03 4.11.2 TL/SS: Ensure the TPR is completed and acceptable for closure.

2-3-03 1-2-03 4.11.3 QE: Complete Quality Inspection Plan documentation review.

2-3-03 1-2-03 4.11.4 QE: Ensure all TPR steps are completed, signed off, and dated. (Appendix B comments should be properly dispositioned and completed.)

2-3-03 1-2-03 4.11.5 QE: Ensure that any Non-Conformance Reports items listed in Appendix B have been reported on a Non Conformance Report (NCR).

2-3-03 1-2-03 4.11.6 QE: Ensure that the total records package is complete (see Section 5) and has been assembled and transmitted to the Project and TAN Document Control Center using Forms 416.04, "QA Record(s) Validation/Verification Form"/241.07, "Records Analysis and Transmittal Form."



<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230 Revision: 0 Page: 39 of 52
---	---

## 5. RECORDS

Record Description	Classification	Uniform File Code	Disposition Authority	Retention Period
TPR-6230 Case File	INEEL Lifetime QA  WIPP-WAP Nonpermanent QA	0250	A16-1.1	Permanent. Cut off when superseded, obsolete, or canceled.
Field TRUPACT-II Loading File: – Consumable TPR-6230 ✓ – Maintenance Record Form, as needed – PATCDs, as applicable – SWB Assembly Details report, as applicable – Shipment Packs and Subassemblies report, as applicable – Radiological Survey ✓ Maps – INEEL Form 433.34, ✓ INEEL Lift Plan – INEEL Form 433.34A, ✓ INEEL Lift Plan Supplement	WIPP-WAP Lifetime QA  INEEL Nonpermanent QA	7403	ENV1-k-2-b EPI*	Cut off at project completion. Destroy 25 years after project completion.
INTEC-QA-0208, Quality Inspection Plan ✓	INEEL Lifetime QA	7204	A17-32-A	Retain until item is removed from service.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN****Identifier:** TPR-6230  
**Revision:** 0  
**Page:** 40 of 52**6. REFERENCES**

DOE-STD-1090-2001, DOE Hoisting and Rigging Standard

INEL-94/0209, "TANO Technical Safety Requirements"

TAN-JSA-6230

DOE/WIPP 02-3183, CH Packaging Program Guidance\*

DOE/WIPP 02-3184, CH Packaging Operations Manual\*

DOE/WIPP 02-3185, CH Packaging Maintenance Manual\*

MCP-139, Radiological Surveys

MCP-535, Inspection and NDE Personnel Certification

MCP-1819, TRUPACT-II Receipt Inspection and Shipment

MCP-2514, Management of Construction Projects

MCP-2985, Operations Procedures

MCP-3003, Performing Pre-Job Briefings and Post-Job Reviews

PLN-577, TRUPACT-II Authorized Methods for Payload Control (TRAMPAC)  
Compliance Plan

PQR-LT17, Process Qualification Report

Radiological Control Manual

TRUPACT-II Certificate of Compliance\*

TPR-1648, TRUPACT-II Payload Assembly Operation

TPR-1666, TRUPACT-II Loading Operation in WMF-635

\* Controlled copies can be viewed on the WIPP Homepage  
<http://www.wipp.carlsbad.nm.us>

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN****Identifier:** TPR-6230  
**Revision:** 0  
**Page:** 41 of 52**7. APPENDIXES**

Appendix A – Procedure Basis

Appendix B – Comment Sheet

Appendix C – TRUPACT-II Packaging Weights (pounds)

Appendix D – OCV/ICV Inspection and Preparation

<p align="center"><b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6230 Revision: 0 Page: 42 of 52</p>
---	--

## APPENDIX A

### Procedure Basis

Step	Basis	Reference
General	Activities affecting quality shall be prescribed by and performed in accordance with documented instructions, procedures, or drawings that include appropriate quantitative or qualitative acceptance criteria for determining that prescribed results have been satisfactorily attained.	PRD-5076, Section 4.1.1.1
2.2	<p>Upon completion, original TRUPACT-II Maintenance Records and copies of supporting documentation shall be transmitted to the WTS Transportation Project, P.O. Box 2078, Carlsbad, NM, 88221, and become a part of the permanent TRUPACT-II system record.</p> <p>All maintenance, repairs performed, or components replaced will be documented using the maintenance record. Information regarding preparation of the maintenance record is outlined in Section 5.6 of DOE/WIPP 02-3183. Records shall be maintained by the WIPP M&amp;O contractor to document completion of the maintenance schedule.</p>	DOE/WIPP 02-3183, Sections 2.2 and 5.0
2.3	<p>The Adjustable Center-of-Gravity Lift Fixture (ACGLF) is designed to handle the weight of the following configurations:</p> <ul style="list-style-type: none"> <li>▪ an OCA lid assembly</li> <li>▪ an ICV lid</li> <li>▪ an empty ICV assembly</li> <li>▪ a loaded payload (i.e., 14 drums), two SWBs, or one ten-drum overpack (TDOP).</li> </ul> <p>The ACGLF is <b>NOT</b> designed to lift the weight of the following configurations:</p> <ul style="list-style-type: none"> <li>▪ a loaded CH package or empty CH packaging</li> <li>▪ a loaded or empty OCA</li> <li>▪ a loaded ICV.</li> </ul>	DOE/WIPP 02-3183, Section 1.6.4
2.5	Annual and 5 years inspections, testing, certifications are performed as a set (lid and body).	DOE/WIPP 02-3185, Section 3

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230 Revision: 0 Page: 43 of 52
---	---

**APPENDIX A**

Step	Basis	Reference
2.6, 2.7, 2.8, 2.10 through 2.16, 3.1.2, 3.1.4, 3.4.1, 4.2 Note, 4.4.2 Warning, 4.5.1, 4.5.6, 4.5.9 Caution, 4.5.10, 4.5.12, 4.5.12 Warning, 4.5.13, 4.5.15.6, 4.5.15.6.1, 4.5.15.5 Caution, 4.5.15.9 Warning, 4.5.15.9, 4.5.15.10, 4.5.15.16 Warning, 4.5.18, 4.5.18.1, 4.5.29, 4.5.30, 4.6.1, 4.6.3, 4.6.3.1, 4.6.9 Caution, 4.7.2, 4.7.11, 4.7.12 Warning, 4.7.12, 4.7.13.2, 4.7.13.3, 4.8.5, 4.8.10 Caution, 4.9.2 Warning and Note, 4.9.4, 4.9.7.2	Implementation of JSA requirements	TAN-JSA-6230
Note preceding 4.2.1	If required, clean and/or dry the package before transport to a designated area. The package may be cleaned with water and dampened cloths or a soft brush. Used cleaning materials should be managed according to site waste management procedures.	DOE/WIPP 02-3183, Section 4.3.1
4.2.1	Record OCA serial number on Attachment 1, CH Packaging Receipt and Inspection Data Sheet.	DOE/WIPP 02-3184, Section 2.2.1
Caution preceding 4.2.2	A physical check shall be made to verify the air bags on the trailer have fully inflated before the trailer is moved by a user site trailer jockey. Failure to do so may cause the tires to rub on the bottom of the rear packaging.	DOE/WIPP 02-3183, Section 4.3.2
4.2.2	Position the transport trailer in a designated parking area. Lower the trailer jacks (landing gear) ensuring the trailer is level. Install wheel chocks. Install trailer stands on free-standing trailers.	DOE/WIPP 02-3184, Section 2.2.6 through 2.2.9

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230  
Revision: 0  
Page: 44 of 52

**APPENDIX A**

Step	Basis	Reference
Caution preceding 4.3.1	The adjusting nuts must be loosened until the tension has been released from the Bellville springs when releasing the tie-down assemblies. The U-bolts can then be lifted and rotated outward away from the tie-down lugs. The U-bolts must be lowered as far as possible onto the trailer bracket below the tie-down lugs to prevent damage to the packaging exterior and the U-bolts.	DOE/WIPP 02-3183, Section 4.2.1
4.3.1	[A] Loosen tie-down adjusting nuts. [B] Lift tie-down assemblies from tie-down lugs. [C] Rotate away from lugs. [D] Lower completely to trailer brackets.	DOE/WIPP 02-3184, Section 2.3.2
4.3.2	Rotate the four forklift pocket covers (4) to the UP position, or remove the covers and store in a designated area.	DOE/WIPP 02-3184, Section 2.3.3
Caution preceding 4.5.6, 4.5.11, 4.5.15.1, 4.5.15.8, 4.7.2, 4.7.13.3, and 4.8.6	Verify that the two ACGLF counterweights are located at the 180 and 000° positions, respectively, prior to lifting an ACGLF, lid or payload.	DOE/WIPP 02-3183, Section 4.3.2
Caution preceding 4.4.1	Tip-back may damage the exterior surface when a forklift is used to relocate a packaging.	DOE/WIPP 02-3183, Section 4.3.2
Note preceding 4.5.1	Rotation of the ACGLF weights should be used to assist in the removal of the OCA and ICV lids; however, care must be taken to verify the weights are positioned in the 180 and 000° positions prior to lifting either lid.	DOE/WIPP 02-3183, Section 4.3.1
4.5.3	Prepare the OCA lid by removing the following: <ul style="list-style-type: none"> <li>▪ OCA lid lift pocket covers</li> <li>▪ OCV lock ring bolts (6)</li> <li>▪ OCA test port access plug and thermal plug</li> <li>▪ OCA vent port access plug and thermal plug</li> <li>▪ Remove OCV seal-test port plug</li> <li>▪ Remove OCV vent port cover</li> <li>▪ Remove OCV vent port plug.</li> </ul>	DOE/WIPP 02-3184, Sections 2.4.1 through 2.4.4
4.5.7	Lower the ACGLF legs into the lift pockets on the OCV lid using crane.	DOE/WIPP 02-3184, Section 2.4.6
4.5.8	Verify the ACGLF legs are locked.	DOE/WIPP 02-3184, Section 2.4.7
Caution preceding 4.5.9, 4.5.15.5, 4.6.9, and 4.8.10	Three operators should be able to rotate the locking ring with reasonable effort. Do not attempt to rotate the OCV or ICV lock ring assembly with mechanical force other than with the lock ring tool (an extension to provide additional leverage and control). Care should be used to prevent the lock ring from slamming into the stops.	DOE/WIPP 02-3183, Section 4.3.2
4.5.9	Rotate lock ring to "UNLOCK" position.	DOE/WIPP 02-3184, Section 2.4.11

<p align="center"><b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6230 Revision: 0 Page: 45 of 52</p>
---	--

## APPENDIX A

Step	Basis	Reference
4.5.9.1 through 4.5.9.14	<ul style="list-style-type: none"> <li>▪ Install vent port tool (2077-091-A2).</li> <li>▪ Connect vacuum line to vent port tool.</li> <li>▪ Start vacuum pump and evacuate to 3 in. Hg minimum/58 Torr abs minimum.</li> <li>▪ Pull a vacuum until lock ring can be rotated.</li> <li>▪ Stop vacuum pump.</li> <li>▪ Disconnect vacuum line from vent port tool.</li> <li>▪ Remove vent port tool.</li> </ul>	DOE/WIPP 02-3184, Sections 2.4.8 through 2.4.14
Caution preceding 4.5.11	When lifting the OCA lid, verify through the use of a load cell that the load exerted on the lift pockets does not exceed 7,500 lb. (Load cell indication of 10,000 lb minus weight of the ACGLF @ 2,500 lb = 7,500 lb load.) An indication of 10,000 lb or greater may mean the lid is binding.	DOE/WIPP 02-3183, Section 4.2.2
4.5.11	Remove OCA lid.	DOE/WIPP 02-3184, Section 2.4.16
4.5.11.1	<p><b>IF</b> lid does not lift off, <b>THEN</b> perform the following:</p> <ul style="list-style-type: none"> <li>a. Contact supervisor.</li> <li>b. GO TO Step 3.2, OR Step 3.3, attempt to remove lid, and RETURN TO Step 2.4.18.</li> </ul>	DOE/WIPP 02-3184, Section 2.4.17
4.5.14	Place the OCA lid on storage stand.	DOE/WIPP 02-3184, Section 2.4.18
4.5.27	Operator shall verify two ACGLF counterweights are 180 and 000,° respectively, <b>BEFORE</b> lifting ACGLF or lid.	DOE/WIPP 02-3183, Section 4.3.2
4.5.15.4	Lower the ACGLF legs into lift pockets on the ICV lid using crane.	DOE/WIPP 02-3184, Section 2.5.2
4.5.15.7	Verify the ACGLF legs are locked.	DOE/WIPP 02-3184, Section 2.5.3
4.5.15.1	<p>Prepare the ICV lid by removing the following:</p> <ul style="list-style-type: none"> <li>▪ Remove ICV Lock Ring Bolts (3)</li> <li>▪ Remove ICV Vent-Port Cover</li> <li>▪ Remove ICV Seal Test Port Plug</li> <li>▪ Remove ICV Outer Vent-Port Plug</li> <li>▪ Remove ICV Inner Vent-Port Plug.</li> </ul>	DOE/WIPP 02-3184, Sections 2.5.4 through 2.5.6

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230  
Revision: 0  
Page: 46 of 52

**APPENDIX A**

Step	Basis	Reference
4.5.15.5.1 through 4.5.15.5.16	Unlock the ICV lock ring by performing the following: <ul style="list-style-type: none"> <li>▪ Install ICV vent port tool (2077-091-A1).</li> <li>▪ Connect vacuum line to vent port tool.</li> <li>▪ Start vacuum pump and evacuate to 3 in. Hg minimum/50 Torr abs minimum.</li> <li>▪ Rotate the ICV lock ring to the UNLOCKED position.</li> <li>▪ Stop vacuum pump.</li> <li>▪ Disconnect vacuum line from vent port tool.</li> <li>▪ Remove vent port tool.</li> </ul>	DOE/WIPP 02-3184, Sections 2.5.7 through 2.5.13
Caution preceding 4.5.15.8	When lifting the ICV lid, verify through the use of a load cell that the load exerted on the lift pockets does not exceed 5,000 lb. (Load cell indication of 7,500 lb or greater may mean the lid is binding.)	DOE/WIPP 02-3183, Section 4.2.2
4.5.15.8	Remove ICV lid using ACGLF and crane.	DOE/WIPP 02-3184, Section 2.5.15
4.5.15.14	Place ICV lid on storage stand.	DOE/WIPP 02-3184, Section 2.5.17
4.5.12, 4.5.15.9	Radiological Control Technician (RCT): IF surveys for items in Steps 2.7.1, 2.8.1, or 2.9.1 have been previously completed, AND results are below contamination limits, THEN enter applicable information for each step on Attachment 1.	DOE/WIPP 02-3184, Section 2.6.1
4.5.15.16	Steps 2.7 through 2.13 (and substeps in those steps) must be completed, but may be performed in any order as long as radiological control steps are not bypassed.	DOE/WIPP 02-3184, Note preceding Section 2.7
Caution preceding 4.5.17	Operator shall verify two ACGLF counterweights are located at the 180 and 000,° respectively, <u>BEFORE</u> lifting ACGLF or lid.	DOE/WIPP 02-3184, Caution preceding Section 2.16.3
4.5.16	Attach the appropriate legs/adaptor to the ACGLF.	DOE/WIPP 02-3184, Section 2.16.3
4.5.18	Lower the ACGLF long legs into the drum payload assembly guide tubes using crane and ACGLF until the red stripes are no longer visible, OR lower SWB or TDOP adapter until no load is indicated on the crane load cell.	DOE/WIPP 02-3184, Section 2.16.4
4.5.19	Lock the ACGLF legs, OR attach the SWB lift fixture to the upper SWB or TDOP adapter to TDOP, as applicable.	DOE/WIPP 02-3184, Section 2.16.5
4.5.20	If necessary, balance the payload using the counterweight controls at the ACGLF console until a reading of $\pm 0.5^\circ$ is obtained.	DOE/WIPP 02-3184, Section 2.16.7
4.5.22	Raise and position the payload assembly over the ICV cavity using crane and ACGLF.	DOE/WIPP 02-3184, Section 2.16.13
Caution preceding 4.6.2	Operator shall verify that the two ACGLF counterweights are at 180 and 000° <u>BEFORE</u> lifting an ACGLF or lid.	DOE/WIPP 02-3183, Section 4.3.2



**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230  
Revision: 0  
Page: 47 of 52

**APPENDIX A**

Step	Basis	Reference
4.6.3	Lower the ACGLF legs into the lifting pockets on the ICV lid using crane.	DOE/WIPP 02-3184, Section 2.17.4
4.6.4	Verify the ACGLF legs are locked.	DOE/WIPP 02-3184, Section 2.17.5
4.6.7	Align UNLOCK arrows and install the ICV lid onto the ICV body using crane on ACGLF.	DOE/WIPP 02-3184, Section 2.17.6
Note preceding 4.5.15.5	The ICV is designed for safe operation with a full internal vacuum. However, due to the possible presence of VOCs in the payload, general operations of the loaded ICV shall be accomplished using less than 15-in. Hg vacuum (a minimum absolute pressure of 300 Torr when the payload is in the ICV).	DOE/WIPP 02-3183, Section 4.3.1
4.6.17	Install the three ICV lock ring bolts and torque to 28 to 32 ft-lb each.	DOE/WIPP 02-3184, Sections 2.17.16 and 2.17.17
4.8.1	Steps are covered in Appendix D and include all of Sections 2.26, 2.28, and 2.29.	DOE/WIPP 02-3184, Sections 2.7.4, 2.9.5 and 2.10.10
4.8.2	Match the OCA lid and body serial numbers. Record the OCA body serial number on Attachment 5.	DOE/WIPP 02-3184, Sections 2.18.1 and 2.18.2
Caution preceding 4.8.6	Operator shall verify that the two ACGLF counterweights are at 180 and 000° <u>BEFORE</u> lifting ACGLF or lid.	DOE/WIPP 02-3183, Caution preceding Section 4.3.2
4.8.6	Lower the ACGLF legs into the lifting pockets on the OCA lid using crane.	DOE/WIPP 02-3184, Section 2.18.3
4.8.7	Verify the ACGLF legs are locked.	DOE/WIPP 02-3184, Section 2.18.4
4.8.8	Install the OCV lid onto the OCV body.	DOE/WIPP 02-3184, Section 2.18.5
4.8.10	Rotate the lock ring to LOCKED position by <ul style="list-style-type: none"> <li>Verify OCV vent port plug is retracted into OCV vent port tool</li> <li>Install the OCV vent port tool into OCV vent port</li> <li>Connect the vacuum line to the OCV vent port tool</li> <li>Start vacuum pump and evacuate to 3-in. Hg minimum/58 Torr abs minimum</li> <li>Rotate the OCV lock ring to LOCKED position</li> <li>Stop vacuum pump and disconnect the vacuum line from vent port tool.</li> </ul>	DOE/WIPP 02-3184, Sections 2.18.13 through 2.18.16
4.8.15	Install the six OCV lock ring bolts, and torque to 28 to 32 ft-lb each.	DOE/WIPP 02-3184, Sections 2.18.14 and 2.18.15
Caution preceding 4.9.2	Tip-back may damage the exterior surface when a forklift is used to relocate a packaging.	DOE/WIPP 02-3183, Section 4.3.2
4.9.5	Load package designated for position #1 onto trailer with vent port on driver side of trailer.	DOE/WIPP 02-3184, Section 2.19.5 [F]
4.9.6	If applicable, load package designated for position #2 onto trailer with vent port on driver side of trailer.	DOE/WIPP 02-3184, Section 2.19.5 [G]

<b>TRUPACT-157 UNLOADING AND LOADING RECOVERY OPERATIONS AT TAN</b>	Identifier: TPR-6230 Revision: 0 Page: 48 of 52
---	---

**APPENDIX A**

Step	Basis	Reference
4.9.7	Install four tie-down assemblies for each package loaded on trailer.	DOE/WIPP 02-3184, Section 2.19.5 [I]
Caution preceding 4.10.2	A physical check shall be made to verify the air bags on the trailer have fully inflated before the trailer is moved by a user site trailer jockey. Failure to do so may cause the tires to rub on the bottom of the rear packaging.	DOE/WIPP 02-3183, Section 4.3.2
4.5.21	If necessary, balance payload using counter weight controls at ACGLF console until a reading of + or – 0.5° is obtained.	DOE/WIPP 02-3184, Sections 2.24.4 and 2.24.6

Identifier: TPR-6230  
Revision: 0  
Page: 49 of 52

## Comment Sheet

Initial	Date/Time	Page No.	Step No.	Comments/Notes/Observations
KL	1-27-03/1245	14	4.5.2	TID SEAL FOUND BROKEN. NOTIFIED SS AND DOUG WALK. RECEIVED PERMISSION FROM CBFO TO CONTINUE OPERATIONS
KL	1-27-03/1345	20	4.5.5.9	PRIOR TO REMOVAL OF THE ICV VENT PORT PLUG, THE ICV LOCK RING ROTATED WITH VERY LITTLE EFFORT (THE INSTANT WAS TO PREPARE TO ROTATE) THIS HAPPENED INSTANT THE PORT PLUG FULLY INSTALLED AND NO VACUUM ON THE CASE. ADVISED SS THAT STOP WAS WORKED OUT OF SEQUENCE AND RECEIVED PERMISSION TO CONTINUE
KL	1-28-03/1630	25/26	4.5.32	STOP 4.5.32 WAS WORKED SEQUENTIALLY WITH STOP 4.6.1 & 4.6.2
KL	2/3/03 1845	39/52	5.	The TPR Case File is stored at TAN not to be included in this procedure close-out. also, the Maintenance Record form, PATCDs, SWB Assembly detail Report, and shipment packs and Subassemblies Report were not included. Because these forms are only applicable to loading SWBs with drums & assembling a TRU Part shipment.

C-53

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**

Identifier: TPR-6230  
Revision: 0  
Page: 50 of 52

**APPENDIX C**

Table 3.1. TRUPACT-II packaging weights (pounds).

Serial Number	TOTAL POUNDS	Serial Number	TOTAL POUNDS	Serial Number	TOTAL POUNDS
125	12,556	156	12,785	187	12,570
126	12,476	157	12,731	188	12,555
127	12,512	158	12,525	189	12,360
128	12,739	159	12,650	190	12,375
129	12,809	160	12,610	191	12,410
130	12,832	161	12,685		
131	12,630	162	12,525		
132	12,656	163	12,720		
133	12,670	164	12,710		
134	12,634	165	12,818		
135	12,556	166	12,737		
136	13,140	167	12,875		
137	13,100	168	12,876		
138	12,700	169	12,738		
139	12,550	170	12,755		
140	12,460	171	12,757		
141	12,475	172	12,739		
142	12,555	173	12,814		
143	12,580	174	12,691		
144	12,550	175	12,631		
145	12,650	176	12,854		
146	12,350	177	12,867		
147	12,500	178	12,650		
148	12,500	179	12,570		
149	13,136	180	12,560		
150	12,465	181	12,445		
151	12,470	182	12,510		
152	12,670	183	12,725		
153	12,627	184	12,605		
154	12,925	185	12,605		
155	12,690	186	12,530		

**NOTE:** Additional TRUPACT-II unit weights can be obtained from the WIPP Waste Information System Packaging Reference Data table or the table provided by the WIPP Shipping Coordinator if not listed above.

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 51 of 52**APPENDIX D****OCV/ICV Inspection and Preparation**Shipment No. EMPTY OCA  
TRUPACT S/N 157NOTE 1: *The steps in Appendix D may be performed simultaneously and out of sequence.*NOTE 2: *Inspections for damage include checking for deformation, scratches, or burrs on metal components; and tears, nicks, flat spots, or cracks on O-rings. Any damage determined will be recorded in Appendix B, Comment Sheet.***D-1. OCV Lid Inspection**RA D-1.1 Check the OCV lid for damage as follows:

- ~~A.~~ visible deformation
- ~~B.~~ dents or abnormal flat spot > ½ inch
- ~~C.~~ abnormal scratches or gouges
- ~~D.~~ obvious punctures, tears, or cracks in exposed welds
- ~~E.~~ distortions or cracks on or around lifting attachments.

RA D-1.2 Check the OCV lid and ensure the following conditions have been met:

- ~~A.~~ plastic burn-out plugs (3) are in place and intact
- ~~B.~~ fiberglass tubes are in place
- ~~C.~~ lid lift pocket covers are attached and serviceable
- ~~D.~~ OCV locking Z-Flange screws are in place and tight
- ~~E.~~ guide plates and screws are in place and tight
- ~~F.~~ locking ring is clean and undamaged
- ~~G.~~ sealing surfaces are clean and undamaged
- ~~H.~~ test access port threads are clean and undamaged.

D-1.2.1 Remove any foreign material found on the lock ring, sealing surfaces, or test access port threads.

**D-2. OCV Body Inspection**M D-2.1 Remove the upper and lower main O-rings and ensure they are clean and undamaged.RA D-2.2 Check the OCV body (outer shell) for damage as follows:

- ~~A.~~ obvious punctures or tears
- ~~B.~~ obvious cracks in exposed welds
- ~~C.~~ dents or abnormal flat spot > ½ inch
- ~~D.~~ abnormal scratches or gouges.

RA D-2.3 Check the OCV body and ensure the following conditions have been met:

- ~~A.~~ six burn-out plugs are in place and intact
- ~~B.~~ eight forklift pocket inserts are intact and threads are undamaged
- ~~C.~~ six lock ring threaded in      intact and threads are undamaged

**TRUPACT-157 UNLOADING AND LOADING  
RECOVERY OPERATIONS AT TAN**Identifier: TPR-6230  
Revision: 0  
Page: 52 of 52**APPENDIX D**

- ~~D.~~ ceramic fiber gasket is intact and undamaged (no tears or excessive wear)
- ~~E.~~ test port and threads are clean and undamaged
- ~~F.~~ vent port and threads are clean and undamaged
- ~~G.~~ lock ring flange is clean and undamaged
- ~~H.~~ O-ring grooves are clean and undamaged
- ~~I.~~ Sealing surfaces are clean and undamaged.

D-2.3.1 Remove any foreign material found on items E through I.

**D-3. OCV Component Inspection**

RA D-3.1 Clean and inspect the following OCV components and ensure the noted conditions have been met:

- ~~A.~~ OCV vent port access plug is clean and undamaged
- ~~B.~~ OCV vent port plug and O-rings are clean and undamaged
  - Seal O-ring is clean and intact
- ~~C.~~ OCV vent port cover and O-rings are clean and undamaged
  - Seal O-ring is clean and intact
- ~~D.~~ OCV test port access plug is clean and undamaged.
- ~~E.~~ OCV test port plug and O-rings are clean and undamaged
  - O-ring is clean and intact
- ~~F.~~ lock ring bolts (6) are clean and undamaged
- ~~G.~~ annulus debris shield is installed and intact
- ~~H.~~ upper main O-ring is clean and undamaged
- ~~I.~~ lower main O-ring is clean and undamaged.

NA11-28-03

D-3.2 IF any O-ring is damaged,  
THEN replace the O-ring per WI CH.01/CH.02.

RA D-3.3 Apply a very light coat of vacuum grease to the following:

- ~~A.~~ OCV vent port plug threads and sealing O-ring
- ~~B.~~ OCV vent port cover threads and sealing O-ring
- ~~C.~~ OCV test port plug threads and O-ring
- ~~D.~~ upper main O-ring
- ~~E.~~ lower main O-ring.

RA D-3.4 Apply a light coat of Nickel bearing lubricant to the following:

- ~~A.~~ OCV lock ring bolt threads (6)
- ~~B.~~ OCV test port access plug threads
- ~~C.~~ OCV vent port access plug threads

RA D-3.5 Reinstall the upper and lower main O-rings.

Job/Title TPR-6230, TRUPACT-157 Unloading and Loading Recovery Operations at TAN		JSA Number TAN-JSA-6230		Revision 0	
Facility/Project & Location TAN-607		Effective Date 11/26/02		Facility/Project Management/Supervisor Approval /	
		Expiration Date 11/26/03		Date	
See DAR 96818					
SME APPROVAL (A "Yes" response requires a signature and date.)					
No	Yes	SME	Signature	Date	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Industrial Safety	See DAR 96818		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Industrial Hygiene	See DAR 96818		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Safety Analysis	See DAR 96818		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	RCT/RAD Eng.	See DAR 96818		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Operations	See DAR 96818		
<b>Briefly Describe The Job and Expected Result</b> This job unloads the TPUPACT-157 at Test Area North (TAN), removes the Inner Containment Vessel (ICV) from the Outer Containment Vessel (OCV), and loads the OCV. <b>Required Job Training/Required Personal Protective Equipment</b> Training: Radworker II, HAZWOPER/TSD, TAN access Job position, hoisting and rigging, pre-job briefing. PPE: Safety shoes, leather gloves, latex/nitrile/butyl rubber gloves, safety glasses with side shields, and other PPE as required by the RWP.					

Q-57

Judence Of Basic Job Steps		Potential Hazards	Hazard Control/PPE (other than that listed above)
1. General	a. Pinching, smashing	a. Pinching, smashing	a. Two spotters must be present when using the forklift to move containers.
	b. Hoisting/rigging	b. Hoisting/rigging	b. Critical lifts require use of a Person in Charge (PIC). Periodic inspections are performed on hoisting and rigging equipment.
	c. Pinching, cuts, scrapes, and burns	c. Pinching, cuts, scrapes, and burns	c. Leather gloves must be worn when handling hot surfaces.
	d. Foot injury	d. Foot injury	d. Safety shoes must be worn when in the TAN Hot Shop.
	e. Smashing	e. Smashing	e. Parts of the body must not be placed under suspended loads with the following exceptions: ACGLF adjustments/log changes, and guiding leg insertions.
	f. Pinching	f. Pinching	f. Non-essential personnel must stay clear during ACGLF operation.
	g. Radiological	g. Radiological	g. Ensure RWP is followed and use good ALARA practices.
	h. Carbon monoxide exposure	h. Carbon monoxide exposure	h. If fossil-fueled vehicle runs continuously, without a ventilation hose attached, for more than approximately 10 minutes inside the building a CO monitor must be obtained from Industrial Hygiene for use.
	i. Lifting strain	i. Lifting strain	i. Proper lifting techniques must be used when handling heavy objects.
	j. Confined space	j. Confined space	j. The interior of the TRUPACT-II is a non-permit confined space. Only hands/arms may break the plane of the TRUPACT-II interior. Contact IH for further direction is the face must break the plane.
	k. Heat stress	k. Heat stress	k. Heat stress monitoring must be performed per MCP-9240.

Sequence Of Basic Job Steps	Potential Hazards	Hazard Control/PPE (other than that listed above)
2. TRUPACT-II Trailer Preparations	a. See general hazards b. Waste disposal	b. Used cleaning materials must be managed per INEEL waste management procedures.
3. Releasing Tiedowns	a. See general hazards	
4. Transfer the TRUPACT-II	a. See general hazards	
5. Unloading a Payload Assembly	a. See general hazards b. Non-permit confined space	b. A survey extension tool must be used when surveying the interior of the TRUPACT-II.
	c. Ergonomic	c. Personnel awareness and good body positioning, use of multiple operators, and use of extended handle must be practiced when rotating the ICV or OCV lock ring assembly.
	d. Chemical	d. IH perform volatile organic compound (VOC) air sampling of OCV/ICV lid interior.
6. ICV Lid Installation	a. See general hazards b. Ergonomic	b. Personnel awareness and good body positioning, use of multiple operators, and use of extended handle must be practiced when rotating the ICV or OCV lock ring assembly.
7. OCV Removal from OCV	a. See general hazards b. Non-permit confined space	b. A survey extension tool must be used when surveying the interior of the TRUPACT-II.
8. OCV Lid Installation	a. See general hazards	
9. Transfer TRUPACT-II to Transport Trailer	a. See general hazards b. Chemical c. Lifting/pinching	b. Latex, nitrile or butyl rubber gloves and safety glasses with side shields must be worn when using nickel-based anti-seize compound. c. Use proper lifting techniques and be aware of pinching hazards when disassembling/reassembling platforms.
10. Releasing the TRUPACT-II Trailer	a. See general hazards	



DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS)  
DOCUMENT ACTION REQUEST (DAR)

1. Document ID: TAN-JSA-6230 Current Revision ID: Rev 11/16/02 HS See Block 8 for DAR # Info.

2. Document Title: TPR-6230, TRUPACT-15? Revised Unemployment Operations and TAN Unemployment and Location Release

3. No. of Pages: 3. Page 1 of 3 Phone: 6-0754 MS: 8893 E-mail: ops@epamail.mil S No.: 090227

4. Type: ☒ Document ☐ Drawing 5. Type of action: ☒ Create ☐ Revise ☐ Cancel

6. Field Change: ☒ No ☐ Yes If Yes, what the change be: ☐ Permanent or ☐ Temporary? If Temporary, enter the field change duration

7. Proposed Action: Create new procedure

Item	Page No./Section/Zone	Description	Justification
1	All	Create new JSA per attached.	A Hazardous Evaluation Group (HEG) review and associated Job Safety Analysis (JSA) is required for TPR-6230.

8. Proposal Approval: ☒ Accepted ☐ Deferred ☐ Rejected DAR No.: 96818  
If rejected, indicate reason: \_\_\_\_\_ (For Accepted Proposals Only)

Document Owner Printed Name: K. E. Streger Signature: K. E. Streger Date: 11-19-02

Is this a minor document change? ☒ No ☐ Yes If Yes, proceed to Block 14. (For Operations procedures, go to Block 11.)

9. Management Approval (Including drawings, minor changes, & field changes):  
Printed Name: K. E. Streger Signature: K. E. Streger Date: 11-19-02

10. Implementation Actions - Will the proposal require:  
Hazard mitigation per MCP-3562 or MCP-3871? ☐ No ☒ Yes If Yes, This is JSA for TPR-6230  
Training? ☐ No ☒ Yes If Yes, Pre-job briefing  
Procurement activities? ☒ No ☐ Yes If Yes, \_\_\_\_\_  
Building modifications? ☒ No ☐ Yes If Yes, \_\_\_\_\_  
Other: None

11. Include a list of reviewers and review comments and resolutions with this form or have reviewers sign below.

Printed Name	Designation	Org. No.	Signature	Date
K. M. Wozniak	TAN System Engineer	5235	<u>K. M. Wozniak</u>	<u>11/19/02</u>
J. E. ...	Operations	5107	<u>J. E. ...</u>	<u>11/19/02</u>
J. Walker	Safety Analyst	5200	<u>J. Walker</u>	<u>11/19/02</u>
J. K. Hizer	TAN QA	5125	<u>J. K. Hizer</u>	<u>11/19/02</u>
B. R. Chinnese	TAN Industrial Safety	5240	<u>B. R. Chinnese</u>	<u>11/19/02</u>
D. J. Sorenson	TAN RiskCon	7610	<u>D. J. Sorenson</u>	<u>11-19-02</u>
B. C. Combs	TAN IH	5410	<u>B. C. Combs</u>	<u>11/19/02</u>
D. Clark	Fire Protection		<u>D. Clark</u>	<u>11/19/02</u>

12. Is document a TPR or EAP? ☒ No ☐ Yes If Yes, indicate procedure validation method used:  
☐ Formal Walkdown ☐ Tabular Analysis ☐ Limited Trial Use/Field Use ☐ Partial Validation

13. Change does not affect a permitted area, TSD facility, or VCO component. (ICRA evaluation NOT required. Proceed to Block 14.)  
☒ Change does affect a permitted area, TSD facility, or VCO component.  
Is ICRA permit application needed? ☐ No ☐ Yes ☐ Unknown  
If Yes or Unknown, attach completed Form 438 29 or reference form's location here: \_\_\_\_\_

\_\_\_\_\_  
Evaluator Printed Name  
\_\_\_\_\_  
Evaluator Signature  
Date: 11-19-02

Is VCO component affected? ☐ No ☐ Yes If Yes, contact the VCO Program Office for direction.

14. USO Screening: (To be completed only after final document review.) List any associated change forms: \_\_\_\_\_

\* Fire protection will review the procedure which covers the fire handling for the Hot Cell. exp 11/19/02

412.11  
09-12-2002  
Rev. 09

DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS)  
DOCUMENT ACTION REQUEST (DAR)

1. Document ID: TAN-JSA-6230		Current Revision ID: 0 3860 11/26/02		See Block 8 for DAR V info.	
2. USQ screening required? (See instructions) <input type="checkbox"/> Not Required (Proceed to Block 15) <input checked="" type="checkbox"/> Required (Submit document and DAR to qualified USQ reviewer and attach USQ screening form.) 3. USQ Evaluation Required? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, attach evaluation. See USQ for TPA-6230					
15. Does this action qualify as a periodic review? <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> N/A					
16. Desired effective date for document: Date of Block 18					
17. Other documents affected by this action: TPA-6230					
18. Document Owner Final Approval: (Changes to address those identified on the DAR, if applicable, are being approved during the review process. See document case for list of changes.) Approval signifies implementation of changes, including any necessary new revised documents. K. E. Strepper Document Owner Printed Name [Signature] Document Owner Signature 11-26-02 Date					
19. Drawing Checker Approval & Date: N/A		20. Document Control Approval & Date: [Signature] 11-26-02		21. Document Control Location: TAN-607 20/12/02	
22. Comments:			23. New Revision ID: 0		

# INSPECTION IN SITUATION FORM

6.19  
1/16/2000  
av. 03

RED ORIGINAL, BLACK COPY

INSPECTION RECORD COPY

specification Type: Construction ☐ Operations ☒ Receiving ☐ Source ☐ Requisition No.: N/A

title/Description/Item: Quality Inspection of TRUPACT-157 Unloading and Loading Recovery Operations At Test Area North (TAN)

sec. No.: N/A Rev.: N/A Dwg. No.: As listed in TPR-6230 Rev.: N/A

sp. Plan No.: INTEC-QA-0208 ID No. (Work Order/Project/Purchase Order etc.): TPR-6230, rev. 0 Quality Level: SC/QL-1

specification Planner: Alan Huot A. Huot Date: 11/27/02 Requesting Organization Review (Optional): Kraig Wendt Date: 11/27/02

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector Initial & Date
	<p><b>GENERAL INSTRUCTIONS</b></p> <p>This inspection plan is written for the Quality Inspector (QI) to inspect the loading and unloading operation of the Transuranic (TRU) Package Transporter (TRUPACT)-II Serial Number 157. This activity includes the removal of the Inner Containment Vessel (ICV) from the Outer Containment Vessel (OCV) at the Test Area North (TAN) Hot Shop.</p> <p>Applicable figures, if any, for this scope of work, are located in the associated Technical Procedure (TPR).</p> <p>If any anomalies are identified, immediately notify the OF or SS. If issues are not resolved by the OF or SS, notify the Shift Lead QE/QA Technical Lead and record the notification information on this form.</p> <p><b>Note: Work will be evaluated per MCP-553 until issues are satisfactorily resolved.</b></p> <p>When specific steps of TPR-6230 are not performed because the applicable portion of the TPR is not required to be performed, the corresponding step on this form must be Marked "N/A" and initialed and dated by the QI.</p> <p><b>PREREQUISITES:</b></p> <p>A qualified and certified QI certified per the requirements of MCP-535 shall perform all inspections.</p> <p>A. Inspections shall be performed by a General Level II QI that is RWMC TRUPACT-II certified.</p> <p>B. Indicate inspection status on all inspection steps/items in the Inspection Status column of this Inspection Plan (IP) with the following nomenclature: "sat" or "unsat"/"acceptable" or "unacceptable". QI add your initials and inspection date.</p> <p>C. Any unacceptable inspection results shall be documented on a Quality Inspection Report, form # 414.03 with reference back to the work authorization document and Step# that is associated with the step, item or process.</p> <p>D. Record all NCR's issued against this item/process in the "Inspection Status" column of this IP that it is associated with. The document should reference back to the work authorization document.</p> <p>E. Attach all inspection reports to this IP documenting work covered.</p> <p>F. Ensure all unacceptable inspection reports are noted in the work authorization document.</p> <p>G. Ensure suspect counterfeit items covered by MCP-9110 are not used in the process of this IP.</p> <p>H. QI shall verify that all in-process and final inspections are performed to the latest figure revisions.</p> <p>I. QI shall sign/initial both the appropriate TPR-6230 Steps and this Inspection Instruction Form.</p>	N/A	N/A

# INSPECTION INSTRUCTION FORM

16.19  
12/16/2000  
Rev. 03

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector Initials & Date
1.	Verify TPR Number, Title, and Revision Number.		SAT RCS 1-27-03
2.	<p><b>PERFORM THIS INSPECTION AT ANY TIME PRIOR TO LOADING THE TRUPACT ON THE TRAILER</b></p> <p>Visually inspect accessible portions of the exterior of the trailer and TRUPACT-II containers for damage. If damage other than cosmetic damage is noted (e.g., cracked locking ring welds) take appropriate action per the <b>GENERAL INSTRUCTIONS</b> of this IP.</p> <p>(Management Request)</p> <p>Verify that there is no trailer or TRUPACT-II damage recorded on the package shipping forms.</p> <p>(Management Request)</p> <p><b>Note:</b> This inspection should be performed at TAN prior to the trailer leaving for WIPP. If damage is recorded on any of the shipping forms, notify the Shift QE/QA Technical Lead, and follow the <b>GENERAL INSTRUCTIONS</b> of this IP.</p>		
3.	<p>Ensure that tamper indicating devices (TIDs) have not been damaged.</p> <p><b>Note:</b> Should there not be any TIDs (seals), "N/A" this inspection, initial and date. Should TIDs be damaged, stop work and notify the TL/SS, follow the <b>GENERAL INSTRUCTIONS</b> of the IP.</p> <p>(Step 4.5.2.1)</p>	Vent Port TID Found broken. Notifications Made. Received Permission To Proceed.	See Remarks RCS 1-27-03
4.	<p>During OCV lid removal, verify that components are placed into labeled storage container.</p> <p>(Step 4.5.4.1)</p>		RCS 1-27-03 SAT
5.	<p>During ICV lid removal, verify that components are placed into labeled storage container.</p> <p>(Step 4.5.15.2.1)</p>		SAT RCS 1-27-03
6.	<p>Record torque wrench serial number and calibration due date in TPR-6230.</p> <ul style="list-style-type: none"> <li>Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6230)</li> <li>Verify calibration is current.</li> </ul> <p>(Step 4.8.3)</p>		SAT RCS 1-28-03

# INSPECTION IN SUCCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector Initials & Date
7.	Verify OCV seal test port plug is installed and torqued to specified values. (55 to 65 in.-lbs. OR 4.6 to 5.5 ft.-lbs.). (Step 4.8.4.1)		SAT RCS 1-28-03
8.	Record torque wrench serial number(s) and calibration due date in TPR-6230 for port plugs and lock ring bolts. • Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6230) • Verify calibration is current. (Step 4.8.11)		SAT RCS 1-28-03
9.	Verify torque of the OCV vent port plug and cover to specified values. (55 to 65 in.-lbs. OR 4.6 to 5.5 ft.-lbs.). (Step 4.8.13)		SAT RCS 1-28-03
10.	Verify torque of vent port/access plug, and thermal plug and seal/test port access plug and thermal plug to specified values. (420 to 540 in.-lbs. OR 35 to 45 ft.-lbs.). (Step 4.8.14)		SAT RCS 1-28-03
11.	Verify torque of OCV lock-ring bolts to specified values (336 to 384 in.-lbs. or 28 to 32 ft.-lbs.). (Step 4.8.15.1)		SAT RCS 1-28-03
12.	Using a GO-NO-GO gauge, verify gap between disk spring container block and compression plate assembly of each tie-down. (Step 4.9.8.2)		SAT RCS 1-29-03
13.	Inspect TRUPACT-II forklift pocket access covers for damage. Note: Should the forklift access covers be damaged, stop work and notify the TL/SS and follow the GENERAL INSTRUCTIONS of this IP. (Step 4.9.11)		SAT RCS 1-29-03
14.	QE complete Quality Inspection Plan documentation required by Step 4.11 of the TPR. (Step 4.11)		K. Kulev SAT 2/3/03

# INSPECTION IN .UCTION FORM

16.19  
2/16/2000  
lev. 03

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector Initials & Date
	<p>OPTIONAL/ADDITIONAL COMMENTS:</p>		

C-64

Final Inspection Documentation Review: Stavric / [Signature] Date: 2/13/03 / 2-3-03

433.34  
05/13/02  
Rev. 00


## INEEL LIFT PLAN

Page 1 of 2

### SEE INSTRUCTIONS

Lift Category: ☐ Critical Lift ☒ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)  
Responsible Person: Doug Wale Phone: 6-1102 Date: 11/4/02  
Facility: TAN-607 W.O./Procedures No.: TPR 6230 Index No. (optional): TP 157-01-0  
Task: OCV LID HANDLING

### Rigging Configuration Sketch



USE OF LOAD CELL  
AND ASSOCIATED SHACKLES  
IS OPTIONAL. SHACKLES MAY  
BE ADDED TO ACCOMMODATE  
DIFFERENT LOAD CELL  
CONFIGURATIONS  
(MIN SWL 10,000 POUNDS)

ORIGINAL IS RED

Weights:

3750 lbs

Dimensions:

~ 6 ft diameter

Comments:

Ref. RWMC lift plan from TPR-1668 Fig B-2 Rev 1.Dwg DAR 33980

### APPROVALS

N/A

Responsible Manager  
Print/Type Name

**S. R. GAMACHE**

Safety Engineer  
Print/Type Name

**BRET PAYNE**

H&R Engineer  
Print/Type Name

Responsible Manager  
Signature

Safety Engineer  
Signature

H&R Engineer  
Signature

Date

**11/7/02**

Date

**11/7/02**

Date

C-65

433.34  
05/13/02  
Rev. 00


## INEEL LIFT PLAN

Page 1 of 2

### SEE INSTRUCTIONS

Lift Category: ☒ Critical Lift ☐ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)  
Responsible Person: Doug Wale Phone: 6-1102 Date: 11/4/02  
Facility: TAN-607 W.O./Procedures No.: TPR 6230 Index No. (optional): TP 157-02-0  
Task: ICV LID HANDLING

### Rigging Configuration Sketch



ORIGINAL IS RED

#### Weights:

945 lbs

#### Dimensions:

~ 6 ft diameter

#### Comments:

Ref: RWMC lift plan from TPR-1668 Fig B-3 Rev 1.Dwg DAR 33980  
Internal vessel may be contaminated from previous condition.

### APPROVALS

Kevin Streep

Responsible Manager  
Print/Type Name

[Signature]

Responsible Manager  
Signature

11-7-02

Date

S. R. GAMACHE

Safety Engineer  
Print/Type Name

[Signature]

Safety Engineer  
Signature

11/7/02

Date

BRET PAYNE

H&R Engineer  
Print/Type Name

C-66

[Signature]

H&R Engineer  
Signature

11/7/02

Date



## INEEL LIFT PLAN

### SEE INSTRUCTIONS

Lift Category: ☒ Critical Lift ☐ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)

Responsible Person: Doug Wale

Phone: 6-1102

Date: 11/4/02


Facility: TAN-607

W.O./Procedures No.: TPR 6230

Index No. (optional): TP 157-03-0

Task: Payload Handling

### Rigging Configuration Sketch



MAXIMUM TOTAL LOAD ON ACGLF: 7265 POUNDS

Weights:  
7265 lbs

Dimensions:  
~ 6 ft diameter x 7 ft height. (Double stack drum array)

Comments:  
Ref: RWMC lift plan from TPR-1648 Fig B-1 Rev 1.Dwg DAR 33891  
Internal vessel may be contaminated from previous condition.

ORIGINAL IS RED

### APPROVALS

Kevin Streiper

Responsible Manager  
Print/Type Name

Ken Streiper

Responsible Manager  
Signature

11-7-02

Date

S.R. GAMACHE

Safety Engineer  
Print/Type Name

S.R. Gamache

Safety Engineer  
Signature

11/7/02

Date

BRET PAYNE

H&R Engineer  
Print/Type Name

C-67

Bret Payne

H&R Engineer  
Signature

11/7/02


Date

## INEEL LIFT PLAN

### SEE INSTRUCTIONS

Lift Category: ☐ Critical Lift ☒ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)  
Responsible Person: Doug Wale Phone: 6-1102 Date: 11/4/02  
Facility: TAN-607 W.O./Procedures No.: TPR 6230 Index No. (optional): TP 157-04-0  
Task: ICV Handling

### Rigging Configuration Sketch



USE OF LOAD CELL  
AND ASSOCIATED SHACKLES  
IS OPTIONAL. SHACKLES MAY  
BE ADDED TO ACCOMMODATE  
DIFFERENT LOAD CELL  
CONFIGURATIONS  
(MIN SWL 10,000 POUNDS)

ORIGINAL IS RED

ICV #157  
LID WEIGHT: 945 POUNDS  
BODY WEIGHT: 1,820 POUNDS  
TOTAL ICV WEIGHT: 2,765 POUNDS

Weights:  
2765 lbs

Dimensions:  
~6 ft diameter x 8 ft height

Comments:  
Ref: RWMC lift plan from ICV #157 rigging.dwg

### APPROVALS

Responsible Manager Print/Type Name	Responsible Manager Signature	Date
N/A		
S. R. GAMACHE		11/7/02
Safety Engineer Print/Type Name	Safety Engineer Signature	Date
BRET PAYNE	Bret Payne	11/7/02
H&R Engineer Print/Type Name	H&R Engineer Signature	Date

C-68

**SEE INSTRUCTIONS**

Lift Category: ☐ Critical Lift ☒ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)

Responsible Person: Doug Wale

**Phone: 6-1102**

Date: 1-27-03

Facility: TAN-607

W.O./Procedures No.: TPR-6230

Index No.: TP 157-01-0

**Task: OCV Lid Handling**


[illegible]

**Comments:**

**Qualified Operator or Rigger:** Perform pre-operational checks listed on back of this form prior to first use, on a shift.

JAKE GREEN

Qualified Operator or Rigger  
Print/Type Name

  
 Qualified Operator  
 Signature

Qualified Operator or Rigger  
Signature

1/27/03  
Date

Date \_\_\_\_\_

Qualified Rigger (If different than Operator)  
Print/Type Name

Qualified Rigger (If different than Operator)  
Signature

Date \_\_\_\_\_

**Person in Charge (PIC) or Designated Leader (DL):** Verify that rigging has been inspected and that the configuration is consistent with corresponding INEEL Lift Plan Form 433.34. (Additional lines are provided for identically configured lifts that occur during the same shift.)

PIC or DL  
Print/Type Name

R. L. KY. VASTON

R. L. CYRILASTON

PIC or DL  
Signature

7625

26+27/

Date/Time

1-27-03/1220

1-28 0.5/17.50



**SEE INSTRUCTIONS**

Lift Category: ☒ Critical Lift ☒ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)

Responsible Person: Doug Wale Phone: 6-1102 Date: 1-28-03

Facility: TAN-607      W.O./Procedures No.: TPR-6230      Index No.: TP 157-02-0

### Task: ICV Lid Handling

[illegible]

**Comments:**

Qualified Operator or Rigger: Perform pre-operational checks listed on back of this form prior to first use on a shift.

TAKE GREEN

**Qualified Operator or Rigger**  
**Print/Type Name**

Qualified Operator or Rigger  
Signature

1/28/03  
Date

Qualified Rigger (If different than Operator)  
Print/Type Name

Qualified Rigger (If different than Operator)  
Signature

Date \_\_\_\_\_

Person in Charge (PIC) or Designated Leader (DL): Verify that rigging has been inspected and that the configuration is consistent with corresponding INEEL Lift Plan Form 433.34. (Additional lines are provided for identically configured lifts that occur during the **same** shift.)

PIC or DL  
Print/Type Name

**PIC or DL  
Signature**

Date/Time

K.L. KYNASTON

~~2472~~

1-28-03 / 1645

**SEE INSTRUCTIONS**

Lift Category: ☐ Critical Lift ☒ Pre-Engineered Product Lift ☐ Personnel Lift ☐ Ordinary Lift (optional)

Responsible Person: Doug Wale Phone: 6-1102 Date: 1-28-83

Facility: TAN-607      W.O./Procedures No.: TPR-6230      Index No.: TP 157-03-0

### Task: Payload Handling

[illegible]

**Comments:**

Qualified Operator or Rigger: Perform pre-operational checks listed on back of this form prior to first use on a shift.

Jake Green

Qualified Operator or Rigger  
Print/Type Name

Qualified Operator or Rigger  
Signature

1-28-03

Date \_\_\_\_\_

Qualified Rigger (If different than Operator)  
Print/Type Name

**Qualified Rigger (If different than Operator)**  
**Signature**

Date \_\_\_\_\_

Person in Charge (PIC) or Designated Leader (DL): Verify that rigging has been inspected and that the configuration is consistent with corresponding INEEL Lift Plan Form 433.34. (Additional lines are provided for identically configured lifts that occur during the **same** shift.)

PIC or DL  
Print/Type Name

Print/Type Name J. L. L. Taylor

PIC or DL  
~~Signature~~

Signature

Date/Time

1-28-03/1200  
~~1-28-03/1200~~



# REQUEST FOR RADIOACTIVE MATERIAL SHIPMENT

## Requestor Use Only

FROM: TAN 607 HOT SHOP FOR U.S. DOE Phone: grifmd@inel TO: RWMC FOR U.S. DOE Phone: 526-2767  
Mike Griffin Email: .gov SCOVILLE, ID  
83415

Chrg. No.: 200123FQ9 Org. No.: 3240

Desired shipping date: 2/4/2003

Required arrival date: 2/4/2003

Purpose of shipment: Transport TRUPACT 157 contents back to RWMC

Consignee notified/agrees to accept delivery Yes ☒ No ☐

Consignee: Randy Kendrick

Authorization No.: N/A

Radioactive License No.: N/A

Radionuclide	Activity (TBq)	Weight of material containing activity (grams)
--------------	----------------	--

See Attachments

Material net weight: 14650

Material net vol.: \_\_\_\_\_

Chemical Form: Oxides

Physical Form: Solid ☒ Liquid ☐ Gas ☐

Normal Form ☒ Special Form ☐ (Requires certification)

Additional Hazards: N/A

Preliminary RadCon Info:

3m from unshielded: N/A

1m from package: \_\_\_\_\_

Contact @ package: \_\_\_\_\_

Additional containers will require attachment sheet.

State container(s) activity data may defer to IWTS or TRIPS

## Waste Information

IWTS Material Profile No.: N/A

IWTS TASK No.: N/A

UHMW required? Yes ☒ No ☐

IWTS Container(s) No.: N/A

## Package Data

Describe current or proposed packaging: Seven WIPP Standard Waste Boxes, one plywood box with ICV

UN or DOT#: 7A-Type A

C of C No.: N/A

TID No.: N/A

No. of packages: 8

Size: SWB (4X6)

1A2 55-gallon  
Type: drums

Gross wt./ pkg: N/A

Shipment gross wt.: 14650

Inner package? Yes ☒ No ☐

Size: 55 gallon

Type: Metal drums

NOTES: This shipment will require two transport vehicles.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS  
CORRECT AS INDICATED.

Requestor Print/Type Name Michael D. Griffin

Requestor Signature Michael D. Griffin

Date 2/3/2004

## RadCon Use Only

### Preshipment Survey Results

All required surveys are complete and results  
approved by supervisor have been provided to P&T.

RadCon Tech Printed Name and Signature

Date



## PRE-JOB BRIEFING CHECKLIST

Title: TRUPACT 157 RAILROAD DISASSEMBLY OPS Procedure or Tracking #: TPK-6233

Name/Title of Person Conducting Briefing: K.L. KYNASTON

Date/Time: 2-3-03 1105

The objective of a good pre-job briefing is to communicate an understanding of scope, hazards, and mitigation to enable the safe completion of work. Follow MCP-3003 for requirements. Additional Radiological Work Permit requirements found in box 10, page 2.

Initial each box upon completion of the section during the pre-job briefing. Mark N/A in the comment box if this section is not applicable to this job.

Initials

1. Discuss Scope of Work to be Performed and Limiting Conditions

KL

Comments:

2. Review Hazards of the Job and Mitigation of those Hazards (JSA's, Permits, LO/TO)

KL

Comments:

3. Review Work Procedures and Initial Conditions Involved

KL

Comments:

4. Discuss Emergency Escape Routes

KL

Comments:

5. Discuss Roles and Responsibilities / Stop Work / Training, and Work Restrictions

KL

Comments:

6. Discuss Needed Tools and Equipment

KL

Comments:

7. Discuss Safety / Radiological (see box 10) / Environmental Requirements/Wastes

KL

Comments:

8. Discuss Error Likely / Feedback / Lessons Learned

KL

Comments:

9. Summarize Scope / Hazards / and Responsibilities

KL

Comments:

Title: T-157 (PAYLOAD) DISASSEMBLY OF 22470005 Procedure or Tracking #: TIR-6233

<b>10. Minimum Radiological Work Permit (RWP) Requirements</b>	<b>Additional Notes and Comments and other Building/Equipment/Process specific pre-job checklists covered.</b>
Scope of work Radiological conditions of the workplace Procedural and RWP requirements Special radiological control requirements Radiologically limiting conditions (may void RWP) Radiological control hold points Communication & coordination with other groups Housekeeping and final cleanup provisions Emergency response provisions	RE PREJOB FOR DAR # 98552

[illegible]

- (1) Supervisor initials to verify employee's required training for planned work is current. Mark N/A for not applicable.  
(2) Worker's initials indicate attendance at the pre-job briefing and satisfactory understanding of all items discussed.

By my signature, I indicate that I have conducted the pre-job briefing covering all items indicated above concerning the requirements specified for the work to be performed.

Person Conducting Briefing: [Signature] Date/Time: 2-3-03 / 1120

# PRE-JOB BRIEFING ATTENDANCE RECORD

Page 3 of 3

Jrk Documentation Tracking/Procedure Number: TPR-6233

Attach filled out form to applicable work control/permit documentation prior to starting work OR file as required by area/organizational procedures. Make copies as necessary.

Print Names of Workers	Training (1)	S/Visitor Badge No.	Craft or Job Title	Company Name (2)	Briefing Date	Worker's Initials (3)
Michael J. Galassi	ML	67558	SO	BBWI	2/3/03	MJG
JAMES WOOLSKI	NAIKL	71715	Observer	DOE-ID	23-03	JW
Jimmy Hernandez	ML	58172	Mech	BBWI	2/3/03	JH
RC JUSTICE	ML	85304	QI	BBWI	2/3/03	RCJ
F. Bush	ML	61058	RCT	BBWI	2/3/03	FB
J. Ely	ML	86250	RCT	BBWI	2/3/03	JE
JAKE GREEN	ML	78067	ops		2/3/03	JG
Lyle McKinnair	ML	51945	RCT		2-3-03	LK
Rocky Allen	ML	56604	mech.	BBWI	2/3/03	RA
John Killian	ML	77456	ops	BBWI	2/3/03	RK
Jody L. Schmardebeck	ML	52993	SO	BBWI	2-3-03	JS
Kelly Hoyle	ML	39819	SO	BBWI	2/3/03	KH
Lewis Bird	ML	53447	RCT		2-3-03	LB
Roger Jackson	ML	50666	RCT		2-3-03	RJ
Ed Lang	ML	50699	RCT		2-3-03	EL
Jon Johnston	ML	62673	RCT		2-3-03	JN
Gary L. Lusk	NAIKL	56428	Lab Cow		2-3-03	GL

- Supervisor initials block verifying employee's training required to complete the planned work is current, mark N/A for not applicable when special training (ES&H or other) not required.
- Briefing attendee required to fill this block if other than company employees, may leave blank for company employees.
- Worker's initials to indicate attendance at pre-job briefing and satisfactory understanding for all items discussed.

## PRE-JOB BRIEFING CHECKLIST

Title: FIRE ALARM OPERATIONS

Procedure or Tracking #: 2012-6233

Name/Title of Person Conducting Briefing: H. L. KILGUSTON

Date/Time: 1-31-03 / 1000

The objective of a good pre-job briefing is to communicate an understanding of scope, hazards, and mitigation to enable the safe completion of work. Follow MCP-3003 for requirements. Additional Radiological Work Permit requirements found in box 10, page 2.

Initial each box upon completion of the section during the pre-job briefing. Mark N/A in the comment box if this section is not applicable to this job.

Initials

**1. Discuss Scope of Work to be Performed and Limiting Conditions**

KL

Comments:

**2. Review Hazards of the Job and Mitigation of those Hazards (JSA's, Permits, LO/TO)**

KL

Comments:

**3. Review Work Procedures and Initial Conditions Involved**

KL

Comments:

**4. Discuss Emergency Escape Routes**

KL

Comments:

**5. Discuss Roles and Responsibilities, Stop Work, Training, and Work Restrictions**

KL

Comments:

**6. Discuss Needed Tools and Equipment**

KL

Comments:

**7. Discuss Safety, Radiological (see box 10), Environmental Requirements/Wastes**

KL

Comments:

**8. Discuss Error Likely, Feedback, Lessons Learned**

KL

Comments:

**9. Summarize Scope, Hazards, and Responsibilities**

KL

Comments:

# PRE-JOB BRIEFING CHECKLIST

Title: RAILROAD DISASSEMBLY  
TRUCK OPERATIONS

Procedure or Tracking #: TPR-6233

<b>10. Minimum Radiological Work Permit (RWP) Requirements</b> Scope of work Radiological conditions of the workplace Procedural and RWP requirements Special radiological control requirements Radiologically limiting conditions (may void RWP) Radiological control hold points Communication & coordination with other groups Housekeeping and final cleanup provisions Emergency response provisions	Additional Notes and Comments and other Building/Equipment/Process specific pre-job checklists covered.  REMOVING DAMAGED GLASSLET MATERIAL ON SWB LIDS, RE-INSTALLING AND INSPECTING GLASSETS, CONTINUING OPERATIONS
--	---

Print Names of Workers	Training (1)	Badge No.	Craft or Job Title	Company Name (If not INEEL)	Briefing Date	Worker's Initials (2)
Rocky Allen	UL	516104	MECH.	BBWI	1/31/03	RA
Timothy Hernandez	UL	58172	MECH.	BBWI	1/31/03	JPH
Blaise J. McMurtry	UL	44306	CARP.		1-31-03	BFM
Joey L. Schmandbeck	UL	52993	SO	BBWI	1-31-03	JLS
Ed Lang	UL	50699	RCT	BBWI	1-31-03	EL
RC Justice	UL	85504	QI	BBWI	1-31-03	RJ
JAKE GREEN	UL	78067	OPS		1-31-03	JG
Michael J Galassi	UL	67558	SO	BBWI	1-31-03	MJG
Mr. (S) S	UL	40535	SO	BBWI	1-31-03	MS
L McKinlay	UL	51945	RCT		1-31-03	LM
Robin Killian	UL	77456	OPS		1/31/03	RK
Levi's Bird	UL	52447	RCT		1-31-03	LB

- (1) Supervisor initials to verify employee's required training for planned work is current. Mark N/A for not applicable.  
 (2) Worker's initials indicate attendance at the pre-job briefing and satisfactory understanding of all items discussed.

By my signature, I indicate that I have conducted the pre-job briefing covering all items indicated above concerning the requirements specified for the work to be performed.

Person Conducting Briefing: [Signature]

Date/Time: 1-31-03 1:10 PM

5

Attach filled out form to applicable work control/permit documentation prior to starting work OR file as required by area/organizational procedures. Make copies as necessary.

[illegible]

- C-80

6

## PRE-JOB BRIEFING CHECKLIST

TRUPACT-157 (PA/LOAD) DISASSEMBLY OPERATIONS AT TAN  
Job Title: LOADING STANDARD WASTE BOXES Procedure or Tracking #: TPR-6233

Name/Title of Person Conducting Briefing: K. L. KYNASTON Date/Time: 1-29-03 10745

The objective of a good pre-job briefing is to communicate an understanding of scope, hazards, and mitigation to enable the safe completion of work. Follow MCP-3003 for requirements. Additional Radiological Work Permit requirements found in box 10, page 2.

Initial each box upon completion of the section during the pre-job briefing. Mark N/A in the comment box if this section is not applicable to this job.

Initials

1. Discuss Scope of Work to be Performed and Limiting Conditions

KL

Comments:

2. Review Hazards of the Job and Mitigation of those Hazards (JSA's, Permits, LO/TO)

KL

Comments:

3. Review Work Procedures and Initial Conditions Involved

KL

Comments:

Discuss Emergency Escape Routes

KL

Comments:

5. Discuss Roles and Responsibilities/ Stop Work/ Training/ and Work Restrictions/

KL

Comments:

6. Discuss Needed Tools and Equipment

KL

Comments:

7. Discuss Safety/ Radiological (see box 10)/ Environmental Requirements/ Wastes

KL

Comments:

8. Discuss Error Likely/ Feedback/ Lessons Learned

KL

Comments:

Summarize Scope/ Hazards/ and Responsibilities

KL

Comments:

# PRE-JOB BRIEFING CHECKLIST

Job Title: PAULAND DISASSEMBLY

Procedure or Tracking #: TPR-6233

<b>10. Minimum Radiological Work Permit (RWP) Requirements</b> Scope of work Radiological conditions of the workplace Procedural and RWP requirements Special radiological control requirements Radiologically limiting conditions (may void RWP) Radiological control hold points Communication & coordination with other groups Housekeeping and final cleanup provisions Emergency response provisions	Additional Notes and Comments and other Building/Equipment/Process specific pre-job checklists covered.
--	---

Print Names of Workers	Training (1)	Badge No.	Craft or Job Title	Company Name (If not INEEL)	Briefing Date	Worker's Initials (2)
FARRELL Bush	KL	61058	PCT		1/29/03	FB
Kelly Hoyle	N/A KL	39819	LA		1/29/03	KH
DARIS WEINER	KL	46876	OPS		1-29-03	DeW
TAKE GREEN	KL	78067	OPS		1/29/03	2G
Mary O'Brien	N/A KL	51686	Engt		1/29/03	pm
Kip Archibald	N/A KL	54941	Engt		1/29/03	Kd
Kelly Thompson	KL	64384	QT		1/30/03	PET

- (1) Supervisor initials to verify employee's required training for planned work is current. Mark N/A for not applicable.  
 (2) Worker's initials indicate attendance at the pre-job briefing and satisfactory understanding of all items discussed.

By my signature, I indicate that I have conducted the pre-job briefing covering all items indicated above concerning the requirements specified for the work to be performed.

Person Conducting Briefing: [Signature]

Date/Time: 1-29-03 1:0840

8



# PRE-JOB BRIEFING ATTENDANCE RECORD

Page 3 of     

Work Documentation Tracking/Procedure Number: TIR-6233

Attach filled out form to applicable work control/permit documentation prior to starting work OR file as required by area/organizational procedures. Make copies as necessary.

Print Names of Workers	Training (1)	S/Visitor Badge No.	Craft or Job Title	Company Name (2)	Briefing Date	Worker's Initials (3)
Michael Griffin	N/A	55461	WCO/TCO	BBWT	1/29/03	MG
Mel Saunders	U	40535	SO	BBWT	1/29/03	MS
R GINN	U	33234	HCO	BBWI	1-29-03	(R)
July L. Schmarbeck	U	52993	SO	BBWI	1-29-03	JL
Robin Killian	U	77456	OPS	BBWI	1/29/03	RK
Michael J. Galassi	U	67558	SO	BBWI	1/29/03	MG
R.C. Justice	U	85504	QI	BBWI	1/29/03	RCS
Lewis Bird	U	52447	RCT	BBWI	1-29-03	LB
JAMES WOSKI	N/A	71715	Observer	DOE-ID	1-29-03	JW
Jon Johnston	U	62673	RCT	BBWI	1-29-03	JJ
JAMES K. RIDER	N/A	62825	QA/QC	BBWI	1-29-03	JKR
Rob Bare	U	32396	EO	BBWI	1/29/03	RB
Gary L. Lusk	N/A	56428	Rad Con	BBWI	1/29/03	GL
Ed Lang	U	50699	Radcon	BBWI	1/29/03	EL
T Mott	U	76252	IN	BBWI	1/29/03	TM
Jimmy Hernandez	U	58122	Mech.	BBWI	1/29/03	JH
Rocky Allen	U	56604	MECH.	BBWI	1/29/03	RA
S.R. GAMACHE	N/A	55788	SAFETY	BBWI	1/29/03	SG
JERRY McNEW	N/A	62862	OBSERVER FACILITY REPRESENTATIVE	DOE-ID	1/29/03	JM
Lyle McKinlay	U	51945	RCT	BBWI	1-29-03	LM
Jonathan Ely	U	86256	RCT	BBWI	1-29-03	JE
Robert Jackson	U	50666	RCT	BBWI	1/29/03	RJ

- Supervisor initials block verifying employee's training required to complete the planned work is current, mark N/A for not applicable when special training (ES&H or other) not required.
- Briefing attendee required to fill this block if other than company employees, may leave blank for company employees.
- Worker's initials to indicate attendance at pre-job briefing and satisfactory understanding for all items discussed.

9

# DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS) DOCUMENT ACTION REQUEST (DAR)

1. Document ID: TPR-6233		Current Revision ID: 1		See Block 8 for DAR # Info.	
2. Document Title: TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN					
3. Requester: C. POSEGATE		Phone: 6-0188	MS: 9201	E-mail: CPOSEGAT	S No.: 60227
4. Type: <input checked="" type="checkbox"/> Document <input type="checkbox"/> Drawing		5. Type of action: <input type="checkbox"/> Create <input checked="" type="checkbox"/> Revise <input type="checkbox"/> Cancel			
6. Field Change: <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, will the change be: <input type="checkbox"/> Permanent or <input checked="" type="checkbox"/> Temporary? If Temporary, enter the field change duration: 1/31/2003 THUR 2/2/2003 2-6-03					
7. Proposed Action:					
Item	Page No./ Section/Zone	Description		Justification	
1	NEW SECTION 4.6 4.7 CP 2-1-03	SEE ATTACHMENT.		TO ALLOW FOR MOVING A DRUM FROM ONE SWB TO ANOTHER	
2	step 4.1.2	Add "Moving A Drum From One SWB to Another SWB" section 4.7		add step to routing table	
3	pg 29 step 4.5.18	Add six signature blocks as follows:		The individual signature blocks	
		WCO: _____ Date: _____ SWB #: _____		allows for more than one shipment.	
8. Proposal Approval: <input checked="" type="checkbox"/> Accepted <input type="checkbox"/> Deferred <input type="checkbox"/> Rejected					
If rejected, indicate reason: _____				DAR No.: 98552 (For Accepted Proposals Only!)	
Document Owner Printed Name: K. Streeper				Signature: C Posegate for K Streeper PTC Date: 1/31/03	
Is this a minor document change? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, proceed to Block 14. (For Operations procedures, go to Block 11.)					
9. Management Approval (Excluding drawings, minor changes, & field changes):					
Printed Name: Kevin Streeper				Signature: C Posegate for K Streeper PTC Date: 1/31/03	
10. Implementation Actions - Will the proposal require:					
Hazard mitigation per MCP-3562 or MCP-3571? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, Hazards already addressed by existing JSA for TPR-6233 K.M.W 2-1-03					
Training? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, tabletop/Pre Job Briefing					
Procurement activities? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Building modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Other: _____					
11. Include a list of reviewers and review comments and resolutions with this form or have reviewers sign below.					
Printed Name	Discipline	Org. No.	Signature	Date	
GARY L LUSK	RAD CON FOREMAN	5243	[Signature]	1/31/03	
S.R. GAMACHE	INDUSTRIAL SAFETY	5240	[Signature]	1/31/03	
J.K. RIDER	TAN QA	5260	[Signature]	1/31/03	
ALAN HUOT	SGAO	3200	[Signature]	1/31/03	
K.L. KYNASTON	OPERATIONS	5240	[Signature]	1-31-03	
12. Is document a TPR or EAR? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, indicate procedure validation method used:					
<input type="checkbox"/> Formal Walkdown <input checked="" type="checkbox"/> Tabletop Analysis <input type="checkbox"/> Limited Trial Use/Field Use <input type="checkbox"/> Partial Validation					
13. <input checked="" type="checkbox"/> Change does not affect a permitted area, TSD facility, or VCO component. (RCRA evaluation NOT required. Proceed to Block 14.)					
<input type="checkbox"/> Change does affect a permitted area, TSD facility, or VCO component.					
Is RCRA permit/application modified: <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> Unknown					
If Yes or Unknown, attach completed Form 435.29 or reference form's location here: _____					
E. Scott		K.M. Wendt for E. Scott per taken		2-1-03	
Evaluator Printed Name		Evaluator Signature		Date	
Is VCO component affected? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, contact the VCO Program Office for direction.					
14. USQ Screening: (To be completed only after final document review.) List any associated change forms: _____					
Is USQ screening required? (See Instructions) C Posegate for D. Swanson PTC 2-1-03					
<input type="checkbox"/> Not Required (Proceed to Block 15)					
<input checked="" type="checkbox"/> Required (Submit document and DAR to qualified USQ screener and attach USQ screening form.) K.M. Wendt 2-1-03					
<input checked="" type="checkbox"/> USQ Evaluation Required? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, attach evaluation. Refer to 03-USQ-TAN-0035 for TAN SAR					

# DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS)

## DOCUMENT ACTION REQUEST (DAR)

1. Document ID: TPR-6233		Current Revision ID: 1		See Block 8 for DAR # Info.	
2. Document Title: TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN					
3. Requester: C. POSEGATE		Phone: 6-0188	MS: 9201	E-mail: CPOSEGAT	S No.: 60227
4. Type: <input checked="" type="checkbox"/> Document <input type="checkbox"/> Drawing		5. Type of action: <input type="checkbox"/> Create <input checked="" type="checkbox"/> Revise <input type="checkbox"/> Cancel			
6. Field Change: <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, will the change be: <input type="checkbox"/> Permanent or <input checked="" type="checkbox"/> Temporary? If Temporary, enter the field change duration: 1/31/2003 THUR 2/2/2003					
7. Proposed Action:					
Item	Page No./ Section/Zone	Description		Justification	
1	NEW SECTION 4.6	SEE ATTACHMENT.		TO ALLOW FOR MOVING A DRUM FROM ONE SWB TO ANOTHER	
2	step 4.1.2	Add "Moving A Drum From One SWB to Another SWB" section 4.7		add step to routing table	
3	pg 29 step 4.5.18	Add six signature blocks as follows:		The individual signature blocks	
		WCO: _____ Date: _____ SWB #: _____		allows for more than one shipment.	
8. Proposal Approval: <input checked="" type="checkbox"/> Accepted <input type="checkbox"/> Deferred <input type="checkbox"/> Rejected				DAR No.: 98552	
If rejected, indicate reason: _____				(For Accepted Proposals Only)	
Document Owner Printed Name: K. Streeper		Signature: _____		Date: 1/31/03	
Is this a minor document change? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, proceed to Block 14. (For Operations procedures, go to Block 11.)					
9. Management Approval (Excluding drawings, minor changes, & field changes):					
Printed Name: _____		Signature: _____		Date: _____	
10. Implementation Actions – Will the proposal require:					
Hazard mitigation per MCP-3562 or MCP-3571? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Training? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, tabletop					
Procurement activities? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Building modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, _____					
Other: _____					
11. Include a list of reviewers and review comments and resolutions with this form or have reviewers sign below.					
Printed Name	Discipline	Org. No.	Signature	Date	
Kraig Wendt	TAN ENGINEERING	6760	C. Posegate PTC K.M. Wendt	2.1.03	
Colvin Jergins	SYSTEM ENGINEER	6760	C. Posegate PTC	2.1.03	
Al. Millhouse	RWMC NFM.	5B30	C. Posegate PTC	2.1.03	
MAX RUSKA	P&T	3280	C. Posegate PTC	2.1.03	
12. Is document a TPR or EAR? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes If Yes, indicate procedure validation method used:					
<input type="checkbox"/> Formal Walkdown <input checked="" type="checkbox"/> Tabletop Analysis <input type="checkbox"/> Limited Trial Use/Field Use <input type="checkbox"/> Partial Validation					
13. <input type="checkbox"/> Change does not affect a permitted area, TSD facility, or VCO component. (RCRA evaluation NOT required. Proceed to Block 14.)					
<input type="checkbox"/> Change does affect a permitted area, TSD facility, or VCO component.					
Is RCRA permit/application modified: <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> Unknown					
If Yes or Unknown, attach completed Form 435.29 or reference form's location here: _____					
Evaluator Printed Name: _____		Evaluator Signature: _____		Date: _____	
Is VCO component affected? <input type="checkbox"/> No <input type="checkbox"/> Yes If Yes, contact the VCO Program Office for direction.					
14. USQ Screening: (To be completed only after final document review.) List any associated change forms: _____					
Is USQ screening required? (See Instructions)					
<input type="checkbox"/> Not Required (Proceed to Block 15)					
<input type="checkbox"/> Required (Submit document and DAR to qualified USQ screener and attach USQ screening form.)					
<input type="checkbox"/> USQ Evaluation Required? <input type="checkbox"/> No <input type="checkbox"/> Yes If Yes, attach evaluation.					

see pg 1

DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS)  
DOCUMENT ACTION REQUEST (DAR)

1. Document ID: TPR-6233	Current Revision ID: 1	See Block 8 for DAR # Info.
5. Does this action qualify as a periodic review? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> N/A		
16. Desired effective date for document: 1/31/03		
17. Other documents affected by this action: none		
18. Document Owner Final Approval: (Changes in addition to those identified on this DAR, if applicable, have been approved during the review process. See document case file for the record of changes.) Approval signifies <del>implementation</del> actions are complete or document is ready as a pending document. <u>K.E. Steeper</u> <u>Per DeLeon</u> <u>[Signature]</u> <u>2-1-03</u> Document Owner Printed Name Document Owner Signature Date		
19. Drawing Checker Approval & Date:	20. Document Control Release & Date	21. Document Control Location:
22. Comments:		23. New Revision ID:

<b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b>	Identifier: TPR-6233 Revision: Field change Page: 1 of 10
--	---

#### 4.7 Moving a Drum From One SWB To Another SWB

**NOTE 1:** *This section is to be performed only if a drum needs to be moved from one SWB into another and steps in this section may be performed concurrently or out of sequence as directed by supervision.*

**NOTE 2:** *SWBs may be changed out at any time during the performance of this procedure.*

**NOTE 3:** *The Quality Inspection Plan shall be worked concurrently with this procedure.*

**NOTE 4:** *Dunnage drums may be moved into and out of an SWB as directed by supervision.*

##### 4.7.1 JS: Record the serial numbers of the SWB to be loaded.

#	SWB #
1	010248

4.7.1.1 QI: Verify that the SWB recorded above are QL-1 SWBs.

(TSR)

QI signature: *re Justice* Date 2-3-03

##### 4.7.2 EO: Transfer the receiving SWB to the loading area, if required.

#	Initial/Date
1	<i>re</i> / 2-3-03

##### 4.7.3 JS: Identify and label each SWB using the approved Load Plan or CBFO-supplied shipping documents.

(WIPP)

#	Initial/Date
1	<i>re</i> / 2-3-03

##### 4.7.4 M: If required, remove all the screws from the SWB lid.

#	Initial/Date
1	<i>re</i> 2-3-03

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: Field change  
Page: 2 of 10

- 4.7.5 M: IF needed,  
THEN chase SWB lid eyebolt threads (using 1/4-20 UNC bottoming tap).

#	Initial/Date
1	1/16 2-3-03

- 4.7.6 OP/EO/SO: Lift lid, as necessary, from the SWB and set it down on blocks to prevent damage to the seal surface, as directed (this may be accomplished manually or using Lift Plan TP 157-06 [INEEL Form 433.34]).

(TSR)

#	Initial/Date
1	1/16 2-3-03

**NOTE:** Step 4.7.7 may be performed at any time as directed by the JS.

- 4.7.7 QI/SO: Perform an inspection of the SWB box and lid before loading for damage such as bulges, dents, or deterioration that would affect the integrity of the container.

(TSR)

#	Initial/Date
1	1/16 2-3-03

**NOTE:** The filter's gasket may not contact the SWB when it is properly seated. The sealant acts as the seal in this application.

- 4.7.8 M: Perform the following:

#	Initial/Date
1	1/16 2-3-03

- 4.7.8.1 Apply thread sealant to the filter body pipe threads and install at least two NF013 filters in each SWB.

(TSR)

- 4.7.8.2 Ensure pipe plugs have been coated with pipe thread sealant and installed into the threaded ports, as applicable.

(TSR)

- 4.7.8.3 Ensure all remaining holes/ports have been plugged.

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: Field change  
Page: 3 of 10

(WIPP, TSR)

4.7.9 QI: **RECORD** torque wrench serial number and calibration due date.Torque wrench serial number: 7,7685Calibration due  
date: 2-20-03QI signature: rcp Date 2-3-034.7.10 M: Torque filters/plugs to 120 to 180 in.-lb or 10 to 15 ft.-lb.

(TSR)

#	Initial/Date
1	rcp 2-3-03

4.7.10.1 QI: Verify that filters/plugs are installed and torqued to specified value (120 to 180 in.-lb or 10 to 15 ft.-lb.)

(TSR)

QI Signature rcp Date 2-3-03 SWB # 0102484.7.11 M/SO: Clean the gasket sealing surfaces of the box and lid, as appropriate.

(TSR)

#	Initial/Date
1	rcp 2-3-03

**NOTE:** The SWB body sealing surface and the adhesive side of the gasket will not be exposed for inspection once the gasket has been adhered to the sealing surface.

**QI HOLD**4.7.12 QI: Perform an inspection of the SWB body seal surface and adhesive side of the gasket.

(TSR)

QI Signature rcp Date 2-3-03 SWB # 010248

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: Field change  
Page: 4 of 104.7.13 QI: Inspect the SWB rivets for damaged threads and loose fit.

(TSR)

QI Signature *RC Jester* Date 2-3-03 SWB # 010248**NOTE:** Steps 4.7.14 and 4.7.15 may be performed concurrently or out of sequence as directed by the JS.4.7.14 M/SO: Place the adhesive side of the gasket down onto the sealing surface of the SWB body, ensuring the ends of the gasket interlock and maintaining alignment of the prepunched gasket holes.

(TSR)

#	Initial/Date
1	<i>1K 2-3-03</i>

4.7.15 QI: Inspect the remaining gasket sealing surfaces, the installed gasket condition, and ensure that the gasket is properly installed.

(TSR)

QI Signature *RC Jester* Date 02-03-03 SWB # 0102484.7.16 OP: Ensure the drum-lifting adapter is rigged to one of the crane hooks or the overhead manipulator (O-Man) shoulder hook per Lift Plan TP 157-05 (INEEL Form 433.34).

(JSA)

#	Initial/Date
1	<i>1K 2-3-03</i>

**NOTE:** The operator or JS will track each drum on a Manual Drum Tracking Form as required to maintain accountability.4.7.17 OP: Remove the designated drum from the SWB as directed by the JS.

#	Initial/Date
1	<i>1K 2-3-03</i>



<p align="center"><b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6233 Revision: Field change Page: 5 of 10</p>
--	--

4.7.18 RCT: Perform surveys on the drum as it is removed from the SWB.

(WIPP, JSA)

#	Initial/Date
1	11/23/03

4.7.19 OP: Place the designated drum into the SWB per the Loading Plan or CBFO-supplied shipping documents.

#	Initial/Date
1	11/23/03

4.7.20 SO/JS: Using a Manual Drum Tracking Form (see Appendix C), log each drum ID (IDRF #) as it is placed into another SWB.

#	Initial/Date
1	11/23/03

4.7.21 QI: Verify that the drum is placed into the SWB in accordance with the Manual Drum Tracking Form.

#	Initial/Date
1	11/23/03

4.7.22 WCO: Using the Loading Plan or CBFO-supplied shipping documents, ensure the placement of each drum as it is placed into the SWB.

#	Initial/Date
1	11/23/03

### Prepare SWB for Shipment

**NOTE 1:** *Alignment pins for the SWB lid may be used as necessary to align the lid.*

**NOTE 2:** Dunnage drums may be moved into and out of an SWB as directed by supervision.

4.7.23 SO: Ensure any dunnage drums have "EMPTY" labels.

#	Initial/Date
1	11/23/03

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: Field change  
Page: 6 of 104.7.24 SO: Ensure any dunnage drums have open vent ports (for each SWB).

(WIPP)

#	Initial/Date
1	lll 2-3-03

4.7.25 SO/OP: Install dunnage drums into the appropriate SWBs per the Loading Plan or CBFO-supplied shipping documents.

#	Initial/Date
1	lll 2-3-03
2	lll 2-3-03

4.7.26 JS: Sign and date the Loading Plan or CBFO-supplied shipping documents indicating that the SWB was assembled with the correct drums.

#	Initial/Date
1	lll 2-3-03
2	lll 2-3-03

4.7.27 Install SWB lid on loaded SWB as follows:

4.7.27.1 EO/SO/OP: Lift the lid above the packaging and center the lid so that the lid is positioned over the body shell flange (this may be accomplished manually or using Lift Plan TP 157-06 [INEEL Form 433.34]).

#	Initial/Date
1	lll 2-3-03

**WARNING****Pinch points are present between lid and body shell flange. Fingers must be kept clear.**

(JSA)

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: Field change  
Page: 7 of 10

- 4.7.27.2 EO/SO/OP: Lower the lid slowly onto the body shell flange, ensuring the gasket is not damaged and the lid and body serial numbers are together.

(TSR)

#	Initial/Date
1	MC 2-3-03

- NOTE 1:** *When installing the screws, a lineup bar may be used to pull the lid into position with the body. Caution will be needed to prevent damage to the male/female threads with the lineup bar.*

- NOTE 2:** *A thread sealer (Locktite #565 or equivalent) is used on the SWB screws.*

(TSR)

- NOTE 3:** *Use of air or electric wrenches to quickly seat the screws is allowable. However, care should be taken to seat the screws only hand-tight and not to apply excessive torque.*

- 4.7.27.3 QI: RECORD torque wrench serial number and calibration due date.

Torque wrench serial number: 716785Calibration due date: 2-20-03QI signature: EC Justice Date 2-3-03

- 4.7.27.4 M: Install four corner screws approximately 1/4-in. or 3 to 4 turns.

(TSR)

#	Initial/Date
1	MC 2-3-03

- 4.7.27.5 M: Install four screws (in the middle of straight sides and the middle of the curved ends).

(TSR)

#	Initial/Date
1	MC 2-3-03

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: Field change  
Page: 8 of 10

4.7.27.6 M: Using a template, install and tighten all screws 360 to 480 in.-lb or 30 to 40 ft.-lb.

(TSR)

#	Initial/Date
1	ML 2-3-03

4.7.27.7 M: Using a template, tighten all screws 600 to 720 in.-lb or 50 to 60 ft.-lb.

(TSR)

#	Initial/Date
1	ML 2-3-03

4.7.27.7.1 QI: Verify that screws are torqued to the specified value.

(TSR)

QI Signature EC Jutice Date 2-3-03 SWB # 010248

4.7.27.8 EO/M: If required, remove lid lift rigging and eyebolt and stage as directed.

#	Initial/Date
1	NAK 2-3-03

4.7.28 RCT: Survey the SWB for contamination as it is removed from the Hot Shop.

(WIPP, JSA)

#	Initial/Date
1	IK 2-3-03

4.7.29 EO: Place the SWB(s) in designated area as directed.

#	Initial/Date
1	IK 2-3-03

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: Field change  
Page: 9 of 10

4.7.30 SO: GO TO Appendix D and perform the container integrity inspection.

#	Initial/Date
1	1/16 2-3-03

4.7.31 RCT: Perform contamination survey and beta-gamma and neutron radiation surveys at contact, 1 m, and 2 m for each SWB; ensure contamination levels are less than or equal to 20 dpm/100 cm<sup>2</sup> alpha, and 200 dpm/100 cm<sup>2</sup> beta-gamma for transportation.

(WIPP, JSA)

#	Initial/Date
1	1/16 2-3-03

4.7.32 RCT: IF not already labeled,  
THEN label SWB "Caution Radioactive Material" in a clearly visible location as required.

#	Initial/Date
1	1/16 2-3-03

4.7.33 SO: Apply hazardous/non-hazardous labels to SWB as required.

(WIPP)

#	Initial/Date
1	1/16 2-3-03

4.7.34 HEO/EO: Lift the packaging into position on the conveyance vehicle.

#	Initial/Date
1	1/16 2-3-03

4.7.35 HEO/EO: Install wood or other material to prevent longitudinal or lateral movement of the packaging.

#	Initial/Date
1	1/16 2-3-03

<p><b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6233 Revision: Field change Page: 10 of 10</p>
---	---

**NOTE:** *The rigging must be anchored to the packaging by the lift clips at the top edge of the packaging.*

4.7.36 HEO/EO: Secure the packaging to the vehicle with webbing or other suitable rigging per 49 CFR 393, Subpart I requirements.

#	Initial/Date
1	14-2-3-03

4.7.37 HEO/EO: Verify that all rigging and equipment is secure before shipment.

#	Initial/Date
1	14-2-3-03

14-2-3-03

4.7.38 WCO: Complete INEEL Form 461.02, "Radioactive Material Packaging Quality Control Inspection," for each SWB.

*Michael J. [Signature]*

2/3/2003

SWB: IDRFXWB030207

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: 1  
Page: 1 of 38

Applicability: Test Area North	Type: Technical Procedure	For Additional Info: <a href="http://EDMS">http://EDMS</a>	Effective Date: 01/22/03
Manual: Detailed Operating Procedures for Test Area North Operations		USE TYPE 1	Change Number: 98036

PROCEDURE REVIEW REQUIREMENTS					
DISCIPLINE	REVISION	CHANGE	DISCIPLINE	REVISION	CHANGE
TAN/RWMC OPERATIONS	X	X	TAN INDUSTRIAL SAFETY	X	A/R
MAINTENANCE	X	A/R	TAN QUALITY	X	X
LANDLORD	N/A	N/A	TAN ENVIRONMENTAL	N/A	N/A
TAN SYSTEM ENGINEER	X	X	TAN RADCON	X	A/R
RWMC SYSTEM ENGINEER	X	X	TAN INDUSTRIAL HYGIENE	X	A/R
TAN SAFETY ANALYSIS	X	A/R	EMERGENCY PLANNER	N/A	N/A
TRAINING	N/A	N/A	SAFEGUARDS (NMC)	N/A	N/A
SITE QUALITY ASSURANCE OFFICER (SQAQ)	X	A/R	TAN CRITICALITY ENGINEER	N/A	N/A
TAN FIRE PROTECTION ENGINEER	N/A	N/A	PACKAGING AND TRANSPORTATION	X	A/R

<b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b>	<b>Identifier: TPR-6233</b>
	<b>Revision: 1</b>
	<b>Page: 2 of 38</b>

## CONTENTS

1.	INTRODUCTION .....	3
1.1	Purpose.....	3
1.2	Scope and Applicability.....	3
2.	PRECAUTIONS AND LIMITATIONS.....	3
3.	PREREQUISITES .....	5
3.1	Planning and Coordination .....	5
3.2	Performance Documents.....	6
3.3	Special Tools, Equipment, Parts, and Supplies.....	6
3.4	Field Preparations .....	7
4.	INSTRUCTIONS.....	8
4.1	General.....	8
4.2	Moving the Payload Assembly .....	9
4.3	Stage SWB for Loading.....	11
4.4	Disassembly of a 14-Pack Payload .....	16
4.5	Prepare SWB for Shipment.....	22
4.6	Post-Performance Activities .....	29
5.	RECORDS .....	30
6.	REFERENCES .....	31
7.	APPENDIXES .....	32
	APPENDIX A – Procedure Basis .....	33
	APPENDIX B – Comment Sheet.....	35
	APPENDIX C – Manual Drum Tracking Form.....	36
	APPENDIX D – Container Integrity Inspection.....	37



**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN****Identifier:** TPR-6233  
**Revision:** 1  
**Page:** 3 of 38**1. INTRODUCTION****1.1 Purpose**

To provide instructions for the disassembly of the TRUPACT-157 payload.

**1.2 Scope and Applicability**

This procedure applies to personnel performing TRUPACT-II Payload disassembly operations. This procedure will provide guidance for the disassembly and temporary disposition of the TRUPACT-157 payload.

**2. PRECAUTIONS AND LIMITATIONS**

2.1 When handling TRU drums, every effort must be made to ensure continued container integrity.

2.2 The Adjustable Center of Gravity Lifting Fixture (ACGLF) is designed to handle the weight of an Outer Containment Vessel (OCV) lid, an Inner Containment Vessel (ICV) lid, an empty ICV assembly, or a payload. Payloads include 14-pack or dummy drums. The ACGLF is not designed to handle the weight of a TRUPACT-II container (loaded or empty), a loaded Outer Containment Assembly (OCA) or a loaded ICV.

(WIPP)

2.3 The ACGLF with short legs may be set directly on the floor and disconnected from the crane. The ACGLF with long legs can be set on the floor but should have minimal vertical support from the crane to prevent tipping.

2.4 Personnel performing this procedure must wear safety shoes.

(JSA)

2.5 The lifts in this procedure are critical lifts, pre-engineered production lifts, or ordinary lifts per DOE-STD-1090-2001, DOE Hoisting and Rigging Standard.

(JSA)

2.6 IF fossil-fueled vehicles are operating continuously, without the ventilation hoses attached, for more than approximately 10 minutes inside the building, THEN a carbon monoxide monitor must be obtained from Industrial Hygiene (IH) for use.

(JSA)

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233

Revision: 1

Page: 4 of 38

- 2.7 Do not place body parts under a suspended load with the following exceptions:  
ACGLF adjustments/leg changes and guiding leg insertion.  
(JSA)
- 2.8 Heat stress stay time must be monitored. Heat stress stay times vary depending upon environmental conditions, work activities, and PPE, and must be initially determined and re-evaluated as conditions change per MCP-9240, "Managing Heat and Cold Stress at TAN."  
(JSA)
- 2.9 During ACGLF operation, non-essential personnel must stay clear of the ACGLF.  
(JSA)
- 2.10 Procedure steps or sections may be performed out-of-sequence as directed. The Technical Lead (TL)/Shift Supervisor (SS) marks the steps or sections to be performed out-of-sequence with a "go to \_\_\_\_\_" and records the justification for no adverse impact on the conduct of the procedure in Appendix B, Comment Sheet. After the last out-of-sequence step, the TL/SS marks "return to Step \_\_\_\_\_".
- 2.11 Procedure steps or sections may be re-performed as directed by the TL/SS. The TL/SS mark the step(s)/section(s) to be re-performed with "step(s)/section(s) \_\_\_\_\_ are to be re-performed and resigned", and enters the number of the step(s)/section(s) to be re-performed in the blank and records the justification for no adverse impact on the conduct of the procedure entered in Appendix B, Comment Sheet.
- 2.12 Procedure steps or sections may be marked N/A as follows:
- 2.12.1 Non-conditional steps or sections that contain technical safety requirements (TSR) or safety analysis report (SAR) commitments require a Document Action Request (DAR) to mark the step or section N/A.
- 2.12.2 Non-conditional steps or sections NOT involving TSR and SAR commitments may be marked N/A, initialed and dated by the TL/SS, and a written justification entered in Appendix B, Comment Sheet.
- 2.12.3 Conditional steps or sections must be marked N/A and initialed/dated by the person performing the procedure if the conditions stated by the procedure exist.

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN****Identifier:** TPR-6233  
**Revision:** 1  
**Page:** 5 of 38

- 2.13 Procedure steps or sections may be signed or initialed by the Job Supervisor (JS), TL/SS, or Person in Charge (PIC) based on personal observation, direct report from the performer, or review of controlled records.
- 2.14 Any problems during procedure performance must be entered into Appendix B. Any documents (NCRs, WOs, DRs, etc.) issued to close, track, or resolve comments must be identified in Appendix B.

**3. PREREQUISITES****3.1 Planning and Coordination**

**NOTE:** *The following is a recommended crew (minimum). Manning may be adjusted as required by the TL/SS.*



3.1.1 TL/SS: As a minimum, ensure the following personnel are available:

- A. Job Supervisor (JS) (continuously present at the job site)
- B. SWEPP Operator (SO)
- C. Mechanic (M)
- D. Radiological Control Technician (RCT)
- E. Equipment Operator (EO)
- F. Heavy Equipment Operator (HEO)
- G. Quality Inspector (QI)
- H. Technical Lead (TL)/Shift Supervisor (SS)
- I. TAN Operator (OP)
- J. Waste Certification Official (WCO)
- K. Carpenter (C).



3.1.2 JS: Conduct a pre-job briefing with personnel conducting this procedure in accordance with MCP-3003, "Performing Pre-Job Briefings and Post-Job Reviews" including TAN-JSA-6233.

**(JSA)**

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

 Identifier: TPR-6233  
 Revision: 1  
 Page: 6 of 38

**3.1.3 SS/TL authorize work:**


SS/TL



Date

**3.1.4 A current Radiological Work Permit is required.**

(JSA)

**3.2 Performance Documents**

INTEC-QA-0221, Quality Inspection of TRUPACT-157 Payload Disassembly Operations at Test Area North (TAN)

PLN-1169, TRUPACT-II Shipping Container 157 Payload Examination Plan

INEEL Form 433.34, INEEL Lift Plan

INEEL Form 433.34A, INEEL Lift Plan Supplement

INEEL Form 461.02, Radioactive Material Packaging Quality Control Inspection

Carlsbad Field Office (CBFO)-supplied shipping documents

**3.3 Special Tools, Equipment, Parts, and Supplies**
**NOTE:** *The following materials and equipment are recommended.*

Item	No.	Comments
HS Crane: CRN-HS-902 110/10	1	Annual maintenance completed 3/8/02; due 3/8/03
Oman: OMAN-SP-901	1	Annual maintenance completed 2/30/02; due 2/30/03
Thread lubricant (Loctite #565 or equivalent)	A/R	For standard waste box (SWB) lid screw thread lubrication
Alpha and Beta-gamma CAMs	1	As required by ALARA review and RWP
RAMs	1	As required by ALARA review and RWP. RAM 3, C Pedestal PM completed 7/30/02
SWB gasket	6	Supplied with (inside) the SWB from vendor

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233

Revision: 1

Page: 7 of 38

Item	No.	Comments
Torque wrench (0-75 ft-lb range)	1	For SWB lid installation
Torque wrench (0-25 ft-lb range)	1	For filter/plug installation
Powered driver with socket adapter and/or hexagon wrench	1	Required for SWB screws
Standard Waste Boxes (SWB)	6	QL-1 required. Each box will have a unique number identifier. (TSR)
SWB alignment pins	A/R	For aligning SWB lid
Dunnage drums	10	Required to complete payload in select SWBs
Video recorder equipment and video tapes	A/R	As needed monitor progress, perform inspections, etc.
Rigging per applicable Lift Plan (INEEL Form 433.34)	A/R	Lift Plan numbers: TP 157-03, Payload Handling
Razor knife	1	Required for cutting plastic sleeving
ACGLF with control console	1	Required for lifting lids and payload
Spill pallets	A/R	Required for staging drums
Drum handler (crane)	1	Required for disassembling payload
Smear extension tool	1	Required for surveying cask and internals
Torque template	1	Required for SWB torque sequence
Drum bags	14	Required for transport of drums to SWBs
Forklift	1	Required for moving SWBs
Decontamination fixative	A/R	ET Glycerin Solution (ETGS), MSDS 20625, required for certain decontamination activities

### 3.4 Field Preparations

3.4.1 The required alpha and beta-gamma CAMs are operating as required by RadCon.

(JSA)

3.4.2 Ensure the ACGLF legs are covered with plastic or tape to minimize the need to decontaminate them later as required by RadCon.

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: 1  
Page: 8 of 383.4.3 JS: Record the serial numbers of the six SWBs to be loaded.

#	SWB #	#	SWB#	#	SWB #
1	010263	2	010221	3	010259
4	010227	5	010288	6	010282

3.4.3.1 QI: Verify that the six SWBs recorded above are QL-1 SWBs.

(TSR)

QI signature: RC Justice Date 1-28-03**4. INSTRUCTIONS**

**NOTE 1:** Procedure steps or sections may be signed off or initialed by the TL/SS, JS, or Performer based on personal observation, direct report from the performer, or review of controlled records.

**NOTE 2:** The Payload Examination Plan (PLN-1169) may be worked at any time during the performance of this procedure at the direction of the TL/JS/SS.

**NOTE 3:** Procedure steps, sections, and steps within a section may be performed concurrently as directed by the TL/SS.

**NOTE 4:** All radiological surveys will be documented in accordance with MCP-139, "Radiological Surveys."

**NOTE 5:** Quality Inspection Plan, INTEC-QA-0221, must be performed in conjunction with this procedure.

**4.1 General**1/28/03  
16L 1-28-034.1.1 JS: Ensure applicable prerequisites have been met.

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 9 of 38

- 4.1.2 GO TO the appropriate procedure section from the following table based on the desired task to be performed,  
THEN RETURN TO this step.

Task	Section to Perform
Moving the Payload Assembly	Section 4.2
Stage SWB for Loading	Section 4.3
Disassembly of a 14-Pack Payload	Section 4.4
Prepare SWB for Shipment	Section 4.5
Post-Performance Activities	Section 4.6 and EXIT this procedure.
Moving A Deum from One SWB to another SWB	Section 4.7

## 4.2 Moving the Payload Assembly

- 4.2.1 TL: Designate a PIC prior to hoisting activities for CRITICAL LIFTS in Section 4.2.

PIC: Kelly Kynaston

- 4.2.2 EO/OP: Rig the ACGLF to the overhead crane and connect to the 14-pack assembly per Lift Plan TP 157-03 (INEEL Form 433.34).

(JSA)

- 4.2.2.1 PIC: Ensure that INEEL Form 433.34A, "INEEL Lift Plan Supplement," has been completed and verified for this CRITICAL LIFT.

PIC: Kelly Kynaston

(JSA)

**NOTE:** Red marks (bands) on the lifting legs indicate that the long lifting legs are fully inserted into the guide tubes. They may reappear as the load is lifted.

- 4.2.2.2 EO: If necessary, visually ensure all three legs are engaged and locked.

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 10 of 38

## CAUTION

Movement of the ACGLF counter weights must not occur with the free load above approximately 6 in.

NA KL  
1-28-03 1/29/03

4.2.2.3 Heavy Equipment Operator (HEO)/OP: If necessary, using the crane, lift the payload approximately 2 to 6 in. above the floor, as applicable.

NA KL  
1-28-03 1/29/03

4.2.2.4 EO: If necessary, adjust the counterweights to compensate for the center-of-gravity of the payload.

4.2.2.5 Remove the bottom section of the containment as required by the JS by performing the following:

### RCT HOLD

KL 1-28-03

4.2.2.5.1 JS/RCT: Ensure that the tent ventilation system is functioning properly.

(JSA)

### RCT HOLD

KL 1-28-03

4.2.2.5.2 JS/RCT: Ensure that the daily tent inspection has been performed.

KL 1-28-03

4.2.2.5.3 JS: Ensure side tent openings are closed.

KL 1-28-03

4.2.2.5.4 RCT: Ensure negative airflow into the top of the tent.

KL 1-28-03

4.2.2.5.5 SO/OP: Remove the bottom section of the containment from the payload.

KL 1-28-03

4.2.2.6 HEO/OP: Place the payload in a storage location, as designated by the JS.

KL 1-28-03

4.2.2.7 HEO: After setting down and stabilizing the payload assembly, position the weights on the ACGLF at 180 and 000 degrees before unlatching the ACGLF from the 14-pack assembly.



# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 11 of 38

KL 1-28-03 4.2.2.8 OP: Remove ACGLF from the payload.

KL 1-28-03 4.2.2.9 SO/OP: Remove the top section of the containment from the payload as required by the JS.

KL 1-28-03 4.2.2.10 C/OP: Close the roof lid on the tent.

## 4.3 Stage SWB for Loading

NOTE 1: SWBs may be changed out at any time during the performance of this procedure.

NOTE 2: The Quality Inspection Plan must be worked concurrently with this procedure.

4.3.1 EO: Transfer the SWB to the loading area, if required.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-29-03	6	KL 1-29-03				

4.3.2 JS: Identify and label each SWB using the CBFO-supplied shipping documents.

(WIPP)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-29-03	6	KL 1-29-03	7	KL 2-3-03		

4.3.3 M: If required, remove all the screws from the SWB lid.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-29-03	6	KL 1-29-03				

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 12 of 38

4.3.4

M: IF needed,

THEN chase SWB lid eyebolt threads (using 1/4-20 UNC bottoming tap).

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA/K 1-29-03	2	NA/K 1-29-03	3	NA/K 1-29-03	4	NA/K 1-29-03
5	NA/K 1-29-03	6	NA/K 1-29-03				

4.3.5

OP/EO/SO: Lift lid, as necessary, from the SWB and set it down on blocks to prevent damage to the seal surface, as directed (this may be accomplished manually or using Lift Plan TP 157-06 [INEEL Form 433.34]).

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	K 1-29-03	2	K 1-29-03	3	K 1-29-03	4	K 1-29-03
5	K 1-29-03	6	K 1-29-03				

**NOTE:** Step 4.3.6 may be performed at any time as directed by the JS.

4.3.6 QI/SO: Perform an inspection of the SWB box and lid before loading for damage such as bulges, dents, or deterioration that would affect the integrity of the container.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	K 1-29-03	2	K 1-29-03	3	K 1-29-03	4	K 1-29-03
5	K 1-29-03	6	K 1-29-03				

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

 Identifier: TPR-6233  
 Revision: 1  
 Page: 13 of 38

**NOTE:** *The filter's gasket may not contact the SWB when it is properly seated. The sealant acts as the seal in this application.*

4.3.7 M: Perform the following:

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	<i>ML 1-29-03</i>	2	<i>ML 1-29-03</i>	3	<i>ML 1-29-03</i>	4	<i>ML 1-29-03</i>
5	<i>ML 1-29-03</i>	6	<i>ML 1-29-03</i>				

✓4.3.7.1 Apply thread sealant to the filter body pipe threads and install four NF013 filters in each SWB.

(TSR)

✓4.3.7.2 Ensure pipe plugs have been coated with pipe thread sealant and installed into the threaded ports, as applicable.

(TSR)

✓4.3.7.3 Ensure all remaining holes/ports have been plugged.

(WIPP, TSR)

4.3.8 QI: **RECORD** torque wrench serial number and calibration due date.

Torque wrench serial number: 704213

Calibration due  
date:

2-27-03

QI signature: *RC Justice* Date 1-29-03

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 14 of 38

4.3.9 M: Torque filters/plugs to 120 to 180 in.-lb or 10 to 15 ft.-lb.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	W 1-29-03	2	W 1-29-03	3	W 1-29-03	4	W 1-29-03
5	W 1-29-03	6	W 1-29-03				

4.3.9.1 QI: Verify that filters/plugs are installed and torqued to specified value (120 to 180 in.-lb or 10 to 15 ft.-lb.

(TSR)

QI Signature RC Justice Date 1-29-03 SWB # 010282  
 QI Signature RC Justice Date 1-29-03 SWB # 010259  
 QI Signature RC Justice Date 1-29-03 SWB # 010221  
 QI Signature RC Justice Date 1-29-03 SWB # 010227  
 QI Signature RC Justice Date 1-29-03 SWB # 010288  
 QI Signature RC Justice Date 1-29-03 SWB # 010263

4.3.10 M/SO: Clean the gasket sealing surfaces of the box and lid, as appropriate.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	W 1-29-03	2	W 1-29-03	3	W 1-29-03	4	W 1-29-03
5	W 1-29-03	6	W 1-29-03				

(7) W 1-31-03  
(8) W 1-31-03

SEE COMMENT  
APPENDIX B FOR  
STEPS 4.3.10  
4.3.11  
4.3.13 + 4.3.14

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: 1  
Page: 15 of 38

**NOTE:** The SWB body sealing surface and the adhesive side of the gasket will not be exposed for inspection once the gasket has been adhered to the sealing surface.

**QI HOLD**

- 4.3.11 QI: Perform an inspection of the SWB body seal surface and adhesive side of the gasket.

(TSR)

QI Signature RC Justice Date 1-29-03 SWB # 010282  
QI Signature RC Justice Date 1-31-03 SWB # 010259  
QI Signature RC Justice Date 1-29-03 SWB # 010221  
QI Signature RC Justice Date 1-29-03 SWB # 010227  
QI Signature RC Justice Date 1-31-03 SWB # 010288  
QI Signature RC Justice Date 1-29-03 SWB # 010263

- 4.3.12 QI: Inspect the SWB rivets for damaged threads and loose fit.

(TSR)

QI Signature RC Justice Date 1-29-03 SWB # 010282  
QI Signature RC Justice Date 1-29-03 SWB # 010259  
QI Signature RC Justice Date 1-29-03 SWB # 010221  
QI Signature RC Justice Date 1-29-03 SWB # 010227  
QI Signature RC Justice Date 1-29-03 SWB # 010288  
QI Signature RC Justice Date 1-29-03 SWB # 010263

\* Steps reformed to replace damaged gasket section.  
RCJ  
1-31-03

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 16 of 38

**NOTE:** Steps 4.3.13 and 4.3.14 may be performed concurrently or out of sequence as directed by the JS.

- 4.3.13 M/SO: Place the adhesive side of the gasket down onto the sealing surface of the SWB body, ensuring the ends of the gasket interlock and maintaining alignment of the prepunched gasket holes.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-29-03	6	KL 1-29-03				

① KL 1-31-03      ⑤ KL 1-31-03

- 4.3.14 QI: Inspect the remaining gasket sealing surfaces, the installed gasket condition, and ensure that the gasket is properly installed.

(TSR)

QI Signature RC Justice Date 1-29-03 SWB # 010282  
 QI Signature RC Justice Date 1-31-03 SWB # 010257  
 QI Signature RC Justice Date 1-29-03 SWB # 010221  
 QI Signature RC Justice Date 1-29-03 SWB # 010227  
 QI Signature RC Justice Date 1-31-03 SWB # 010288  
 QI Signature RC Justice Date 1-29-03 SWB # 010263

## 4.4 Disassembly of a 14-Pack Payload

**NOTE:** The disassembly of the payload will be directed by the JS with RCT assistance.

RCT HOLD

STARTED REPAIRS 1-30-03

KL 1-29-03  
KL 1-30-03

- 4.4.1 JS: Ensure that the tent ventilation system is functioning properly.

(JSA)

RCT HOLD

KL 1-29-03  
KL 1-30-03

- 4.4.2 JS: Ensure that the daily tent inspection has been performed.

\* Steps reformed to replace damaged gasket section, RCT 1-31-03

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 17 of 38

11/1-29-03 4.4.3 RCT/SO/OP: Perform inspections and surveys on the payload assembly per the Payload Examination Plan as required.

**NOTE:** *The disassembly of the payload may be performed from inside the containment tent or from outside of the tent based on survey results, RWP requirements, and RadCon direction*

(JSA)

11/1-29-03 4.4.4 SO/OP/RCT: If necessary, with RadCon concurrence, remove the containment from around the payload.

(JSA)

11/1-29-03 4.4.5 SO/OP/RCT: Perform surveys and inspections of the payload per the Payload Examination Plan as required.

11/1-29-03 4.4.6 SO/OP: Remove stretch-wrap material from the upper layer of the payload assembly.

11/1-29-03 4.4.7 SO/OP: Remove the upper slip sheet from the payload assembly.

11/1-29-03 4.4.8 SO: Remove guide tubes as required to facilitate payload disassembly.

**NOTE 1:** *Each drum will be inspected and video taped as it is removed from the payload per the Payload Examination Plan.*

**NOTE 2:** *Steps 4.4.9 through 4.4.17 may be performed concurrently.*

4.4.9 OP: Ensure the drum-lifting adapter is rigged to one of the crane hooks or the overhead manipulator (O-Man) shoulder hook per Lift Plan TP 157-05 (INEEL Form 433.34).

(JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	11/1-29-03	2	11/1-29-03	3	11/1-29-03	4	11/1-29-03
5	11/1-30-03	6	11/1-30-03	7	11/1-30-03		

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 18 of 38

**NOTE:** The operator or JS will track each drum on a Manual Drum Tracking Form as required to maintain accountability.

4.4.10 OP: Remove each drum from the upper portion of the payload as directed by the JS.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

4.4.11 RCT: Perform surveys on each drum as it is removed from the payload per the Payload Examination Plan if required.

(WIPP, JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

## RCT HOLD

4.4.11.1 OP/RCT: IF contamination survey of the top of the drum is greater than 1000 dpm/100 cm<sup>2</sup> alpha, THEN decontaminate or apply fixative per RadCon direction.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA KL 1-29-03	2	NA KL 1-29-03	3	NA KL 1-29-03	4	NA KL 1-29-03
5	NA KL 1-30-03	6	NA KL 1-30-03	7	NA 1-30/03		

4.4.12 OP: Place each drum in a poly bag, if directed by JS/RCT.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA KL 1-29-03	2	NA KL 1-29-03	3	NA KL 1-29-03	4	NA KL 1-29-03
5	NA KL 1-30-03	6	NA KL 1-30-03	7	KL 1-30-03		

4.4.13 OP: Ensure the drum-lifting adapter is rigged to one of the crane hooks or the overhead manipulator (O-Man) shoulder hook per Lift Plan TP 157-05 (INEEL Form 433.34).

(JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

SEE COMMENT  
SHEET for Position #7  
@ 1/30/03



# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 19 of 38

- 4.4.14 OP: Place each drum into the SWB per the CBFO-supplied shipping documents.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.15 SO/JS: Using a Manual Drum Tracking Form (see Appendix C), log each drum ID (IDRF #) as it is placed into the SWB.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.16 QI: Verify that each drum is placed into the SWB in accordance with the Manual Drum Tracking Form.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.17 WCO: Using the CBFO-supplied shipping documents, ensure the placement of each drum as it is placed into the SWB.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-29-03	2	KL 1-29-03	3	KL 1-29-03	4	KL 1-29-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 500000 1-29-03 4.4.18 Repeat Steps 4.4.9 through 4.4.17 for each drum to be removed from the upper level.

- KL 1-30-03 4.4.19 SO/OP: Remove the TRUPACT-II slip-sheet from the top of the bottom layer of drums.

- KL 1-30-03 4.4.20 SO/OP: Remove remaining stretch wrap material.

- KL 1-30-03 4.4.21 SO/OP: Remove the lower slip sheet from the payload assembly.

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 20 of 38

**NOTE:** Steps 4.4.22 through 4.4.30 may be performed concurrently.

4.4.22 OP: Ensure the drum-lifting adapter is rigged to one of the crane hooks or the overhead manipulator (O-Man) shoulder hook per Lift Plan TP 157-05 (INEEL Form 433.34).

(JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

4.4.23 OP: Remove each drum from the lower portion of the payload as directed by the JS.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

4.4.24 RCT: Perform surveys on each drum as it is removed from the payload per the Payload Examination Plan if required.

(WIPP, JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

## RCT HOLD

4.4.24.1 OP/RCT: If contamination survey of the top of the drum is greater than 1000 dpm/100 cm<sup>2</sup> alpha, THEN decontaminate or apply fixative per RadCon direction.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA KL 1-30-03	2	NA KL 1-30-03	3	NA KL 1-30-03	4	NA KL 1-30-03
5	NA KL 1-30-03	6	NA KL 1-30-03	7	NA KL 1-30-03		

4.4.25 OP: Place each drum in a poly bag, if directed by JS/RCT.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA KL 1-30-03	2	NA KL 1-30-03	3	NA KL 1-30-03	4	NA KL 1-30-03
5	NA KL 1-30-03	6	NA KL 1-30-03	7	NA KL 1-30-03		

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 21 of 38

- 4.4.26 OP: Ensure the drum-lifting adapter is rigged to one of the crane hooks or the overhead manipulator (O-Man) shoulder hook per Lift Plan TP 157-05 (INEEL Form 433.34).

(JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.27 OP: Place each drum into the SWB per the CBFO-supplied shipping documents.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.28 SO/JS: Using a Manual Drum Tracking Form, enter each drum ID (IDRF #) as it is placed into the SWB.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.29 QI: Verify that each drum is placed into the SWB in accordance with the Manual Drum Tracking Form.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.30 WCO: Using the CBFO-supplied shipping documents, ensure the placement of each drum as it is placed into the SWB.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-30-03	2	KL 1-30-03	3	KL 1-30-03	4	KL 1-30-03
5	KL 1-30-03	6	KL 1-30-03	7	KL 1-30-03		

- 4.4.31 Repeat Steps 4.4.22 through 4.4.30 for each drum to be removed from the lower level.

- 4.4.32 SO/OP/RCT: Perform any additional inspections and surveys per the Payload Examination Plan.

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 22 of 38

## 4.5 Prepare SWB for Shipment

**NOTE:** Alignment pins for the SWB lid may be used as necessary to align the lid.

4.5.1 SO: Ensure any dunnage drums have "EMPTY" labels.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA 1-31-03	2	1-31-03	3	NA 1-31-03	4	1-31-03
5	1-31-03	6	1-31-03				

4.5.2 SO: Ensure any dunnage drums have open vent ports.

(WIPP)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA 1-31-03	2	1-31-03	3	NA 1-31-03	4	1-31-03
5	1-31-03	6	1-31-03				

4.5.3 SO/OP: Install dunnage drums into the appropriate SWBs per the CBFO-supplied shipping documents.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA 1-31-03	2	1-31-03	3	NA 1-31-03	4	1-31-03
5	1-31-03	6	1-31-03				

4.5.4 JS: Sign and date the CBFO-supplied shipping documents indicating that the SWB was assembled with the correct drums.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1-31-03	2	1-31-03	3	1-31-03	4	1-31-03
5	1-31-03	6	1-31-03				

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 23 of 38

4.5.5 Install SWB lid on loaded SWB as follows:

## RCT HOLD

4.5.5.1

RCT: Ensure the top of the drum below the area where the hole will be created has been decontaminated to less than 1000 dpm/100 cm<sup>2</sup> alpha or has fixative applied.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA111 1-31-03	2	NA111 1-31-03	3	NA111 1-31-03	4	NA111 1-31-03
5	NA111 1-31-03	6	NA111 2-3-03				

## RCT HOLD

4.5.5.2

RCT: Ensure local HEPA-filtered ventilation has been provided to direct airflow away from personnel performing venting operations.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA111 1-31-03	2	NA111 1-31-03	3	NA111 1-31-03	4	NA111 1-31-03
5	NA111 1-31-03	6	NA111 2-3-03				

## CAUTION

Care should be taken to avoid damaging the drum vent filter when creating the vent hole for the bagged drums.

## RCT HOLD

4.5.5.3

RCT/SO/OP: For each bagged drum in the SWB, apply fixative, create a 2-in.-minimum vent hole through the plastic sleeve, and apply fixative as directed by the JS/RCT.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA111 1-31-03	2	NA111 1-31-03	3	NA111 1-31-03	4	NA111 1-31-03
5	NA111 1-31-03	6	NA111 2-3-03				

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 24 of 38

**NOTE:** *The following step may be N/A'd for any SWBs that have no bagged drums.*

4.5.5.4 QI: Ensure each bagged drum in the SWB has a 2-in.-minimum vent hole.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL NA 1-31-03	2	NA KL 1-31-03	3	NA KL 1-31-03	4	NA KL 1-31-03
5	NA KL 1-31-03	6	NA KL 2-3-03				

4.5.5.5 EO/SO/OP: Lift the lid above the packaging and center the lid so that the lid is positioned over the body shell flange (this may be accomplished manually or using Lift Plan TP 157-06 [INEEL Form 433.34]).

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

## WARNING

Pinch points are present between lid and body shell flange. Fingers must be kept clear.

(JSA)

4.5.5.6 EO/SO/OP: Lower the lid slowly onto the body shell flange, ensuring the gasket is not damaged and the lid and body serial numbers are together.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 25 of 38

**NOTE 1:** *When installing the screws, a lineup bar may be used to pull the lid into position with the body. Caution will be needed to prevent damage to the male/female threads with the lineup bar.*

**NOTE 2:** *A thread sealer (Loctite #565 or equivalent) is used on the SWB screws.*

(TSR)

**NOTE 3:** *Use of air or electric wrenches to quickly seat the screws is allowable. However, care should be taken to seat the screws only hand-tight and not to apply excessive torque.*

4.5.5.7 QI: RECORD torque wrench serial number and calibration due date.

Torque wrench serial number: 704213 / 718305 / 716785  
Calibration due date: 2-27-03 / 2-7-03 / 2-20-03

QI signature: RC Justice Date 1-31-03  
RC Justice 2-3-03

4.5.5.8 M: Install four corner screws approximately 1/4-in. or 3 to 4 turns.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	MC 1-31-03	2	MC 1-31-03	3	MC 1-31-03	4	MC 1-31-03
5	MC 1-31-03	6	MC 2-3-03				

4.5.5.9 M: Install four screws (in the middle of straight sides and the middle of the curved ends).

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	MC 1-31-03	2	MC 1-31-03	3	MC 1-31-03	4	MC 1-31-03
5	MC 1-31-03	6	MC 2-3-03				

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

 Identifier: TPR-6233  
 Revision: 1  
 Page: 26 of 38

4.5.5.10 M: Using a template, install and tighten all screws 360 to 480 in.-lb or 30 to 40 ft.-lb.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	MC 1-31-03	2	MC 1-31-03	3	MC 1-31-03	4	MC 1-31-03
5	MC 1-31-03	6	MC 2-3-03				

4.5.5.11 M: Using a template, tighten all screws 600 to 720 in.-lb or 50 to 60 ft.-lb.

(TSR)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	MC 1-31-03	2	MC 1-31-03	3	MC 1-31-03	4	MC 1-31-03
5	MC 1-31-03	6	MC 2-3-03				

4.5.5.11.1 QI: Verify that screws are torqued to the specified value.

(TSR)

QI Signature EC Justice Date 1-31-03 SWB # 010282  
 QI Signature EC Justice Date 1-31-03 SWB # 010259  
 QI Signature EC Justice Date 1-31-03 SWB # 010277  
 QI Signature EC Justice Date 1-31-03 SWB # 010288  
 QI Signature EC Justice Date 1-31-03 SWB # 010263  
 QI Signature EC Justice Date 2-5-03 SWB # 010221

4.5.5.12 EO/M: If required, remove lid lift rigging and eyebolt and stage as directed.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	NA 1-31-03	2	NA 1-31-03	3	NA 1-31-03	4	NA 1-31-03
5	NA 1-31-03	6	NA 2-3-03				



# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 27 of 38

4.5.6 RCT: Survey each SWB for contamination as it is removed from the Hot Shop.

(WIPP, JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

4.5.7 EO: Place the SWB(s) in designated area as directed.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

4.5.8 SO: GO TO Appendix D and perform the container integrity inspection.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

4.5.9 RCT: Perform contamination survey and beta-gamma and neutron radiation surveys at contact, 1 m, and 2 m for each SWB; ensure contamination levels are less than or equal to 20 dpm/100 cm<sup>2</sup> alpha, and 200 dpm/100 cm<sup>2</sup> beta-gamma for transportation.

(WIPP, JSA)

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

4.5.10 RCT: IF not already labeled,  
THEN label SWB "Caution Radioactive Material" in a clearly visible location.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	KL 1-31-03	2	KL 1-31-03	3	KL 1-31-03	4	KL 1-31-03
5	KL 1-31-03	6	KL 2-3-03				

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 28 of 38

4.5.11 SO: Apply hazardous/non-hazardous labels to SWB.

(WIPP)

*Step 22 WIPP  
1-31-03*

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1/31/03	2	1/31/03	3	1/31/03	4	1/31/03
5	1/31/03	6	1/31/03				

4.5.12 HEO/EO: Lift the packaging into position on the conveyance vehicle.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1/31/03	2	1/31/03	3	1/31/03	4	1/31/03
5	1/31/03	6	1/31/03				

4.5.13 HEO/EO: Install wood or other material to prevent longitudinal or lateral movement of the packaging.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1/31/03	2	1/31/03	3	1/31/03	4	1/31/03
5	1/31/03	6	1/31/03				

**NOTE:** The rigging must be anchored to the packaging by the lift clips at the top edge of the packaging.

4.5.14 HEO/EO: Secure the packaging to the vehicle with webbing or other suitable rigging per 49 CFR 393, Subpart I requirements.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1/31/03	2	1/31/03	3	1/31/03	4	1/31/03
5	1/31/03	6	1/31/03				

4.5.15 HEO/EO: Verify that all rigging and equipment is secure before shipment.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1/31/03	2	1/31/03	3	1/31/03	4	1/31/03
5	1/31/03	6	1/31/03				

4.5.16 WCO: Input required data into the Waste Isolation Pilot Plant (WIPP) Waste Information System (WWIS) for the SWB.

#	Initial/Date	#	Initial/Date	#	Initial/Date	#	Initial/Date
1	1/31/03	2	1/31/03	3	1/31/03	4	1/31/03
5	1/31/03	6	1/31/03				

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 29 of 38

**NOTE:** *If previously-approved WWIS container data is required to be changed to facilitate WIPP acceptance of the SWBs, the approved WWIS Data Change Request Form must be obtained from the WWIS Data Administrator and included as an attachment to this procedure.*

## 4.5.17 WCO: Certify data for the SWB.

WCO Michael Xuffe Date 2/3/03 SWB # TPRFXWB030001  
WCO Michael Xuffe Date 2/3/03 SWB # TPRFXWB030002  
WCO Michael Xuffe Date 2/3/03 SWB # TPRFXWB030003  
WCO Michael Xuffe Date 2/3/03 SWB # TPRFXWB030004  
WCO Michael Xuffe Date 2/3/03 SWB # TPRFXWB030005  
WCO Michael Xuffe Date 2/3/03 SWB # TPRFXWB030006

4.5.18

## WCO: Complete INEEL Form 461.02, "Radioactive Material Packaging Quality Control Inspection," for each SWB.

See bottom of page for remaining

1 WCO Michael Xuffe DATE: 2/3/03 SWB# TPRFXWB030001

## 4.6 Post-Performance Activities

4.6.1

## JS: Conduct a post-job review in accordance with MCP-3003.

4.6.2

## TL/SS: Ensure the TPR is completed and acceptable for closure.

4.6.3

## QE: Complete Quality Inspection Plan documentation.

4.6.4

## QE: Ensure all TPR steps are completed, signed off, and dated. (Appendix B comments should be properly dispositioned and completed.)

4.6.5

## QE: Ensure that any Non-Conformance Report items listed in Appendix B have been reported on a Non Conformance Report (NCR).

4.6.6

## QE: Ensure that the total records package is complete (see Section 5) and has been assembled and transmitted to the Project and TAN Document Control Center using Forms 416.04, "QA Record(s) Validation/Verification Form," and 241.07, "Records Analysis and Transmittal Form."

## 4.5.19 Signoffs

2 WCO: Michael Xuffe DATE: 2/3/03 SWB#: TPRFXWB030002  
3 WCO: Michael Xuffe DATE: 2/3/03 SWB#: TPRFXWB030003  
4 WCO: Michael Xuffe DATE: 2/3/03 SWB#: TPRFXWB030004  
5 WCO: Michael Xuffe DATE: 2/3/03 SWB#: TPRFXWB030005  
6 WCO: Michael Xuffe DATE: 2/3/03 SWB#: TPRFXWB030006

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 30 of 38

## 5. RECORDS

Record Description	Classification	Uniform File Code	Disposition Authority	Retention Period
TPR-6233 Case File	INEEL Lifetime QA	0276	A16-1.1	Permanent. Cut off when superseded, obsolete, or canceled.
	WIPP WAP Nonpermanent QA			
Field Pack File: RWMC Form-287, Operations Document Checklist for Field Pack/TRUPACT Loading File	INEEL Nonpermanent QA	7403	ENVI-k-2-b EPI*	Cut off at project completion. Destroy 25 years after project completion.
<ul style="list-style-type: none"> <li>✓ - Consumable TPR-6233</li> <li>- SWB Assembly Details Report, as applicable</li> <li>- <del>Payload Assembly</del> 14-Pack Layout report, as applicable</li> <li>- <del>PATCD(s)</del> report as applicable</li> <li>- Copy of any NCR Report associated with TPR performance</li> <li>✓ - Copy of Radiological Survey Report</li> <li>- Manual Drum Tracking Form</li> <li>✓ - INEEL Form 433.34, INEEL Lift Plan</li> <li>✓ - INEEL Form 433.34A, INEEL Lift Plan Supplement</li> <li>- CBFO-supplied shipping documents</li> <li>- W WIS Data Change Request Form, if needed</li> </ul>	WIPP WAP Nonpermanent QA			

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 31 of 38

Record Description	Classification	Uniform File Code	Disposition Authority	Retention Period
INTEC-QA-0221, Quality Inspection of TRUPACT-157 Payload Disassembly Operations at Test Area North (TAN)	INEEL Lifetime QA	7204	A17-32-a EPI	Retain until item is removed from service.
	WIPP WAP Nonpermanent QA			

## 6. REFERENCES

DOE-STD-1090-2001, DOE Hoisting and Rigging Standard

DOE Docket: 98-45-7A (Section 3.2), TRUPACT-II Standard Waste Box (SWB)

INEL-94/0209, "TANO Technical Safety Requirements"

TAN-JSA-6233

Code of Federal Regulation (CFR), Title 10, Part 835, Occupational Radiation Protection

CFR, Title 40, Subpart C, 262.32, Marking

CFR, Title 49, Part 393, Subpart I, Protection Against Shifting or Falling Cargo

DOE/WIPP-02-3122, Contact-Handled Transuranic Waste Acceptance Criteria for the Waste Isolation Pilot Plant

DOE/WIPP 02-3183, CH Packaging Program Guidance

DOE/WIPP 02-3184, CH Packaging Operations Manual

WIPP Procedure WP 08-PT.01, Standard Waste Box Handling and Operation Manual

EDF-2326, Dented 55 Gal. Drum Stress Analysis

INEEL Radiological Control Manual

MCP-139, Radiological Surveys

MCP-2520, TRU Waste Characterization Program Quality Assurance Records Management

MCP-2716, Personal Protective Equipment

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN****Identifier:** TPR-6233  
**Revision:** 1  
**Page:** 32 of 38

MCP-3003, Performing Pre-Job Briefings and Post-Job Reviews

PLN-577, TRUPACT-II Authorized Methods for Payload Control (TRAMPAC)  
Compliance Plan

PLN-1165, Transport Plan for Shipment of Transuranic Waste Drums between TAN and  
RWMC

TRUPACT-II Certificate of Compliance

TRUPACT-II Safety Analysis Report, Appendix 1.3.5

## **7. APPENDIXES**

Appendix A – Procedure Basis

Appendix B – Comment Sheet

Appendix C – Manual Drum Tracking Form

Appendix D – Container Integrity Inspection

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 33 of 38

**APPENDIX A**

**Procedure Basis**

Step	Basis	Reference
General	Activities affecting quality shall be prescribed by and performed in accordance with documented instructions, procedures, or drawings that include appropriate quantitative or qualitative acceptance criteria for determining that prescribed results have been satisfactorily attained.	PRD-5076 Section 4.1.1.1
2.4 through 2.9, 3.1.2, 3.1.4, 3.4.1, 4.2.2, 4.2.2.1, 4.2.2.5.1, 4.4.1, Note preceding 4.4.4, 4.4.4, 4.4.9, 4.4.11, 4.4.13, 4.4.22, 4.4.24, 4.4.26, Warning preceding 4.5.5.6, 4.5.6, 4.5.9	Implementation of JSA requirements.	TAN JSA-6233
2.2	<p>The Adjustable Center-of-Gravity Lift Fixture (ACGLF) is designed to handle the weight of the following configurations:</p> <ul style="list-style-type: none"> <li>an OCA lid assembly</li> <li>an ICV lid</li> <li>an empty ICV assembly</li> <li>a loaded payload (i.e., 14 drums), two SWBs, or one ten-drum overpack (TDOP).</li> </ul> <p>The ACGLF is <b>NOT</b> designed to lift the weight of the following configurations:</p> <ul style="list-style-type: none"> <li>a loaded CH package or empty CH packaging</li> <li>a loaded or empty OCA</li> <li>a loaded ICV.</li> </ul>	DOE/WIPP 02-3183, Section 1.6.4

<p align="center"><b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6233 Revision: 1 Page: 34 of 38</p>
--	--

Step	Basis	Reference
3.3, 4.3.5, 4.3.6, 4.3.7.2, 4.3.7.3, 4.3.9, 4.3.9.1, 4.3.10, 4.3.11, 4.3.12, 4.3.13, 4.3.14, 4.5.5.6, 4.5.5.7, Note 2, 4.5.5.8, 4.5.5.9, 4.5.5.10, 4.5.5.11, 4.5.5.11.1	The TRU mixed waste drums shall be transported in a standard waste box. The standard waste box shall be assembled in accordance with the WP 08-PT.01, <i>Standard Waste Box Handling and Operation Manual</i> .	PLN-1165 Section (TSR) 7.1
3.3, 3.4.3.1	For the purpose of hazardous material procurement, a quality level (QL) is assigned to each type of packaging that correlates with the MCP-540 assigned safety categories: safety class is equivalent to QL-1. Section 6.5 assigns a safety class category to SWBs used for TRU mixed waste drum transport activity.	PLN-1165 Section 1.3
4.3.7.1, 4.3.9, 4.3.9.1	The standard waste boxes will be vented through two filters as specified in DOE/RL-96-57, <i>Test and Evaluation Document for DOT Specification 7A Type A Packaging</i> .	PLN-1165 Section (TSR) 7.3
4.5.12, 4.5.13, 4.5.14, 4.5.15	The standard waste boxes and ICV container will be secured to the transport vehicles in accordance with DOT instructions specified in 49 CFR 393, Subpart I. The tiedowns for the standard waste boxes will also be in accordance with the WP 08-PT.01, <i>Standard Waste Box Handling and Operation Manual</i> .	PLN-1165 Section 8.5
4.3.2, 4.5.11	Verify SWBs are properly labeled (e.g., bar code, shipping category)	DOE/WIPP 02-3184 Section 1.3.2
4.3.7.3	Verify at least two filters are installed in each SWB and the remaining ports are plugged (if not filtered).	DOE/WIPP 02-3184 Section 1.3.1
4.4.11, 4.4.24	If beta-gamma and alpha surveys are required, survey using site-specific procedures	DOE/WIPP 02-3184 Section 1.3.7
4.5.6, 4.5.9	If beta-gamma and alpha surveys are required, survey using site-specific procedures	DOE/WIPP 02-3184 Section 1.3.7
4.5.2	Dunnage drums shall have open vent ports (i.e., not filtered or plugged).	DOE/WIPP 02-3184



**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 35 of 38

**APPENDIX B**

**Comment Sheet**

**NOTE:** Any documents (Such as NCRs, WOs, DRs) issued to close, track, or resolve comments are recorded in the comment section.

Initial	Date/Time	Page No.	Step No.	Comments/Notes/Observations
<i>Q</i>	1/30/03 0800	11/38	4.3	Steps in sec 4.3 were reperformed in order to promote efficiency, and complete sub staging, and did not misdirect procedure flow.
<i>Q</i>	1/30/03 0845	16/38	4.4.1 4.4.2	these steps were reperformed to ensure equipment and conditions were adequate for a new day.
<i>Q</i>	1/30/03 1045	18/38	4.4.11.1	position #7 was N/A'd per step directions, however Rad-con foreman directed operators to apply fixative as Best Management Practice.
<i>Q</i>	1/31/03 1230	14, 15/38	4.3.10 Thru 4.3.14,	These steps were reperformed two additional times due to the need to replace damaged sub lid gaskets. step 4.3.12 was not reperformed because it did not deal with the gaskets.
<i>Q</i>	1/31/03 1320	22/38	4.5.3	this step re-performed to <sup>re-</sup> install drainage deems that were found to contain water, drained, then replaced.
<i>Q</i>	1/31/03 1330	23/38	4.5.3.1 4.5.3.2	steps were not performed for deems not bagged.
<i>Q</i>	1/31/03 1520	25/38	4.5.5.7	Reperform step for new torque wrench DUE TO MALFUNCTION OF ORIGINAL TORQUE WRENCH
<i>Q</i>	1/31/03 1535	25/38	4.5.5.7	performed step 4.5.5.7 the third time with additional torque wrench that has a narrower range.

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 35 of 38

## APPENDIX B

## Comment Sheet

**NOTE:** Any documents (Such as NCRs, WOs, DRs) issued to close, track, or resolve comments are recorded in the comment section.

Initial	Date/Time	Page No.	Step No.	Comments/Notes/Observations
A	2/3/03 1420		4.7.27.8	We are performing a "Go to" step to go to step 4.7.25 + "Reperform" steps 4.7.25 and 4.7.26 then "Go to" step 4.5.5. this action has no adverse impact on procedure.
A	2/3/03 1500	11	4.3.2	Reperformed this step because the SWB Weight changed by exchanging drums in SWB.
A	2/3/03 1915	22	4.5.1 to 4.5.3.	Block #1, SWB had no Damage Drum. Block #3, initially had no Damage until Payload was reconfigured, Steps for adding Damage were worked in Sec. 4.7 per Doc 98552.
A	2/3/03 1930	30	Sec. 5.	the SWB assembly Details Report, the Payload Assembly 14-Pack Lay-out Report, and the PATCD's Report are to be supplied by TRAPP's System as applicable.

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: 1  
Page: 36 of 38**APPENDIX C****Manual Drum Tracking Form**

	Container ID# (IDRF)	Standard Waste Box ID#	SO (initial) <sup>a</sup>	QI (initial) <sup>b</sup>	Comments
1.	IDRF 741 202 484	IDRF XWB0 30007	RK/JS	PCS	
2.					
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					
11.					
12.					
13.					
14.					

a. SO initials indicate drum was moved to the correct Standard Waste Box (SWB).

b. QI initials indicate proper placement of the drum in the designated SWB.

SWEPP Operator (SO) Signature Robin Kellie / [Signature] Date 02-03-03Quality Inspector (QI) Signature [Signature] Date 2-3-03

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 36 of 38

**APPENDIX C**

**Manual Drum Tracking Form**

	Container ID# (IDRF)	Standard Waste Box ID#	SO (initial) <sup>a</sup>	QI (initial) <sup>b</sup>	Comments
1.	IDRF004 102263	IDRFXW80 30001	RK/JS	RCS	
2.	IDRF004 002801	IDRFXW80 30001	RK/JS	RCS	
3.	IDRF004 101890	IDRFXW80 30001	RK/JS	RCS	
4.	IDRF004 102254	IDRFXW80 30001	RK/JS	RCS	
5.	IDRF004 002790	IDRFXW80 30002	RK/JS	RCS	
6.	IDRF 741 202088	IDRFXW80 30003	RK/JS	RCS	
7.	IDRF 741 202484	IDRFXW80 30003	RK/JS	RCS	> 100 dpm Contamination Found on top of drum. Fixadent applied. Drum bagged
8.	IDRF 741 205405	IDRFXW80 30003	RK/JS	RCS	
9.	IDRF 741 201615	IDRFXW80 30003	RK/JS	RCS	
10.	IDRF 074 700411	IDRFXW80 30006	RK/JS	KET	
11.	IDRF 741 201718	IDRFXW80 30004	RK/JS	KET	
12.	IDRF 741 204650	IDRFXW80 30004	RK/JS	KET	
13.	IDRF 074 700394	IDRFXW80 30006	RK/JS	KET	
14.	IDRF 074 221338	IDRFXW80 30005	RK/JS	KEI	

a. SO initials indicate drum was moved to the correct Standard Waste Box (SWB).

b. QI initials indicate proper placement of the drum in the designated SWB.

SWEPP Operator (SO) Signature Robin Killian / [Signature] Date 1-30-03

Quality Inspector (QI) Signature Kelly Thompson / [Signature] Date 1-30-03 / 1-30-03

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 37 of 38

## APPENDIX D

### Container Integrity Inspection

SWB # IDRF XWB030001

Note: The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
		YES	NO
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.		<input checked="" type="radio"/>
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES	<input checked="" type="radio"/>
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusty payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES	<input checked="" type="radio"/>
4. Are any of the following apparent?	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES	<input checked="" type="radio"/>
<ul style="list-style-type: none"> <li>• wall thinning</li> <li>• pinholes</li> <li>• breaches</li> </ul>			
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES	<input checked="" type="radio"/>

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233

Revision: 1

Page: 38 of 38

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE
6. Is the load-bearing capacity suspect?	The load-bearing capacity could be reduced for excessive rust (see discussion for #3), wall thinning (see discussion for #4), breaches, cracks, creases, broken welds, etc. (see discussion for #5).	YES <u>NO</u>
7. Is the payload container improperly closed?	Inspect the fastener and fastener ring (chine) if applicable for damage or excessive corrosion. Check the alignment of the fastener to ensure that it is in firm contact around the entire lid and the payload container will not open during transportation.	YES <u>NO</u>
8. Are there any dents, scrapes, or scratches that make the payload container's structural integrity questionable or prevent the top and bottom surfaces from being parallel?	Deep gouges, scratches, or abrasions over wide areas are not acceptable. If top and bottom surfaces are not parallel, this would indicate that the container is warped. Dents should be less than ¼ inch deep by 3 inches long and between ½ inch to 6 inches wide. All other dents must be examined to determine impact of structural integrity if doing an inspection. (EDF-2326).	YES <u>NO</u>
9. Is there discoloration which would indicate leakage or other evidence of leakage of material from the payload container?	Examine the payload container regions near vents, top lid fittings, bottom fittings, welds, seams and intersections of one or more metal sheets or plates. Payload containers must be rejected if evidence of leakage is present.	YES <u>NO</u>
10. Is the payload container bulged?	For the purposes of this examination, bulging is indicated by: <ul style="list-style-type: none"> <li>A fairly uniform expansion of the sidewalls, bottom, or top (e.g., in the case of a drum, either the top or bottom surface protrudes beyond the planar surface of the top or bottom ring,</li> <li>A protrusion of the side wall (e.g., in the case of a drum, beyond a line connecting the peaks of the surrounding rolling hoops or a line between a surrounding rolling hoop and the bottom or top ring), or</li> <li>Expansion of the sidewall (e.g., in the case of a drum, such that it deforms any portion of a rolling hoop).</li> </ul>	YES <u>NO</u>

SO:

Relly Doyle Michael Moore 1-31-03

Signature

Date

<p align="center"><b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6233 Revision: 1 Page: 37 of 38</p>
--	--

## APPENDIX D

## Container Integrity Inspection

SWB # IDRFXWB030002

Note: The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.	YES	<input checked="" type="radio"/> NO
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES	<input checked="" type="radio"/> NO
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusted payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES	<input checked="" type="radio"/> NO
4. Are any of the following apparent? • wall thinning • pinholes • breaches	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES	<input checked="" type="radio"/> NO
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, creases, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES	<input checked="" type="radio"/> NO

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 37 of 38

**APPENDIX D**

**Container Integrity Inspection**

SWB # IDRF-XWB030003

**Note:** The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.	YES	<input checked="" type="radio"/> NO
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES	<input checked="" type="radio"/> NO
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusty payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES	<input checked="" type="radio"/> NO
4. Are any of the following apparent? <ul style="list-style-type: none"> <li>• wall thinning</li> <li>• pinholes</li> <li>• breaches</li> </ul>	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES	<input checked="" type="radio"/> NO
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, creases, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES	<input checked="" type="radio"/> NO



# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233  
Revision: 1  
Page: 38 of 38

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE
6. Is the load-bearing capacity suspect?	The load-bearing capacity could be reduced for excessive rust (see discussion for #3), wall thinning (see discussion for #4), breaches, cracks, creases, broken welds, etc. (see discussion for #5).	YES <input checked="" type="radio"/> NO
7. Is the payload container improperly closed?	Inspect the fastener and fastener ring (chine) if applicable for damage or excessive corrosion. Check the alignment of the fastener to ensure that it is in firm contact around the entire lid and the payload container will not open during transportation.	YES <input checked="" type="radio"/> NO
8. Are there any dents, scrapes, or scratches that make the payload container's structural integrity questionable or prevent the top and bottom surfaces from being parallel?	Deep gouges, scratches, or abrasions over wide areas are not acceptable. If top and bottom surfaces are not parallel, this would indicate that the container is warped. Dents should be less than ¼ inch deep by 3 inches long and between ½ inch to 6 inches wide. All other dents must be examined to determine impact of structural integrity if doing an inspection. (EDF-2326).	YES <input checked="" type="radio"/> NO
9. Is there discoloration which would indicate leakage or other evidence of leakage of material from the payload container?	Examine the payload container regions near vents, top lid fittings, bottom fittings, welds, seams and intersections of one or more metal sheets or plates. Payload containers must be rejected if evidence of leakage is present.	YES <input checked="" type="radio"/> NO
10. Is the payload container bulged?	For the purposes of this examination, bulging is indicated by: <ul style="list-style-type: none"> <li>A fairly uniform expansion of the sidewalls, bottom, or top (e.g., in the case of a drum, either the top or bottom surface protrudes beyond the planar surface of the top or bottom ring,</li> <li>A protrusion of the side wall (e.g., in the case of a drum, beyond a line connecting the peaks of the surrounding rolling hoops or a line between a surrounding rolling hoop and the bottom or top ring), or</li> <li>Expansion of the sidewall (e.g., in the case of a drum, such that it deforms any portion of a rolling hoop).</li> </ul>	YES <input checked="" type="radio"/> NO

SO:

Robin Killian Michael Halani 02-03-03  
Signature Date

<p align="center"><b>TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN</b></p>	<p>Identifier: TPR-6233 Revision: 1 Page: 37 of 38</p>
--	--

## APPENDIX D

## Container Integrity Inspection

SWB # IDRFxWB030004

Note: The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.	YES	NO
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES	NO
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusted payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES	NO
4. Are any of the following apparent? • wall thinning • pinholes • breaches	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES	NO
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, creases, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES	NO

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233

Revision: 1

Page: 38 of 38

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
6. Is the load-bearing capacity suspect?	The load-bearing capacity could be reduced for excessive rust (see discussion for #3), wall thinning (see discussion for #4), breaches, cracks, creases, broken welds, etc. (see discussion for #5).	YES	<input checked="" type="radio"/> NO
7. Is the payload container improperly closed?	Inspect the fastener and fastener ring (chine) if applicable for damage or excessive corrosion. Check the alignment of the fastener to ensure that it is in firm contact around the entire lid and the payload container will not open during transportation.	YES	<input checked="" type="radio"/> NO
8. Are there any dents, scrapes, or scratches that make the payload container's structural integrity questionable or prevent the top and bottom surfaces from being parallel?	Deep gouges, scratches, or abrasions over wide areas are not acceptable. If top and bottom surfaces are not parallel, this would indicate that the container is warped. Dents should be less than ¼ inch deep by 3 inches long and between ½ inch to 6 inches wide. All other dents must be examined to determine impact of structural integrity if doing an inspection. (EDF-2326).	YES	<input checked="" type="radio"/> NO
9. Is there discoloration which would indicate leakage or other evidence of leakage of material from the payload container?	Examine the payload container regions near vents, top lid fittings, bottom fittings, welds, seams and intersections of one or more metal sheets or plates. Payload containers must be rejected if evidence of leakage is present.	YES	<input checked="" type="radio"/> NO
10. Is the payload container bulged?	For the purposes of this examination, bulging is indicated by: <ul style="list-style-type: none"><li>• A fairly uniform expansion of the sidewalls, bottom, or top (e.g., in the case of a drum, either the top or bottom surface protrudes beyond the planar surface of the top or bottom ring,</li><li>• A protrusion of the side wall (e.g., in the case of a drum, beyond a line connecting the peaks of the surrounding rolling hoops or a line between a surrounding rolling hoop and the bottom or top ring), or</li><li>• Expansion of the sidewall (e.g., in the case of a drum, such that it deforms any portion of a rolling hoop).</li></ul>	YES	<input checked="" type="radio"/> NO

SO:

J. J. Schmandl  
Signature1-31-03

Date

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 37 of 38

**APPENDIX D**

**Container Integrity Inspection**

SWB # IDAFXW3030005

**Note:** The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.	YES	<u>NO</u>
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES	<u>NO</u>
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusty payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES	<u>NO</u>
4. Are any of the following apparent? <ul style="list-style-type: none"> <li>• wall thinning</li> <li>• pinholes</li> <li>• breaches</li> </ul>	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES	<u>NO</u>
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, creases, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES	<u>NO</u>

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**Identifier: TPR-6233  
Revision: 1  
Page: 38 of 38

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
6. Is the load-bearing capacity suspect?	The load-bearing capacity could be reduced for excessive rust (see discussion for #3), wall thinning (see discussion for #4), breaches, cracks, creases, broken welds, etc. (see discussion for #5).	YES	<input checked="" type="radio"/> NO
7. Is the payload container improperly closed?	Inspect the fastener and fastener ring (chine) if applicable for damage or excessive corrosion. Check the alignment of the fastener to ensure that it is in firm contact around the entire lid and the payload container will not open during transportation.	YES	<input checked="" type="radio"/> NO
8. Are there any dents, scrapes, or scratches that make the payload container's structural integrity questionable or prevent the top and bottom surfaces from being parallel?	Deep gouges, scratches, or abrasions over wide areas are not acceptable. If top and bottom surfaces are not parallel, this would indicate that the container is warped. Dents should be less than ¼ inch deep by 3 inches long and between ½ inch to 6 inches wide. All other dents must be examined to determine impact of structural integrity if doing an inspection. (EDF-2326).	YES	<input checked="" type="radio"/> NO
9. Is there discoloration which would indicate leakage or other evidence of leakage of material from the payload container?	Examine the payload container regions near vents, top lid fittings, bottom fittings, welds, seams and intersections of one or more metal sheets or plates. Payload containers must be rejected if evidence of leakage is present.	YES	<input checked="" type="radio"/> NO
10. Is the payload container bulged?	For the purposes of this examination, bulging is indicated by: <ul style="list-style-type: none"><li>• A fairly uniform expansion of the sidewalls, bottom, or top (e.g., in the case of a drum, either the top or bottom surface protrudes beyond the planar surface of the top or bottom ring,</li><li>• A protrusion of the side wall (e.g., in the case of a drum, beyond a line connecting the peaks of the surrounding rolling hoops or a line between a surrounding rolling hoop and the bottom or top ring), or</li><li>• Expansion of the sidewall (e.g., in the case of a drum, such that it deforms any portion of a rolling hoop).</li></ul>	YES	<input checked="" type="radio"/> NO

SO:



Signature

1-31-03

Date

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233  
Revision: 1  
Page: 37 of 38

**APPENDIX D**

**Container Integrity Inspection**

SWB # IDRF XLVB030006

**Note:** The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.	YES <input checked="" type="radio"/> NO <input type="radio"/> KH-31-03
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES <input type="radio"/> NO <input checked="" type="radio"/>
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusty payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES <input type="radio"/> NO <input checked="" type="radio"/>
4. Are any of the following apparent? <ul style="list-style-type: none"> <li>• wall thinning</li> <li>• pinholes</li> <li>• breaches</li> </ul>	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES <input type="radio"/> NO <input checked="" type="radio"/>
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, creases, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES <input type="radio"/> NO <input checked="" type="radio"/>

# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 38 of 38

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE	
6. Is the load-bearing capacity suspect?	The load-bearing capacity could be reduced for excessive rust (see discussion for #3), wall thinning (see discussion for #4), breaches, cracks, creases, broken welds, etc. (see discussion for #5).	YES	<input checked="" type="radio"/> NO
7. Is the payload container improperly closed?	Inspect the fastener and fastener ring (chine) if applicable for damage or excessive corrosion. Check the alignment of the fastener to ensure that it is in firm contact around the entire lid and the payload container will not open during transportation.	YES	<input checked="" type="radio"/> NO
8. Are there any dents, scrapes, or scratches that make the payload container's structural integrity questionable or prevent the top and bottom surfaces from being parallel?	Deep gouges, scratches, or abrasions over wide areas are not acceptable. If top and bottom surfaces are not parallel, this would indicate that the container is warped. Dents should be less than ¼ inch deep by 3 inches long and between ½ inch to 6 inches wide. All other dents must be examined to determine impact of structural integrity if doing an inspection. (EDF-2326).	YES	<input checked="" type="radio"/> NO
9. Is there discoloration which would indicate leakage or other evidence of leakage of material from the payload container?	Examine the payload container regions near vents, top lid fittings, bottom fittings, welds, seams and intersections of one or more metal sheets or plates. Payload containers must be rejected if evidence of leakage is present.	YES	<input checked="" type="radio"/> NO
10. Is the payload container bulged?	For the purposes of this examination, bulging is indicated by: <ul style="list-style-type: none"> <li>A fairly uniform expansion of the sidewalls, bottom, or top (e.g., in the case of a drum, either the top or bottom surface protrudes beyond the planar surface of the top or bottom ring,</li> <li>A protrusion of the side wall (e.g., in the case of a drum, beyond a line connecting the peaks of the surrounding rolling hoops or a line between a surrounding rolling hoop and the bottom or top ring), or</li> <li>Expansion of the sidewall (e.g., in the case of a drum, such that it deforms any portion of a rolling hoop).</li> </ul>	YES	<input checked="" type="radio"/> NO

SO:

*Relly Hoyt Michael Malavi*  
Signature

*1-31-03*  
Date

**TRUPACT-157 PAYLOAD DISASSEMBLY  
OPERATIONS AT TAN**

Identifier: TPR-6233

Revision: 1

Page: 37 of 38

**APPENDIX D****Container Integrity Inspection**SWB # IDRFxWB030007

Note: The SO should circle the correct answer in the "Compliance" column.

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE
1. Is the payload container obviously degraded?	Obviously degraded means clearly visible and potentially significant defects in the payload container or payload container surface.	YES <input checked="" type="radio"/> NO
2. Is there evidence that the payload container is, or has been, pressurized?	Pressurization can be indicated by a fairly uniform expansion of the sidewalls, bottom or top. Past pressurization can be indicated by a notable outward deflection of the bottom or top. Verify that the drum is not warped.	YES <input checked="" type="radio"/> NO
3. Is there any potentially significant rust or corrosion such that wall thinning, pinholes, or breaches are likely or the load bearing capacity is suspect?	<p>Rust shall be assessed in terms of its type, extent, and location. Pitting, pocking, flaking, or dark coloration characterizes potentially significant rust or corrosion. This includes the extent of the payload container surface area covered, thickness, and, if it occurs in large flakes or built-up (caked) areas. Rusted payload containers may not be accepted if:</p> <ul style="list-style-type: none"> <li>• Rust is present in caked layers or deposits</li> <li>• Rust is present in the form of deep metal flaking, or built-up areas of corrosion products</li> </ul> <p>In addition, the location of rust should be noted; for example on a drum: top lid; filter region; locking chine; top one-third, above the second rolling hoop; middle one-third, between the first and second rolling hoops; bottom one-third, below the second rolling hoop; and on the bottom.</p> <p>Payload containers may still be considered acceptable if the signs of rust show up as:</p> <ul style="list-style-type: none"> <li>• Some discoloration on the payload container</li> <li>• If rubbed would produce fine grit or dust or minor flaking (such that wall thinning does not occur)</li> </ul>	YES <input checked="" type="radio"/> NO
4. Are any of the following apparent? <ul style="list-style-type: none"> <li>• wall thinning</li> <li>• pinholes</li> <li>• breaches</li> </ul>	Wall thinning, pinholes, and breaches can be a result of rust/corrosion (see discussion for #3).	YES <input checked="" type="radio"/> NO
5. Are there any split seams, tears, obvious holes, punctures (of any size), creases, broken welds, or cracks?	Payload containers with obvious leaks, holes or openings, cracks, deep crevices, creases, tears, broken welds, sharp edges or pits, are either breached or on the verge of being breached. Verify that there is no warpage that could cause the container to be unstable or prevent it from fitting properly in the TRUPACT-II.	YES <input checked="" type="radio"/> NO



# TRUPACT-157 PAYLOAD DISASSEMBLY OPERATIONS AT TAN

Identifier: TPR-6233

Revision: 1

Page: 38 of 38

CONTAINER EXAMINATION	DISCUSSION OF CRITERIA	COMPLIANCE
6. Is the load-bearing capacity suspect?	The load-bearing capacity could be reduced for excessive rust (see discussion for #3), wall thinning (see discussion for #4), breaches, cracks, creases, broken welds, etc. (see discussion for #5).	YES <input checked="" type="radio"/> NO
7. Is the payload container improperly closed?	Inspect the fastener and fastener ring (chine) if applicable for damage or excessive corrosion. Check the alignment of the fastener to ensure that it is in firm contact around the entire lid and the payload container will not open during transportation.	YES <input checked="" type="radio"/> NO
8. Are there any dents, scrapes, or scratches that make the payload container's structural integrity questionable or prevent the top and bottom surfaces from being parallel?	Deep gouges, scratches, or abrasions over wide areas are not acceptable. If top and bottom surfaces are not parallel, this would indicate that the container is warped. Dents should be less than ¼ inch deep by 3 inches long and between ½ inch to 6 inches wide. All other dents must be examined to determine impact of structural integrity if doing an inspection. (EDF-2326).	YES <input checked="" type="radio"/> NO
9. Is there discoloration which would indicate leakage or other evidence of leakage of material from the payload container?	Examine the payload container regions near vents, top lid fittings, bottom fittings, welds, seams and intersections of one or more metal sheets or plates. Payload containers must be rejected if evidence of leakage is present.	YES <input checked="" type="radio"/> NO
10. Is the payload container bulged?	For the purposes of this examination, bulging is indicated by: <ul style="list-style-type: none"> <li>A fairly uniform expansion of the sidewalls, bottom, or top (e.g., in the case of a drum, either the top or bottom surface protrudes beyond the planar surface of the top or bottom ring,</li> <li>A protrusion of the side wall (e.g., in the case of a drum, beyond a line connecting the peaks of the surrounding rolling hoops or a line between a surrounding rolling hoop and the bottom or top ring), or</li> <li>Expansion of the sidewall (e.g., in the case of a drum, such that it deforms any portion of a rolling hoop).</li> </ul>	YES <input checked="" type="radio"/> NO

SO:

*Robin Killian* *Mohal Halawi* 02-03-03  
Signature Date

Job/Title TPR-6233, TRUPACT-157 Payload Disassembly Operations at TAN		JSA Number TAN-JSA-6233	Revision 0
Facility/Project & Location  TAN-607	Effective Date 11/26/02 Expiration Date 11/26/03	Facility/Project Management/Supervisor Approval / Date  See DAR 96877	
SME APPROVAL (A "Yes" response requires a signature and date.)			
No	Yes	SME	Signature
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Industrial Safety	See DAR 96877
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Industrial Hygiene	See DAR 96877
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Safety Analysis	See DAR 96877
<input type="checkbox"/>	<input checked="" type="checkbox"/>	RCT/RAD Eng.	See DAR 96877
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Operations	See DAR 96877
No	Yes	SME	Signature
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Quality Assurance	See DAR 96877
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Engineering	See DAR 96877
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Safeguards/NMC	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Maintenance	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Fire Protection	
Briefly Describe The Job and Expected Result This job disassembles the TPUPACT-157 payload at Test Area North (TAN).			
Required Job Training/Required Personal Protective Equipment Training: Radworker II, HAZWOPER/TSD, TAN access Job position, hoisting and rigging, pre-job briefing. PPE: Safety shoes and other PPE as required by the RWP.			

Sequence Of Basic Job Steps	Potential Hazards	Hazard Control/PPE (other than that listed above)
1. General	a. Hoisting/rigging	a. Critical lifts require use of a Person in Charge (PIC). Periodic inspections are performed on hoisting and rigging equipment.
	b. Foot injury	b. Safety shoes must be worn when in the TAN Hot Shop.
	c. Carbon monoxide exposure	c. If fossil-fueled vehicle runs continuously, without a ventilation hose attached, for more than approximately 10 minutes inside the building a CO monitor must be obtained from Industrial Hygiene for use.
	d. Smashing	d. Parts of the body must not be placed under suspended loads with the following exceptions: ACGLF adjustments/leg changes, and guiding leg insertions.
	e. Heat stress	e. Heat stress monitoring must be performed per MCP-9240.
	f. Pinching	f. Non-essential personnel must stay clear during ACGLF operation.
	g. Radiological	g. Ensure RWP is followed and use good ALARA practices.
2. Moving the Payload assembly	a. See general hazards	
3. Disassembly of a 14-Pack Payload	a. See general hazards	
	b. Radiological	b. Ensure the tent ventilation system is functioning properly prior to performing work in the tent.
	c. Radiological	c. RadCon will direct whether the disassembly of the payload will be performed from inside the containment tent or from outside of the tent based on survey results and RWP requirements.

74 10/20/02



DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS)  
DOCUMENT ACTION REQUEST (DAR)

11/20/02

1. Document ID: TAN-JSA-6233		Current Revision ID: 0-100		See Block # for DAR # Info.	
2. Document Title: TPA-6233, TRUPACT-157 Payload Disassembly Operations at TAN					
3. Requester: C. Pongratte		Phone: 6-6784	MS: 6201	E-mail: cpong@tal	S No: 060227
4. Type: <input checked="" type="checkbox"/> Document <input type="checkbox"/> Drawing		5. Type of action: <input checked="" type="checkbox"/> Create <input type="checkbox"/> Revise <input type="checkbox"/> Cancel			
6. Field Change: <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes. If Yes, what the change is: <input type="checkbox"/> Permanent or <input type="checkbox"/> Temporary? If Temporary, enter the field change duration.					
7. Proposed Action: Create new procedure					
Item	Page No / Section/Zone	Description	Justification		
1	All	Create new JSA per attached.	A Hazards Evaluation Group (HEG) review and associated Job Safety Analysis (JSA) is required for TPA-6233.		
8. Proposal Approved: <input checked="" type="checkbox"/> Accepted <input type="checkbox"/> Deferred <input type="checkbox"/> Rejected		DAR No: 06977			
If rejected, indicate reason:		(For Accepted Proposal Only)			
Document Owner Printed Name: K.E. Strecker		Signature: <i>K.E. Strecker</i>		Date: 11-19-02	
Is this a minor document change? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes. If Yes, proceed to Block 14. (For Operations procedures, go to Block 11.)					
9. Management Approval (Excluding drawings, minor changes, & field changes):					
Printed Name: K. E. Strecker		Signature: <i>K.E. Strecker</i>		Date: 11-19-02	
10. Implementation Actions - Will the procedure require:					
Hazard mitigation per MCP-3562 or MCP-3571? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes. If Yes, <i>TPA-6233</i>					
Training? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes. If Yes, <i>On job training</i>					
Procurement activities? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes. If Yes, _____					
Building modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes. If Yes, _____					
Other: <i>None</i>					
11. Include a list of reviewers and review comments and signatures with this form or have reviewers sign below.					
Printed Name	Discipline	Org. No.	Signature	Date	
K. M. Wandt	TAN System Engineer	5225	<i>K.M. Wandt</i>	11-19-02	
	Operations	5225	<i>C. Pongratte</i>	11-19-02	
J. Walker	Safety Analyst	5225	<i>J. Walker</i>	11-19-02	
K. Packer	TAN QA	5240	<i>K. Packer</i>	11-19-02	
S. R. Gumpach	TAN Industrial Safety	5240	<i>S. R. Gumpach</i>	11-19-02	
D. J. Sommers	TAN RedCon	5240	<i>D. J. Sommers</i>	11-19-02	
S. G. Combs	TAN IH	5240	<i>S. G. Combs</i>	11-19-02	
12. Is document a TPR or EAR? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes. If Yes, indicate procedure validation method used:					
<input type="checkbox"/> Formal Walkdown <input type="checkbox"/> Tasklist Analysis <input type="checkbox"/> Limited Trial Use/Field Use <input type="checkbox"/> Partial Validation					
13. <input checked="" type="checkbox"/> Change does not affect a permitted area, TSD facility, or VCO component. (RCRA evaluation NOT required. Proceed to Block 14.)					
<input type="checkbox"/> Change does affect a permitted area, TSD facility, or VCO component.					
Is RCRA permit/approval modified? <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> Unknown					
If Yes or Unknown, attach completed Form 495.2B or reference form's location here: _____					
Evaluator Printed Name: <i>P. Scott</i>		Signature: <i>P. Scott</i>		Date: 11-19-02	
Is VCO component affected? <input type="checkbox"/> No <input type="checkbox"/> Yes		If Yes, contact the VCO Program Office for direction.			
14. USG Screening: (To be completed only after final document review.) List any associated change forms: _____					

DOCUMENT MANAGEMENT CONTROL SYSTEM (DMCS)  
DOCUMENT ACTION REQUEST (DAR)

Document ID: TAN-JSA-6232		Current Revision ID: <i>P. New</i> <i>03</i>		See Block 8 for DAR # info.	
Is USC screening required? (See instructions) <input type="checkbox"/> Not Required (Proceed to Block 15) <input checked="" type="checkbox"/> Required (Submit document and DAR to qualified USC screener and attach USC screening form.) USC Evaluation Required? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If Yes, attach evaluation. See USA Fm 7PA-6233					
15. Does the action qualify as a summary review? <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> N/A					
16. Desired effective date for document: Only at Block 19					
17. Other documents affected by this action: TIA-6233					
18. Document Owner Final Approval: Changes in action to those identified on the DAR, if appropriate, have been approved during the review process. See document case file for the record of changes. Approver certifies representation: approve the scope and content of document is ready as a pending document.					
K. E. Stinger		Signature for K. E. Stinger PKC		11-26-02	
Document Owner Printed Name		Document Owner Signature		Date	
19. Drawing Checker Approval & Date: N/A		20. Document Control Release & Date: <i>EMD</i> <i>11-26-02</i>		21. Document Control Location: TAN-517 <i>EMD</i>	
22. Comments:		23. New Revision ID: 0			

416.19  
02/16/2000  
Rev. 03

## INSPECTION INSTRUCTION FORM

*RED ORIGINAL Black Copy - Surreceps INTEC-QA-0221, 1/22/03 - Inspection Record Copy*

Inspection Type:	Construction <input type="checkbox"/>	Operations <input checked="" type="checkbox"/>	Receiving <input type="checkbox"/>	Source <input type="checkbox"/>	Requisition No.: N/A
Title/Description/Item: Quality Inspection Plan for TRUPACT-157 Payload Disassembly Operations At Test Area North (TAN)					
Spec. No.: N/A	Rev.: N/A	Dwg. No.: As referenced in TPR-6233	Rev.: N/A		
Insp. Plan No.: INTEC-QA-0221	ID No. (Work Order/Project/Purchase Order etc.): TPR-6233, Rev. 1	Quality Level: SC/QL-1			
Inspection Planner: <i>Alan Huot/Jim Rider</i>	Date: 02/01/03	Requesting Organization Review (Optional): telecon			
		Kraig Wendt per		Date: 02/01/03	

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	<p>This inspection plan (IP) is written for Quality Inspection of payload disassembly/examination operations for the Transuranic (TRU) Package Transporter (TRUPACT)-II, Serial Number 157 recovery and subsequent loading of the waste barrels into Standard Waste Boxes (SWBs). This activity includes removal of the Inner Containment Vessel (ICV) from the Outer Containment Assembly/Vessel (OCA/V) at the Test Area North (TAN) Hot Shop.</p> <p><b>PREREQUISITES:</b></p> <p>Quality Inspector(s) (QI) shall be certified as a General Level II QI per the requirements of MCP-535 and RWMC TRUPACT-II certified.</p> <p><b>GENERAL INSTRUCTIONS:</b></p> <ol style="list-style-type: none"> <li>Applicable figures, if any, for this scope of work, are located in the associated Technical Procedure (TPR).</li> <li>Immediately notify the JS or SS if any anomalies are identified. Notify the Shift Lead QE/QA Technical Lead if issues are not resolved by the JS or SS. Record notification information on this form. <b>Note: Work will be evaluated per MCP-553 until issues are satisfactorily resolved.</b></li> <li>When specific steps of TPR-6233 are not performed because the applicable portion of the TPR is not required to be performed, the corresponding step on this form must be Marked "N/A" and initialed and dated by the QI.</li> <li>Indicate inspection status on all inspection steps/items in the Inspection Status column of this Inspection Plan (IP) with the following nomenclature: "sat" or "unsat"/"acceptable" or "unacceptable". QI add your initials, inspection date.</li> <li>Any unacceptable inspection results shall be documented on a Quality Inspection Report, form # 414.03 with reference back to the associated with the step and/or item. Attach any generated inspection reports to this IP.</li> <li>Record all NCR's issued in the "M&amp;TE/Notes" column for the associated IP item. The NCR should reference back to the associated TPR step. Ensure any such NCR is also recorded in TPR-6233, Appendix B.</li> <li>Attach all inspection reports to this IP documenting work covered.</li> </ol>	N/A	N/A

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
8.	Ensure all unacceptable inspection results are noted in the TPR comments, Appendix B.		
9.	Ensure suspect counterfeit items covered by MCP-9110 are not used in the process of this IP.		
10.	QI shall verify that all inspections are performed to the latest figure/drawing revisions, when referenced.		
11.	QI shall sign/initial both the appropriate TPR-6233 Steps and this Inspection Instruction Form: For TPR steps requiring multiple item inspection – sign the IP item after all the individual inspections are completed in the referenced TPR step.		
1.0	Verify that the current revision of TPR-6233 is in use.	Use of TPR-6233, Rev 1, verified in 01/22/03 rev of IP.	
2.0	Verify that the SWBs staged for use at TAN are green tagged "QL-1" and SWB S/Ns match those listed in Packaging and Transportation (P&T) evaluation letter no. JLN-03-03.  Record the SWB Serial numbers verified. (N/A any unused data blocks)  SWB S/N: _____  SWB S/N: _____  (Step 3.4.3.1)	Verified in 01/22/03 revision of this IP.	
3.0	Accompany/observe the SO perform an inspection of SWB boxes and lids before loading. Inspect for damage.  Acceptance Criteria: No bulges, dents, or deterioration that would affect the integrity of the container.  <b>Note:</b> Take appropriate action per the <b>GENERAL INSTRUCTIONS</b> of this IP if damage in excess of that allowed is identified.  (Step 4.3.6)	Verified in 01/22/03 revision of this IP.	
4.0	Record, in TPR-6233, torque wrench serial number(s) and calibration due date(s) for wrench to be used on SWB filters (Minimum 2, Maximum 4 each) and any plugs installed in unused filter ports. <ul style="list-style-type: none"> <li>Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6233.)</li> <li>Verify calibration is current.</li> </ul> (Step 4.3.8)	Verified in 01/22/03 revision of this IP.	

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
5.0	<p>Verify SWB filters are installed. Verify pipe plugs are installed in any remaining open filter mount locations.</p> <p>Verify that installed filters are green tagged QL-2 (safety significant, SS) and listed by filter S/N in EDF-3435 (EDF upgraded these filters to QL-2 for use under Transport Plan PLN-1165).</p> <p>Record S/N of filters installed on each SWB. (N/A any unused data blocks)</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p> <p>SWB S/N: _____</p> <p>Filter S/N: _____</p>	<p>Verified in 01/22/03 revision of this IP.</p>	



# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	<p>Verify appropriate range of wrench is used for torque (Reference Table 3.3 of TPR-6233.).</p> <p>Verify torque value of 120 to 180 <u>in.-lbs.</u> OR 10 to 15 <u>ft.-lbs.</u> each.</p> <p>(Step 4.3.9.1)</p>		
6.0	<p>Inspect SWB body sealing surface and adhesive side of gasket.</p> <p><b>Acceptance criteria:</b></p> <p>Gasket is free of rips, gouges or tears.</p> <p>SWB body sealing surface is free of damage, foreign particles or other contaminants that would inhibit sealing.</p> <p>(Step 4.3.11)</p>	<p>Verified in 01/22/03 revision of this IP.</p>	
7.0	<p>Inspect SWB threaded rivets for damaged threads, loose fit, etc.</p> <p><b>Acceptance criteria:</b></p> <p>Rivet will be tight (does not rotate) when checked by hand.</p> <p>rivet shall be undamaged -visually free of thread deformation, burrs, cross thread, cracks, etc.</p> <p>Note: If a rivet has minor thread deformation (burrs, cross thread, etc.) the user is permitted to correct the thread deformation by running a 1/2 in. 13 UNC thread tap through the rivet. If a tap is used, reinspect to original criteria.</p> <p>(Step 4.3.12)</p>	<p>Verified in 01/22/03 revision of this IP.</p>	
8.0	<p>Inspect SWB lid sealing surfaces, installed gasket condition, and ensure that the gasket is properly installed for each SWB.</p> <p><b>Acceptance criteria:</b></p> <ol style="list-style-type: none"> <li>1. Sealing surface is free of damage, foreign particles or other contaminants that would inhibit sealing.</li> <li>2. The four gasket parts are installed with mitered gasket ends interlocking without an overlap.</li> <li>3. Holes in gasket align with bolt-holes in body of SWB.</li> <li>4. Gasket is free of damage, foreign particles or other contaminants that would inhibit sealing.</li> </ol> <p>(Step 4.3.14)</p>	<p>Verified in 01/22/03 revision of this IP.</p>	
9.0	<p>Observe loading of the upper payload drums into their respective SWBs and perform the following:</p> <ol style="list-style-type: none"> <li>1. Verify that drum placement entries on the Manual Drum Tracking Form (See Appendix C, Manual Drum Tracking form of the TPR) for drums relocated from the upper payload position are in compliance with the SWB shipping document supplied by the Carlsbad Field Office (CBFO).</li> </ol>	<p>Verified in 01/22/03 revision of this IP.</p>	

21

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	<p>2. Verify that the final location of each drum in the SWB is in compliance with the above entries on the Manual Drum Tracking Form.</p> <p>3. Initial the Manual Drum tracking Form as each drum is loaded into the respective SWB and sign the bottom of the form at completion of the loading activity.</p> <p>4. Sign the TPR referenced step when all drums from the upper payload position are loaded into their SWBs and the Manual Drum Tracking Form(s) are signed off by the QI verifying the loaded position.</p> <p>5. Sign this IP item when upper payload layer drum placement signoffs are completed in the TPR.</p> <p>(Step 4.4.16)</p> <p>Observe loading of the lower payload drums into their respective SWBs and perform the following:</p> <ol style="list-style-type: none"> <li>1. Verify that drum placement entries on the Manual Drum Tracking Form (See Appendix C, Manual Drum Tracking form of the TPR) for drums relocated from the lower payload position are in compliance with the SWB shipping document supplied by the Carlsbad Field Office (CBFO).</li> <li>2. Verify that the final location of each drum in the SWB is in compliance with the above entries on the Manual Drum Tracking Form.</li> <li>3. Initial the Manual Drum tracking Form as each drum is loaded into the respective SWB and sign the bottom of the form at completion of the loading activity.</li> <li>4. Sign the TPR referenced step when all drums from the lower payload position are loaded into their SWBs and the Manual Drum Tracking Form(s) are signed off by the QI verifying the loaded position.</li> <li>5. Sign this IP item when lower payload layer drum placement signoffs are completed in the TPR.</li> </ol> <p>(Step 4.4.29)</p>	<p>Verified in 01/22/03 revision of this IP.</p>	
10.0 C-156			
11.0	<p>Verify that bagged payload drums in the SWB have a 2" minimum vent hole cut.</p> <p>(Step 4.5.5.4)</p>	N/A	N/A RCS 2-303
12.0	<p>Record torque wrench serial number(s) and calibration due date(s) (for use on SWB lid screws) in TPR-6233.</p> <ul style="list-style-type: none"> <li>• Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6233.)</li> <li>• Verify calibration is current.</li> </ul> <p>(Step 4.5.5.7)</p>	<p>Verified in 01/22/03 revision of this IP.</p>	

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
13.0	<p>Verify appropriate range of wrench issued for torque of SWB lid screws (Reference Table 3.3 of TPR-6233.).</p> <p>Verify final torque values of 600 to 720 in.-lbs. OR 50 to 60 ft.-lbs. In the template sequence.</p> <p>(Step 4.5.5.11.1)</p>	<p>SIC-NEED OWN (VERIFIED) 1/22/03 REV. OF THIS IP. JAN 22/03 2/2/03</p>	<p>SAT RCS 2-3-03</p>
14.0	<p>Verify that the SWBs staged for use at TAN are green tagged "QL-1" and SWB S/Ns match those listed in Packaging and Transportation (P&amp;T) evaluation Letter No. J1H-03-03.</p> <p>Record the SWB Serial number verified. SWB S/N: <u>010248</u></p> <p>(Step 4.7.1.1)</p>	<p>2/3/03</p>	<p>SAT RCS 2-3-03</p>
15.0	<p>Accompany/observe the SO perform an inspection of SWB box and lid before loading. Inspect for damage.</p> <p>Acceptance Criteria: No bulges, dents, or deterioration that would affect the integrity of the container.</p> <p>Note: Take appropriate action per the <b>GENERAL INSTRUCTIONS</b> of this IP if damage in excess of that allowed is identified.</p> <p>(Step 4.7.7)</p>		<p>SAT RCS 2-3-03</p>
16.0	<p>Record, in TPR-6233, torque wrench serial number(s) and calibration due date(s) for wrench to be used on SWB filters (Minimum 2, Maximum 4 each) and any plugs installed in unused filter ports.</p> <ul style="list-style-type: none"> <li>Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6233.)</li> <li>Verify calibration is current.</li> </ul> <p>(Step 4.7.9)</p>		<p>SAT RCS 2-3-03</p>
17.0	<p>Verify SWB filters are installed. Verify pipe plugs are installed in any remaining open filter mount locations.</p> <p>Verify that installed filters are green tagged QL-2 (safety significant, SS) and listed by filter S/N in EDF-3435 (EDF upgraded these filters to QL-2 for use under Transport Plan PLN-1165).</p> <ul style="list-style-type: none"> <li>Record S/N of filters installed on each SWB. SWB S/N: <u>010248</u></li> <li>Filter S/N: <u>NFT-LH-6507</u>, <u>NFT-LH-6509</u>, <u>N/A</u></li> <li>Verify appropriate range of wrench is used for torque (Reference Table 3.3 of TPR-6233.).</li> <li>Verify torque value of 120 to 180 in.-lbs. OR 10 to 15 ft.-lbs. each.</li> </ul> <p>(Step 4.7.10.1)</p>		<p>SAT RCS 2-3-03</p>

83

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
18.0	<p>Inspect SWB body sealing surface and adhesive side of gasket.</p> <p><b>Acceptance criteria:</b> Gasket is free of rips, gouges or tears. SWB body sealing surface is free of damage, foreign particles or other contaminants that would inhibit sealing.</p> <p>(Step 4.7.12)</p>		<p>SAT RCS 2-3-03</p>
19.0	<p>Inspect SWB threaded rivets for damaged threads, loose fit, etc.</p> <p><b>Acceptance criteria:</b> Rivets will be tight (does not rotate) when checked by hand. Rivets shall be undamaged -visually free of thread deformation, burrs, cross thread, cracks, etc.</p> <p>Note: If a rivet has minor thread deformation (burrs, cross thread, etc.) the user is permitted to correct the thread deformation by running a 1/2 in. 13 UNC thread tap through the rivet. If a tap is used, re-inspect to original criteria.</p> <p>(Step 4.7.13)</p>		<p>SAT RCS 2-3-03</p>
20.0	<p>Inspect SWB lid sealing surfaces, installed gasket condition, and ensure that the gasket is properly installed for each SWB.</p> <p><b>Acceptance criteria:</b></p> <ul style="list-style-type: none"> <li>Sealing surface is free of damage, foreign particles or other contaminants that would inhibit sealing.</li> <li>The four gasket parts are installed with mitered gasket ends interlocking without an overlap.</li> <li>Holes in gasket align with bolt-holes in body of SWB.</li> <li>Gasket is free of damage, foreign particles or other contaminants that would inhibit sealing.</li> </ul> <p>(Step 4.7.14)</p>		<p>SAT RCS 2-3-03</p>
21.0	<p>Observe loading of the drum removed from the SWB for relocation into another SWBs and perform the following:</p> <ul style="list-style-type: none"> <li>Verify that drum placement entries on the Manual Drum Tracking Form (See Appendix C, Manual Drum Tracking form of the TPR) for relocated drum for compliance with the Loading Plan or the shipping document supplied by the Carlsbad Field Office (CBFO).</li> <li>Verify that the final location of the drum(s) in the SWB is in compliance with the above entries on the Manual Drum Tracking Form.</li> <li>Initial the Manual Drum tracking Form when the drum(s) is loaded into the respective SWB and sign the bottom of the form at completion of the loading activity.</li> <li>Sign the TPR referenced step when the relocated drum(s) is loaded into their SWBs and the Manual Drum Tracking Form(s) are signed off by the QI verifying the loaded position.</li> <li>Sign this IP item when relocated drum placement signoff(s) is completed in the TPR.</li> </ul> <p>(Step 4.7.21)</p>		<p>SAT RCS 2-3-03</p>

29.

# INSPECTION INSTRUCTION FORM

[illegible]

416.19  
02/16/2000  
Rev. 03

# INSPECTION INSTRUCTION FORM

*Red Original/Black Copy Inspection Record Copy*

Inspection Type: Construction <input type="checkbox"/> Operations <input checked="" type="checkbox"/> Receiving <input type="checkbox"/> Source <input type="checkbox"/>	Requisition No.: N/A
Title/Description/Item: Quality Inspection Plan for TRUPACT-157 Payload Disassembly Operations At Test Area North (TAN)	
Spec. No.: N/A	Dwg. No.: As referenced in TPR-6233 Rev.: N/A
Insp. Plan No.: INTEC-QA-0221	ID No. (Work Order/Project/Purchase Order etc.): TPR-6233, Rev. 1
Inspection Planner: <i>Alan Huot/Jim Rider</i>	Date: 01/22/03
Requesting Organization Review (Optional): Kraig Wendt per e-mail	
Date: 01/22/03	
Quality Level: SC/QL-1	

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	<p>This inspection plan (IP) is written for Quality Inspection of payload disassembly/examination operations for the Transuranic (TRU) Package Transporter (TRUPACT)-II, Serial Number 157 recovery and subsequent loading of the waste barrels into Standard Waste Boxes (SWB)s. This activity includes removal of the Inner Containment Vessel (ICV) from the Outer Containment Assembly/Vessel (OCA/V) at the Test Area North (TAN) Hot Shop.</p> <p><b>PREREQUISITES:</b></p> <p>Quality Inspector(s) (QI) shall be certified as a General Level II QI per the requirements of MCP-535 and RWMC TRUPACT-II certified.</p> <p><b>GENERAL INSTRUCTIONS:</b></p> <ol style="list-style-type: none"> <li>1. Applicable figures, if any, for this scope of work, are located in the associated Technical Procedure (TPR).</li> <li>2. Immediately notify the JS or SS if any anomalies are identified. Notify the Shift Lead QE/QA Technical Lead if issues are not resolved by the JS or SS. Record notification information on this form. <b>Note: Work will be evaluated per MCP-553 until issues are satisfactorily resolved.</b></li> <li>3. When specific steps of TPR-6233 are not performed because the applicable portion of the TPR is not required to be performed, the corresponding step on this form must be Marked "N/A" and initialed and dated by the QI.</li> <li>4. Indicate inspection status on all inspection steps/items in the Inspection Status column of this Inspection Plan (IP) with the following nomenclature: "sat" or "unsat"/"acceptable" or "unacceptable". QI add your initials, inspection date.</li> <li>5. Any unacceptable inspection results shall be documented on a Quality Inspection Report, form # 414.03 with reference back to the associated with the step and/or item. Attach any generated inspection reports to this IP.</li> <li>6. Record all NCR's issued in the "M&amp;TE/Notes" column for the associated IP item. The NCR should reference back to the associated TPR step. Ensure any such NCR is also recorded in TPR-6233, Appendix B.</li> <li>7. Attach all inspection reports to this IP documenting work covered.</li> <li>8. Ensure all unacceptable inspection results are noted in the TPR comments, Appendix B.</li> </ol>	N/A	N/A

86

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	<p>9. Ensure suspect counterfeit items covered by MCP-9110 are not used in the process of this IP.</p> <p>10. QI shall verify that all inspections are performed to the latest figure/drawing revisions, when referenced.</p> <p>11. QI shall sign/initial both the appropriate TPR-6233 Steps and this Inspection Instruction Form. For TPR steps requiring multiple item inspection – sign the IP item after all the individual inspections are completed in the referenced TPR step.</p>		
1.0	Verify that the current revision of TPR-6233 is in use.		SAT RCS 1-28-03
2.0	<p>Verify that the SWBs staged for use at TAN are green tagged "QL-1" and SWB S/Ns match those listed in Packaging and Transportation (P&amp;T) evaluation letter no. JLH-03-03.</p> <p>Record the SWB Serial numbers verified. (N/A any unused data blocks)</p> <p>SWB SN: <u>010263 010231 010259 010227</u></p> <p>SWB SN: <u>010288 010282 N/A N/A</u></p> <p>(Step 3.4.3.1)</p>		SAT RCS 1-28-03
3.0	<p>Accompany/observe the SO perform an inspection of SWB boxes and lids before loading. Inspect for damage.</p> <p>Acceptance Criteria: No bulges, dents, or deterioration that would affect the integrity of the container.</p> <p>Note: Take appropriate action per the <b>GENERAL INSTRUCTIONS</b> of this IP if damage in excess of that allowed is identified.</p> <p>(Step 4.3.6)</p>		SAT RCS 1-29-03
4.0	<p>Record, in TPR-6233, torque wrench serial number(s) and calibration due date(s) for wrench to be used on SWB filters (Minimum 2, Maximum 4 each) and any plugs installed in unused filter ports.</p> <ul style="list-style-type: none"> <li>Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6233.)</li> <li>Verify calibration is current.</li> </ul> <p>(Step 4.3.8)</p>		SAT RCS 1-29-03

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
5.0	<p>Verify SWB filters are installed. Verify pipe plugs are installed in any remaining open filter mount locations.</p> <p>Verify that installed filters are green tagged QL-2 (safety significant, SS) and listed by filter S/N in EDF-3435 (EDF upgraded these filters to QL-2 for use under Transport Plan PLN-1165).</p> <p>Record S/N of filters installed on each SWB. (N/A any unused data blocks)</p> <p>SWB S/N: <u>0102282</u></p> <p>Filter S/N: <u>NFT-LH-6501, NFT-LH-6505, NFT-LH-6529, NFT-LH-6530</u></p> <p>SWB S/N: <u>0102259</u></p> <p>Filter S/N: <u>NFT-LH-6540, NFT-LH-6394, NFT-LH-6535, NFT-LH-6314</u></p> <p>SWB S/N: <u>0102221</u></p> <p>Filter S/N: <u>NFT-LH-6534, NFT-LH-6539, NFT-LH-6528, NFT-LH-6527</u></p> <p>SWB S/N: <u>0102227</u></p> <p>Filter S/N: <u>NFT-LH-6320, NFT-LH-6318, NFT-LH-6392, NFT-LH-6538</u></p> <p>SWB S/N: <u>0102288</u></p> <p>Filter S/N: <u>NFT-LH-6502, NFT-LH-6510, NFT-LH-6506, NFT-LH-6504</u></p> <p>SWB S/N: <u>0102263</u></p> <p>Filter S/N: <u>NFT-LH-6512, NFT-LH-6615, NFT-LH-6620, NFT-LH-6605</u></p> <p>SWB S/N: <u>N/A</u></p> <p>Filter S/N: <u>N/A</u></p> <p>SWB S/N: <u>N/A</u></p> <p>Filter S/N: <u>N/A</u></p>		<p>SAT RJS 1-27-03</p>



# INSPECTION INSTRUCTION FORM



No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	Verify appropriate range of wrench is used for torque (Reference Table 3.3 of TPR-62333.) Verify torque value of 120 to 180 in.-lbs. OR 10 to 15 ft.-lbs. each. (Step 4.3.9.1)		RCJ 1-29-03
6.0	Inspect SWB body sealing surface and adhesive side of gasket.  <b>Acceptance criteria:</b> Gasket is free of rips, gouges or tears. SWB body sealing surface is free of damage, foreign particles or other contaminants that would inhibit sealing. (Step 4.3.11)	Step repeated To replace damaged gasket sections on SWB 010259 and 010288 RCJ 1-31-03	RCJ 1-29-03
7.0	Inspect SWB threaded rivets for damaged threads, loose fit, etc.  <b>Acceptance criteria:</b> Rivet will be tight (does not rotate) when checked by hand. rivet shall be undamaged -visually free of thread deformation, burrs, cross thread, cracks, etc.  Note: If a rivet has minor thread deformation (burrs, cross thread, etc.) the user is permitted to correct the thread deformation by running a 1/2 in. 13 UNC thread tap through the rivet. If a tap is used, reinspect to original criteria. (Step 4.3.12)		RCJ 1-29-03
8.0	Inspect SWB lid sealing surfaces, installed gasket condition, and ensure that the gasket is properly installed for each SWB.  <b>Acceptance criteria:</b> 1. Sealing surface is free of damage, foreign particles or other contaminants that would inhibit sealing. 2. The four gasket parts are installed with mitered gasket ends interlocking without an overlap. 3. Holes in gasket align with bolt-holes in body of SWB. 4. Gasket is free of damage, foreign particles or other contaminants that would inhibit sealing. (Step 4.3.14)	Step repeated To replace damaged gasket sections on SWB 010259 and 010288 RCJ 1-31-03	RCJ 1-29-03
9.0	Observe loading of the upper payload drums into their respective SWBs and perform the following:  1. Verify that drum placement entries on the Manual Drum Tracking Form (See Appendix C, Manual Drum Tracking form of the TPR) for drums relocated from the upper payload position are in compliance with the SWB shipping document supplied by the Carlsbad Field Office (CBFO).		RCJ SET 1-30-03

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
	<p>2. Verify that the final location of each drum in the SWB is in compliance with the above entries on the Manual Drum Tracking Form.</p> <p>3. Initial the Manual Drum tracking Form as each drum is loaded into the respective SWB and sign the bottom of the form at completion of the loading activity.</p> <p>4. Sign the TPR referenced step when all drums from the upper payload position are loaded into their SWBs and the Manual Drum Tracking Form(s) are signed off by the QI verifying the loaded position.</p> <p>5. Sign this IP item when upper payload layer drum placement signoffs are completed in the TPR.</p> <p>(Step 4.4.16)</p>		<p>Set RCS 1-30-03</p>
10.0	<p>Observe loading of the lower payload drums into their respective SWBs and perform the following:</p> <ol style="list-style-type: none"> <li>1. Verify that drum placement entries on the Manual Drum Tracking Form (See Appendix C, Manual Drum Tracking form of the TPR) for drums relocated from the lower payload position are in compliance with the SWB shipping document supplied by the Carlsbad Field Office (CBFO).</li> <li>2. Verify that the final location of each drum in the SWB is in compliance with the above entries on the Manual Drum Tracking Form.</li> <li>3. Initial the Manual Drum tracking Form as each drum is loaded into the respective SWB and sign the bottom of the form at completion of the loading activity.</li> <li>4. Sign the TPR referenced step when all drums from the lower payload position are loaded into their SWBs and the Manual Drum Tracking Form(s) are signed off by the QI verifying the loaded position.</li> <li>5. Sign this IP item when lower payload layer drum placement signoffs are completed in the TPR.</li> </ol> <p>(Step 4.4.29)</p>		<p>Set RCS 1-30-03</p>
11.0	<p>Verify that bagged payload drums in the SWB have a 2" minimum vent hole cut.</p> <p>(Step 4.5.5.4)</p>	N/A	<p>RCS 2-3-03</p>
12.0	<p>Record torque wrench serial number(s) and calibration due date(s) (for use on SWB lid screws) in TPR-6233.</p> <ul style="list-style-type: none"> <li>• Verify that torque wrench is within range for the intended use. (Reference Table 3.3 of TPR-6233.)</li> <li>• Verify calibration is current.</li> </ul> <p>(Step 4.5.5.7)</p>		<p>Set RCS 1-31-03</p>

# INSPECTION INSTRUCTION FORM

No.	Inspection Instruction & Acceptance Criteria	M&TE/Notes	Inspection Status/ Inspector & Date
13.0	Verify appropriate range of wrench issued for torque of SWB lid screws (Reference Table 3.3 of TPR-6233.).  Verify final torque values of 600 to 720 in.-lbs. OR 50 to 60 ft.-lbs. in the template sequence. (Step 4.5.5.11.1)	*	
14.0	QE complete Quality Inspection Plan and TPR documentation reviews required by Section 4.6 of the TPR. (Section 4.6)		SAT Jkluh 2/3/03
OPTIONAL/ADDITIONAL COMMENTS:			
* Verified Torque wrench and Final Torque of 5 SWB's. See step 4.5.5.11.1 FTS 1-31-03			
* Verified Torque wrench and Final Torque of 674 SWB, SAT FTS 2-3-03			
Final Inspection Documentation Review:		Date:	
Jkluh		2/3/03	

1. Title: Upgrade Bung Filter Quality Level for Transport Plan PLN-1165																																		
2. Project File No.: 23235																																		
3. Index Codes:																																		
Building/Type _____	SSC ID <u>NFT-013 Bung Filter</u>	Site Area <u>TAN</u>																																
<p>4. Summary:</p> <p>This Engineering Design File justifies upgrading the following Bung Filters (NFT-013) purchased in 1996 with Requisition # 15828 on Purchase Order C96-180477 from Quality Level 3 to Quality Level 2. This upgrade is required to comply with Transport Plan, PLN-1165 Rev 0 Sec 6.5.2 requiring the filters to be safety significant. The serial numbers of the filters to be upgraded are listed in the following table.</p> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td>NFT-LH-6314</td><td>NFT-LH-6394</td><td>NFT-LH-6506</td><td>NFT-LH-6512</td><td>NFT-LH-6533</td><td>NFT-LH-6540</td></tr> <tr> <td>NFT-LH-6318</td><td>NFT-LH-6501</td><td>NFT-LH-6507</td><td>NFT-LH-6527</td><td>NFT-LH-6534</td><td>NFT-LH-6605</td></tr> <tr> <td>NFT-LH-6320</td><td>NFT-LH-6502</td><td>NFT-LH-6509</td><td>NFT-LH-6528</td><td>NFT-LH-6535</td><td>NFT-LH-6610</td></tr> <tr> <td>NFT-LH-6321</td><td>NFT-LH-6504</td><td>NFT-LH-6510</td><td>NFT-LH-6529</td><td>NFT-LH-6538</td><td>NFT-LH-6615</td></tr> <tr> <td>NFT-LH-6392</td><td>NFT-LH-6505</td><td>NFT-LH-6511</td><td>NFT-LH-6530</td><td>NFT-LH-6539</td><td>NFT-LH-6620</td></tr> </table> <p>Based on the information developed in this EDF, the Bung Filters procured from Nuclear Filter Technology, Inc (NFT) are consistent and acceptable with all the requirements set up by WIPP and incorporated into Specification ES-51589, Revision 1, Bung Style Drum Vent Filters. The filters were procured as Quality Level 2, receipt inspected, accepted and assigned QA Number 96A1665. Subsequently, the filters were tested at NFT under a Quality Level (QL) 3 procurement action. They were again processed through receipt inspection, accepted, and assigned QA No. 91012, and tagged as QL-3. The material, dimensions and performance of the filters have not changed (no modifications have been made). The testing was done using an approved procedure and meets the requirements identified in the Specification ES-51589 Rev 1. Based on this, the filters can be upgraded to QL-2.</p>					NFT-LH-6314	NFT-LH-6394	NFT-LH-6506	NFT-LH-6512	NFT-LH-6533	NFT-LH-6540	NFT-LH-6318	NFT-LH-6501	NFT-LH-6507	NFT-LH-6527	NFT-LH-6534	NFT-LH-6605	NFT-LH-6320	NFT-LH-6502	NFT-LH-6509	NFT-LH-6528	NFT-LH-6535	NFT-LH-6610	NFT-LH-6321	NFT-LH-6504	NFT-LH-6510	NFT-LH-6529	NFT-LH-6538	NFT-LH-6615	NFT-LH-6392	NFT-LH-6505	NFT-LH-6511	NFT-LH-6530	NFT-LH-6539	NFT-LH-6620
NFT-LH-6314	NFT-LH-6394	NFT-LH-6506	NFT-LH-6512	NFT-LH-6533	NFT-LH-6540																													
NFT-LH-6318	NFT-LH-6501	NFT-LH-6507	NFT-LH-6527	NFT-LH-6534	NFT-LH-6605																													
NFT-LH-6320	NFT-LH-6502	NFT-LH-6509	NFT-LH-6528	NFT-LH-6535	NFT-LH-6610																													
NFT-LH-6321	NFT-LH-6504	NFT-LH-6510	NFT-LH-6529	NFT-LH-6538	NFT-LH-6615																													
NFT-LH-6392	NFT-LH-6505	NFT-LH-6511	NFT-LH-6530	NFT-LH-6539	NFT-LH-6620																													
5. Review (R) and Approval (A) and Acceptance (Ac) Signatures: (See instructions for definitions of terms and significance of signatures.)																																		
	R/A	Typed Name/Organization	Signature	Date																														
Author		Larry C Lewis		1/22/03																														
Checker	R	Charley Posegate		1/22/03																														
Independent Peer Reviewer	A	Kraig Wendt	Kraig Wendt per Telecon By Larry C Lewis	1/22/03																														
Doc Owner	A	Tom Clements	Tom Clements per Telecon By Larry C Lewis	1/22/03																														

ENGINEERING DESIGN FILE

Requestor	Ac	James Rider	<i>JK Rider</i>	<i>1/22/03</i>
SQAO	A	Alan Hout	<i>JK Rider for A.J. Hout Per Wilson</i>	<i>1/22/03</i>
Engineering Manager	A	W. E. Landon	<i>W.E. LANDIN per Telecon By Larry Lewis</i>	<i>1/24/03</i>
6. Distribution: (Name and Mail Stop)		Clements T. L. 2510; WALE D. A. 9206; Rider J. K. 5306; Project File		
7. Does document contain sensitive unclassified information? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No  If Yes, what category:				
8. Can document be externally distributed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				
9. Uniform File Code: _____ Disposition Authority: _____  Record Retention Period: _____				
10. For QA Records Classification Only: <input checked="" type="checkbox"/> Lifetime <input type="checkbox"/> Nonpermanent <input type="checkbox"/> Permanent  Item and activity to which the QA Record apply: _____				
11. NRC related? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
12. Registered Professional Engineer's Stamp (if required)  <i>No.</i>				

## MAIN BODY

### History

These Bung filters were procured from Nuclear Filter Technology, Inc. (NFT) in 1996 under Purchase Order (PO)# C96-180477. The filters were purchased to Quality Level (QL) 2 requirements to the Idaho National Engineering and Environmental Laboratory (INEEL) engineering Specification ES-51589, Rev. 0. Documentation was provided with the filters verifying compliance with the requirements in the specification that included a Certificate of Compliance certifying the type of material the filter, filter lid and gasket were made of and the testing performed on the filters. The filters were procured as Quality Level 2, receipt inspected, accepted and assigned Quality Assurance (QA) No. 96A1665.

In March of 2002, the filters were sent to NFT to verify that the filters were in compliance with INEEL Specification ES-51589, Rev. 1 using PO 6314. The testing was done at NFT's facility in Denver. They were again processed through receipt inspection, accepted, and assigned QA No. 91012, and tagged as QL-3.

### Discussion

Flow and efficiency testing was done at NFT using an approved test method. That method was approved by Bechtel BWXT Idaho, LLC, (BBWI) through several onsite observations by INEEL personnel during the testing. Acceptance criteria for the performance testing are listed in Appendix 2.5, Specification for Filter Vents for the TRAMPAC and are identified in INEEL Specification for Bung Filters ES-51589, Rev. 2. - Only filters passing the performance testing criteria were sent back to INEEL in March, 2002.

Performance requirements for the Bung Filters in Specification ES-51589, Rev. 1 are the same as identified in ES-51589, Rev. 0. Material requirements have not changed and are the same for all revisions of the INEEL Specification. The only difference between Rev. 1 and the current revision, Rev. 2 is on page 3 of 9, the second sentence which was changed to allow the use of a hexagonal shaped filter head, and a sentence was added to the Performance Requirements identifying what documents drive the requirements.

The maximum envelope dimensions have not changed in the revisions of the specifications.

Documentation provided with the original procurement (PO # C-96-180477) and required by INEEL Specification ES-51589, Rev. 0 is the same as required by Rev. 1 of the specification. This documentation is included with the receiving inspection report and is attached to this EDF. 100 % performance testing was done by NFT in 1996 and those results are included in the receiving documentation. At the time this was done, there were some questions concerning the flow testing performed by NFT. This required sending the filters back to NFT in March, 2002 and having them retested. The other remaining documentation met the requirements of the specification and was accepted by INEEL.

The Bung Filters received in 1996 were sent back for retesting in March, 2002 under PO 6314. The retesting was done under INEEL Specification ES-51589, Rev. 1. As discussed earlier, there are no technical changes between Rev. 0 and Rev. 1 of the specification. The receiving inspection instructions for the tested filters require that test results be verified/included with tested filters, absent of shipping damage; and the quantity and serial numbers of filters checked. Documentation included with the filters is attached and includes the flow testing performed by NFT along with an interface document, ID-1, waiving source inspection by "over check" of performance testing of the NFT-013 bung filters. Any filter that was damaged or incomplete was "scrapped" and not included with the approved filters. The approved filters were given a QL 3 green tag with QA No. 91012.

Based on the above discussion, noting no differences in the Specifications, and that retesting has added additional insurance that the filters meet the flow requirements, the identified filters can be upgraded from QL-3 to QL-2 filters, and the Green tag changed accordingly.

431.02  
02/26/2002  
Rev. 10

## ENGINEERING DESIGN FILE

EDF- 3435  
Rev. No. 0  
Page 4 of 4

### APPENDICES

**Receiving Inspection Information for P.O. C-96-180477**

**Receiving Inspection Information for P.O. 6314**

Idaho National Engineering and Environmental Laboratory



## INTEROFFICE MEMORANDUM

**Date:** January 20, 2003

**To:** A. J. Huot MS 3730 6-3569

**From:** J. L. Hansen MS 4105 6-8721

**Subject:** STANDARD WASTE BOX SAFETY CLASS EVALUATION, REVISION 1

The eight (8) TRUPACT-II Standard Waste Boxes (SWBs), listed below by their manufacturer's serial number, were purchased from Westinghouse TRU Solutions LLC, under BBWI Purchase Order # 00004539, as procurement Quality Level (QL) 3 items. These SWBs will be used to over-pack fourteen (14), 55-gallon drums of contact-handled transuranic (CH-TRU) waste for transport between the INEEL's Test Area North (TAN) Building 607, the Radioactive Waste Management Complex (RWMC), and the Waste Isolation Pilot Plant (WIPP). These drums that are to be overpacked in SWBs are from the INEEL's TRUPACT-II, certified Shipment No. IN020271, that was sent to the WIPP from RWMC and was involved in a vehicular mishap just outside of Carlsbad, New Mexico.

Transfer of the CH-TRU mixed waste drums within the INEEL's, TAN, and RWMC boundaries is neither regulated by the U.S. Department of Transportation nor licensed by the U.S. Nuclear Regulatory Commission. To ensure equivalent safety, the transport will be performed under INEEL Transport Plan 1165. A thorough hazard and accident analysis was performed per DOE-STD-1027-92, DOE-STD-3009-94, and 10 CFR 830, Subpart B requirements and guidelines. As a result of that hazard and accident analysis documented in Section 6.3 of Transport Plan (PLN-1165), the SWBs are considered *Safety Class* Structures, Systems, and Components (SSCs) per INEEL Management Control Procedure (MCP)-540, Rev. 13, *Documenting the Safety Category of Structures, Systems, and Components*. This Interoffice Memorandum documents the evaluation of previously procured SWBs for use during transport under PLN-1165.

As *Safety Class* SSCs, the SWBs would normally have been procured as Quality Level 1 items according to MCP-540, MCP-T185, and PLN-120 engineering and quality requirements. Because the SWBs were procured as QL 3 items under the original purchase order, an evaluation was conducted to ensure that adequate documentation and certification justify use of the SWBs in the *Safety Class* SSC application.

A graded approach is applied to all INEEL SSCs according to MCP-540 to determine a SSC's safety category. QLs are applied to each of the safety categories for procurement purposes in MCP-1185. The difference between the procurement of a QL 1 and a QL 3 hazardous material packaging is the documentation that ensures traceability to a specific specification or drawing, and the appropriate packaging test documentation required by the 49 CFR Hazardous Material Regulations. The evaluation of the SWBs *safety class* safety category was based on the procurement documentation to ensure traceability to specific design specifications and drawings, and documentation of required testing.

The SWBs were purchased by Westinghouse TRU Solutions LLC, from Petersen Incorporated, under Purchase Order (P.O.) Number 32653 with a Certificate of Conformance (see Enclosures 2, 3 and 4). BBWI purchased the SWBs from Westinghouse TRU Solutions under P.O. No. 00004539. The

910



A. J. Huot  
January 20, 2003  
Page 2

following table provides the Manufacturer's Serial Number, the Westinghouse TRU Solutions P.O. and Release Number, the BBWI P.O. and Shipment Number, and the BBWI Quality Assurance (QA) Identification Number applied to the SWB upon completion of receipt inspection.

Manufacturer's Serial Number	Westinghouse TRU Solutions P.O. & (Release) Numbers	BBWI P.O. & Shipment Numbers	BBWI-QA Identification Number
010221	32653, Shipment 11	0004539, Rev. 1, Shipment 12	91863
010248	32653, Shipment 13	0004539, Rev. 1, Shipment 12	91863
010251	32653, Shipment 13	0004539, Rev. 1, Shipment 12	91863
010263	32653, Shipment 13	0004539, Rev. 1, Shipment 14	91969
010282	32653, Shipment 13	0004539, Rev. 1, Shipment 14	91969
010288	32653, Shipment 13	0004539, Rev. 1, Shipment 14	91969
010259	32653, Shipment 12	0004539, Rev. 1, Shipment 13	91863
010227	32653, Shipment 12	0004539, Rev. 1, Shipment 13	91863

A procurement data package is enclosed (Enclosures 2, 3, and 4) for each of the three BBWI SWB shipments. The SWB data packages include procurement data for all SWBs, including certificates of conformance for all eight (8) SWBs. This data provides conclusive evidence that the eight (8) SWBs were purchased from Westinghouse TRU Solutions LLC, under Blanket Purchase Order 32653, as Standard Waste Boxes, according to Westinghouse TRU Solutions LLC Drawing 165-F-001-W1, 165-F-001-W2, 165-F-001-W3, and 165-F-001-W4.

In addition, the SWBs have been evaluated and tested as DOT Specification 7A Type A Packagings for the U.S. Department of Energy. The test and evaluation was performed at the DOE laboratory in Richland, Washington, and is documented in DOE/RL-96-57, *Test and Evaluation Document for DOT Specification 7A Type A Packaging*. The testing was performed and documented according to the same specifications and drawings included in the BBWI procurement requirements for the SWBs. Enclosure 1 is a copy of the *Test and Evaluation Document for U.S. DOT Specification 7A Type A Packaging* for the TRUPACT-II Standard Waste Box under DOE Docket: 98-45-7A, 6/99. The package description section lists the drawing and specification numbers for the SWB consistent with the BBWI procurement data:

- *Westinghouse Waste Isolation Division Drawing No. 165-F-001-W, Revisions F through K*
- *Westinghouse Electric Company, Waste Isolation Division, Specification E-1-343, Revision 3, Specification for the TRUPACT-II Standard Waste Box (WEC 1999).*

In conclusion, the procurement documentation, Certifications of Conformance, and the TRUPACT II Test and Evaluation Document for the SWBs provide adequate justification for the Transport Plan (PLN-1165), Safety Class application. Therefore, all eight SWBs can be retagged and used as safety class items. Please contact myself on 526-8721, or Gene Kanemoto on 526-6161 with any questions.

bar

A. J. Huot  
January 20, 2003  
Page 3

Enclosures:

1. Test and Evaluation Document for U.S. DOE Specification 7A Type A Packaging [3.2 TRUPACT-II Standard Waste Box (SWB) (Docket: 98-45-7A, 6/99)]
2. Records for SWBs SN 010263, SN 010282, SN 010288
3. Records for SWB SN 010221
4. Records for SWBs SN 010227, SN 010248, SN 010251, SN 010259

cc: (w/o Enc.)  
T. F. Fallon, MS 5306  
G. K. Kanemoto, MS 4105  
M. D. Ruska, MS 4105  
C. R. Tyler, MS 4105  
R. J. Wade, MS 3114  
R. L. Widhalm, MS 4105  
Packaging & Transportation Document Control, MS 4105  
J. L. Hansen Letter File (JLH-03-03)

Uniform File Code: 7253

Disposition Authority: ENVI-5-4-a

Retention Schedule: Cutoff at project completion. Destroy 25 years after project completion.

NOTE: Original disposition authority, retention schedule, and Uniform Filing Code applied by the sender may not be appropriate for all recipients. Make adjustments as needed.

## OPERATIONS DOCUMENT CHECKLIST FOR FIELD PACK FILE/TRUPACT LOADING FILE

### PAYLOAD ASSEMBLY OPERATIONS

Pack No. and/or SWB No. 1DRFXW13030007

Check or N/A

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> <u>NA</u> <u>2-3-03</u> | Payload Assembly, 14-Pack Layout Report(s)      |
| <input type="checkbox"/>                                    | Payload Disassembly, 14-Pack Layout Report(s)   |
| <input type="checkbox"/>                                    | TPR-1648, TRUPACT-II Payload Assembly Operation |
| <input type="checkbox"/>                                    | SWB Assembly Details Report(s)                  |
| <input type="checkbox"/>                                    | Shipments, Packs, And Subassemblies             |
| <input checked="" type="checkbox"/> <u>NA</u> <u>2-3-03</u> | Copy of NCR Report                              |
| <input checked="" type="checkbox"/>                         | Copy of Radiological Survey Report(s)           |

### TRUPACT LOADING OPERATIONS

TRUPACT-II(s) NA 2-3-03

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> <u>NA</u> <u>2-3-03</u> | TPR-1666, TRUPACT-II Loading Operation in WMF-635                                 |
| <input type="checkbox"/>                                    | TPR-1649, TRUPACT-II Loading Operation in WMF-618                                 |
| <input type="checkbox"/>                                    | TRUPACT-II Maintenance Record Form  |
| <input type="checkbox"/>                                    | PATCDs  |
| <input type="checkbox"/>                                    | SWB Assembly Details Report(s)  |
| <input checked="" type="checkbox"/> <u>NA</u> <u>2-3-03</u> | Container, Pack, TRUPACT, and Shipment Association Form/Report (Final Load Check) |

OF Signature: [Signature]

Date: 2-3-03

Comments: SWB IS ASSEMBLED USING TPR-6233

## OPERATIONS DOCUMENT CHECKLIST FOR FIELD PACK FILE/TRUPACT LOADING FILE

### PAYLOAD ASSEMBLY OPERATIONS

Pack No. and/or SWB No. 1) DRFXWB030005  
1) DRFXWB030006

Check or N/A

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> NA 2-3-03 | Payload Assembly, 14-Pack Layout Report(s)      |
| <input type="checkbox"/>                      | Payload Disassembly, 14-Pack Layout Report(s)   |
| <input type="checkbox"/>                      | TPR-1648, TRUPACT-II Payload Assembly Operation |
| <input type="checkbox"/>                      | SWB Assembly Details Report(s)                  |
| <input type="checkbox"/>                      | Shipments, Packs, And Subassemblies             |
| <input checked="" type="checkbox"/> NA 2-3-03 | Copy of NCR Report                              |
| <input checked="" type="checkbox"/>           | Copy of Radiological Survey Report(s)           |

### TRUPACT LOADING OPERATIONS

TRUPACT-II(s) NA 2-3-03

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> NA 2-3-03 | TPR-1666, TRUPACT-II Loading Operation in WMF-635                                 |
| <input type="checkbox"/>                      | TPR-1649, TRUPACT-II Loading Operation in WMF-618                                 |
| <input type="checkbox"/>                      | TRUPACT-II Maintenance Record Form  |
| <input type="checkbox"/>                      | PATCDs  |
| <input type="checkbox"/>                      | SWB Assembly Details Report(s)  |
| <input type="checkbox"/>                      | Container, Pack, TRUPACT, and Shipment Association Form/Report (Final Load Check) |

OF Signature: [Signature]

Date: 2-3-03

Comments: SWB'S ASSEMBLED USING TPR-6233

---

---

---

## OPERATIONS DOCUMENT CHECKLIST FOR FIELD PACK FILE/TRUPACT LOADING FILE

### PAYLOAD ASSEMBLY OPERATIONS

Pack No. and/or SWB No. 1DRFXWB030003  
1DRFXWB030004

Check or N/A

<input checked="" type="checkbox"/> NA 2-3-03	Payload Assembly, 14-Pack Layout Report(s)
<input type="checkbox"/>	Payload Disassembly, 14-Pack Layout Report(s)
<input type="checkbox"/>	TPR-1648, TRUPACT-II Payload Assembly Operation
<input type="checkbox"/>	SWB Assembly Details Report(s)
<input type="checkbox"/>	Shipments, Packs, And Subassemblies
<input checked="" type="checkbox"/> NA 2-3-03	Copy of NCR Report
<input checked="" type="checkbox"/>	Copy of Radiological Survey Report(s)

### TRUPACT LOADING OPERATIONS

TRUPACT-II(s) NA 2-3-03

<input checked="" type="checkbox"/> NA 2-3-03	TPR-1666, TRUPACT-II Loading Operation in WMF-635
<input type="checkbox"/>	TPR-1649, TRUPACT-II Loading Operation in WMF-618
<input type="checkbox"/>	TRUPACT-II Maintenance Record Form
<input type="checkbox"/>	PATCDs
<input type="checkbox"/>	SWB Assembly Details Report(s)
<input checked="" type="checkbox"/> NA 2-3-03	Container, Pack, TRUPACT, and Shipment Association Form/Report (Final Load Check)

OF Signature:

7C+21

Date:

2-3-03

Comments:

SWB'S ASSEMBLED USING TPR-6233

## OPERATIONS DOCUMENT CHECKLIST FOR FIELD PACK FILE/TRUPACT LOADING FILE

### PAYLOAD ASSEMBLY OPERATIONS

Pack No. and/or SWB No. IDRF XW 130 3000 1  
IDRF XW 130 3000 2

Check or N/A

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> <u>NA 11-2-03</u> | Payload Assembly, 14-Pack Layout Report(s)      |
| <input type="checkbox"/>                              | Payload Disassembly, 14-Pack Layout Report(s)   |
| <input type="checkbox"/>                              | TPR-1648, TRUPACT-II Payload Assembly Operation |
| <input type="checkbox"/>                              | SWB Assembly Details Report(s)                  |
| <input type="checkbox"/>                              | Shipments, Packs, And Subassemblies             |
| <input checked="" type="checkbox"/> <u>NA 11-2-03</u> | Copy of NCR Report                              |
| <input checked="" type="checkbox"/>                   | Copy of Radiological Survey Report(s)           |

### TRUPACT LOADING OPERATIONS

TRUPACT-II(s) NA 11-2-03

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> <u>NA 11-2-03</u> | TPR-1666, TRUPACT-II Loading Operation in WMF-635                                 |
| <input type="checkbox"/>                              | TPR-1649, TRUPACT-II Loading Operation in WMF-618                                 |
| <input type="checkbox"/>                              | TRUPACT-II Maintenance Record Form  |
| <input type="checkbox"/>                              | PATCDs  |
| <input type="checkbox"/>                              | SWB Assembly Details Report(s)  |
| <input type="checkbox"/>                              | Container, Pack, TRUPACT, and Shipment Association Form/Report (Final Load Check) |

OF Signature: [Signature]

Date: 2-3-03

Comments: SWB 15 ASSEMBLY (13) USING TPR-6233

## RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

sk or Container Serial Number: IDRFXWB030001

Cask Approved for INEEL Use Only: N/A

DOT Specification or Certificate of Compliance No.: N/A

Expiration Date: N/A

Shipment No.: RW03003

Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

- |   | YES                                 | NO                       | NA                                  |
|---|-------------------------------------|--------------------------|-------------------------------------|
| a. The packaging is proper for the contents to be shipped:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| b. The packaging is in unimpaired physical condition, except for superficial marks:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:  | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement: | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| h. The internal pressure of the containment system will not exceed the design pressure during transportation:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

Michael D. Griffin  
Container Inspector  
(Name)

  
Container Inspector  
(Signature)

2/3/2003  
Date

# RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

Sk or Container Serial Number: IDRFXWB030002

Cask Approved for INEEL Use Only: N/A

DOT Specification or Certificate of Compliance No.: N/A


Expiration Date: N/A Shipment No.: RW03003

Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

	YES	NO	NA
a. The packaging is proper for the contents to be shipped:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
b. The packaging is in unimpaired physical condition, except for superficial marks:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
h. The internal pressure of the containment system will not exceed the design pressure during transportation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Michael D. Griffin  
Container Inspector  
(Name)

  
Container Inspector  
(Signature)

2/3/2003  
Date



# RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

sk or Container Serial Number: IDRFXWB030003

Cask Approved for INEEL Use Only: N/A

DOT Specification or Certificate of Compliance No.: N/A

Expiration Date: N/A Shipment No.: RW03003

Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

- |   | YES                                 | NO                       | NA                                  |
|---|-------------------------------------|--------------------------|-------------------------------------|
| a. The packaging is proper for the contents to be shipped:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| b. The packaging is in unimpaired physical condition, except for superficial marks:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:  | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement: | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| h. The internal pressure of the containment system will not exceed the design pressure during transportation:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

Michael D. Griffin  
Container Inspector  
(Name)

  
Container Inspector  
(Signature)

2/3/2003  
Date

## RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

Sk or Container Serial Number: IDRFXWB030004

Cask Approved for INEEL Use Only: N/A

DOT Specification or Certificate of Compliance No.: N/A


Expiration Date: N/A Shipment No.: RW03003

Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

- |   | YES                                 | NO                       | NA                                  |
|---|-------------------------------------|--------------------------|-------------------------------------|
| a. The packaging is proper for the contents to be shipped:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| b. The packaging is in unimpaired physical condition, except for superficial marks:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:  | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement: | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| h. The internal pressure of the containment system will not exceed the design pressure during transportation:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

Michael D. Griffin  
Container Inspector  
(Name)

  
Container Inspector  
(Signature)

2/3/2003  
Date

# RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

sk or Container Serial Number: IDRFXWB030005  
Cask Approved for INEEL Use Only: N/A  
DOT Specification or Certificate of Compliance No.: N/A  
Expiration Date: N/A Shipment No.: RW03003  
Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

- |   | YES                                 | NO                       | NA                                  |
|---|-------------------------------------|--------------------------|-------------------------------------|
| a. The packaging is proper for the contents to be shipped:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| b. The packaging is in unimpaired physical condition, except for superficial marks:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:  | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement: | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| h. The internal pressure of the containment system will not exceed the design pressure during transportation:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

\_\_\_\_\_  
Michael D. Griffin  
Container Inspector  
(Name)

\_\_\_\_\_  
Michael D. Griffin  
Container Inspector  
(Signature)

\_\_\_\_\_  
2/3/2003  
Date

## RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

sk or Container Serial Number: IDRFXWB030006

Cask Approved for INEEL Use Only: N/A

DOT Specification or Certificate of Compliance No.: N/A

Expiration Date: N/A Shipment No.: RW03003

Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

- |   | YES                                 | NO                       | NA                                  |
|---|-------------------------------------|--------------------------|-------------------------------------|
| a. The packaging is proper for the contents to be shipped:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| b. The packaging is in unimpaired physical condition, except for superficial marks:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:  | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement: | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| h. The internal pressure of the containment system will not exceed the design pressure during transportation:   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

\_\_\_\_\_  
Michael D. Griffin  
Container Inspector  
(Name)

\_\_\_\_\_  
Michael D. Griffin  
Container Inspector  
(Signature)

\_\_\_\_\_  
2/3/2003  
Date

## RADIOACTIVE MATERIAL PACKAGING QUALITY CONTROL INSPECTION

sk or Container Serial Number: IDRFXWB030007

Cask Approved for INEEL Use Only: N/A

DOT Specification or Certificate of Compliance No.: N/A

Expiration Date: N/A Shipment No.: RW03003

Shipping Date: 2/4/2003

This checklist is to ensure that the above reference shipping container meets the applicable DOE or DOT design standards.

	YES	NO	NA
a. The packaging is proper for the contents to be shipped:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
b. The packaging is in unimpaired physical condition, except for superficial marks:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
c. Each closure device of the packaging, including any required gasket, is properly installed, secured, and free of defects:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
d. For fissile material, each moderator and neutron absorber, if required, is present and in proper condition:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. Each special instruction for filling, closing, and preparing the package for shipment has been followed:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. Each closure, valve or other opening of the containment system through which the radioactive content might escape is properly closed and sealed:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
g. Each packaging containing liquid in excess of an A <sub>2</sub> quantity and intended for air shipment has been tested to show that it will not leak under an ambient atmospheric pressure of not more than 0.25 atmosphere, absolute (0.25 kilograms per square centimeter or 3.6 psia). The test must be conducted on the entire containment system, or any receptacle or vessel within the containment system, to determine compliance with this requirement:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
h. The internal pressure of the containment system will not exceed the design pressure during transportation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Michael D. Griffin  
Container Inspector  
(Name)

  
Container Inspector  
(Signature)

2/3/2003  
Date

# **WIPP Waste Information System**

## **Waste Container Data Report**

**Report**            *RP0360*  
**Version**        *1.8*  
**Instance**       *TST01*  
**Run by**         *OFFNERS*  
**Report Date**   *01/20/2003 08:39*  
**Total Pages**   *4*

### **Selection Criteria -**

**Container Number**   *IDRFXWB030005*  
                              **Site Id**        %  
                              **Waste Stream**   %  
                              **Data Status Code**   %

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 2 of 4

Container Number : IDRFXWB030005  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW216.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION


## Waste Container Information

WAC Ex. # :		Handling Code :	CH
WAC Rev # :	0	Waste Type:	MTRU
Cert Date :	01/16/2003	Waste Stream BIR ID :	IN-W228
Cert Site :	IN - IDAHO NATIONAL ENGINEERING	Waste Stream MWIR ID :	IN-W228
Generator Site :	RF - ROCKY FLATS	TRU Alpha Act (Ci) :	1.432E-01
IDC Code :	002	TRU Alpha Act Uncert (Ci) :	6.472E-02
Matrix Code :	S3121	TRU Alpha Act Conc (Ci/g) :	6.203E-07
TRUCON Code :	ID211A	TRU Alpha Act Conc Uncert (Ci/g) :	2.809E-07
Shipping Category :	1001300250	Pu239 Eq Act (PE Ci) :	1.431E-01
PCB Conc (ppm) :	0	Pu239 Fiss Gm Eq (FGE) :	1.300E+00
Decay Heat (watts) :	4.687E-03	Pu239 Fiss Gm Eq Uncert (FGE) :	5.900E-01
Decay Heat Uncert (watts) :	2.118E-03	Layers of Packaging :	0
Closure Date :	01/04/1973	Fill Factor (%) :	11
Vent Date :	12/07/1987	Liner Exists :	Y
Aspiration Method ID :	3	Liner Hole Size (mm) :	7.62
Gas Gen Rate :		Gross Weight (kg) :	641.9
Gas Hyd Meth Gen Rate :		Gross Weight Uncert (kg) :	2.2
Gas Gen Comp Date :		Alpha Surf Cont (dpm/100cm2) :	0
Shipment Num :		BG Surf Cont (dpm/100cm2) :	0
Packaging Num :		BG Dose Rate (mrem/hr) :	.2
Assembly ID :		Neut Dose Rate (mrem/hr) :	0
		Total Dose Rate (mrem/hr) :	.2
Container Disposal Date :		Overpack Cntr Num :	
Container Status Code :	PRE	Overpack Cntr Type :	

It can be established through process knowledge  
that the concentration of flammable VOCs present  
in the headspace of this container is  $\leq 500$ ppm: N

## Inner Container Information

Container Number	Container Type
IDRF074221338	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD

 1-31-03

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 3 of 4

Container Number : IDRFXWB030005  
 Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
 Data Status Code : Pending Certification Data Approval by WIPP  
 Waste Stream Profile : INW216.001  
 Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Nuclide Information

Radionuclide	Description	Activity (Ci)	Activity Uncert (Ci)	Mass (g)	Mass Uncert (g)	List
AM-241	AMERICIUM 241	9.809E-02	4.439E-02	2.827E-02	1.279E-02	Y
CS-137	CESIUM 137	.000E+00	.000E+00	.000E+00	.000E+00	Y
PU-238	PLUTONIUM 238	1.106E-03	6.599E-04	6.392E-05	3.814E-05	Y
PU-239	PLUTONIUM 239	3.601E-02	1.625E-02	5.726E-01	2.584E-01	Y
PU-240	PLUTONIUM 240	8.008E-03	3.676E-03	3.482E-02	1.598E-02	Y
PU-241	PLUTONIUM 241	1.095E-01	5.342E-02	1.053E-03	5.136E-04	Y
PU-242	PLUTONIUM 242	1.039E-06	7.089E-07	2.617E-04	1.786E-04	Y
SR-90	STRONTIUM 90	.000E+00	.000E+00	.000E+00	.000E+00	Y
U-233	URANIUM 233	.000E+00	.000E+00	.000E+00	.000E+00	
U-234	URANIUM 234	9.272E-06	5.358E-06	1.467E-03	8.478E-04	Y
U-235	URANIUM 235	1.582E-06	7.143E-07	7.223E-01	3.261E-01	Y
U-238	URANIUM 238	7.071E-05	3.352E-05	2.080E+02	9.857E+01	Y

## Material Parameters Information

Waste Matl Parm	Description	Weight (kg)
1	IRON BASE METAL ALLOYS	26.76
4	OTHER INORGANIC MATERIALS	29.03
8	PLASTICS	7.71
9	SOLIDIFIED INORGANIC MATERIAL	201.40
13	STEEL CONTAINER MATERIALS	377.00

## Filter Model Information

Filter Model	Description	Quantity	Install Date
NF013	NUCFIL CARBON COMPOSIT	4	01/16/2003

## Assay Methods Information

See Assay Methods Information for Inner containers.



# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 4 of 4

Container Number : IDRFXWB030005  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW216.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Characterization Methods Information

See Characterization Methods Information for Inner containers.

## Hazardous Code Information

Haz Code	Description
D004	ARSENIC
D005	BARIUM
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D010	SELENIUM
D011	SILVER
D022	CHLOROFORM
F001	SPENT HALOGENATED SOLVENTS
F002	SPENT HALOGENATED SOLVENTS
F005	SPENT NON-HALOGENATED SOLVENTS
F006	WASTEWATER TREATMENT SLUDGE
F007	SPENT CYANIDE PLATING BATH
F009	SPENT STRIPPING SOLUTION

## Sample Information

See Sample Information for Inner containers.

# WIPP Waste Information System

## Waste Container Data Report

Report **RP0360**  
Version **1.8**  
Instance **TST01**  
Run by **OFFNERS**  
Report Date **01/20/2003 08:40**  
Total Pages **4**

### Selection Criteria -

Container Number **IDRFXWB030006**  
Site Id %  
Waste Stream %  
Data Status Code %

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 2 of 4

Container Number : IDRFXWB030006  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW218.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Waste Container Information

WAC Ex. # :		Handling Code :	CH
WAC Rev # :	0	Waste Type:	MTRU
Cert Date :	01/16/2003	Waste Stream BIR ID :	IN-W218
Cert Site :	IN - IDAHO NATIONAL ENGINEERING	Waste Stream MWIR ID :	IN-W218
Generator Site :	RF - ROCKY FLATS	TRU Alpha Act (Ci) :	3.795E-01
IDC Code :	007	TPU Alpha Act Uncert (Ci) :	1.509E-01
Matrix Code :	S3121	TRU Alpha Act Conc (Ci/g) :	7.945E-07
TRUCON Code :	ID211A	TRU Alpha Act Conc Uncert (Ci/g) :	6.444E-07
Shipping Category :	1001300250	Pu239 Eq Act (PE Ci) :	3.792E-01
PCB Conc (ppm) :	0	Pu239 Fiss Gm Eq (FGE) :	2.570E+00
Decay Heat (watts) :	1.241E-02	Pu239 Fiss Gm Eq Uncert (FGE) :	9.508E-01
Decay Heat Uncert (watts) :	4.945E-03	Layers of Packaging :	0
Closure Date :	01/17/1983	Fill Factor (%) :	19
Vent Date :	07/11/1989	Liner Exists :	Y
Aspiration Method ID :	3	Liner Hole Size (mm) :	7.62
Gas Gen Rate :		Gross Weight (kg) :	893.67
Gas Hyd Meth Gen Rate :		Gross Weight Uncert (kg) :	2.16
Gas Gen Comp Date :		Alpha Surf Cont (dpm/100cm2) :	0
Shipment Num :		BG Surf Cont (dpm/100cm2) :	0
Packaging Num :		BG Dose Rate (mrem/hr) :	0
Assembly ID :		Neut Dose Rate (mrem/hr) :	0
		Total Dose Rate (mrem/hr) :	0
Container Disposal Date :		Overpack Cntr Num :	
Container Status Code :	PRE	Overpack Cntr Type :	

It can be established through process knowledge  
that the concentration of flammable VOCs present  
in the headspace of this container is  $\leq 500$ ppm: N

## Inner Container Information

Container Number	Container Type
IDRF074700411	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD
IDRF074700394	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD

*WIP* 1-31-03

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 3 of 4

Container Number : IDRFXWB030006  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW218.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Nuclide Information

Radionuclide	Description	Activity (Ci)	Activity Uncert (Ci)	Mass (g)	Mass Uncert (g)	List
AM-241	AMERICIUM 241	2.549E-01	1.068E-01	7.347E-02	3.079E-02	Y
CS-137	CESIUM 137	.000E+00	.000E+00	.000E+00	.000E+00	Y
PU-238	PLUTONIUM 238	3.051E-03	1.482E-03	1.764E-04	8.568E-05	Y
PU-239	PLUTONIUM 239	9.938E-02	3.600E-02	1.580E+00	5.724E-01	Y
PU-240	PLUTONIUM 240	2.210E-02	8.153E-03	9.608E-02	3.545E-02	Y
PU-241	PLUTONIUM 241	3.022E-01	1.189E-01	2.906E-03	1.143E-03	Y
PU-242	PLUTONIUM 242	2.867E-06	1.599E-06	7.223E-04	4.028E-04	Y
SR-90	STRONTIUM 90	.000E+00	.000E+00	.000E+00	.000E+00	Y
U-233	URANIUM 233	.000E+00	.000E+00	.000E+00	.000E+00	
U-234	URANIUM 234	1.446E-05	5.950E-06	2.289E-03	9.414E-04	Y
U-235	URANIUM 235	2.163E-06	8.208E-07	9.876E-01	3.748E-01	Y
U-238	URANIUM 238	1.256E-04	4.807E-05	3.695E+02	1.414E+02	Y

## Material Parameters Information

Waste Matl Parm	Description	Weight (kg)
1	IRON BASE METAL ALLOYS	53.52
4	OTHER INORGANIC MATERIALS	72.57
8	PLASTICS	19.06
9	SOLIDIFIED INORGANIC MATERIAL	400.52
13	STEEL CONTAINER MATERIALS	348.00

## Filter Model Information

Filter Model	Description	Quantity	Install Date
NF013	NUCFIL CARBON COMPOSIT	4	01/16/2003

## Assay Methods Information

See Assay Methods Information for Inner containers.

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 4 of 4

Container Number : IDRFXWB030006  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW218.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Characterization Methods Information

See Characterization Methods Information for Inner containers.

## Hazardous Code Information

Haz Code	Description
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D010	SELENIUM
D011	SILVER
D032	HEXACHLOROBENZENE
F001	SPENT HALOGENATED SOLVENTS
F002	SPENT HALOGENATED SOLVENTS
F005	SPENT NON-HALOGENATED SOLVENTS
F006	WASTEWATER TREATMENT SLUDGE
F007	SPENT CYANIDE PLATING BATH
F009	SPENT STRIPPING SOLUTION

## Sample Information

See Sample Information for Inner containers.

## Waste Information System Waste Container Data Report

Report *RP0360*  
Version *1.8*  
Instance *TST01*  
Run by *OFFNERS*  
Report Date *01/20/2003 08:36*  
Total Pages *4*

### Selection Criteria -

Container Number *IDRFXWB030001*  
Site Id %  
Waste Stream %  
Data Status Code %

# Waste Container Data Report

Info

Waste Isolation Pilot Plant

Page 2 of 4

Container ID: IDRF030001  
Site ID: IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code: Pending Certification Data Approval by WIPP  
Waste Stream Profile: INW211.001  
Container Type: 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Waste Container Information

WAC Ex. #:		Handling Code:	CH
WAC Rev #:	0	Waste Type:	MTRU
Cert Date:	01/16/2003	Waste Stream BIR ID:	N/A
Cert Site:	IN - IDAHO NATIONAL ENGINEERING	Waste Stream MWIR ID:	N/A
Generator Site:	RF - ROCKY FLATS	TRU Alpha Act (Ci):	1.484E+01
IDC Code:	376	TRU Alpha Act Uncert (Ci):	1.110E+00
Matrix Code:	S5410	TRU Alpha Act Conc (Ci/g):	1.404E-04
TRUCON Code:	ID219A	TRU Alpha Act Conc Uncert (Ci/g):	4.251E-05
Shipping Category:	3001090568	Pu239 Eq Act (PE Ci):	1.481E+01
PCB Conc (ppm):	0	Pu239 Fiss Gm Eq (FGE):	1.744E+02
Decay Heat (watts):	4.651E-01	Pu239 Fiss Gm Eq Uncert (FGE):	1.671E+01
Decay Heat Uncert (watts):	3.457E-02	Layers of Packaging:	2
Closure Date:	06/07/1984	Fill Factor (%):	36
Vent Date:	11/16/2001	Liner Exists:	Y
Aspiration Method ID:	3	Liner Hole Size (mm):	7.62
Gas Gen Rate:		Gross Weight (kg):	534.02
Gas Hyd Meth Gen Rate:		Gross Weight Uncert (kg):	2.08
Gas Gen Comp Date:		Alpha Surf Cont (dpm/100cm2):	0
Shipment Num:		BG Surf Cont (dpm/100cm2):	0
Packaging Num:		BG Dose Rate (mrem/hr):	2
Assembly ID:		Neut Dose Rate (mrem/hr):	2
		Total Dose Rate (mrem/hr):	4
Container Disposal Date:		Overpack Cntr Num:	
Container Status Code:	PRE	Overpack Cntr Type:	

It can be established through process knowledge that the concentration of flammable VOCs present in the headspace of this container is  $\leq 500$ ppm: N

## Inner Container Information

Container Number	Container Type
IDRF004102254	16 - 55 GAL DRUM TO BE OVERPACKED - GOOD CONDITION
IDRF004101890	16 - 55 GAL DRUM TO BE OVERPACKED - GOOD CONDITION
IDRF004002801	16 - 55 GAL DRUM TO BE OVERPACKED - GOOD CONDITION
IDRF004102263	16 - 55 GAL DRUM TO BE OVERPACKED - GOOD CONDITION

*Handwritten signature and date:* 1-31-03

# Waste Container Data Report

Info.

Waste Isolation Pilot Plant

Page 3 of 4

Cont: IDRFXWB030001  
 Site ID: IN - IDAHO NATIONAL ENGINEERING LAB  
 Data Status Code: Pending Certification Data Approval by WIPP  
 Waste Stream Profile: INW211.001  
 Container Type: 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Nuclide Information

Radionuclide	Description	Activity (Ci)	Activity Uncert (Ci)	Mass (g)	Mass Uncert (g)	List
AM-241	AMERICIUM 241	1.188E+00	2.399E-01	3.423E-01	6.915E-02	Y
CS-137	CESIUM 137	.000E+00	.000E+00	.000E+00	.000E+00	Y
PU-238	PLUTONIUM 238	3.357E-01	7.347E-02	1.941E-02	4.247E-03	Y
PU-239	PLUTONIUM 239	1.090E+01	1.051E+00	1.733E+02	1.671E+01	Y
PU-240	PLUTONIUM 240	2.415E+00	2.541E-01	1.050E+01	1.105E+00	Y
PU-241	PLUTONIUM 241	3.316E+01	4.429E+00	3.188E-01	4.258E-02	Y
PU-242	PLUTONIUM 242	3.164E-04	8.801E-05	7.970E-02	2.217E-02	Y
SR-90	STRONTIUM 90	.000E+00	.000E+00	.000E+00	.000E+00	Y
U-233	URANIUM 233	.000E+00	.000E+00	.000E+00	.000E+00	
U-234	URANIUM 234	.000E+00	.000E+00	.000E+00	.000E+00	
U-235	URANIUM 235	.000E+00	.000E+00	.000E+00	.000E+00	
U-238	URANIUM 238	.000E+00	.000E+00	.000E+00	.000E+00	

## Material Parameters Information

Waste Matl Parm	Description	Weight (kg)
1	IRON BASE METAL ALLOYS	107.04
2	ALUMINUM BASE METAL/ALLOYS	9.89
4	OTHER INORGANIC MATERIALS	2.04
6	CELLULOSICS	92.74
8	PLASTICS	32.31
13	STEEL CONTAINER MATERIALS	290.00

## Filter Model Information

Filter Model	Description	Quantity	Install Date
NF013	NUCIFIL CARBON COMPOSIT	4	01/16/2003

## Assay Methods Information

See Assay Methods Information for Inner containers.



# Waste Container Data Report

Waste  
Information

Waste Isolation Pilot Plant

Page 4 of 4

Container : IDRFXWB030001  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW211.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Characterization Methods Information

See Characterization Methods Information for Inner containers.

## Hazardous Code Information

Haz Code	Description
D005	BARIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D011	SILVER
D022	CHLOROFORM
F001	SPENT HALOGENATED SOLVENTS
F002	SPENT HALOGENATED SOLVENTS
F005	SPENT NON-HALOGENATED SOLVENTS
F006	WASTEWATER TREATMENT SLUDGE
F007	SPENT CYANIDE PLATING BATH
F009	SPENT STRIPPING SOLUTION

## Sample Information

See Sample Information for Inner containers.

**WIPP Waste Information System**  
**Waste Container Data Report**

**Report**            *RP0360*  
**Version**        *1.8*  
**Instance**       *TST01*  
**Run by**          *OFFNERS*  
**Report Date**   *01/20/2003 08:37*  
**Total Pages**   *4*

**Selection Criteria -**

**Container Number**   *IDRFXWB030002*  
                              **Site Id**    %  
                              **Waste Stream**   %  
                              **Data Status Code**   %

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 2 of 4

Container Number : IDRFXWB030002  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW211.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Waste Container Information

WAC Ex. # :		Handling Code :	CH
WAC Rev # :	0	Waste Type:	MTRU
Cert Date :	01/16/2003	Waste Stream BIR ID :	N/A
Cert Site :	IN - IDAHO NATIONAL ENGINEERING	Waste Stream MWIR ID :	N/A
Generator Site :	RF - ROCKY FLATS	TRU Alpha Act (Ci) :	3.690E+00
IDC Code :	376	TRU Alpha Act Uncert (Ci) :	5.422E-01
Matrix Code :	S5410	TRU Alpha Act Conc (Ci/g) :	9.684E-05
TRUCON Code :	ID219A	TRU Alpha Act Conc Uncert (Ci/g) :	1.423E-05
Shipping Category :	3001090568	Pu239 Eq Act (PE Ci) :	3.682E+00
PCB Conc (ppm) :	0	Pu239 Fiss Gm Eq (FGE) :	4.282E+01
Decay Heat (watts) :	1.157E-01	Pu239 Fiss Gm Eq Uncert (FGE) :	8.180E+00
Decay Heat Uncert (watts) :	1.688E-02	Layers of Packaging :	1
Closure Date :	10/21/1986	Fill Factor (%) :	11
Vent Date :	01/20/2001	Liner Exists :	Y
Aspiration Method ID :	3	Liner Hole Size (mm) :	7.62
Gas Gen Rate :		Gross Weight (kg) :	449.57
Gas Hyd Meth Gen Rate :		Gross Weight Uncert (kg) :	2.2
Gas Gen Comp Date :		Alpha Surf Cont (dpm/100cm2) :	0
Shipment Num :		BG Surf Cont (dpm/100cm2) :	0
Packaging Num :		BG Dose Rate (mrem/hr) :	3
Assembly ID :		Neut Dose Rate (mrem/hr) :	0
		Total Dose Rate (mrem/hr) :	3
Container Disposal Date :		Overpack Cntr Num :	
Container Status Code :	PRE	Overpack Cntr Type :	

It can be established through process knowledge  
that the concentration of flammable VOCs present  
in the headspace of this container is <= 500ppm: N

## Inner Container Information

Container Number

Container Type

IDRF004002790

16 - 55 GAL DRUM TO BE OVERPACKED - GOOD CONDITION

74574 1-31-03

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 3 of 4

Container Number : IDRFWB030002  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW211.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Nuclide Information

Radionuclide	Description	Activity (Ci)	Activity Uncert (Ci)	Mass (g)	Mass Uncert (g)	List
AM-241	AMERICIUM 241	3.394E-01	1.120E-01	9.781E-02	3.226E-02	Y
CS-137	CESIUM 137	.000E+00	.000E+00	.000E+00	.000E+00	Y
PU-238	PLUTONIUM 238	8.240E-02	3.604E-02	4.763E-03	2.083E-03	Y
PU-239	PLUTONIUM 239	2.675E+00	5.145E-01	4.253E+01	8.179E+00	Y
PU-240	PLUTONIUM 240	5.928E-01	1.244E-01	2.577E+00	5.410E-01	Y
PU-241	PLUTONIUM 241	8.138E+00	2.170E+00	7.825E-02	2.087E-02	Y
PU-242	PLUTONIUM 242	7.767E-05	4.319E-05	1.956E-02	1.088E-02	Y
SR-90	STRONTIUM 90	.000E+00	.000E+00	.000E+00	.000E+00	Y
U-233	URANIUM 233	.000E+00	.000E+00	.000E+00	.000E+00	
U-234	URANIUM 234	.000E+00	.000E+00	.000E+00	.000E+00	
U-235	URANIUM 235	.000E+00	.000E+00	.000E+00	.000E+00	
U-238	URANIUM 238	.000E+00	.000E+00	.000E+00	.000E+00	

## Material Parameters Information

Waste Matl Parm	Description	Weight (kg)
1	IRON BASE METAL ALLOYS	26.76
2	ALUMINUM BASE METAL/ALLOYS	3.81
6	CELLULOSICS	34.29
8	PLASTICS	7.71
13	STEEL CONTAINER MATERIALS	377.00

## Filter Model Information

Filter Model	Description	Quantity	Install Date
NF013	NUCFIL CARBON COMPOSIT	4	01/16/2003

## Assay Methods Information

See Assay Methods Information for Inner containers.

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 4 of 4

Container Number : IDRFXWB030002  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW211.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Characterization Methods Information

See Characterization Methods Information for Inner containers.

## Hazardous Code Information

Haz Code	Description
D005	BARIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D011	SILVER
D022	CHLOROFORM
F001	SPENT HALOGENATED SOLVENTS
F002	SPENT HALOGENATED SOLVENTS
F005	SPENT NON-HALOGENATED SOLVENTS
F006	WASTEWATER TREATMENT SLUDGE
F007	SPENT CYANIDE PLATING BATH
F009	SPENT STRIPPING SOLUTION

## Sample Information

See Sample Information for Inner containers.

# WIPP Waste Information System

## Waste Container Data Report

Report **RP0360**  
Version **1.8**  
Instance **TST01**  
Run by **OFFNERS**  
Report Date **01/20/2003 08:38**  
Total Pages **4**

### Selection Criteria -

Container Number **IDRFXWB030003**  
Site Id %  
Waste Stream %  
Data Status Code %

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 2 of 4

Container Number : IDRFXWB030003  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW216.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Waste Container Information

WAC Ex. # :		Handling Code :	CH
WAC Rev # :	0	Waste Type:	MTRU
Cert Date :	01/16/2003	Waste Stream BIR ID :	IN-W216
Cert Site :	IN - IDAHO NATIONAL ENGINEERING	Waste Stream MWIR ID :	IN-W216
Generator Site :	RF - ROCKY FLATS	TRU Alpha Act (Ci) :	1.137E+01
IDC Code :	001	TRU Alpha Act Uncert (Ci) :	3.168E+00
Matrix Code :	S3121	TRU Alpha Act Conc (Ci/g) :	1.450E-05
TRUCON Code :	ID211A	TRU Alpha Act Conc Uncert (Ci/g) :	1.587E-05
Shipping Category :	1001300250	Pu239 Eq Act (PE Ci) :	1.137E+01
PCB Conc (ppm) :	0	Pu239 Fiss Gm Eq (FGE) :	3.864E+01
Decay Heat (watts) :	3.766E-01	Pu239 Fiss Gm Eq Uncert (FGE) :	9.682E+00
Decay Heat Uncert (watts) :	1.046E-01	Layers of Packaging :	2
Closure Date :	02/08/1982	Fill Factor (%) :	37
Vent Date :	07/20/1989	Liner Exists :	Y
Aspiration Method ID :	3	Liner Hole Size (mm) :	7.62
Gas Gen Rate :	.000E+00	Gross Weight (kg) :	1212.15
Gas Hyd Meth Gen Rate :	1.026E-08	Gross Weight Uncert (kg) :	2.08
Gas Gen Comp Date :	02/20/2002	Alpha Surf Cont (dpm/100cm2) :	0
Shipment Num :		BG Surf Cont (dpm/100cm2) :	0
Packaging Num :		BG Dose Rate (mrem/hr) :	20
Assembly ID :		Neut Dose Rate (mrem/hr) :	0
Container Disposal Date :		Total Dose Rate (mrem/hr) :	20
Container Status Code :	PRE	Overpack Cntr Num :	
		Overpack Cntr Type :	

It can be established through process knowledge  
that the concentration of flammable VOCs present  
in the headspace of this container is <= 500ppm: N

## Inner Container Information

Container Number	Container Type
IDRF741202484	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD
IDRF741201615	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD
IDRF741202088	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD
IDRF741205405	18 - 55 GAL DRUM TO BE OVERPACKED - SOLID/VITRIFIED - GOOD

202

# Waste Container Data Report

WIPP Waste  
Information System

Waste Isolation Pilot Plant

Page 3 of 4

Container Number : IDRFXWB030003  
Site ID : IN - IDAHO NATIONAL ENGINEERING LAB  
Data Status Code : Pending Certification Data Approval by WIPP  
Waste Stream Profile : INW216.001  
Container Type : 14 - SWB - USED TO OVERPACK 4 - 55 GAL. DRUMS IN GOOD CONDITION

## Nuclide Information

Radionuclide	Description	Activity (Ci)	Activity Uncert (Ci)	Mass (g)	Mass Uncert (g)	List
AM-241	AMERICIUM 241	9.802E+00	2.623E+00	2.825E+00	7.560E-01	Y
CS-137	CESIUM 137	.000E+00	.000E+00	.000E+00	.000E+00	Y
PU-238	PLUTONIUM 238	3.840E-02	1.956E-02	2.219E-03	1.131E-03	Y
PU-239	PLUTONIUM 239	1.251E+00	4.619E-01	1.988E+01	7.343E+00	Y
PU-240	PLUTONIUM 240	2.781E-01	1.048E-01	1.209E+00	4.558E-01	Y
PU-241	PLUTONIUM 241	3.803E+00	1.540E+00	3.657E-02	1.481E-02	Y
PU-242	PLUTONIUM 242	3.608E-05	2.128E-05	9.089E-03	5.360E-03	Y
SR-90	STRONTIUM 90	.000E+00	.000E+00	.000E+00	.000E+00	Y
U-233	URANIUM 233	.000E+00	.000E+00	.000E+00	.000E+00	
U-234	URANIUM 234	2.678E-04	9.467E-05	4.237E-02	1.498E-02	Y
U-235	URANIUM 235	4.074E-05	9.952E-06	1.860E+01	4.544E+00	Y
U-238	URANIUM 238	2.291E-03	6.709E-04	6.737E+03	1.973E+03	Y

## Material Parameters Information

Waste Matl Parm	Description	Weight (kg)
1	IRON BASE METAL ALLOYS	107.04
4	OTHER INORGANIC MATERIALS	84.37
8	PLASTICS	34.04
9	SOLIDIFIED INORGANIC MATERIAL	696.73
13	STEEL CONTAINER MATERIALS	290.00

## Filter Model Information

Filter Model	Description	Quantity	Install Date
NF013	NUCFIL CARBON COMPOSIT	4	01/16/2003

## Assay Methods Information

See Assay Methods Information for Inner containers.



**Appendix D**  
**Examination Engineers' Daily Log**



TRUPACT-157 Examination Engineer's Log

pg 1

Date 1/27/83 Shift 7 AM - 7 PM Engineer P.H. O'Brien  
0700 - 1300 hrs K.E. Archibald

Time	Initial	Comments/Notes/Observations
9:50 AM	KA	TRUPACT-157 ARRIVED AT HOT SHOP.
		TAPE #1 9:48. 10:00 AM - TRUPACT-157
		WAS REMOVED FROM TRUCK AND MOVED
		INTO THE HOT SHOP.
10:21	PHO	One of the tamper resistant device on
		the OCV vent port plug was off.
		Doug Wales said that CBFO concurred
		that we should proceed with ops.
10:45	KA	TRUPACT ENTERED HOT SHOP AT
		9:45 AM
11:10	PHO	Finished installing short legs on ACGLF.
13:07	PHO	Started Tape #2. OCV lid is off
13:19	PHO	Lid off. and <sup>and</sup> Tape #2 time = 0hr 13 min.
		Lid is on ring stand (OCV lid).
13:37	PHO	There <sup>was</sup> <del>is</del> no vacuum on the ICV <sup>inside</sup> . PHO
		When the EO test <sup>PHO</sup> leaned on the <sup>PHO 2/24/83</sup>
		ICV lid, it rotated, indicating a high
		vacuum inside the cask. It has completely
		rotated off the lock. This is visible in the video.
13:52	PHO	Per Doug Wales & ops, they are proceeding
		with removal of the vent plug.

JMCL 1-28-83 1329

TRUPACT-157 Examination Engineer 'sLog

PS<sup>2</sup>

Date 1/27/2003 Shift 0700 - 1900hrs Engineer B.H. O'Brien

Time	Initial	Comments/Notes/Observations
<del>1356</del>	pno	Retrieved vent plug. Cask has 4" Hg vacuum.
1400	pno	Time on tape #2 = 0:45:40"
1435	pno	Vent port tool d plug smeared clean.
1442	pno	ACGLF is locked onto the ICV lid over the sleeving. Stop tape for break.
		Tape #2 time = 1hr 29'25"
1535	pno	Tape #2 on
1545	pno	Took camera shots of the playpen, scaffolding, inside and outside of the tents. Tape #2 off 1hr 39:54"
1605	pno	Tape <del>on</del> <sup>off</sup> on 1:39:54.
1620 <del>1420</del>	pno	Took smears from inside of ICV Lid and top of payload.
1623 <del>1423</del>	pno	Took air sample from inside of ICV ( $> 15 \text{ min spi}$ )
<del>162</del>		Stopped tape #2
1623	pno	Started tape #3
<del>1650/1630</del>	pno	Vacuum pump blew circuit breaker. Air sample stopped.
1641	pno	Payload top of ICV inside lid smears are $< 1000 \text{ } \beta \text{ } \text{dpm}/100 \text{ cm}^2$ , $< 20 \text{ dpm}/100 \text{ cm}^2$ - that is low levels / clean levels.

JMC 1-29-03 1830

Date 1/27/03 Shift 0700-1900 hrs Engineer B. H. O'Brien

Time	Initial	Comments/Notes/Observations
1654	BNW	Dps & Radcon determined not to add fixation due to Low C on smears. Pulling ICV lid to separate it. <del>from</del> <sup>from</sup> 2-28-03
1704	BNW	1 DRP 0041002632263 is next to the <sup>seal test</sup> vent port. Drum sample port on the cask is next drum clockwise from the seal test port drum. The drum next to the sample test port is in position #3, #1 DRP 004002801
1719	BNW	From a visual inspection, they can see the bottom of the ICV and see no free liquid or evidence of free liquid.
1722	BNW	Inserted puppet camera in ICV, payload. No evidence of shifting of drums, or loose lock chains from the puppet cam.
1739	BNW	No evidence of liquid or spills on the bottom plate near the seal test port. Time = 1:12:34
1739	BNW	Above 2 o'clock from <sup>ICV</sup> <del>ICV</del> vent port (a 12 o'clock puppet cam video of black argonne repack drum.
1741	BNW	1:17:46 on tape 3. Center drum

TRUPACT-157 Examination Engineer 'sLog

Date 1/27/03 Shift 0700-1900 hrs Engineer B.H. O'Brian

Time	Initial	Comments/Notes/Observations
1754	pno	Finished with puppet camera inside payload. Maybe some evidence of white (print chips?) on one of the slipsheets - otherwise looks good.
1756	pno	Tape 3 off 1:32:28 - end of taping for 1/27/03.
1832	pno	Kelly Vynaster (Ardenman) says the guide tubes are still loose, as they should be, indicating the top & bottom drums haven't rotated. -pno
<div></div>		
3:		

7:10 1/28/03 Rep C. B. H. O.  
13:33 1-29-03 JMC

TRUPACT-157 Examination Engineer 'sLog

pg 5

Date 1/28/03 Shift 0700-1900 Engineer K. Archibald

Time	Initial	Comments/Notes/Observations
7:09	Ku	Renewed Engr. Log From 1/27/03
7:49	Ku	TAPE #4 WAS PUT INTO SYSTEM. IT WAS DETERMINED FROM TITE POD TO TAKE AS MANY SURVEYS AS POSSIBLE BEFORE LIFTING THE PAYLOAD.
8:35	Ku	SURVEYS WERE STARTED. A SURVEY MAP WAS USED TO CONDUCT THE WORK.
9:15	Ke	PURRET CAMERA WAS INSERTED INTO PAYLOAD. ALL FOUR <sup>TOP</sup> DRUMS HAD FILTERS. THE CAMERA WAS MOVED TO THE NEXT LEVEL <sup>IN THE PAYLOAD.</sup> <del>WHERE</del> <sup>ALL</sup> FILTERS WERE IN PLACE. FIVE BOMB FILTERS WERE LOCATED INSIDE THE PAYLOAD.
9:38	Ka	Smear SURVEYS were completed.
12:00	Ku	STARTED 4-SCREEN VIDEO IN CONF. Room # 135 B. (TANO)
12:25	BM	Fixed connections on 4 screen video feed in Room 135 B. Also reviewed prior log entries.

entry out of sequence by BM 1/28/03 - BM

JML 1.29.03 1335

TRUPACT-157 Examination Engineer 'sLog

pg 6

Date 1/28/03 Shift 0700 - 1900 Engineer KIP Archibald  
1000 - 1900 B.M. O'Brien

Time	Initial	Comments/Notes/Observations
12:10	Ka	RAD support entered the Hot SHOP. IT WAS DETERMINED TO CONTINUE AS PLANNED. USING THE EXAMINATION PLAN.
12:22	Ka	PAYLOAD IS BEING REMOVED FROM ICV.
1250	pno	Payload bottom umbilical was cut and the payload rotated to view through all 4 windows on payload sleeve side. RCT's did rad surgery of payload as it was removed from ICV. Operators say the inside of the ICV looks visually OK. No abnormalities.
1257	pno	Video power tripped out Tape = 2:01:02.
1259	pno	Tape #5 started. Power to video back on
1304	pno	Payload dropped into tent.
1308	pno	Bottom of drum ... 1338 ring looks quite rusty. Lost power again.
1330	pno	Tape #5 paused, during power off. Now back on time = 0:0:00.

JML 1:29:03 1335



TRUPACT-157 Examination Engineer 'sLog

Date 1/28/03 Shift 0700-1900 Engineer K. E. Archibald  
B. H. O'Brien

Time	Initial	Comments/Notes/Observations
13:20	KA	PAYLOAD WAS DISCONNECTED FROM Casting Device. THERE WERE NO DISCONTINUES WITH PAYLOAD.
13:24	pno	Sleeve removed from top of payload.
13:37	pno	Can see evidence of white spots from liquid in the slipshat below down 1DRF004002790, <del>Swirl</del> <sup>mechanic (TAN)</sup> (Jim Fernandez) says some of the slipshats had bird droppings on them. The spots look like something has been wiped off them, such as would have been for bird droppings.
<del>13:37</del>	<del>pno</del>	<del>2-28-03</del>
13:41	pno	There are also drip marks near 200394 tape #5 00:39:06. They appear to be in line with the plastic wrap above them. The Swirl operators say some of the payloads were built, then sent back (-transferred in the rain). <del>who</del> <sup>pno</sup> We will have the RCTi scan these spots.

Date 1/28/03 Shift 0700-1900 Engineer K. E. Archibald  
B. H. D'Brien

Time	Initial	Comments/Notes/Observations
1403	βND	Casey Gubbey (CBFO) says we need to look for rubbing between the top rolling hoops of the top drums and the rivets on the inside sides of the 1CV lid. Will need to position the lid over a camera to look at these before replacing the 1CV lid.
1410	βND	Tape 5 01:07', looked at an item on the side of the payload. After inspection, it appears to be part of the slip sheet.
1417	βND	Waiting for results of inside of 1CV smears. Tape 5 off, 01:14 hrs run time.
1618	βND	Restarted single monitor & 4 screen monitor VHS recorders. Rewound and wrote over tape #2 as nothing was happening while we waited for smear results except trash bag out. The area was recleared for no anti-c's required for 1CV processing.

Date 1/28/03 Shift 0700-1900 Engineer B. H. O'Brien  
K. E. Archibald.

Time	Initial	Comments/Notes/Observations
1630	pro	Step 4.5.32 "inspect ICV interior" will be worked out-of-sequence after the sleeving is removed from the ICV cavity so that we can take pictures of the ICV cavity from the O-man (overhead manipulator) camera.
1635	pro	Sleeving removed from ICV cavity.
1638	pro	Looked into <sup>pro</sup> top NE angled side and bottom. Bottom brackets look good. There are a few squiggly scratches on the sides and radial black marks on the bottom. The RCT's took more smears of the ICV cavity. The QI(CS.) says the scrapes look like normal wear. Casey Cudbury (CBFO) concurred. There was one small <sup>dent</sup> <del>dent</del> in the bottom oriented close to the vent port.
1657	pro	Operator took digital stills of the inside of the ICV cavity and the ICV lid.

Date 1/28/03 Shift D 700-1100 Engineer BHO Brian  
K. E. Archibald.

Time	Initial	Comments/Notes/Observations
1702	bho	Stopped Tape #5, started tape #6
1705	bho	there are a few dark spots a little bit above the weld line. There are also a few grinder marks on the welds.
1707	bho	Verified w/ SS that RCT's resumed ICV lid as it was lifted from the ring stand.
1730	bho	00:27:10 on Tape #6. Video'd outside of ICV, prior to dropping it in the disposal box. Nothing special noted.
1757	bho	The OCV lid was replaced on the OCV. The inside of the lid was not recovered as it previously surveyed clean upon removal.
1810	bho	Plastic sheeting was placed on the OCV Lid in preparation for removal from the hot shop. tape time = 01:07:~ hrs
1813	bho	Tape stopped (#6.). 4-screen / split screen tape # 2ss stopped @ 01:58 hrs run time.

## TRUPACT-157 Examination Engineer 'sLog

#11 p10

Date 1/29/03 Shift 0700-1900 Engineer KE Archuleta  
B H O'BRIEN

Time	Initial	Comments/Notes/Observations
9:26	ka	THE REMOVAL OF THE OCV. SMOGAS ARE BEING TAKEN ON THE TOP OF THE OCV CID.
10:04	ka	THE OCV WAS MOVED TO THE HOT SHOP OUTSIDE THE HOT SHOP AREA. THERE WERE SEVERAL SMOAS TAKEN WHEN THE OCV WAS MOVED.
10:26	pno	stopped tape #7 tape = 1:12 hrs
11:10	pno	Casey Gadbary asked for still photos of the payload e-mailed to Kerry Watson at CPFD prior to payload disassembly. Pictures were taken of the video image of the tent <sup>video</sup> camera inside the tent with the still camera and sent to him.
11:29	pno	01:25 hrs tape time. Stayed SWB's in Hot shop. Stopped tape for lunch.
12:23	ka	TAPE IN CONFERENCE ROOM WAS STARTED.
12:34	pno	Tape #3 split screen started later than previous note. @ 12:34. pno

TRUPACT-157 Examination Engineer 'sLog

1644  
12 p.m.

Date 1/28/03 Shift 0700-1900 Engineer K.G. Archibald  
BOB BROWN  
J.M. LACY

Time	Initial	Comments/Notes/Observations
		pnw 2-28-03
1252	pnw	SWB Hs) Starting from east are 1) <del>IDRF</del> IDRFXWBD30001, 2) ... 30002, 3) ... 30003, as viewable from the video cameras. Cannot see the westernmost 3 yet.
1301	pnw	Stopped tape #7, 1:55:45 hrs. Started tape #8.
1341	JML	READ LOG SHEETS 1:27:03 700AM THRU CURRENT
1408	pnw	Clarification for previous notes on loss of video. This was due to the breakers in the Hot shop tripping. This was resolved by swapping some equipment to different circuits.
1418	pnw	SWBs are staged ready for accepting drums. Shut off videotape while crew is on break. Run time 1:15 hrs
1428	pnw	IN regards to note at 12:52, the operator moved the tape & plastic on the westernmost 3 drums so we can see the SWB Hs from the cameras. These are 4) IDRFXWBD30004, 5) IDRFXWBD30005, and 6) IDRFXWBD30006.

## TRUPACT-157 Examination Engineer's Daily Log

Date 1/29/03 Shift 0700-1900 Engineer B.M.O. Brian, K.E. Archibald,  
J. M. Hacy

Time	Initial	Comments/Notes/Observations
1444	BMO	Tape #4 split screen was started.
1501	BMO	Restarted tape #8.
1520	BMO	Regarding entry on 1/28/03 17:57 pg 10.- the RCT's say the <u>did</u> survey the underside of the DCA lid, when I asked late last night (1/28/03).
1528	JML	PACK ROTATED, VIDEO AND STILL PHOTOS TAKEN
1532	JML	PAYLOAD ROTATED FURTHER 120° - VIDEO (STILL PHOTOS TAKEN
1545	JML	BEGIN REMOVING SHRINK WRAP FROM PAYLOAD AND REMOVE TOP SLIP SHEET.
1546	JML	REMOVE TAPE 8 AT 15:46 - REPLACE WITH TAPE 9 BEGIN TIME 1546.
1550	JML	NO OBVIOUS DAMAGE TO DRUM TOPS OR FILTERS WE NOTE SOME LIDS ARE CONCAVE.
15:56	JML	SMEAR SAMPLES OF DRUM 1 (IDRF004102263) DRUM LID APPEARS CONCAVE - NO ISSUES OR CONCERNS NOTED
1621	JML	DRUM IS CLEAN - MOVING OUT OF TENT
1630	JML	DRUM SURVEY PRIOR TO PLACEMENT IN SWD OCCOUNT ON MASLIN
1639	JML	LIFT DRUM IDRF004002801 (Pos 3) (6. exam)

pg 14

TRUPACT-157 Examination Engineer's Daily Log

Date 1-29-03 Shift 0700-1900 Engineer JML LACY  
BH O'BRIEN  
KE ARCHIMED

Time	Initial	Comments/Notes/Observations
1647	JML	SURVEYS COMPLETE, BEGIN INSPECTION (2801)
		NO RUST OR DAMAGE EXCEPT SOME WEAR LOWER ROLL
		HOOP. LOCK RING : FILTER RESULTS BACK CLEAN, LID IS
		DOWN. LOCK RING BOLT : FILTER ARE SECURE.
		SWEPP OPP. ASSESSMENT GOOD.
1658	JML	SMEARS CLEAN - DRUM MOVING OUT OF TENT.
1643	JML	(SS) (SS) JML 3.3.03 TAPE 4 OUT, TAPE 5 IN (SPLIT SCREEN - JML)
1714	JML	2801 INTO SWB 30001
1717	JML	DRUM IDRF004101890 BEGIN SMEARS
1728	JML	1890 - SMEARS OK, FILTER, LOCKRING SECURE.
<del>1737</del>	JML	LID IS UP. DRUM IN GOOD CONDITION
1737	JML	Count 1 dpm α - DRUM LEAVING TENT
1745	JML	Maselin swipes complete - DRUM INTO SWB 30001
1747	JML	DRUM IDRF004102254 POLLED FROM PACK
1800	JML	FILTER : LOCK RING CLEAN : SECURE, SWEPP
		OP EVAL GOOD. DRUM LID UP
1808	JML	SURVEY COMPLETE - NO CONTAMINATION - MOVING OUT
		OF TENT.
1815	JML	Maselin SURVEY COMPLETE - DRUM INTO BOX 30001
		STOP FOR THE DAY



TRUPACT-157 Examination Engineer's Daily Log

Date 1/30/03 Shift 0700-1900 Engineer B. M. O'Brien  
J. M. Lally

Time	Initial	Comments/Notes/Observations
8:00	JML	BHO: JML ATTENDED DAILY BRIEF AND PRE-JOB MTGS. WORK WENT WELL 1-29, WITH COMPLIMENTS ALL AROUND, SO WORK WILL CONTINUE TODAY WITHOUT SIGNIFICANT MODIFICATION.
8:23	JML	OF JML 3-3-3 JML 3-3-03 TAPES FOR SPLIT SCREEN <del>RENUMBER</del> NUMBERS MODIFIED WITH ADDITION OF "SS" TO NUMBERS
8:35	JML	TAPE 11 STARTED
8:36	JML	TAPE 6 SS STARTED
8:50	JML	REF JML 3-3-03 DRUM ID#004002790 LIFTED FROM PAYLOAD
8:58	JML	FILTER, LOCK RING SMEARS CLEAN, SECURE, SWEEP UP ASSESSMENT SATISFACTORY
9:08	JML	NOTE SOME PAINT CHIPS LEFT ON SLIP SHEET ALSO EVIDENCE OF MOISTURE - CURRENTLY DRY ON SURFACE - THIS IS MIDDLE SLIP SHEET
9:10	JML	SWIPE ASSESSMENT - DRUM IS CLEAN - MOVING OUT OF TENT
9:20	JML	DRUM INTO SWB ID#FXWB030002
9:22	JML	JML 3-3-03 LIFT DRUM 4#2070 ID#F741202088 FROM PAYLOAD. TOP NOTED CONCAVE, RUST ON SIDE NEAR BOTTOM HEAD - MINOR. BOTTOM CLEAN.
9:33	JML	FILTER, LOCKING, CLEAN, SECURE, SWEEP UP ASSESS ACCEPTABLE

pg 16

# TRUPACT-157 Examination Engineer's Daily Log

Date 1-30-03 Shift 0700 → 1900 Engineer JM LALY  
BH O'BRIEN

Time	Initial	Comments/Notes/Observations
9:33 cont'd	JML	MISSED VIDEO RECORD OF FILTER, LOCKRING CHECK REPORTED SECURE BY FOREMAN
9:42	JML	SURVEYS ALL BELOW LIMITS - DRUM MOVING FROM TENT.
9:50	JML	DRUM INTO SWB 30003
9:52	JML	DRUM IDRF741202484 LIFTED FROM PAYLOAD DRUM APPEARS IN BRAND NEW CONDITION BOTTOM SHOW PAINT RUNS - NOT MOISTURE OR DAMAGE.
10:02	JML	DRUM LID SURVEY 27.7 DPM & ADDITIONAL SMEARS OF LID AND FILTER TAKEN
10:20	JML	2 <sup>nd</sup> Smears Filter 55, LID <sup>1236 JML 3-3-03</sup> 42 and 39 dpm these are in-shop prelim. LID WILL BE SPRAYED WITH FIXATIVE AND BAGGED
1033	BHO	Fixative sprayed on top. Filter was re checked and is tight,
1035	BHO	The lock ring bolt is slightly loose and the lock nut <sup>same BHO, BHO 3/5/03</sup> was loose. <del>was</del> Jam Nut
10:35	JML	SPLIT SCREEN TAPE 6 STOPPED, TAPE 7 STARTED
10:38	JML	TAPE 11 STOPPED, TAPE 12 <sup>JML - 3-3-03</sup> STARTED JML PLACED AND PAUSED

p2 17

TRUPACT-157 Examination Engineer's Daily Log

Date 1-30-03 Shift 0700-1900 Engineer J. MALACY  
DH O'BRIEN

Time	Initial	Comments/Notes/Observations
10:40	JML	INSPECTION COMPLETE, CONTINUE DRUM BAGGOUT
10:45	JML	TAPE 12 STARTED
10:54	JML	DRUM BAGGED AND TAPED
10:57	JML	OBTAINED RADIO TO MONITOR COMMS - PREVIOUS TO THIS HAVEN'T HAD DIRECT ACCESS TO RADIO TRAFFIC
11:01	JML	FOREMAN SHOWED THAT LOCKRING CAN BE ROTATED BY HAND. <sup>JML-33-03</sup> <del>STOOD</del> SEE TAPE 12, DRUM IN SWB 30003, CREW WILL BREAK.
11:04	JML	TAPE 12 STOPPED @ 17min 48 sec
11:05	JML	STICKY ROLLER WITH DEBRIS FROM SLIP SHEET MOVED FROM PAYLOAD AREA
11:06	phw	Tape 12 was restarted as the roller was passed out of the drum inspection room smear port.
11:10	phw	Tape 12 stopped again. 00:23 hrs run time
12:50	JML	TAPE 7SS PAUSE 1147 - RESTART 1250 (SHOULD BE CHANGED in 50min 1340)
12:54	JML	TAPE 12 RESTARTED
12:56	JML	OPERATIONS RESTARTED
1300	JML	SLIP SHEETS, SHRINKWRAP REMOVED FROM LOWER PAYLOAD

ps 18

# TRUPACT-157 Examination Engineer's Daily Log

Date 1.30.03 Shift 0700 - 1900 Engineer JM LACY  
BH O'BRIEN

Time	Initial	Comments/Notes/Observations
1:00	JML	continued ALL ARGONNE-STYLE FILTER GASKETS HAVE
		SIMILAR LOOK TO 1ST.
1:05	JML	LIFTED DRUM IDRF 741205405
1:08	JML	1 DRF 074700411 JML 3.3.03 OBSERVE <del>IDRF 074700411</del> JAMB NOT NOT TIGHT
		LOCK RING SPACING APPEARS SIMILAR TO PREVIOUS
1:16	JML	DRUM TOP SURVEYS BELOW LIMITS, FILTER
		JML 3.3.03 AND LOCK RING SEAR SECURE, CONTAINER
		INTEGRITY ACCEPTABLE. LARGE DENT PREVIOUSLY
		WIPP - APPROVED
1324	JML	DRUM SURVEY ACCEPTABLE - MOVING DRUM OUT OF
		TENT
1332	JML	MASECIN SURVEY COMPLETE - DRUM MOVED INTO
		SWB 30003
1335	JML	DRUM IDRF 741201615 LIFTED FROM PAYLOAD
1337	JML	STICKY ROLLER SURVEY OF BOTTOM SLIPSHEET
		FROM TOP PAYLOAD WITHIN LIMITS
1348	JML	SURVEYS OF FILTER, LOCKING CLEAN, BOTH ARE
		SECURE.
1350	BHO	Surveys are complete of drum. Levels
		are within limits.
1353	JML	TAPE 7SS REMOVED TAPE 8SS STARTED

BHO  
2/28/13

ps 19

TRUPACT-157 Examination Engineer's Daily Log

JM LACY

Date 1-30-03 Shift 0700-1900 Engineer BH O'BRIEN

Time	Initial	Comments/Notes/Observations
1405	JML	MASELIN SURVEY ACCEPTABLE, DRUM INTO BOX 30003
1408	JML	LIFT IDRF074700411 FROM PAYLOAD
		LID IS DOMED UP (NORMAL) EVIDENCE OF RAIN JML 3-3-03 OR MOISTURE ON <del>TOP</del> LID SURFACE, JAMB NOT VISIBLY LOOSE, FILTER APPEARS OK, DRUM AS NEW.
1420	JML	SURVEYS ON TOP ARE COMPLETE, ACCEPTABLE
1425	JML	FILTER SECURE, 2 ROTATIONS OF BOLT, DRIVING JAMB NOT TO SEAT. SLEPP OP ASSESSMENT OK.
1428	JML	DRUM SURVEY OK - DISCUSSION CAN DRUM BE MOVED WITH LOOSE BOLT? → DRUM WILL BE BAGGED
1430	JML	TAPE 12 REMOVED, TAPE 13 STARTED
1435	JML	<u>CORRECTION</u> BOLT TIGHT - MOTION WAS ON THE JAMB NUT. BOX WILL BE MOVED TO SWB0006 SW CORNER
1447	JML	MASELIN COMPLETE - DRUM INTO SWB
1448	JML	DRUM IDRF741201718 LIFTED FROM PAYLOAD LID IS UP, LIKE NEW CONDITION, FILTER APPEARS SECURE, SOME VERY SMALL DENTS OBSERVED.
1458	JML	TOP SMEARS BELOW LIMITS - LOCK RING CLEAN & SECURE

TRUPACT-157 Examination Engineer's Daily Log

Date 1-20-03 Shift 0700 - 1900 Engineer JMLACY  
BH O'BRIEN

Time	Initial	Comments/Notes/Observations
1508	JML	DRUM SURVEYS ACCEPTABLE - MOVING OUT OF TENT DRUM INTO BOX 0004, SW CORNER
1515	JML	OP BREAK FOR LUNCH
1518	JML	TAPE 13 PAUSED 46 min on tape
1518	JML	TAPE 8SS PAUSED WITH 1HR 25min out tape
1632	JML	TAPE 8SS RE-STARTED @ 1630 - NEED TO CHANGE TAPE AT 1705
1633	JML	OPERATIONS RE-STARTED
1635	JML	DRUM IDRF741204650 LIFTED FROM PAYLOAD LARGE-ISH DENT ON UPPER ROLL RING - NOT SERIOUS, ONLY VISIBLE DENT, BOTTOM IS GOOD
1642	JML	TOP SMEARS OK, FILTER, LOCK RING ARE SECURE SWEPP OP ASSESSMENT OK
1645	JML	TAPE <sup>JM 3.3.03</sup> <del>12</del> 13 RE STARTED - REPERFORM VIDEO AND FILTER CHECK
1652	JML	VIDEO EXAM COMPLETE
1653	JML	DRUM SMEARS BELOW LIMITS, DRUM MOVING OUT OF TENT
1704		DRUM IN SWB 0004, MASELIN COMPLETE

pg 21

TRUPACT-157 Examination Engineer's Daily Log

Date 1/30/03 Shift 0700-1900 Engineer B.M. O'Brien  
J. M. Lacy

Time	Initial	Comments/Notes/Observations
1709	JML	074 JML 3.3.03 DRUM IDRF <del>704</del> 700394 LIFTED OFF PAYLOAD DRUM IN GOOD CONDITION
1716	JML	SMEAR RESULTS FROM TOP OK, FILTER, LOCK RING SECURE, DRUM INTEGRITY OK, &
1719	JML	ONE SMALL DENT ON SIDE NOTED. NO OTHER DAMAGE
1723	JML	DRUM SURVEYS BELOW LIMITS - MOVING OUT OF TENT AFTER CAM AIR FILTER CHANGED
1738	JML	MASELIN SURVEY COMPLETE, DRUM INTO SUB0006
1740	JML	DRUM IDRF 074221338 (FINAL DRUM) LIFTED INTO INSPECTION AREA
1750	JML	TOP SMEARS BELOW LIMITS, FILTER, LOCK RING SECURE, SWEEP OF ACCEPTABLE (THO RUSTY) QUITE A BIT OF RUST OVER SIDES AND NEAR BOTTOM RIM, NO SIGNIFICANT DENTS, THO SEVERAL SMALL ONES
1759	JML	DRUM SURVEYS BELOW LIMIT, MOVING OUT OF TENT
1804	JML	TAPE 13 STOPPED TAPE 14 STARTED
1807	BHO	Last Drum <sup>put</sup> in SWB IDRF XWB 030003
1810	BHO	Tape 14 stopped <sup>map</sup> . Run time = 00:07 hrs:min.
1816	JML	LATE ENTRY TAPE 8SS STOPPED, TAPE 9SS STARTED AT 1705

TRUPACT-157 Examination Engineer's Daily Log

Date 1.31.03 Shift 0700-1900 Engineer JM LACY  
BH O'BRIEN

Time	Initial	Comments/Notes/Observations
1815	pro	Restarted Tape #14. Tape time = 00:06:40
0819	JML	Tape 1055 SPLIT SCREEN STARTED
0818	JML	TID # <del>963</del> <sup>JML-3.3.03</sup> 3963! TID ON BAGGED
		DRUM 1DRF741202484
0847	JML	CONDUCTED VISUAL EXAM OF BOTTOM SLIP PLATE
		OF LOWER 7-PACK. EVIDENCE OF MOISTURE,
		SOME DEBRIS.
0901	JML	DUNNAGE DRUMS! NUMBER VISUALLY INSPECTED
		ON VIDEO
0905	JML	SOME WATER IN DUNNAGE DRUMS - REMOVING
		LIDS - DUN. DRUMS WERE STORED OUTDOORS
0909	pro	pro Dunnage drums were stored
		w/o the bungs in.
0915	pro	The water was poured out of the
		drums #5 & 6
		(IN DUNN 800008 IN DUNN 800006).
0919	pro	Workers out of the ship. Tape #14
		stopped. Run time = 01:10:31.
0920	pro	Turned off tape 1055 off. Run time =
		01:03:11.
0958	JML	TAPE 14 ON



pg 23

# TRUPACT-157 Examination Engineer's Daily Log

Date 1-31-03 Shift 0700 - 1900 Engineer JML LACY  
BHO'BRIEN

Time	Initial	Comments/Notes/Observations
1005	JML	TAPE 10SS ON
1051	JML	TAPE 14 STOP
1053	JML	TAPE 15 START
1113	JML	TAPE 11 SS STARTED (TAPE 10SS OUT)
1121	JML	TAPE 15 STOP 00:28 ON TAPE
1123	JML	TAPE 11SS STOP 00:10 ON TAPE
1243	JML	LATE ENTRY - PRIOR TO LUNCH (11:30) DAMAGED SECTIONS OF GASKET ON SWDS 2 & 4, BOTH ON THE WEST SEMICIRCULAR SIDE, WERE REPLACED WITH NEW GASKET MATERIAL
1252	βho	Tape 15 restarted. run time = 00:28
1254	JML	TAPE 11SS RESTART
1304	JML	2 DUNNAGE DRUMS REMOVED FROM SWB 2 FOR WATER INSPECTION - UNCLEAR FROM VIDEO WHETHER ANY WATER PRESENT
1307	JML	DRUMS RETURNED TO SWB 2 (Dunnage - βho)
1315	βho	All dunnage drums in SWB 2, 4, 5, 6.
1337	βho	Tape 15 stopped. run time 01:08. Tape 11SS stopped at 13:27.
1343	pro	Tape 15 restarted.
1344	pro	Tape 11SS stopped & restarted. βho 3/3/03

βho 12/24/03

## TRUPACT-157 Examination Engineer's Daily Log

Date 1/31/03 Shift 0700-1900 Engineer B. H. O'Brien  
J. M. Lacy

Time	Initial	Comments/Notes/Observations
1422	pmo	SWB #1, 2, 4, 5 & 6 drum lids are on. Mechanics are installing the bolts on them now.
1436	pmo	Tape #15 stopped run = 02:00. Tape #16 started.
1449	pmo	Torque wrench broke. Tape off at run time 00:12 on tape.
1451	pmo	Tape #1155 stopped run time = 01:47.
1455	pmo	Reviewed digital stills of TID on drum 1DRF741202484, photo MVC-861X.JPG. It is stamped ANL-W 3963.
1552	pmo	Restarted tape #16
1706	pmo	Operations found another torque wrench, finished bolting the SWB Lids (except no lid on #3) and moved them to the Warm Shop next door. The SWB's were smeared before they were moved out. SWB #3 remains in the TAN Hot Shop w/o a lid.
1713	JML	<sup>JML 3:3:03</sup> <del>First</del> <del>5</del> ALL BUT BVD3 ARE MOVED OUT OF HOT SHOP AND INTO WARM SHOP, WHERE THEY WILL STAY FOR THE WEEKEND.
1715	pmo	Tape #16 stopped.

pg 25

TRUPACT-157 Examination Engineer's Daily Log

Date 2/3/03 Shift 1200-1900 Engineer B.H. O'Brien

Time	Initial	Comments/Notes/Observations
1257	BHO	Read DAR to TPR-6233 (DAR 98552)
1257	BHO	Re-read previous log entries
1257	BHO	OCV on trailer is hooked up and will be transported to RUMC today.
1310	BHO	SWB #7 was moved into the hot shop and Labeled.
1314	BHO	Operators put shrink wrap on the hot ship crane hook to keep it from contaminating the rigging.
1339	BHO	Gasket put on SWB #7 (IDRF XWB 030007)
1346	BHO	Drum IDRF 741202484 removed from box SWB #6 (IDRF XWB 030006) and put it in the NE corner of SWB #7. <del>RCT's</del> RCT's measured rad levels at the drum as it was pulled out, and remeasured the bottom of the bagged drum.
1400	BHO	3 damage drums are now in SWB #7.
1423	BHO	The Lid is on and bolts torqued on SWB #7.
1424	BHO	Bob Miklos says the bag around drum IDRF 741202484 was <u>not</u> slit for shipment since it will not begin to wrapp on is.

BHO 2/28/03

TRUPACT-157 Examination Engineer's Daily Log

pg 26

Date 2/3/03 Shift 1200-1900 Engineer B. H. D' Brian

Time	Initial	Comments/Notes/Observations
1429	pno	Lid was set on IDRFXWB03003 <sup>30003 pno</sup> after <sup>pno 2/2/03</sup>
1449	pno	a dunnage drum was added to the SWB. The lid has been torqued on SWB IDRFXWB030003. <del>Tape run</del> pno pno 3/3/03
1450	pno	Tape #17 run time = 01:46
1500	pno	Both SWB's were smeared by RCT's in preparation for removal from the Hot Shop.
1504	pno	Tape #17 run time = 02:00 hrs.
1507	pno	Late entry, Tape #17 started at 1304 hrs
1507	pno	Tape #18 started. <del>pno</del> ← pno 2/28/03
1509	pno	Tape #18 started.
1510	pno	<del>pno</del> pno 2/28/03
1511	pno	Both SWB's were moved out of the hot shop into the extension.
1513	pno	Late entry, Tape #17 was stopped at 1507 hrs RCT's took rad readings on SWB IDRFXWB030003.
1518	pno	<del>pno</del> Tape #18 stopped. Run time = 00:09:49.
1524	pno	The wooden box with the ICU, box #522163, was loaded on the trailer this morning.

Date 2/5/03 Shift 120-190 Engineer B.M. J. Brian

Time	Initial	Comments/Notes/Observations
1545	pno	Took still digital pictures of the ICV box on the trailer.
1551	pno	SWB 1DRFXWB030007 was placed on the trailer with the ICV box.
1628	pno	S.S. had a carpenter check the height of the ICV box on the trailer to make sure it would fit under the pipe rack at (TAN?). pno 2/28/03
1654	pno	The other six SWBs are loaded on the trailer. Order (front to back) is SWB 1DRFXWB 030003, 030006, 030004, 030002, 030001, 030005.

Last pz pmo 2/14/03

## 1. TRUPACT 157 EXAMINATION CHECKLIST FOR ENGINEER'S LOG

This checklist is per the information to record as specified in PLN-1169. The purpose of the checklist is to ensure that all items specified in the plan are implemented.

The examining engineer is to initial each item completed or N/A if applicable. Any additional notes and comments shall be placed in the Engineer's log sheets. Any N/A'd items shall have an accompanying note placed on the daily comment sheet.

### 1.1 General Information on Video Recordings

Video recordings are not required to be operating 100% of the time, but will be taken during major operation sequences where feasible as indicated in this plan. The video recording will include date and time if practicable. Video recording may be taken during other activities as directed by project supervision. Audio recordings may be made during the evolutions if practicable .

### 1.2 General Information to Record

The purpose of the examination plan is to provide the basis for the disassembly of the contaminated payload in TRUPACT-157 and collect information for preparation of a final report on the as-found conditions during the disassembly operation. The operations will be directed by TAN operating procedures.

The examination data will include:

- Data recorded as part of operations procedures
- Radiological surveys to support determination of contamination release and the extent of contamination spread and type of contamination found.
- An engineer's log of physical observations supporting determination of position and as-found conditions of drums, lids, filters, etc.
- Videotape recording during major operation sequences. At other times, such as when conditions of interest are found, recording will be as directed by the Job Supervisor. Audio recordings may be made during the evolutions if practicable.
- Photographic documentation of key findings/observations will be indexed to a specific drum number.
- Documentation of as-found conditions of interest that might indicate the failure mechanism, such as:
  - Filter or Lid Loosening:
    - Filters all in place
    - Hand-tightness of filters and lock-chines
  - Drum lid popping during pressure cycles:

- Drum lid shape – domed up or down
- Evidence of drum lid paint cracking or flaking
- Crash Impact or Rumble Strip Effects:
  - Evidence of motion between the ICV and OCV such as crushed foam spacer, gaps, or ICV off-center in the OCV
  - Evidence of motion between the package and ICV such as scuffs or marks on the ICV at drum height, package off-center, or torn or worn plastic wrap
  - Wear pattern on the ICV floor
  - Dents or flat spots around the drum heads
  - Any indentation, or buckling and depth measurements of any dents found
- Rust-Through or Leak:
  - Moisture or condensate on the outside of the drums or inside of the ICV
  - Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - Rust on drums

*paper  
Copied video  
obtained*

## 2. EXAMINATION CHECKLIST

### 2.1 Information to Record for the OCA

- ✓ • Date 1/27/03 Init psw Video documentation of OCA processing
- ✓ • Date 1/27/03 Init psw Pre-operational <sup>Nothing above</sup> external surveys of the Hot Shop
- ✓ • Date 1/27/03 Init psw Installation of OCA protective sheeting for protection from contamination
- ✓ • Date 1/27/03 Init psw Removal of the OCA lid

### 2.2 Information to Record before Payload Removal

- Date 1/28/03 Init psw Video of containment systems used to contain contamination prior to and during ICV lid removal and payload removal
- Date 1/28/03 Init psw Airborne contamination surveys of the inside of the ICV
- Date 1/27/03 Init psw Video documentation of ICV lid removal process. The ICV should be opened using extended lock ring handles if possible. If vacuum on the ICV is required to remove the lid, the vacuum should be relieved slowly to minimize disturbance inside.

- Date 1/27/03 Init pmo Radiological surveys under ICV lid.
- Date 1/28/03 Init pmo Decision was made not to add fixative. Fixatives should be used only if absolutely necessary to protect the health and safety of the workers since they will affect the results of the examination. If fixation materials are required by Radiological Engineering to control airborne contamination, an attempt should be made to survey the inside of the ICV prior to application of the fixative since the fixative will attenuate alpha contamination. This survey is desirable for determination of TRU content on the ICV for disposition. *low/no* *Con* *Smears* *an airborne sample.*
- *NA* Date 1/28/03 Init pmo If fixatives are used, documentation, written and video, of application of any contamination fixation materials applied to control contamination spread or release.
- Date 1/28/03 Init pmo Video documentation and radiation surveys and smears following lid removal
- Date 1/28/03 Init pmo Radiological surveys of accessible surfaces of payload

### 2.3 Information to be Recorded During Payload Disassembly

- Date 1-29-03 Init pmo Photos of payload before any disassembly from top, and at each 120 degrees of rotation so that all drum exteriors on the assembled payload are documented
- Date 1-29-03 Init pmo Video of opening of payload shrink wrap and removal of each 7-pack slip-sheet
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video and photographs of the top of the 7-pack prior to removal of any individual drums.
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of removal of the guide tubes from the payload assembly
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of the removal of each individual drum from the 7-pack
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of 360-degree rotation of individual drum to examine sides and bottom
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date \_\_\_\_\_ Init \_\_\_\_\_ Radiological surveys of individual drums to determine contamination levels
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of hand checking of filter tightness

See page for  
an individual  
drum  
pmo  
1/29/03



PS 4

**TRUPACT-157 Examination Engineer's Log**

Drum # 1DRF004102263 <sup>JML 3.3.03</sup> ~~1DRF004102263~~ Position # 2

- Date 1-29-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-29-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-29-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-29-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-29-03 Init JML Video of hand checking of filter tightness
- Date 1-29-03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - DN Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - Yes - Noted by obs team - minor Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - Minor Rust on drums
- Information to Record During Drum Repackaging
- Date 1-29-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-29-03 Init JML Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init JML Video of bags around drums in the overpacks.
 

*SWB: 1DRFXWB030001*

*No Bag - BTW pms 2/28/03*

*Since no contamination on drum.*

## TRUPACT-157 Examination Engineer's Log

Drum # 1DRF004102254 Position # 1

- Date 1-29-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-29-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-29-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-29-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-29-03 Init JML Video of hand checking of filter tightness
- Date 1-29-03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - DP Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1-29-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-29-03 Init JML 1DRFXWB030001 Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init JML No Bag - saw Video slitting of bags around drums in the overpacks.  
Since no contamination on drum

P2 6

TRUPACT-157 Examination Engineer's Log

Drum # IDRF004002801 Position # 3

- Date 1-29-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-29-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-29-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-29-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-29-03 Init JML Video of hand checking of filter tightness
- Date 1-29-03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - DN Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1-29-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-29-03 Init JML Documentation of drum numbers and associated overpack number. SWB # IDRFXWB030001
- Date 1/31/03 Init BN Video slitting of bags around drums in the overpacks. No Bag  
Since No Contamination on drum.

PJ 7

# TRUPACT-157 Examination Engineer's Log

Drum # 1DRF004101890 Position # 4

- Date 1-29-03 Init JMC Video of the removal of each individual drum from the 7-pack
- Date 1-29-03 Init JMC Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-29-03 Init JMC Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-29-03 Init JMC Radiological surveys of individual drums to determine contamination levels
- Date 1-29-03 Init JMC Video of hand checking of filter tightness
- Date 1-29-03 Init JMC Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1-29-03 Init JMC Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-29-03 Init JMC Documentation of drum numbers and associated overpack number. SLB 1DRFXWB03004
- Date 1/31/03 Init BM Video ~~slitting~~ Mo Bag BM of bags around drums in the overpacks.   
Since No Contamination on drum

p2 J

# TRUPACT-157 Examination Engineer's Log

Drum # 1DRF004002790 Position # 5

- JML 3.3.03

Date 1.30.03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1.30.03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1.30.03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1.30.03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1.30.03 Init JML Video of hand checking of filter tightness
- Date 1.30.03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape - domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - MINOR JML 3.3.03  
N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1.30.03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1.30.03 Init JML SLWB 1DRFXWB 030002  
Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init JML No bag - JML  
Since No Contamination on drum  
Video slitting of bags around drums in the overpacks.

## TRUPACT-157 Examination Engineer's Log

Drum # 1DRF741202484 Position # 6

- Date 1-30-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init JML Video of hand checking of filter tightness
- Date 1-30-03 Init JML LOOSE - The gap was small Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape – domed up or down
  - NO Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1-30-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-30-03 Init JML 30003 Documentation of drum numbers and associated overpack number.
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video slitting of bags around drums in the overpacks.

The bag was not slit. Bob Miklos said the drum will be re examined prior to shipment to WEP. The drum is in SWBH 1DRFXWB030007. - BKO/pmj 2/3/03

p210

# TRUPACT-157 Examination Engineer's Log

Drum # IDRF 741202088 Position # 7

- Date 1-30-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date \_\_\_\_\_ Init No Video of hand checking of filter tightness
- Date \_\_\_\_\_ Init No Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - DN Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - Y - MINOR Rust on drums
- Information to Record During Drum Repackaging
- Date 1-30-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC. IDRF XWB030003
- Date 1-30-03 Init JML Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init JML Video ~~slitting~~ no bag since no of bags around drums in the overpacks. contamination found.  
- JML

## TRUPACT-157 Examination Engineer's Log

Drum # 1DRF741205405 Position # 8

- Date 1-30-03 Init Jm Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init Jm Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init Jm Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init Jm Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init Jm Video of hand checking of filter tightness
- Date 1-30-03 Init Jm Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - Yes Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1-30-03 Init Jm Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-30-03 Init Jm <sup>1DRFXW030003</sup> Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init Jm <sup>No Bag since</sup> Video ~~slitting~~ of bags around drums in the overpacks.  
<sup>No contamination found - Jm</sup>



# TRUPACT-157 Examination Engineer's Log

Drum # 1DRF741201615 Position # 9

- Date 1-30-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init JML Video of hand checking of filter tightness
- Date 1-30-03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - DN Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1-30-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-30-03 Init JML 1DRFXWBO30003 Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init JML Video ~~slitting of bags~~ around drums in the overpacks.  
 Since no contamination found on drum — for for 2/28/03

# TRUPACT-157 Examination Engineer's Log

Drum # IDRF741201718 Position # 10

- Date 1.30.03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1.30.03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1.30.03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1.30.03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1.30.03 Init JML Video of hand checking of filter tightness
- Date 1.30.03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - N Dents or flat spots around the drum heads
  - N Any indentation, or buckling and depth measurements of any dents found
  - N Moisture or condensate on the outside of the drums or inside of the ICV
  - N Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - N Rust on drums
- Information to Record During Drum Repackaging
- Date 1.30.03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1.30.03 Init JML Documentation of drum numbers and associated overpack number. IDRFXJ030004
- Date 1/31/03 Init pmo Video ~~slitting of bags around drums in the overpacks.~~  
 No bag since no contamination found on drum — pmo pmo 1/28/03

TRUPACT-157 Examination Engineer's Log

074221338

Drum # 1DRF74221338 Position # 11

- Date 1-30-03 Init JM Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JM Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JM Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JM Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init JM Video of hand checking of filter tightness
- Date 1-30-03 Init JM Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - DN Drum lid shape – domed up or down
  - Yes - Rust ONLY Evidence of drum lid paint cracking or flaking
  - No Dents or flat spots around the drum heads
  - No Any indentation, or buckling and depth measurements of any dents found
  - No Moisture or condensate on the outside of the drums or inside of the ICV
  - No Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - Yes Rust on drums
- Information to Record During Drum Repackaging
- Date 1/30/03 Init bm Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1/30/03 Init bm Documentation of drum numbers and associated overpack number. 1DRFXWB030005
- Date NA Init No bag Video slitting of bags around drums in the overpacks. Since No contamination found on drum. - bm

ps 15

TRUPACT-157 Examination Engineer's Log

Drum # 1DRF074700394 Position # 12

- Date 1-30-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init JML Video of hand checking of filter tightness
- Date 1-30-03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape – domed up or down
  - No Evidence of drum lid paint cracking or flaking
  - No Dents or flat spots around the drum heads
  - No Any indentation, or buckling and depth measurements of any dents found
  - No Moisture or condensate on the outside of the drums or inside of the ICV
  - No Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - No Rust on drums
- Information to Record During Drum Repackaging
- Date 1-30-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-30-03 Init JML 1DRFXWB030006 Documentation of drum numbers and associated overpack number.
- Date 1/31/03 Init pbw Video ~~slitting of bags around drums in the overpacks.~~ Since no contamination found in drum - photo 2/28/03

# TRUPACT-157 Examination Engineer's Log

Drum # 1DRF074700411 Position # 13

- Date 1-30-03 Init JML Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JML Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JML Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JML Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init JML Video of hand checking of filter tightness
- Date 1-30-03 Init JML Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):

- Y Filters all in place
- UP Drum lid shape – domed up or down
- N Evidence of drum lid paint cracking or flaking
- N Dents or flat spots around the drum heads
- N Any indentation, or buckling and depth measurements of any dents found
- N ~~Yes - dry drops on top~~ Moisture or condensate on the outside of the drums or inside of the ICV
- Yes - dry drops on top Spots left by dried liquid on the drums, ICV walls or ICV bottom
- N Rust on drums

JML 3-3-03

- Information to Record During Drum Repackaging
- Date 1-30-03 Init JML Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-30-03 Init JML Documentation of drum numbers and associated overpack number. 1DRF07470030006
- Date 1/31/03 Init BSN Video ~~slitting of bags~~ around drums in the overpacks.

No Bag since No Contamination found on drum - BSN - pro 2/28/03

p2 17

TRUPACT-157 Examination Engineer's Log

Drum # 1DRF741204650 Position # 14

- Date 1-30-03 Init JMC Video of the removal of each individual drum from the 7-pack
- Date 1-30-03 Init JMC Video of 360-degree rotation of individual drum to examine sides and bottom
- Date 1-30-03 Init JMC Video and photographs of the as-found condition of the top of each drum, including the vent filter and lid locking ring, paint on drum with close up pictures and video as necessary to identify conditions of special interest such as indentation, rust or buckling.
- Date 1-30-03 Init JMC Radiological surveys of individual drums to determine contamination levels
- Date 1-30-03 Init JMC Video of hand checking of filter tightness
- Date 1-30-03 Init JMC Video of hand checking of lock-chine tightness
- Video of As-Found conditions (Yes/No):
  - Y Filters all in place
  - UP Drum lid shape – domed up or down
  - N Evidence of drum lid paint cracking or flaking
  - NO Dents or flat spots around the drum heads
  - Yes Any indentation, or buckling and depth measurements of any dents found
  - NO Moisture or condensate on the outside of the drums or inside of the ICV
  - NO Spots left by dried liquid on the drums, ICV walls or ICV bottom
  - NO Rust on drums
- Information to Record During Drum Repackaging
- Date 1-30-03 Init JMC Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date 1-30-03 Init JMC Documentation of drum numbers and associated overpack number.

1DRFXW0030004 NE (JMC)  
NEW CORNER
- Date 1/31/03 Init fbm Video ~~slitting~~ of bags around drums in the overpacks.

No bag since no contamination  
found on drum - fbm  
2/28/03

## TRUPACT-157 Examination Engineer's Log

See page for each individual drum *pnw* 1/29/03

Date \_\_\_\_\_ Init \_\_\_\_\_ Video of hand checking of lock-chine tightness

**2.4 Information to Record During Drum Repackaging**

- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of drums removal from the payload.
- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of drums placement into a suitable overpack for return to storage at RWMC.
- Date \_\_\_\_\_ Init \_\_\_\_\_ Documentation of drum numbers and associated overpack number.

**2.5 ICV Examination and Reinstallation of Lid Following Payload Removal**

- Date 1/28/03 Init pnw Video examination of the internals of the ICV documenting as found conditions
- Date 1/28/03 Init pnw *No Fixations used - pnw 2/28/03*  
Documentation, written and video, of application of any contamination fixation materials (fixatives may affect ability to determine surface contamination of the payload and ICV)
- Date 1/28/03 Init pnw Radiological surveys of ICV internal documenting the extent of contamination for disposal information
- Date 1/28/03 Init pnw Radiological surveys of accessible surfaces of ICV and OCA following removal of any radiological contamination systems prior to removal of ICV from the OCA.
- Date 1/28/03 Init pnw Video of lid installation

**2.6 Information to Record During ICV Removal from OCA**

- Date 1/28/03 Init pnw Video of removal of ICV from OCA to show ICV external and OCA internal as-found conditions
- Date 1/28/03 Init pnw Radiological surveys of ICV external surfaces as ICV is extracted from the OCA
- Date 1/28/03 Init pnw Radiological surveys of OCA internal surfaces following ICV removal.

**2.7 Information to Record During OCA Lid Installation and OCA Removal from Hot Shop**

- Date 1/29/03 Init pnw Removal of OCA from TAN Hot Shop
- Date 1/29/03 Init pnw *→ performed on 1/28/03*  
Internal and external OCA surveys (outside of ICV, underside of OCA lid)

*underside of OCA lid was not resurveyed since it was previously surveyed clean - pnw Don Wiles & Kevin Steeper concurred.*

*Late entry - R-45 confirmed that smears of the underside of the OCA lid were taken. - pnw 1/29/03*

TRUPACT-157 Examination Engineer 'sLog

p2 20  
Last page - 300

- Date 1/30/03 Init pmw Video and documentation of all surveys of OCA (internal and external) during removal of contamination barriers for removal from the Hot Shop

- Date \_\_\_\_\_ Init \_\_\_\_\_ Video of OCA removal from the Hot Shop.

Duplicate  
check SA  
previous gr.  
pmw 1/30/03



**Appendix E**  
**Sequence of Operations and Equipment Used**



## **Appendix E**

### **Sequence of Operations and Equipment Used**

#### **Sequence of Events Prior to Recovery Operations**

August 23, 2002, Transuranic waste shipment IN020271 shipped from INEEL to WIPP

August 25, 2002, 1:30AM. Transport truck involved in collision with privately owned vehicle.

August 25, 2002, 6:30 a.m. Shipment arrived at WIPP and processing was begun.

Initial RAF sample drawn as part of receipt processing indicates elevated alpha contamination within ICV.

August 26, 2002. Three follow-up RAF samples were collected and counting begun. Samples indicated elevated airborne contamination within ICV.

August 28, 2002. TRUPACT-II 157 was resealed and returned to the INEEL.

August 29, 2002. Shipment arrived at RWMC and placed in storage.

October 10, 2002. Draft recovery plan submitted to DOE-ID.

October 11, 2002. DOE-ID letter of direction to proceed received by contractor.

October 17, 2002. Revision 1 of recovery plan issued.

December 2, 2002. Operational readiness review completed and approval to start operations received on schedule.

Early December. Issues developed with respect to obtaining regulatory permits to perform recovery operations.

December 24, 2002. DOE-ID issued direction to develop revised recovery plan by January 16, 2003.

January 16, 2003. Revised recovery plan issued.


January 23, 2003. DOE-ID contracting officer issued letter directing execution of recovery plan.

January 27, 2003. Readiness achieved for operations at TAN. TRUPACT-II arrives and recovery activities begin.

# TRUPACT-157 Recovery Operations

**January 27, 2003**

9:50 a.m. TRUPACT-157 was shipped from RWMC to the TAN Hot Shop on January 27, 2003, and placed in the TAN Hot Shop (Figure E-1).



PD03-0078-035

Figure E-1. TRUPACT 157 handling in the hot shop.

CBFO was contacted to clarify when a CBFO representative needed to be present for the recovery operation. Direction received from CBFO was for the representative to be present during payload removal.

10:21 a.m. Outer Containment vent port plug tamper indicating device was not intact. One wire had pulled out of the crimp seal. The tamper indicating device on the OCV lid lock ring bolt was still intact. Received WIPP direction to proceed.

13:07 p.m. Removed the OCV Lid (Figure E-2).




PD03-0078-03

Figure E-2. Removal of OCV lid.


- Installed sleeving on the ICV (see Figure E-3).





PD03-0078-006

Figure E-3. Sleeve installation on ICV.



PD03-0078-008

Figure E-4. Air sampling of ICV interior and payload.

- ICV lid lifted approximately 18" and air sampling performed on internal ICV atmosphere. Sampling performed for 15 minutes using calibrated pumps (Figure E-4).

4:20 p.m. Radiological smears of OCV and ICV are within allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1,000 dpm/100 cm<sup>2</sup> beta-gamma).

4:23 p.m. Air sampling results indicate only naturally occurring activity. Levels of contamination reported by WIPP are not seen at INEEL based on this initial sampling. Elevated radon levels in sample, compared to normal background, confirm that sample air was drawn from ICV interior.


6:00 p.m. Operations ceased until WIPP representative was onsite for payload removal sequence per direction from WIPP.



## January 28, 2003

8:35 a.m. Additional contamination surveys of ICV and accessible portions of payload. All radiological surveys are within allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1000 dpm/100 cm<sup>2</sup> beta-gamma).

12:22 p.m. TRUPACT-157 payload lifted from ICV and placed into radiological tent (Figure E-5).



PD03-0078-013

Figure E-5. Transfer of payload into tent.

4:32 p.m. ICV sleeving removed and lid reinstalled. ICV removed from OVA and packaged in box. Radiological surveys all within allowable limits. The inside of the ICV lid is shown in Figure E-6.

5:57 p.m. Outer Containment Vessel (OCV) surveyed and results within allowable limits. Lid installation completed.





PD03-0078-032

Figure E-6. Underside of ICV lid.

**January 29, 2003**

10:04 a.m. OCV removed from Hot Shop and reloaded onto transport trailer (Figure E-7).



PD03-0078-0039


Figure E-7. Transfer of OCV from hot shop onto transport trailer

- Hot Shop reconfigured to support TRUPACT-157 disassembly operations. Figure E-8 show the Standard waste boxes (SWBs) staged for receipt of waste drums. Figure E-9 shows the payload just prior to disassembly.

3:45 p.m. Initiated payload disassembly operation. Four drums from top seven-pack removed. Detailed radiological contamination surveys (12 locations on each drum) are all within allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1000 dpm/100 cm<sup>2</sup> beta-gamma). Figure E-10 is a photo of smears taken of the first drum after it had been examined and it had left the tent.

- All drums were checked for filter and lock ringbolt tightness using finger-tight criteria. A container integrity inspection was performed by SWEPP operators. No discrepancies noted.





PD03-0078-054

Figure E-8. SWBs staged for receipt of waste drums.



PD03-0078-067

Figure E-9. Payload prior to disassembly.



PD03-0078-072

Figure E-10. Smears of the first drum after leaving the tent.

## January 30, 2003

8:50 a.m. Fifth and sixth drum removed from top seven-pack layer. Detailed radiological contamination surveys are within allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1,000 dpm/100 cm<sup>2</sup> beta-gamma). Finger tightness checks of filters and lock ringbolts do not identify any discrepancies. Container integrity determined to be adequate.

9:22 a.m. Initial smears on the lid of the seventh drum (IDRF741202484) were: 9 dpm/100 cm<sup>2</sup> alpha (drum filter area), 3 dpm/100 cm<sup>2</sup> alpha (drum lid), 19 dpm/100 cm<sup>2</sup> alpha (drum lid), and 39 dpm/100 cm<sup>2</sup> alpha (drum lid around bar code label). The smear of 39 dpm/100 cm<sup>2</sup> alpha was above allowable limits. A photo of the first smear being taken is shown in Figure E-11. No other contamination above allowable limits was detected on other portions of the drum.

- Three follow-up lid smears were taken and the results were: 110 dpm/100 cm<sup>2</sup> alpha, 13 dpm/100 cm<sup>2</sup> alpha, and 33 dpm/100 cm<sup>2</sup> alpha (drum lid around filter area). Two of these smears were above the limit of 20 dpm/100 cm<sup>2</sup> alpha.

10:33 a.m. A glycerin-based fixative was applied to the drum lid to prevent any contamination spread.

- 10:35 a.m. Drum IDRF741202484 lock ring bolt was found to be loose (about 5 degrees rotation to the extent allowed by the tamper seal wire).
- Finger-tightness check of filter does not indicate any discrepancy. No container integrity discrepancies were noted.

11:01 a.m. Drum IDRF741202484 bagged in plastic bagging. During removal, operator notes that the lock ring could be rotated about 2-inches (bagging prevents further rotation). Drum placed in standard waste box. Contamination surveys of both the top and bottom of the drum ring are within allowable limits.

1:00 p.m. Processing of bottom seven-pack is initiated with removal of slip sheet and reinforcement sheet.


1:05 p.m. Eighth and ninth drums removed from payload. Radiological contamination surveys are all less than allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1000 dpm/100 cm<sup>2</sup> beta-gamma). Finger-tightness checks of filters and lock ringbolts do not identify any discrepancies. No container integrity discrepancies were noted. Figure E-12 shows the ninth drum being lowered into the SWB.

2:08 p.m. Tenth drum (IDRF74700411) radiological contamination surveys are all less than allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1000 dpm/100 cm<sup>2</sup> beta-gamma). Finger-tightness checks of filter and bolt do not identify any discrepancies. However, visual observation of jam nut indicates the nut was not seated against the lock ring. No container integrity discrepancies were noted.

2:48–6:07 p.m. Processing of eleventh through fourteenth drums completed. All radiological contamination surveys are within allowable limits (less than 20 dpm/100 cm<sup>2</sup> alpha and less than 1,000 dpm/100 cm<sup>2</sup> beta-gamma). Finger-tightness checks of the filters and lock ringbolts do not identify any discrepancies. No container integrity discrepancies were noted. Drum handling operations at 5:00 p.m. are shown in Figure E-13.


4:50 p.m. Gamma scans of plastic wrap from payload discover no contamination above background.





PD03-0078-108

Figure E-11. Drum 2484 Smear 1.



PD03-0078-093

Figure E-12. Ninth drum being lowered into an SWB.



PD03-0078-108

Figure E-13. Drum handling operations.



## January 31, 2003

7:00 a.m – 7:00 p.m. Completed closure of five of six SWBs containing the TRUPACT-157 payload drums. Figure E-14 shows SWB IDRFXWB030001 prior to closure.

- Received direction from DOE-ID to recover the contaminated drum (IDRF741202484) from the standard waste box and place in separate SWB for future testing. Direction also received to keep the OCV and ICV in storage at RWMC pending future decisions.
- Relocated completed SWBs from Hot Shop to Warm Shop for staging.



PD03-0078-121

Figure E-14. IDRFXWB030001 with four drums of filter waste.

## **February 1-2, 2003**

- Implemented procedural changes to TAN procedure to allow removal of contaminated drum.
- Modified procedure submitted to WIPP for approval.
- Modifications to WWIS to support SWB payload configuration changes.

## February 3, 2003

Obtained WIPP approval of procedure changes.

7:00 a.m.–2:43 p.m. Completed removal of contaminated drum and transfer into SWB #7 and lid closure.

3:10 p.m. SWBs #3 and #7 transferred out of hot shop to await transfer to RWMC.

3:45 p.m. Completed ICV box closure, and transferred onto transport trailer (Figure E-15).

4:54 p.m. Completed loading all seven SWBs and the ICV for transport to RWMC.



PD03-0079-05

Figure E-15. ICV in disposal box being loaded on transport trailer.

OCV transported to RWMC for storage (Figure E-16).

7:00 p.m. Radiological smears of slipsheets, remaining shrink-wrap, guide tubes, pallet, and containment tent completed. All results were less than allowable limits.



## February 4, 2003

9:30 a.m. ICV and seven SWBs shipped to RWMC



PD03-0079-10

Figure E-16. Seven SWBs and ICV departing for RWMC.

- ICV and one SWB containing the contaminated drum IDRF741202484 stored in WMF-628
- Six SWBs delivered to Advanced Mixed Waste Treatment Project building WMF-618 for loading by the WIPP Mobile TRUPACT-II Loading Team.

## February 5, 2003

WIPP Mobile Loading Team completes loading of six SWBs containing the TRUPACT-157 payload drums (minus one drum) into three TRUPACT-II's.

## **February 12, 2003**

Assimilation, review, certification, and release of TRUPACT-II shipment containing the TRUPACT-157 payload (minus one drum) completed.

3:20 p.m. Shipment IN030001 leaves RWMC destined for WIPP (Figure E-17).



PD03-0080-01

Figure E-17. Loaded TRUPACT-II depart for WIPP.

## **February 13, 2003**

Shipment IN030001 arrives at WIPP.

## **February 19, 2003**

Six SWBs containing TRUPACT-157 payload (minus one drum) emplaced at WIPP.



**Appendix F**  
**Video Log of Recovery Operations**





## Appendix F

### Video Log of Recovery Operations

Digital photos taken during operations, with descriptions have been interspersed throughout the report. Therefore, they have not been included in this appendix. Six remotely controlled cameras, one boroscope camera were used during the operations. One camera was recorded from the main monitor, and four of the cameras were recorded from a four-screen/split screen monitor starting on February 23, 2003. Twenty-nine videotapes were recorded during the recovery operations and are described in Table F-1. A more detailed summary of activities and elapsed tape times for the Main Monitor videotapes is provided in Table F-2.

Three segments of video showing the smears of drum IDRF741202484 are included in electronic MPEG movie format on this disk with the Appendices. They are the [initial smears](#), [initial smears of the drum bottom](#), and [follow-up smears of the lid](#), that are included in the electronic copy of this report. A [separate video of the entire processing sequence for drum IDRF741202484 is also provided on the disk](#).

Table F-1. Log of videotapes recorded during recovery operations.

Date	Main Monitor Tape No.	Time (24 hr format)	Split Screen Tape No.	Time	Activities / Notes / Observations
1/27/2003	1	1002 -- 1307			TRUPACT- 157 moved into hot shop, initial disassembly operations.
	2	1307 -- 1442, 1535 -- 1548, 1605 -- 1623			Remove OCV lid, vent port survey. Surveys inside ICV and air samples of ICV volume.
	3	1623 -- 1756			Remove ICV lid, visual and puppet CAM inspections of payload inside ICV.
1/28/2003	4	0833 -- 1257 (intermittent)	1SS	1225 -- 1428	Continue surveys of ICV and payload. Puppet CAM inspection of drum filters. Remove payload from ICV. Conduct surveys of payload.
	5	1259 -- 1330, 1341 -- 1417, 1618 -- 1702	2SS	1618 --	Payload into tent. ICV Sleeve removed, Inspect interior and rad surveys of inside of ICV. Power glitches cause videotape outages.
	6	1702 -- 1813	2SS	--1813	ICV reassembled and placed in disposal box. OCV reassembled
1/29/2003	7	0914 -- 1026, 1114 -- 1127, 1231 -- 1301	3SS	1234 -- 1444	OCV re-surveyed and moved out of hot shop. SWBs staged in hot shop.
	8	1301 -- 1418, 1501 -- 1546	4SS	1444 --	Video inspection of payload, remove wrapping and top slip sheet from payload.
	9	1546 --	4SS	--1643	Drum IDRF004102263 inspected and moved to SWB, Drum IDRF004002801 inspected.
	9	-- 1745	5SS	1643 --	IDRF004002801 moved to SWB 0001. Drum IDRF004101890 inspected and moved to SWB 0001.
	10	1745 -- 1815	5SS	-- 1818	Drum IDRF004102254 inspected and moved to SWB 0001

Table F-1. (Continued).

Date	Main Monitor Tape No.	Time (24 hr format)	Split Screen Tape No.	Time	Activities / Notes / Observations
1/30/2003	11	0835 -- 1038	6SS	0836 -- 1035	Drum IDRF004002790 inspected and moved to SWB 0002. Video inspection of top pack lower slip sheet. Drum IDRF741202088 inspected and moved to SWB 0003. Drum IDRF741202484 inspection begins 0952.
Date	Main Tape No.	Time	Split Screen Tape No.	Time	Activities / Notes / Observations
1/30/2003	12	1045 -- 1104, 1106 -- 1110, 1254 --	7SS	1035 -- 1147, 1250 -- 1353	Drum IDRF741202484 bagged and taped. Drum lockring rotated by hand. Drum moved to SWB 0003. Upper slipsheet and wrapping removed from lower payload pack. Drum IDRF741205405 inspected, moved to SWB 0003. Drum IDRF741201615 inspected.
	12	-- 1430	8SS	1353 --	IDRF741201615 moved into SWB 0003. Drum IDRF074700411 inspected.
	13	1430 -- 1518, 1645 --	8SS	-- 1518, 1630 -- 1705	IDRF074700411 into SWB. Drum IDRF741201718 inspected and moved to SWB 0004. Drum IDRF741204650 inspected and moved to SWB 0004.
	13	-- 1804	9SS	1705 --	Drum IDRF074700394 inspected and moved to SWB 0006, Drum IDRF074221338 inspected.
	14	1804 -- 1810	9SS	--1815	Drum IDRF074221338 moved to SWB 0003.
1/31/2003	14	0815 -- 0919, 0958 -- 1051	10SS	0817 -- 0920, 1005 -- 1102	Examination of TID on bagged drum IDRF741202484. Visual examination of lower pack bottom slip plate. Inspection of dunnage drums. Begin removing rain water from dunnage drums.
	15	1053 -- 1121, 1252 -- 1331, 1343 -- 1436	11SS	1113 -- 1123, 1254 -- 1327, 1344 --	Replace damaged gasket sections on SWBs. Dunnage drums removed from SWB 0002, inspected for rain water, and returned to the SWB. SWB lids placed on boxes, begin installing bolts.
	16	1436 -- 1449, 1552 -- 1715	11SS	-- 1451	Torque wrench fails, obtain new torque wrench. All SWBs except 0003 closed, surveyed, and moved to warm shop for weekend storage.
2/3/2003	17	1304 -- 1507			Removal of drum IDRF074700484 from SBW IDRFXWB030003 and placement in IDRFXWB030007. Installation of dunnage drums, and torquing of the SBW lids. Removal of the SBWs from the TAN Hot Shop.
	18	1509 -- 1518			Removal of the SBW's from the TAN Hot Shop.

Table F-2. TRUPACT-II 157 Main Monitor Videotape Detailed Summary

Tape #	Description	Start Location on Tape (Elapsed Time)		
		Hr	Min	Sec
1	TRUPACT assembly rolls into hot shop extension	0	00	05
1	Trupact assembly placed in work platform	0	14	41
1	Second half of work platform placed	0	31	20
1	Cover OCA Lid with plastic	0	45	00
1	Tape plastic to lid	0	48	00
1	Lifting fixture legs into OCV lid pockets	1	19	40
1	Lift OCA lid and survey	1	56	00
2	Move OCV Lid	0	07	25
2	Lifting fixture to ICV Lid	0	15	10
2	Check Lock ring	0	20	55
2	Sleeve around vessel	0	54	14
2	ACGLF to ICV (unsure about this shot)	1	21	30
2	Lift ICV lid	1	48	40
2	Survey and air sample interior of ICV	1	53	10
3	Remove ICV Lid	0	29	30
		0	33	30
		0	38	40
		0	42	25
3	Puppet CAM inspection of payload	1	17	01
		1	20	41
		1	27	58
4	Surveys of payload sides	0	05	30
4	Survey shots	0	38	00
4	Puppet CAM shots	0	42	40
4	Lifting fixture to payload, and lift payload out of ICV	1	27	00
4	Video exam of payload	1	43	40
5	Lift Payload into tent	0	03	25
5	Lift sleeve off payload	0	23	40
5	survey ICV interior	0	45	05
5	Remove sleeving from OCV/ICV cavities	1	29	10
6	Lowr ICV Lid onto cavity	0	03	30
6	Lift ICV out of OCV	0	20	50
6	Lower ICV into disposal box	0	28	30
6	Surveys of OCV cavity	0	41	10
6	OCV lid onto cavity	0	51	55

Table F-2. (continued).

Tape #	Description	Start Location on Tape (Elapsed Time)		
		Hr	Min	Sec
7	Remove work platform half from OCV	0	21	00
7	Remove OCV from Hot Shop	0	43	00
7	Move SWB 02 into hot shop	1	14	30
7	Removing the lid from SWB 02	1	53	25
8	Installing gaskets on SWBs	0	38	45
8	Removal of payload top slip sheet	1	56	40
9	1st Drum Lift to inspection (IDRF004102263, pos. # 2)	0	01	15
9	Lid smears	0	10	10
9	Out of tent	0	35	00
9	Maslin swipe	0	42	18
9	into SWB	0	48	30
9	2nd Drum into inspection area (IDRF004002801, pos. #3)	0	50	00
9	Survey top	0	52	40
9	Tightness check	1	03	00
9	Maslin swipe	1	16	25
9	Into SWB	1	25	15
9	3rd Drum into inspection area (IDRF004101890, pos. #4)	1	30	20
9	Out of tent	1	50	00
9	Maslin swipe	1	54	10
9	Into SWB	1	57	43
9	4th Drum into inspection area (IDRF004102254, pos. #1)	1	59	40
9	Lid smears	2	01	30
10	Out of tent	0	13	15
10	Maslin swipe	0	17	00
10	Into SWB	0	19	30
11				
11	5th Drum into inspection area (IDRF004002790, pos. #5)	0	14	50
11	Lid smears	0	15	55
11	Maslin swipe	0	39	00
11	6th Drum into inspection area (IDRF741202088, pos. #7)	0	46	45
11	Lid smears	0	48	40
11	Out of tent	1	07	10
11	Maslin swipe	1	09	20
11	into SWB	1	13	30
11	7th Drum Lid Smears (IDRF741202484, pos. #6)	1	16	45
11	Drum IDRF741202484 2nd lid smears	1	28	30

Table F-2. (continued).

Tape #	Description	Start Location on Tape (Elapsed Time)		
		Hr	Min	Sec
11	Application of fixative	1	54	10
11	Filter tightness check	1	58	37
12	Out of tent	0	01	55
12	Tape below lock ring	0	03	55
12	Lift drum to playpen	0	06	15
12	Maslin swipe	0	09	46
12	Move lock ring on drum	0	13	10
12	Move lock ring -- zoomed	0	14	05
12	Top pack lower slip sheet off	0	27	55
12	Lower pack upper slip sheet off	0	29	50
12	8th Drum to inspection area (IDRF741205405, pos. #8)	0	34	30
12	Check filter and lock ring	0	46	30
12	Out of tent	0	55	55
12	Lift to playpen	0	58	00
12	Maslin swipe	0	59	40
12	Into SWB	1	02	30
12	9th Drum into inspection area (IDRF741201615, pos. #9)	1	05	00
12	Lid smears	1	07	30
12	Bottom smears	1	12	38
12	Check filter and lock ring	1	18	15
12	Out of tent	1	27	10
12	Lift to playpen	1	29	40
12	Maslin swipe	1	31	20
12	Into SWB	1	35	35
12	10th Drum into inspection area (IDRF074700411, pos. #13)	1	38	50
12	Lid smears	1	40	35
12	Side smear	1	43	38
12	Bottom smears	1	45	40
12	Inspection of loose jamb nut	1	51	29
12	Check filter and lock ring	1	54	25
13	Out of tent	0	05	20
13	Lift to playpen	0	07	30
13	Maslin swipe	0	09	15
13	Into SWB	0	13	20
13	11th Drum into inspection area (IDRF741201718, pos. #10)	0	15	48
13	Lid smears	0	17	30
13	Check filter and lock ring	0	26	50

Table F-2. (continued).

Tape #	Description	Start Location on Tape (Elapsed Time)		
		Hr	Min	Sec
13	Out of tent	0	36	11
13	Lift to playpen	0	37	30
13	Maslin swipe	0	39	50
13	Into SWB	0	43	00
13	12th Drum into inspection area (IDRF741204650, pos. #14)	0	46	20
13	Check filter and lock ring	0	50	00
13	Out of tent	0	54	20
13	Lift to playpen	0	57	20
13	Maslin swipe	0	59	35
13	Into SWB	1	02	20
13	13th Drum into inspection area (IDRF074700394, pos. #12)	1	04	13
13	Lid smears	1	06	10
13	Bottom smears	1	09	40
13	Check filter and lock ring	1	16	10
13	Out of tent	1	30	24
13	Lift to playpen	1	32	55
13	Maslin swipe	1	35	45
13	Into SWB	1	38	00
13	14th Drum into inspection area (IDRF074221338, pos. #11)	1	40	15
13	Lid smears	1	41	35
13	Bottom smears	1	45	50
13	Check filter and lock ring	1	49	45
13	Change vestibule	1	58	30
13	Out of tent	1	59	40
13	Lift to playpen	2	01	50
14	Maslin swipe	0	00	00
14	Into SWB	0	00	50
14	Check lock ring seal (t-cup) on contam drum	0	07	25
14	Dunnage drums into SWBs	0	44	15
15	Lid onto SWB IDRFXWB030001	1	22	30
15	Torqueing lid on SWB 01	1	48	05
16	Maslin swipe survey SWBs IDRFXWB030001,-2,-4,-5,-6	1	04	15
16	SWB IDRFXWB030006 out of shop	1	13	10
16	SWB IDRFXWB030004 out of shop	1	20	20
16	Shift SWB 3 out of the way	1	22	15
16	SWB IDRFXWB030001 out of shop	1	25	50
17	Bring SWB IDRFXWB030007 into shop	0	04	15

Table F-2. (continued).

Tape #	Description	Start Location on Tape (Elapsed Time)		
		Hr	Min	Sec
17	Move contaminated drum from SWB 3 to SWB 7	0	40	50
17	Dunnage drums into SWBs	0	51	10
17	Lid onto SWB IDRFXWB030007	0	58	40
17	Bolts into SWB IDRFXWB030007	1	02	50
17	Torqueing lid on SWB IDRFXWB030007	1	17	00
17	Maslin swipe SWBs	1	59	00
18	SWB IDRFXWB03000 out of shop	0	00	30





**Appendix G**  
**Resumes of Investigators**



# Barry H. O'Brien

---

## Summary

Nineteen years of experience with chemical process development, pilot plant design and operation, and support of plant operations for high-level radioactive waste processes. Primary areas of expertise are fluidized-bed technology, solids processing, waste treatment, process control systems, modeling of aqueous nitrate/nitric acid processes, and hazardous waste management. Nine years of experience as a supervisor and technical lead. Registered Professional Engineer in Chemical Engineering.

## Experience

2000–Present Bechtel BWXT Idaho (BBWI) Idaho Falls, ID

### **Advisory Engineer, ChE Systems Design**

- Supported feasibility studies for treatment of non-HLW tank farm wastes and disposal as remote-handled TRU waste.
- Researched gasification and fuel cell technologies for next generation Coal Power Plants for Bechtel Power
- Was process engineer for design of a steam reformer demonstration unit to convert fossil fuel to hydrogen for use in fuel cells. Became the team expert on chemistry of the process and served as liaison for process issues for other disciplines. Modeled portions of the process using ASPEN, OLI, and HSC Chemistry.
- Prepared a feasibility study comparing methods of denitrating and grouting radioactive waste for disposal.
- Modeled feed blends and prepared process flowsheets for High Level Waste Evaporator operation in summer of 2001.
- Provide technical review of documents generated by the ChE Systems Design and by others. Verified calculations of TMI fuel drying and Irradiated Fuel Storage Facility fuel cooling requirements

1999-2000 Bechtel BWXT Idaho (BBWI) Idaho Falls, ID

### **Technical Lead, INTEC RCRA Liquid Sampling**

- Sampled waste processes at INTEC to support RCRA permitting of waste treatment processes.
- Prepared sampling plans, coordinated sampling with Operations and the Analytical Laboratories, and interpreted data.
- Managed a sampling budget of \$1.2M.

### **Technical Lead, Process Support**

- Led a team to identify and resolve off-gas plugging which caused shutdown of the New Waste Calciner Facility in May 1999.
- Provided direct process support and pilot plant testing for existing INTEC waste systems – High Level Waste Tank Farm, New Waste Calcining Facility, High Level Liquid Waste Evaporator, and Calcined Solids Storage Facilities.

1994-1999      Lockheed Martin Idaho Technologies Co      Idaho Falls, ID

**Technical Lead, Process Support**

- Provided direct process support and pilot plant testing for existing INTEC waste systems – High Level Waste Tank Farm, New Waste Calcining Facility, High Level Liquid Waste Evaporator, and Calcined Solids Storage Facilities.
- Maintained pilot plant equipment, procedures and training,.
- Managed a permitted hazardous waste storage facility for pilot plant wastes.
- Directed integrated process modeling for INTEC waste processes, including the Process Evaporative Waste Evaporator and Liquid Effluent Treatment and Disposal Facility.
- Managed and tracked budget accounts of \$440K and \$180K.
- Provided feed flowsheets to Operations for the New Waste Calcining Facility and High-level Liquid Waste Evaporator at INTEC.

1990-1994      Westinghouse Idaho Nuclear Co., Inc.      Idaho Falls, ID

**Subsection Manager, Pilot Plant Support and Development**

- Supervised a group of six engineers and scientists which provided process development for existing and new plant processes for high-level radioactive waste through process modeling, laboratory tests, mock-ups, and pilot-plant testing.
- Prepared schedules and budgets for the subsection with an annual budget of \$800K.
- Prepared feed flowsheets and provided trouble-shooting support for the New Waste Calcining Facility, a fluidized-bed process for converting liquid waste to granular solid.

1983-1990      Westinghouse Idaho Nuclear Co., Inc.      Idaho Falls, ID

**Engineer III and Senior Engineer I, High-Level Waste Process Development**

- Performed laboratory tests and modeling for various high-level waste processes such as the New Waste Calcining Facility, HEPA filter leach, and tank farm.
- Supervised construction and startup of the Enclosed 15-cm Diameter Calciner Pilot Plant.
- Specified, purchased, installed, and configured the distributed control system for the calciner pilot plants.
- Developed Expert Systems from process data for a fluidized-bed uranyl nitrate denitrator and radioactive waste calciner.

**Education**

1978–1982      University of Idaho      Moscow, ID  
B.S., Chemical Engineering. Graduated Cum Laude.

1982–1983      University of Idaho      Moscow, ID

- M.S., Chemical Engineering.
- Masters Thesis - "A Gradientless Spinning-Film Reactor for Gas-Liquid and Gas-Liquid-Solid Reaction Studies."

**Publications/  
Presentations**

- 2000 Summary of Waste Calcination at the Idaho Nuclear Technology and Engineering Center, INEEL/EXT-2000-01206. Co-author with B. J. Newby.
- 2000 NWCF Off-gas Line Restriction Identification and Resolution, INEEL/EXT-2000-00322. Co-author with J. A. Nenni, R. E. Schindler, and R. A. Wood.
- 2000 NWCF Calciner Emissions Inventory – Final Report for Test Series 1, 2, and 3, INEEL/EXT-2000-00114, with L. J. Young et. al.
- 1995 Estimation of Alkali Metal Mole Percent and Weight of Calcined Solids for ICPP Calcine, INEL-95/0184.
- 1993 Calcination Of Fluorinel-Sodium Waste Blends Using Sugar as a Feed, WINCO-1130, Westinghouse Idaho Nuclear Company, co-author with B. J. Newby and T. D. Thomson.
- 1991 "Inductive Classification of Pilot Plant Data from a Fluidized Bed Calciner," presented at ANS Topical Meeting. "AI91 Frontiers: Innovative Computing for the Nuclear Industry," September 1991, Jackson, Wyoming.
- 1990 "Inductive Classification of Pilot Plant Data from a Fluidized Bed Calciner," presented at the Westinghouse Artificial Intelligence/Neural Network Conference, June 1990, Baltimore, Maryland.
- 1986 "A Gradientless Spinning Film Reactor for Gas-Liquid and Gas-Liquid-Solid Reaction Studies," presented at the AIChE National Conference, November, 1986, Miami, Florida.

**Professional  
Societies**

- AIChE – Local section webmaster. Have served as treasurer, secretary, vice-chairman, chairman, and director for the local section.
- ISA – Local Section webmaster and Senior Member.

**Licenses**

Registered Professional Engineer in Chemical Engineering in Idaho since 1987.



# Jeffrey M. Lacy

Work: 526-2788

## EDUCATION

Registered Professional Engineer, State of Idaho, since 1995  
M.S., Engineering Mechanics, Montana State University, 1989  
B.S., Civil Engineering, with Honors, Montana State University, 1987

## PROFESSIONAL ENGINEERING EXPERIENCE—15 YEARS

2002 – Present. Advisory Engineer, Building Technologies and Energy Management, BBWI/INEEL  
1999 - 2002. Principal Research Engineer, Aerospace Systems Engineering, BWX Technologies.  
1989 - 1999. Staff Engineer, Applied Mechanics, BBWI/INEEL  
1987 - 1989. Engineering Research Assistant, Engineering Mechanics, Montana State University.

## BUILDING TECHNOLOGIES AND ENERGY MANAGEMENT, BBWI/INEEL, 2002–PRESENT

Principal Investigator on projects involving theoretical and experimental wind flow, energy flow, shock and vibration, strength of materials and structural systems.

## AEROSPACE ENGINEERING, BWX TECHNOLOGIES, 1999–2002

### Engineering Research

Principal researcher for the engine development of the Solar Orbit Transfer Vehicle Space Experiment. I planned and implemented complex physical experiments, wrote the data acquisition and system control software; designed, evaluated and installed test hardware; reduced and analyzed the data, and wrote test plans and reports [1,2].

### Automated Systems and Motion Control

Designed, implemented, and programmed multi-axis automated motion systems for phased array ultrasonic and laser profilometric inspection of manufactured parts, including rectilinear and elliptical/helical automated incrementing scans. Involved physical integration of disparate controllers, amplifiers, motors, and rotary and linear encoders.

## APPLIED MECHANICS, BBWI / INEEL, 1989 – 1999

Performed a variety of design, analysis, and research functions related to nuclear reactor safety, nuclear aerospace systems, hurricane wind evaluation, wind tunnel design, and structural response to wind and earthquake. Projects over this period included

### Aerospace systems

Topaz-II Joint U.S./Russian Space Program, Lead Structural Engineer, Flight Safety Team Kirtland Air Force Base, New Mexico 1993.

USAF/DOE Bimodal Program Design Team, 1993-1994

SPRE/ISUS Solar Bimodal Engine, 1994.

COMET Nuclear Rocket, 1992.

## Wind and Buildings Research

Hurricane Interception and Measurement, Principal Investigator, 1998 – 1999

Pilot Windstorm Center, Design Manager, 1998-1999

Windstorm Simulation Center, Design Lead, 1997

Manufactured home static and dynamic structural tests, 1998 – 1999

## Nuclear Reactor Safety

Advanced Test Reactor fuel buckling predictions, 1990-1992

## PUBLICATIONS

1. Lacy, J. M., Carmack, W. J., et al, "Creep Response of Rhenium to High-Temperature Cyclic Loads," Proceedings of the National Space and Missile Materials Symposium, June 24-28, 2001, Monterey, CA.
2. Carmack, W. J., Lacy, J. M., et al, "High-Temperature Thermal Conductivity of Graphite Felt Insulation," Proceedings of the National Space and Missile Materials Symposium, June 24-28, 2001, Monterey, CA.
3. Richins, W. D., Lacy, J. M., et al, "Full-Scale Structural Testing of a Single-Wide Manufactured Home," Proceedings of the World Conference on Timber Engineering, July 31 - Aug. 3, 2000, Whistler, BC.
4. Lacy, J. M., Larson, T.K., and Richins, W. D., "Defining Hurricane Winds – Engineers Capture Georges," Structure Magazine, Summer 1999 edition, June, 1999.
5. Lacy, J. M. et al, Operational Requirements and Concept for a Full-Scale Structural Wind Test Facility, INEEL/INT-99-00838, August, 1999.
6. Oh, C.H., and Lacy, J.M., "Numerical Calculations of Wind Flow in a Full-Scale Wind Test Facility," Proceedings of the 10<sup>th</sup> International Conference on Wind Engineering, Copenhagen, Denmark, June, 1999.
7. Richins, W. D., et al, Full-Scale Structural Testing of a Single-Wide Manufactured Home, Oakwood Model 1320; 14 ft. x 62 ft., INEEL-EX-1999-301, March, 1999.
8. Lacy, J.M., and Earl, J.S., Main Drive Selection for the Windstorm Simulation Center, INEEL/EXT-98-00089, February, 1998.
9. Lacy, J. M., O'Brien, C. C., "Design Considerations for a Full-Scale Windstorm Test Facility," Eighth U.S. National Conference on Wind Engineering, Baltimore, MD, June, 1997
10. Idaho National Engineering and Environmental Laboratory, Partnership for Natural Disaster Reduction, Test Complex Phase 1 Conceptual Design Report, INEEL-EXT-97-00436, May, 1997
11. Lacy, J. M., Earthquake Engineering Needs and Solutions, Proceedings of the INEL Seismic Testing Workshop, INEL-95/0587, December, 1995.
12. Schaefer, E. D., and Lacy, J.M., "Structural Evaluation of Topaz-II, The Russian Space-Based Nuclear Reactor," IES 19<sup>th</sup> Space Simulation Conference, Baltimore MD, October, 1996.
13. Lacy, J. M., and Miller, G. K., "Modeling Considerations for Large Deformation Impact Problems," ASME 4<sup>th</sup> International Conference on Nuclear Engineering, pp 497-501, 1996.
14. Reynolds, E., Schaefer, E.D., Polansky, G. , Lacy, J.M., Bocharov, A., "Utilizing a Russian Space Nuclear Reactor for a United States Space Mission: Systems Integration Issues," Proceedings, 11<sup>th</sup> Symposium on Space Nuclear Power and Propulsion, Albuquerque, NM, January, 1994.



# KIP E. ARCHIBALD

1914 Burlwood Drive  
Idaho Falls, Idaho 83402  
Home: 529-8865  
Work: 526-3187

## EDUCATION

**B. S. Mechanical Engineering**, University of Idaho, 1989.

## EXPERIENCE

1999 – present **PRINCIPAL ENGINEER** , BBWI

Project Team member for the Cold Crucible Induction Melter.

Primary responsibilities include researching and testing of various decontamination and waste minimization techniques.

Responsible for planning and conducting evaluations of new waste minimization technologies including procuring equipment, directing tests, and evaluating results.

Responsible for deploying new decontamination techniques at INTEC, training operators on new techniques, writing and aiding in completing SO tests and operating procedures.

Project Team Member (FY2000) for testing and deployment of NPOx decontamination process.

Project Team Member for Debris Treatment at the NWCF Facility.

Principal Investigator (FY2001) responsible for making NPOx decontamination process mobile and ready for deployment.

Project Team Member for evaluating for a Plasma Etching process that is being developed at UCLA. This process is being developed to aid in the decontamination of material. Responsibilities were to provide test coupons and to compare this technique to other decontamination techniques.

1995 – 1999 **PRINCIPAL ENGINEER** , LMITCO

Primary responsibilities include researching and testing of various decontamination and waste minimization techniques.

Responsible for planning and conducting evaluations of new waste minimization technologies including procuring equipment, directing tests, and evaluating results.

Responsible for implementing new techniques in the plant, training operators on new techniques, writing and aiding in completing SO tests and operating procedures.

Project Team Member for installation and testing of NWCF liquid abrasive system.

Project Team Member for creating waste generator procedure.

1992 – 1995 **SENIOR ENGINEER**, WINCO

Primary responsibilities include researching and testing of various decontamination methods. Extensive involvement with:

- **CO<sub>2</sub> Pellet Blasting** – Designed a test plan and conducted a 13-week test of the CO<sub>2</sub> pellet blasting method.
- **Vacuum Systems** – Conducted research of all the DOE sites to determine the criteria for selecting the vacuum system to be used in ICPP decontamination activities.
- **Concrete Decontamination** – Designed a test plan and conducted testing of three concrete decontamination methods. Brought three vendors onsite to demonstrate proven, new, and experimental methods.

Involved with NEPA, RCRA, Safety, and waste disposal issues while conducting demonstrations.

Involved with supporting the upgrade of the NWCF decontamination facility for debris treatment.

Technical support for the Decontamination and Decommissioning group.

1991 – 1992 **ENGINEER**, WINCO

Reviewed and dispositioned Nonconformance Reports (NCRs), Construction Interface Documents (CIDs), drawings, and vendor data for the following FPR Projects: 1) siding, 2) roofing, 3) piping, 4) slab tanks, and 5) steel cylindrical vessels.

Developed and performed SO testing.

1990 – 1991 **ENGINEER**, WINCO

Prepared and revised operating procedures, manuals, data sheets, and other documents for the liquid effluent treatment and disposal (LET&D) system and the PWL drain system in support of the New Waste Calcining Facility (NWCF) startup. This involved research and development of all technical aspects; as both systems were new and no previous procedures existed.

PUBLICATIONS

“CO<sub>2</sub> Pellet Blasting Literature Search and Decontamination Scoping Tests Report,” December 1993.

“ICPP Decontamination Development Program,” April 1994.

“Waste Minimization and Decontamination Development at the ICPP,” August 1994.

“A Review of Decontamination Technologies under Development and Demonstration at the ICPP,” November 1994.

“Concrete Decontamination Scoping Tests,” January 1995.

“Development of Waste Minimization and Decontamination Technologies at the Idaho Chemical Processing Plant,” May 1995.

“Liquid Abrasive Pressure Pot Scoping Tests Report,” January 1996.

“CO<sub>2</sub> Pellet Blasting Studies,” January 1997.

“Cleaning and Decontamination Using Strippable and Protective Coatings at the Idaho National Engineering and Environmental Laboratory,” March 1999.

“NWCF Facility Waste Streams,” August 1999.

“Tests Conducted with Strippable Coatings,” August 1999.

“Nitric Acid/Potassium Permanganate/Oxalic Acid (NPOx) System Modifications,” September 2001.

#### PROFESSIONAL ORGANIZATIONS/QUALIFICATIONS

Member of the American Society of Mechanical Engineers (ASME) since 1988.

Trained Radiation and Respirator Worker.

Received a National Award for Pollution Prevention (June 2001)

#### REFERENCES

Mike Greene  
Pr. Tech. Spec.  
BBWI  
526-3239

Terry Todd  
Fellow Engr / Sci.  
BBWI  
526-3365

Julia Tripp  
Advisory Engineer  
BBWI  
526-3876

